

**OWNER:** GURLEY LEEP OLDSMOBILE-CADILLAC, INC.  
**ADDRESS:** 51366 SIMMONS DRIVE  
SOUTH BEND IN 46637  
**PHONE:** 574 532 3395  
**FAX:** 574 247 2200

**OPERATOR:** DUNCAN AVIATION INCORPORATED - BATTLE CREEK  
**ADDRESS:** 15745 SOUTH AIRPORT ROAD  
BATTLE CREEK MI 49015  
**PHONE:** 269-969-8400  
**FAX:** 269-969-8432

**ANALYST:** ERIC FOSTER  
**EMAIL:** EFOSTER@CAMPSYSTEMS.COM

+1-316-928-7887 (DIRECT)  
1-866-581-2267 (OFFICE)  
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

**AIRCRAFT SERIAL/REGNO:** 45-330/N36GL      **MODEL:** LEARJET 45      **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 26-MAR-2007	3787.7 A/C HRS	as of 20-JAN-2021	A/C HRS	as of ___/___/___
	2992 AFL	as of 20-JAN-2021	AFL	as of ___/___/___
	1233.12 APH	as of 31-DEC-2020	APH	as of ___/___/___

**APU SERIAL/PART:** P-366/3800726-1      **MODEL:** RE100 (CIMMS)      **MANUFACTURER:** HONEYWELL

INSTALLED ON 26-MAR-2007	LAST ACTUALS		CURRENT ACTUAL	
4.32 APU HRS	1233.12 APU HRS	as of 31-DEC-2020	APU HRS	as of ___/___/___
28 APUS	2635 APUS	as of 31-DEC-2020	APUS	as of ___/___/___

**ENGINE NO. 1 SERIAL/PART:** P-116817C/3060084-2      **MODEL:** TFE731-20BR-1B      **MANUFACTURER:** HONEYWELL

INSTALLED ON 27-MAR-2007	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS      0 A/C HRS	3787.7 ENG. HRS	as of 20-JAN-2021	ENG. HRS	as of ___/___/___
0 ENC	2992 ENC	as of 20-JAN-2021	ENC	as of ___/___/___

**ENGINE NO. 2 SERIAL/PART:** P-116818C/3060084-2      **MODEL:** TFE731-20BR-1B      **MANUFACTURER:** HONEYWELL

INSTALLED ON 27-MAR-2007	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS      0 A/C HRS	3787.7 ENG. HRS	as of 20-JAN-2021	ENG. HRS	as of ___/___/___
0 ENC	2992 ENC	as of 20-JAN-2021	ENC	as of ___/___/___



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 05</b>	<b>TIME LIMITS/MAINTENANCE CHECKS</b>								
051101	PHASE A1-300 HOUR CHECKS								
05.110	PKG 1	MOS	12				13-JAN-2021	<b>13-JAN-2022</b>	27-JAN-2022
		HRS/MSC	300	+14d/-14d			3778.2	<b>4078.2</b>	4103.2
	REF: See Workcard	AFL		+25/-25			2986		
051102	PHASE A2-300 HOUR CHECKS								
	PKG 2	MOS	12				13-JAN-2021	<b>13-JAN-2022</b>	27-JAN-2022
		HRS/MSC	300	+14d/-14d			3778.2	<b>4078.2</b>	4103.2
	REF: See Workcard	AFL		+25/-25			2986		
051103	PHASE A3-300 HOUR CHECKS								
	PKG 3	MOS	12				13-JAN-2021	<b>13-JAN-2022</b>	27-JAN-2022
		HRS/MSC	300	+14d/-14d			3778.2	<b>4078.2</b>	4103.2
	REF: See Workcard	AFL		+25/-25			2986		
051104	PHASE A4-300 HOUR CHECKS								
	PKG 4	MOS	12				13-JAN-2021	<b>13-JAN-2022</b>	27-JAN-2022
		HRS/MSC	300	+14d/-14d			3778.2	<b>4078.2</b>	4103.2
	REF: See Workcard	AFL		+25/-25			2986		
051105	PHASE A5-300 HOUR CHECKS								
	PKG 5	MOS	12				13-JAN-2021	<b>13-JAN-2022</b>	27-JAN-2022
		HRS/MSC	300	+14d/-14d			3778.2	<b>4078.2</b>	4103.2
	REF: See Workcard	AFL		+25/-25			2986		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051106	PHASE A6-300 HOUR CHECKS							
	PKG 6	MOS	12			13-JAN-2021	<b>13-JAN-2022</b>	27-JAN-2022
		HRS/MSC	300			3778.2	<b>4078.2</b>	4103.2
	REF: See Workcard	AFL				2986		
051201	PHASE B1 600 HOUR CHECKS							
	PKG 7	MOS	24			29-JAN-2020	<b>29-JAN-2022</b>	12-FEB-2022
		HRS/MSC	600		-20.1	3544.5	<b>4124.4</b>	4149.4
	REF: See Workcard	AFL				2781		
051202	PHASE B2 600 HOUR CHECKS							
	PKG 8	MOS	24			29-JAN-2020	<b>29-JAN-2022</b>	12-FEB-2022
		HRS/MSC	600		-20.1	3544.5	<b>4124.4</b>	4149.4
	REF: See Workcard	AFL				2781		
051203	PHASE B3 600 HOUR CHECKS							
	PKG 9	MOS	24			29-JAN-2020	<b>29-JAN-2022</b>	12-FEB-2022
		HRS/MSC	600		-20.1	3544.5	<b>4124.4</b>	4149.4
	REF: See Workcard	AFL				2781		
051204	PHASE B4 600 HOUR CHECKS							
	PKG 10	MOS	24			29-JAN-2020	<b>29-JAN-2022</b>	12-FEB-2022
		HRS/MSC	600		-20.1	3544.5	<b>4124.4</b>	4149.4
	REF: See Workcard	AFL				2781		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051205	PHASE B5 600 HOUR CHECKS							
	PKG 11	MOS	24	+14d/-14d		29-JAN-2020	<b>29-JAN-2022</b>	12-FEB-2022
		HRS/MSC	600	+25/-25	-20.1	3544.5	<b>4124.4</b>	4149.4
	REF: See Workcard	AFL				2781		
051206	PHASE B6 600 HOUR CHECKS							
	PKG 12	MOS	24	+14d/-14d		29-JAN-2020	<b>29-JAN-2022</b>	12-FEB-2022
		HRS/MSC	600	+25/-25	-20.1	3544.5	<b>4124.4</b>	4149.4
	REF: See Workcard	AFL				2781		
051301	PHASE C1 1200 HOUR CHECKS							
	PKG 13	MOS	48	+14d/-14d		08-MAR-2019	<b>08-MAR-2023</b>	22-MAR-2023
		HRS/MSC	1200	+25/-25	-24.4	3241.7	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL				2541		
051302	PHASE C2 1200 HOUR CHECKS							
	PKG 14	MOS	48	+14d/-14d		08-MAR-2019	<b>08-MAR-2023</b>	22-MAR-2023
		HRS/MSC	1200	+25/-25	-24.4	3241.7	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL				2541		
051303	PHASE C3 1200 HOUR CHECKS							
	PKG 15	MOS	48	+14d/-14d		08-MAR-2019	<b>08-MAR-2023</b>	22-MAR-2023
		HRS/MSC	1200	+25/-25	-24.4	3241.7	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL				2541		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051304	PHASE C4 1200 HOUR CHECKS							
	PKG 16	MOS	48	+14d/-14d		08-MAR-2019	<b>08-MAR-2023</b>	22-MAR-2023
		HRS/MSC	1200	+25/-25	-24.4	3241.7	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL				2541		
051305	PHASE C5 1200 HOUR CHECKS							
	PKG 17	MOS	48	+14d/-14d		08-MAR-2019	<b>08-MAR-2023</b>	22-MAR-2023
		HRS/MSC	1200	+25/-25	-24.4	3241.7	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL				2541		
051306	PHASE C6 1200 HOUR CHECKS							
	PKG 18	MOS	48	+14d/-14d		08-MAR-2019	<b>08-MAR-2023</b>	22-MAR-2023
		HRS/MSC	1200	+25/-25	-24.4	3241.7	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL				2541		
051401	PHASE D1 2400 HOUR CHECKS							
	PKG 19	MOS	96	+14d/-14d	-15	10-APR-2015	<b>26-MAR-2023</b>	09-APR-2023
		HRS/MSC	2400	+25/-25		2017.3	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL						
051402	PHASE D2 2400 HOUR CHECKS							
	PKG 20	MOS	96	+14d/-14d	-15	10-APR-2015	<b>26-MAR-2023</b>	09-APR-2023
		HRS/MSC	2400	+25/-25		2017.3	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL						



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051403	PHASE D3 2400 HOUR CHECKS							
	PKG 21	MOS	96	+14d/-14d	-15	10-APR-2015	<b>26-MAR-2023</b>	09-APR-2023
		HRS/MSC	2400	+25/-25		2017.3	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL						
051404	PHASE D4 2400 HOUR CHECKS							
	PKG 22	MOS	96	+14d/-14d	-15	10-APR-2015	<b>26-MAR-2023</b>	09-APR-2023
		HRS/MSC	2400	+25/-25		2017.3	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL						
051405	PHASE D5 2400 HOUR CHECKS							
	PKG 23	MOS	96	+14d/-14d	-15	10-APR-2015	<b>26-MAR-2023</b>	09-APR-2023
		HRS/MSC	2400	+25/-25		2017.3	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL						
051406	PHASE D6 2400 HOUR CHECKS							
	PKG 24	MOS	96	+14d/-14d	-15	10-APR-2015	<b>26-MAR-2023</b>	09-APR-2023
		HRS/MSC	2400	+25/-25		2017.3	<b>4417.3</b>	4442.3
	REF: See Workcard	AFL						
051500	4800 HOUR CHECKS							
	PKG 25	MOS				26-MAR-2007		
		HRS/MSC	4800	+25/-25		0	<b>4800</b>	4825
	REF: See Workcard	AFL				0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051600	9600 HOUR CHECKS								
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0	9600	9625
	REF: See Workcard	AFL					0		
051700	MAJOR LANDING GEAR INSPECTION								
	PKG 27	MOS					26-MAR-2007		
		HRS/MSC					0		
	REF: See Workcard	AFL	10000				0	10000	10025
ENGINE NO. 1 Model : TFE731-20/-40/-60 (CIMMS) Serial # P-116817C Part # 3060084-2									
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					27-JUL-2020		
		HRS/MSC	150				3663.9	(3813.9) 3813.9	3913.9
	REF: LMM 72-00-00	ENC					2882		
057120	NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					19-DEC-2006		
		HRS/MSC	N/A				0		
	REF: LMM 72-00-00	ENC					0		
057130	NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					27-JUL-2020		
		HRS/MSC	600				3663.9	(4263.9) 4263.9	
	REF: LMM 72-00-00	ENC					2882		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057140	NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					27-JUL-2020		
		HRS/MSC	800				3663.9	(4463.9) 4463.9	4513.9
	REF: LMM 72-00-00	ENC					2882		
057150	NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					03-AUG-2018		
		HRS/MSC	1200				3058.3	(4258.3) 4258.3	
	REF: LMM 72-00-00	ENC					2403		
057160	NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					03-AUG-2018		
		HRS/MSC	1600				3058.3	(4658.3) 4658.3	4708.3
	REF: LMM 72-00-00	ENC					2403		
<b>ENGINE NO. 2 Model : TFE731-20/-40/-60 (CIMMS) Serial # P-116818C Part # 3060084-2</b>									
057110	NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					27-JUL-2020		
		HRS/MSC	150				3663.9	(3813.9) 3813.9	3913.9
	REF: LMM 72-00-00	ENC					2882		
057120	NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					19-DEC-2006		
		HRS/MSC	N/A				0		
	REF: LMM 72-00-00	ENC					0		





# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057130	NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					27-JUL-2020		
		HRS/MSC	600				3663.9	(4263.9)	4263.9
	REF: LMM 72-00-00	ENC					2882		
057140	NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					27-JUL-2020		
		HRS/MSC	800	+50/-300			3663.9	(4463.9)	4463.9
	REF: LMM 72-00-00	ENC					2882		4513.9
057150	NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					06-AUG-2018		
		HRS/MSC	1200				3058.3	(4258.3)	4258.3
	REF: LMM 72-00-00	ENC					2403		
057160	NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					06-AUG-2018		
		HRS/MSC	1600	+50/-100			3058.3	(4658.3)	4658.3
	REF: LMM 72-00-00	ENC					2403		4708.3



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 00</b>	<b>INFORMATION</b>								
CI45-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E								
		MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI45</b>	HRS/MSC -							
		AFL							
CI45-160527	REVIEW LEARJET AMM REVISION 66								
		MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI45</b>	HRS/MSC -							
		AFL							
CI45-160603	REVIEW LEARJET 45 AMM TR 4-40								
		MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI45</b>	HRS/MSC -							
		AFL							
CI45-160613	REVIEW LEARJET 45 AMM TR 5-110								
		MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI45</b>	HRS/MSC -							
		AFL							
CI45-161207	REVIEW LEARJET 45 EINSPECTOR REVISION 2016.12.07								
		MOS							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI45</b>	HRS/MSC -							
		AFL							
CI45-161207B	REVIEW LEARJET 45 AMM REVISION 67								
		MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI45</b>	HRS/MSC -							
		AFL							

## Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI45-170118	REVIEW LEARJET 45 EINSPECTOR REVISION 2017.01.18								
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-170421	REVIEW LEARJET 45 AMM REVISION 68								
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-170421A	REVIEW LEARJET 45 EINSPECTOR REVISION 2017.04.21								
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-170504	REVIEW LEARJET 45 EINSPECTOR REVISION 2017.05.04								
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-181109B	REVIEW LEARJET 45/45XR AMM REVISION 71						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-190429A	REVIEW LEARJET 45/45XR AMM REV 72						(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF CI45	MOS HRS/MSC - AFL							

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ CI45-200529	REVIEW AUDIT SUMMARY CHANGE FORM								
		MOS					(EBT)		
<b>AUDIT SUMMARY CHANGE FORM</b>	REF: RCF CI45	HRS/MSC -							
		AFL							
+ CI45-210120	REVIEW LEARJET 45/45XR AUDIT SUMMARY CHANGE FORM								
		MOS					(EBT)		
<b>AUDIT SUMMARY CHANGE FORM</b>	REF: RCF CI45	HRS/MSC -							
		AFL							
	NEW REQUIREMENT ADDED ON 20-JAN-2021 (EFFECTIVE: 20-JAN-2021). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
<b>ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116817C Part # 3060084-2</b>									
EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF EC04-180802	HRS/MSC -							
		ENC							
<b>ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116818C Part # 3060084-2</b>									
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF EC04-180802	HRS/MSC -							
		ENC							
<b>CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS</b>									
+ 5-50-00-BS	INSPECTION BIRD STRIKE								
		MOS							
<b>INSPECT</b>	REF: GENERIC NO REF	HRS/MSC A/R							
		AFL							
5-50-00-CS	INSPECTION PRESSURE CABIN SKIN THICKNESS MEASUREMENT (P-STATIC TEST)								
		MOS					26-MAR-2007		
<b>INSPECT</b>	REF: AMM 05-50-00	HRS/MSC A/R					0		
		AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-50-00-ED	INSPECTION ELEVATOR DISCONNECT	MOS					26-MAR-2007		
	REF: AMM 05-50-00	HRS/MSC	O/C				0		
		AFL					0		
5-50-00-EV	PERFORM ENGINE VIBRATION TEST AND INSPECTION	MOS							
	REF: AMM 05-50-00	HRS/MSC	A/R						
		AFL							
5-50-00-GW	INSPECTION HIGH GROUND WIND GUST	MOS					26-MAR-2007		
<b>INSPECT</b>	REF: AMM 05-50-00	HRS/MSC	A/R				0		
		AFL					0		
5-50-00-HD	INSPECTION HEAT DAMAGE	MOS					26-MAR-2007		
	REF: AMM 05-50-00	HRS/MSC	O/C				0		
		AFL					0		
5-50-00-HE	INSPECTION HIGH ENERGY STOP	MOS					26-MAR-2007		
<b>INSPECT</b>	REF: AMM 05-50-00	HRS/MSC	A/R				0		
		AFL					0		
+ 5-50-00-HL	INSPECTION HARD LANDING	MOS							
<b>INSPECT</b>	REF: AMM 05-50-00	HRS/MSC	A/R						
		AFL							
+ 5-50-00-LS	INSPECTION LIGHTNING STRIKE	MOS					26-MAR-2007		
<b>INSPECT</b>	REF: AMM 05-50-00	HRS/MSC	A/R				0		
		AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-50-00-NH	INSPECTION NACELLE HEAT FAIL MESSGE	MOS					26-MAR-2007		
	REF: AMM 05-50-00	HRS/MSC	O/C				0		
		AFL					0		
5-50-00-OS	INSPECTION OVERSPEED RECOVERY LANDING GEAR	MOS					26-MAR-2007		
INSPECT	REF: AMM 05-50-00	HRS/MSC	A/R				0		
		AFL					0		
+ 5-50-00-OW	INSPECTION OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT)	MOS							
INSPECT	REF: AMM 05-50-00	HRS/MSC	A/R						
		AFL							
5-50-00-ST	INSPECTION SEVERE TURBULANCE AND OR MANEUVERS	MOS					26-MAR-2007		
INSPECT	REF: AMM 05-50-00	HRS/MSC	A/R				0		
		AFL					0		
5-50-00-SW	AIRCRAFT OPERATIONS IN SALT INFLUENCED ENVIRONMENTS	MOS					26-MAR-2007		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
5-50-00-TR	INSPECTION THRUST REVERSER SYSTEM	MOS					26-MAR-2007		
	REF: AMM 05-50-00	HRS/MSC	O/C				0		
		AFL					0		
5-50-00-UE	PERFORM UNSCHEDULED ENGINE CHANGE/REMOVAL INSPECTION	MOS					26-MAR-2007		
	REF: AMM 05-50-00	HRS/MSC	O/C				0		
		AFL					0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5-50-00-UE	PERFORM UNSCHEDULED ENGINE CHANGE/REMOVAL INSPECTION - NO. 1 ENGINE	MOS						26-MAR-2007	
	REF: AMM 05-50-00	HRS/MSC	O/C					0	
		AFL						0	
+ 5-50-00-UE	PERFORM UNSCHEDULED ENGINE CHANGE/REMOVAL INSPECTION - NO. 2 ENGINE	MOS						26-MAR-2007	
	REF: AMM 05-50-00	HRS/MSC	O/C					0	
		AFL						0	
5-50-00-VA	INSPECTION VOLCANIC ASH	MOS						26-MAR-2007	
INSPECT	REF: AMM 05-50-00	HRS/MSC	A/R					0	
		AFL						0	
5-50-00-WF	INSPECTION WING FLAP SYSTEM OVERSPEED CHECK	MOS						26-MAR-2007	
	REF: AMM 05-50-00	HRS/MSC	O/C					0	
		AFL						0	

**CHAPTER 05-50 TIME LIMITS/MAINTENANCE CHECKS**

5-50-00-FD	INSPECTION FOREIGN OBJECT DAMAGE	MOS							
	REF: AMM 05-50-00	HRS/MSC	O/C						
		AFL							

**CHAPTER 08 LEVELING AND WEIGHING**

082000	REWEIGH AIRCRAFT	MOS						20-APR-2007	
	REF: See Workcard	HRS/MSC	A/R					0	
		AFL						0	

**CHAPTER 11 PLACARDS AND MARKINGS**

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G1130000 (s)	CHECK CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS PKG 13	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	REF: AMM 11-30-00	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
<b>CHAPTER 12 SERVICING</b>									
5-19-00-Q1221064	FLAP ACTUATOR JOINT (P/N 145673-1) - APPLY CORROSION PREVENTIVE COMPOUND (CPC). (REFER TO 12-21-03.)	MOS					PKG	06-NOV-2009	
NOT APPLICABLE	REF: AMM 12-21-03	HRS/MSC AFL	N/A				717.1 549		
5-19-00-U1210004	LUBRICATE FLAP FLEXIBLE TRANSMISSION SHAFTS - BY HAND (U1210004)	MOS					PKG	26-MAR-2007	
	REF: GENERIC NO REF	HRS/MSC AFL	4800	+25/-25			0 0	4800	4825
+ AB1210060 (s)	MAIN LANDING GEAR UP-LOCK ACTUATOR - LUBRICATE PKG 5	MOS	12	+14d/-14d			PKG	13-JAN-2021	
	REF: AMM 12-21-01	HRS/MSC AFL	300	+25/-25			3778.2 2986		
O1210002 (s)	FLAP ACTUATORS - CHECK OIL LEVEL. PKG 10	MOS	24	+14d/-14d			PKG	29-JAN-2020	
	REF: AMM 12-21-03	HRS/MSC AFL	600	+25/-25			3544.5 2781		
Y1210000 (s)	NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. PKG 5	MOS	12	+14d/-14d			PKG	13-JAN-2021	
	REF: AMM 12-10-02	HRS/MSC AFL	300	+25/-25			3778.2 2986		
Y1210001 (s)	MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. PKG 5	MOS	12	+14d/-14d			PKG	13-JAN-2021	
	REF: AMM 12-10-03	HRS/MSC AFL	300	+25/-25			3778.2 2986		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y1210003 (s)	FLAP ACTUATOR BALLNUT - LUBRICATE. PKG 4 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210005 (s)	NOSE LANDING GEAR TRUNNION PIN - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210006 (s)	NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210007 (s)	NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION. PKG 5 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210009 (s)	NOSE GEAR DOOR HINGE - LUBRICATE. PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210011 (s)	MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210012 (s)	MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y1210013 (s)	MAIN LANDING GEAR TORQUE LINKS - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210014 (s)	MAIN GEAR DOOR HINGE - LUBRICATE PKG 5 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210016 (s)	PASSENGER/CREW DOOR HINGE - LUBRICATE PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210017 (s)	PASSENGER/CREW DOOR PINS - LUBRICATE PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210018 (s)	PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210019 (s)	EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210020 (s)	EMERGENCY EXIT DOOR PINS - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y1210021 (s)	BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210022 (s)	BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210023 (s)	OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210024 (s)	TOILET SERVICING DOOR HINGE - LUBRICATE. PKG 4 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210025 (s)	PRESSURE REFUELING DOOR HINGE - LUBRICATE. PKG 2 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210026 (s)	FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE PKG 2 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210027 (s)	TAILCONE ACCESS DOOR PINS - LUBRICATE PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y1210028 (s)	TAILCONE ACCESS DOOR HINGE - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1210029 (s)	MAIN LANDING GEAR TRUNNION PIN - LUBRICATE PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1221037 (s)	FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS PKG 4 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y1221042 (s)	HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE PKG 9 REF: AMM 12-21-03	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y1227000 (s)	EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE PKG 1 REF: AMM 12-27-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
<b>CHAPTER 21 AIR CONDITIONING</b>									
211001	SERVO AIR PRESSURE REGULATING VALVE PN SN-UNKNOWN REF: AMM 36-15-01	MOS HRS/MSC AFL							
					N:0		26-MAR-2007		
			O/C		N:0		0		
					N:0		0		
211011	LEFT PLENUM CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-09	MOS HRS/MSC AFL							
					N:0		26-MAR-2007		
			O/C		N:0		0		
					N:0		0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
211012	RIGHT PLENUM CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
211017	LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE 3202744-1 2820 REF: AMM 21-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
211018	RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE 3202744-1 2823 REF: AMM 21-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
212001	COCKPIT AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
212007	AFT BLOWER MOTOR PN SN-UNKNOWN REF: AMM 21-51-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
212008	FWD BLOWER MOTOR PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
212011	LINEAR ELECTRO-MECHANICAL ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212041	LEFT ENGINE OZONE CONVERTER 53A405-4 0865/1750 REF: AMM 21-20-12	MOS HRS/MSC AFL	O/C				29-JAN-2020 3544.5 2781		
212041A	TEST LEFT ENGINE OZONE CONVERTER EFFICIENCY. (Y2140001) 53A405-4 0865/1750 REF: AMM 21-20-12	MOS HRS/MSC AFL	3600	+25/-25			29-JAN-2020 3544.5 2781	7144.5	7169.5
212042	RIGHT ENGINE OZONE CONVERTER 53A405-4 0440/0874 REF: AMM 21-20-12	MOS HRS/MSC AFL	O/C				29-JAN-2020 3544.5 2781		
212042A	TEST RIGHT ENGINE OZONE CONVERTER EFFICIENCY (Y2140001) 53A405-4 0440/0874 REF: AMM 21-20-12	MOS HRS/MSC AFL	3600	+25/-25			29-JAN-2020 3544.5 2781	7144.5	7169.5
212101	NO. 1 THERMAL CONTROL ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		
212102	NO. 2 THERMAL CONTROL ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		
212105	LEFT ECS TRANSITION DUCT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212106	RIGHT ECS TRANSITION DUCT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
212201	LEFT GASPER AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
212202	RIGHT GASPER AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
212213	LEFT CABIN AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
212214	RIGHT CABIN AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
212801	AVIONICS COOLING B13 FAN 4521208521-009 A00806528-01 REF: AMM 21-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
213000	CABIN PRESSURE CONTROLLER 2119858-10 17-J0177 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213001	LEFT EMERGENCY PRESSURE SHUTOFF VALVE 3291224-1 955 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
213002	RIGHT EMERGENCY PRESSURE SHUTOFF VALVE 3291224-1 954 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
213021	JET PUMP EJECTOR PN SN-UNKNOWN REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
213031	PRIMARY OUTFLOW VALVE 103858-1 A0443 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
213032	SECONDARY OUTFLOW VALVE 103858-2 C0241 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
213055	EMERGENCY PRESSURE ANEROID SWITCH E45C-47 6351 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-MAR-2020 3581.1 2802		
213056	ABSOLUTE PRESSURE SWITCH E45C-47 5409 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213101	TAILCONE CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
213110	CABIN PRESSURIZATION CHECK VALVE 130158-3-1 86A0899 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
214301	FOOT WARMER (S167) THERMOSTAT PN SN-UNKNOWN REF: AMM 21-41-02	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0			26-MAR-2007 0 0 0		
214302	PILOT HEEL PLATE ASSEMBLY, FOOT WARMER CHANGE PN SN-UNKNOWN REF: AMM 21-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
214303	CO-PILOT HEEL PLATE ASSEMBLY, FOOT WARMER CHANGE PN SN-UNKNOWN REF: AMM 21-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
214925	LEFT CHECK, ECS (3.0 DIAMETER) VALVE 3202742-1 2955 REF: AMM 36-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2007 10.9 11		
214926	RIGHT CHECK, ECS (3.0 DIAMETER) VALVE 3202742-1 SN-UNKNOWN REF: AMM 36-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215001	WATER SEPARATOR ASSEMBLY 2341168-1 520 REF: AMM 21-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215002	WATER SEPARATOR BYPASS VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215010	ACM PRECOOLER ASSEMBLY PN SN-UNKNOWN REF: AMM 21-50-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215013	BI-LEVEL PRESSURE REGULATING & SHUTOFF (L19) VALVE PN SN-UNKNOWN REF: AMM 21-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215015	ACM BYPASS CHECK VALVE PN SN-UNKNOWN REF: AMM 21-50-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215019	CABIN REFRIGERATION CONDENSER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215030	ENVIRONMENTAL CONTROL UNIT 2215150-3 550 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215033	AIR CYCLE MACHINE 2205580-2 107-180 REF: AMM 21-50-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0				18-JUN-2008 357 277	
215036	HEAT, PRIMARY, SECONDARY EXCHANGER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215039	AIR CYCLE MACHINE TURBINE PN SN-UNKNOWN REF: AMM 21-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215043	AFT EVAPORATOR PN SN-UNKNOWN REF: AMM 21-51-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215044	FORWARD EVAPORATOR PN SN-UNKNOWN REF: AMM 21-51-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215100	AIR CONDITIONING COMPRESSOR PN SN-UNKNOWN REF: AMM 21-51-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
215101	AIR CONDITIONING COMPRESSOR DRIVE MOTOR PN SN-UNKNOWN REF: AMM 21-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215101A	PERFORM AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSH WEAR INSPECTION - IRN L2150054 PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C					26-MAR-2007 0 0	
215101B	OVERHAUL AIR CONDITIONING COMPRESSOR DRIVE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C					26-MAR-2007 0 0	
216001	INTEGRATED ECS TEMPERATURE CONTROLLER 1151830-3 00813 REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
216012	COCKPIT TEMPERATURE CONTROL VALVE FILTER PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
216013	COCKPIT TEMPERATURE CONTROL VALVE 3291222-1 961 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
216014	CABIN TEMPERATURE CONTROL VALVE 3291222-1 954 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
216015	CABIN TEMPERATURE CONTROL VALVE FILTER PN SN-UNKNOWN REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C						

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216025	COCKPIT TEMPERATURE CONTROL SELECTOR 1151502-1 SN-UNKNOWN REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
216026	CABIN TEMPERATURE CONTROL SELECTOR 1151502-1 SN-UNKNOWN REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
216036	OVERHEAT, COCKPIT DUCT THERMOSTAT PN SN-UNKNOWN REF: AMM 21-60-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
216037	OVERHEAT, CABIN DUCT THERMOSTAT PN SN-UNKNOWN REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
216040	CABIN TEMP 28VDC SENSOR/FAN ASSEMBLY PN SN-UNKNOWN REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
216049	CABIN DUCT OVERTEMP LIMITER PN SN-UNKNOWN REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
216071	LOW LIMIT TEMPERATURE CONTROL VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216074	REGULATING, SERVO AIR PRESSURE VALVE 60810-1 11883Q06 REF: AMM 36-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
216081	TEMPERATURE, COCKPIT DUCT SENSOR 627962-2 627962-20421 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
216083	COCKPIT TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
216084	CABIN TEMPERATURE, LOW LIMIT SENSOR PN SN-UNKNOWN REF: AMM 21-50-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
5-19-00-L2150054	WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
<b>NOT INSTALLED</b>	REF: GENERIC NO REF								
5-19-00-L2150055	OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)	MOS HRS/MSC AFL	-				26-MAR-2007 0 0		
<b>NOT INSTALLED</b>	REF: GENERIC NO REF								

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-Y2130065	LEAK TEST CABIN PRESSURIZATION SYSTEM. (IRN # Y2130065).	MOS					08-MAR-2019		
	REF: AMM 21-30-00	HRS/MSC	1200	+25/-25			3241.7	4441.7	4466.7
		AFL					2541		
5-19-01-Y2141002	REPLACE WATER SEPARATOR COALESCER BAG. (ZONE/ACCESS 310HL, 310RR IRN # W2141002)	MOS					30-APR-2007		
	REF: GENERIC NO REF	HRS/MSC	O/C				8.2		
		AFL							
J2160007 (s)	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-232 POST SB 45-21-16, AND AIRCRAFT 45-233 THRU 45-2000.)	MOS	24	+14d/-14d			29-JAN-2020		
	PKG 8	HRS/MSC	600	+25/-25			3544.5		
	REF: AMM 21-60-11	AFL					2781		
L2150056 (s)	** AUXILIARY HEAT SYSTEM - PERFORM FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-250 AND SUBSEQUENT EQUIPPED WITH KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM USING REFRIGERANT R-134.)	MOS	24	+14d/-14d			29-JAN-2020		
	PKG 8	HRS/MSC	600	+25/-25			3544.5		
<b>AIRWORTHINESS</b>	REF: AMM 21-51-00	AFL					2781		
L2150057 (s)	PERFORM ** AUXILIARY HEAT SYSTEM - AUXILIARY HEATER ELECTRICAL AND TEMPERATURE SWITCH TEST. (EFFECTIVE ON AIRCRAFT 45-250 AND SUBSEQUENT EQUIPPED WITH KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM USING REFRIGERANT R-134.)	MOS	48	+14d/-14d			08-MAR-2019		
	PKG 14	HRS/MSC	1200	+25/-25			3241.7		
<b>AIRWORTHINESS</b>	REF: AMM 21-51-00	AFL					2541		
O2130000 (s)	PERFORM PRIMARY AND SECONDARY OUTFLOW VALVES - INSPECTION.	MOS	48	+14d/-14d			08-MAR-2019		
	PKG 13	HRS/MSC	1200	+25/-25			3241.7		
	REF: See Workcard	AFL					2541		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
O2130001 (s)	REPLACE OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE. PKG 19	MOS	96	+14d/-14d			PKG 10-APR-2015 2017.3		
	REF: AMM 21-30-04	HRS/MSC AFL	2400	+25/-25					
O2130002 (s)	PERFORM ** PRESSURIZATION CONTROL SYSTEM - FUNCTIONAL TEST. PKG 13	MOS	48	+14d/-14d			PKG 08-MAR-2019 3241.7 2541		
<b>AIRWORTHINESS</b>	REF: AMM 21-30-00	HRS/MSC AFL	1200	+25/-25					
Y2130003 (s)	PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK PKG 7	MOS	24	+14d/-14d			PKG 29-JAN-2020 3544.5 2781		
	REF: AMM 21-30-00	HRS/MSC AFL	600	+25/-25					
Y2140000 (s)	PERFORM AIR CYCLE MACHINE HEAT EXCHANGER INLET - VISUAL INSPECTION PKG 14	MOS	48	+14d/-14d			PKG 08-MAR-2019 3241.7 2541		
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25					
Y2141000 (s)	PERFORM ENVIRONMENTAL CONTROL UNIT - VISUAL INSPECTION PKG 14	MOS	48	+14d/-14d			PKG 08-MAR-2019 3241.7 2541		
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25					
Y2141001 (s)	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY. (NOTE: THE SERVICING ACTIVITY MAY REQUIRE A MORE FREQUENT INTERVAL, DEPENDING ON ENVIRONMENTAL AND OPERATIONAL REQUIREMENTS, AND SHOULD BE ADJUSTED BY INDIVIDUAL OPERATORS) PKG 2	MOS	12	+14d/-14d			PKG 13-JAN-2021 3778.2 2986		
	REF: AMM 05-10-00	HRS/MSC AFL	300	+25/-25					



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2142000 (s)	PERFORM BAGGAGE COMPARTMENT HEATING SYSTEM - FUNCTIONAL TEST PKG 20 REF: AMM 21-40-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 10-APR-2015 2017.3		
Y2145000 (s)	PERFORM ECS PLENUM ASSEMBLY CHECK VALVES - VISUAL INSPECTION. VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY PKG 14 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
Y2150058 (s)	PERFORM VISUAL INSPECTION OF THE AIR CONDITIONING SYSTEM COMPONENTS, INCLUDING COMPRESSOR MOTORBELT FOR WEAR AND PROPER V-BELT TENSION, CONDENSER COILS FOR CLEANLINESS AND HOSES FOR CHAFING AND WEAR. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND THE SHAFT.) PKG 14 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
Y2150059 (s)	PERFORM AIR CONDITIONING SYSTEM - LOAD SHED ASSEMBLY CHECK PKG 14 REF: AMM 21-51-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
<b>CHAPTER 22 AUTO FLIGHT</b>									
2210-RVSM	FLIGHT CHECK AUTOMATIC ALTITUDE HOLD FUNCTIONAL. RVSM COMPLIANT AIRCRAFT. MOS HRS/MSC REF: GENERIC CUSTOM	N/R AFL					26-MAR-2007 0 0		
221001	FLIGHT GUIDANCE, AUTOPILOT CONTROLLER 7021170-901 06111717 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221041	AUTOPILOT, ROLL SERVO 4006719-949 0607H293 REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
221045	SERVO, ROLL BRACKET 4005842 0606H302 REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
221051	AUTOPILOT, PITCH SERVO 4006719-923 0604H186 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
221055	SERVO, PITCH BRACKET 4005842 06018289 REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
221061	AUTOPILOT, YAW SERVO 7012919-904 0603H018 REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
221065	SERVO, YAW BRACKET 7012098-902 06010636 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
225001	YAW INTERFACE UNIT 4522108501-018 863044 REF: AMM 22-50-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			21-MAR-2018 2931.7 2312		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
225031	PILOT YAW FORCE, RUDDER BOOST SYSTEM SENSOR 662250001-005 SN-UNKNOWN REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C				22-MAY-2017 2680.8 2104		
225032	COPILOT YAW FORCE, RUDDER BOOST SYSTEM. SENSOR 662250001-005 SN-UNKNOWN REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
A2210033 (s)	** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST PKG 7 REF: AMM 22-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
G2210030 (s)	PERFORM PITCH SERVO CABLES - CABLE TENSION CHECK PKG 14 REF: AMM 22-10-03	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
G2210031 (s)	PERFORM ROLL SERVO CABLES - CABLE TENSION CHECK PKG 13 REF: AMM 22-10-05	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
G2210032 (s)	PERFORM YAW SERVO CABLES - CABLE TENSION CHECK. PKG 14 REF: AMM 22-10-07	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
<b>CHAPTER 23 COMMUNICATIONS</b>									
230001	UNILINK PROCESSER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230002	CONFIGURATION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231011	NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231012	NO. 2 POWER AMPLIFIER/HF ANTENNA COUPLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231021	NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT 7510700-766 0610B100 REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C	N:144 N:3241.7 N:2541			08-MAR-2019 3241.7 2541		
231021A	TEST/INSPECT NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT ATC TRANSPONDER 7510700-766 0610B100 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			13-JAN-2021	13-JAN-2023	27-JAN-2023
231022	NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT 7510700-766 0702B238 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAR-2019 3241.7 2541		
231022A	TEST/INSPECT NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT ATC TRANSPONDER 7510700-766 0702B238 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			13-JAN-2021	13-JAN-2023	27-JAN-2023

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231025	NO. 1 COMM. CIRCUIT CARD ASSEM. REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231026	NO. 2 COMM. CIRCUIT CARD ASSEM. REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231030	NO. 1 HF SELCAL RECEIVER/EXCITER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231031	NO. 2 HF SELCAL RECEIVER/EXCITER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231032	HF SELCAL ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231033	UPPER VHF ANTENNA DM C60-17-1 14620 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231034	LOWER VHF ANTENNA DM C60-17-1 14628 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231045	NO. 1 HF (KCU-951) CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231046	NO. 2 HF (KCU-951) CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231051	NO. 1 BRIDGING, HF AMPLIFIER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231052	NO. 2 BRIDGING, HF AMPLIFIER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231090	PILOT HEADSET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231091	COPILOT HEADSET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231200	KHF-1050 HIGH FREQUENCY COMMUNICATION SYSTEM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231200A	GENERAL VISUAL INSPECTION KHF-1050 HIGH FREQUENCY COMMUNICATION SYSTEM OF THE SYSTEM COMPONENTS AND WIRING								
	PN	MOS					26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	4800	+25/-25			0	4800	4825
	REF: AMM 23-12-04	AFL					0		
231200B	CHECK KHF-1050 HIGH FREQUENCY COMMUNICATION SYSTEM NITROGEN PRESSURE OF THE ANTENNA COUPLER. THE PRESSURE SHOULD BE MEASURED AT THE VALVE ADJACENT TO P10522. WHEN MEASURED AT ROOM TEMPERATURE, IT SHOULD BE BETWEEN 8 AND 10 PSIG (55 TO 69 KPA GAUGE). IF BELOW 8 PSIG, ADD NITROGEN TO BRING THE PRESSURE UP TO 8 TO 10 PSIG.								
	PN	MOS					26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	N/A				0		
<b>N/A EQUIPMENT NOT INSTALLED</b>	REF: GENERIC CUSTOM	AFL					0		
231201	RENEWAL OF RADIO STATION LICENCE								
		MOS					26-MAR-2007		
		HRS/MSC	-				0		
	REF: GENERIC CUSTOM	AFL					0		
231300	PHONE MAGNASTAR TRANSCEIVER								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
231305	MAGNASTAR ANTENNA								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
231307	COCKPIT ASSEMBLY PHONE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231308	CABIN ASSEMBLY PHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231310	ARTU TRAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231313	NO. 1 CABIN DISTRIBUTION BUS REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231314	NO. 2 CABIN DISTRIBUTION BUS REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231315	CALL ALERTER (CAS) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
231351	SATELLITE DATA (SDU) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
232120	UNILINK ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
232200	SELCAL SYSTEM CHANGE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
232200A	GENERAL VISUAL INSPECTION SELCAL SYSTEM CHANGE OF THE SELCAL DECODER AND WIRING. PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	4800	+25/-25			26-MAR-2007 0 0	4800	4825
233001	FORWARD CABIN VIDEO MONITOR- AI-LCD104-04-1 020700385 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233002	AFT CABIN VIDEO MONITOR- PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233003	AUDIO DISTRIBUTION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233005	PA SYSTEM AMPLIFER PA-7501-01-1 010700018 REF: AMM 23-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233010	INFRARED REMOTE MODULE RECEIVER IFR-485-05-01 010700719 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233015	AUDIO/VIDEO CONTROLLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233053	DVD PLAYER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233054-1	CD PLAYER CHANGER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233054-2	CD PLAYER CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233055	CASSETTE TAPE PLAYER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233101	LEFT FORWARD CABIN SPEAKER EN-MT-45A 020700550 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233102	RIGHT FORWARD CABIN SPEAKER EN-MT-45A 020700549 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233103	LEFT AFT CABIN SPEAKER EN-MT-45A 020700557 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233104	RIGHT AFT CABIN SPEAKER EN-MT-45A 020700547 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233105	SUBWOOFER SPEAKER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
233201	PASSENGER INTERFACE UNIT PIU-45-04-1 010601072 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
234000	INTERPHONE JACK BOX ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
235001	#1 AUDIO CONTROL UNIT 4523558501-003 0609B361 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
235002	#2 AUDIO CONTROL UNIT 4523558501-003 0610B600 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
235013	LEFT COCKPIT SPEAKER PN SN-UNKNOWN REF: AMM 23-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
235014	RIGHT COCKPIT SPEAKER PN SN-UNKNOWN REF: AMM 23-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
236005	WEATHER XM RADIO RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
236010	WEATHER XM DATA PORT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
236012	XM WX ANTENNA REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
236015	XM RADIO ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
236020	GDC34 CONVERTER REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
236025	AIRSERV TRANSMITTER REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
236096	NO. 1 NAVIGATION STRAP BOARD PN SN-UNKNOWN REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
236097	NO. 2 NAVIGATION STRAP BOARD PN SN-UNKNOWN REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
236098	NO. 1 COMMUNICATION STRAP BOARD PN SN-UNKNOWN REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
236099	NO. 2 COMMUNICATION STRAP BOARD PN SN-UNKNOWN REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
237001	COCKPIT VOICE (CVR) RECORDER 980-6020-011 CVR30-04188 REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
237001A	INTELLIGIBILITY CHECK COCKPIT VOICE (CVR) RECORDER CVR 980-6020-011 CVR30-04188 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	A/R				26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237005	CVR UNDERWATER LOCATOR (ULB) BEACON DK120 AT83349 REF: AMM 25-61-01	MOS HRS/MSC AFL	O/C				13-JAN-2021 3778.2 2986		
237005A	FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON / CLEAN BEACON SWITCH AND PERFORM TEST OF ULB BATTERY (IRN AA2560000) DK120 AT83349 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	24	+14d/-14d			13-JAN-2021 3778.2 2986	13-JAN-2023	27-JAN-2023
237005B	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY ON OR BEFORE ULB BATTERY REPLACEMENT DATE. (ZONE/ACCESS 300 IRN # D2566001) DK120 AT83349 REF: AMM NO REF Expiry Date: 31-DEC-2024	MOS HRS/MSC AFL	DUE				13-JAN-2021 3778.2 2986	31-DEC-2024 M	
237018	CVR INERTIA SWITCH 3LO-453/8 81234 REF: AMM 23-70-05	MOS HRS/MSC AFL	O/C				26-MAR-2007 0 0		
237019	COCKPIT AREA MICROPHONE 980-6113-001 04087 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				26-MAR-2007 0 0		
237030	PANEL SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				26-MAR-2007 0 0		
237031	COCKPIT VOICE RECORDER PRE-AMPLIFIER 980-6118-001 CAMPRAMP-00644 REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C				26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
238001	NO. 1 RADIO MANAGEMENT (RMU) UNIT 7013270-985 06095451 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C				12-JUN-2018 3014.9		
238002	NO. 2 RADIO MANAGEMENT (RMU) UNIT 7013270-985 06095475 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C				12-JUN-2018 3014.9		
238025	CLEARANCE DELIVERY UNIT 7513000-835 06083313 REF: AMM 23-82-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
239004	MASTER CONTROL SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
239011	LAVATORY MASTER CONTROL SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
A2300000 (s)	** COMMUNICATIONS SYSTEMS - PERFORM OPERATIONAL CHECK PKG 7 REF: AMM 23-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
V2312003 (s)	HF ANTENNA- PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION ON HF ANTENNA WIRE PKG 14 REF: AMM 23-12-04	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
Y2360020 (s)	PERFORM AIRCRAFT STATIC DISCHARGERS - FUNCTIONAL TEST PKG 20 REF: AMM 23-60-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 10-APR-2015 2017.3		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2360023 (s)	PERFORM AIRCRAFT STATIC DISCHARGERS - FUNCTIONAL TEST PKG 22	MOS	96	+14d/-14d			PKG	10-APR-2015	
	REF: AMM 23-60-00	HRS/MSC AFL	2400	+25/-25			2017.3		
<b>CHAPTER 24 ELECTRICAL POWER</b>									
240109	AFT CIRCUIT BREAKER PANEL ASSY PN	MOS		N:0				26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-60-04	AFL		N:0			0		
242001	NO. 1 AC 5KVA ALTERNATOR 90278-2	MOS		O:0				27-JUL-2020	
	1326	HRS/MSC	O/C	O:0			3663.9		
	REF: AMM 24-20-01	AFL		O:0			2882		
242001A	REPLACE NO. 1 AC 5KVA ALTERNATOR ** BEARING. (F2420000) 90278-2	MOS						27-JUL-2020	
<b>AIRWORTHINESS</b>	1326	HRS/MSC	1200	+25/-25			3663.9	<b>4863.9</b>	4888.9
	REF: GENERIC NO REF	AFL					2882		
242002	NO. 2 AC 5KVA ALTERNATOR 90278-2	MOS		O:0				27-JUL-2020	
	1074	HRS/MSC	O/C	O:0			3663.9		
	REF: AMM 24-20-01	AFL		O:0			2882		
242002A	REPLACE NO. 2 AC 5KVA ALTERNATOR ** BEARING. (F2420000) 90278-2	MOS						27-JUL-2020	
<b>AIRWORTHINESS</b>	1074	HRS/MSC	1200	+25/-25			3663.9	<b>4863.9</b>	4888.9
	REF: GENERIC NO REF	AFL					2882		
242008	AC/DC VOLT INDICATOR PN	MOS		N:0				26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242050	REMOTE CONTROL CIRCUIT BREAKER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
242052	REMOTE CONTROL CIRCUIT BREAKER SM600BA75N1 53119 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-JUN-2007 41.5 37		
242054	REMOTE CONTROL CIRCUIT BREAKER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
242081	CABIN AC INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
242082	TAILCONE AC INVERTER SS120(2) 539 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				29-JAN-2020 3544.5 2781		
242083	AC INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			26-MAR-2007 0 0		
243001	NO. 1 STARTER/GENERATOR 23080-059 P1132 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			27-JUL-2020 3663.9 2882		
243001A	OVERHAUL NO. 1 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410) 23080-059 P1132 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+25/-25			27-JUL-2020 3663.9 2882	4863.9	4888.9

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243001B	REPLACE NO. 1 STARTER/GENERATOR BEARING 23080-059 P1132 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+25/-25			27-JUL-2020 3663.9 2882	4263.9	4288.9
243002	NO. 2 STARTER/GENERATOR 23080-059 991019 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			27-JUL-2020 3663.9 2882		
243002A	OVERHAUL NO. 2 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410) 23080-059 991019 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+25/-25			27-JUL-2020 3663.9 2882	4863.9	4888.9
243002B	REPLACE NO. 2 STARTER/GENERATOR BEARING 23080-059 991019 REF: GENERIC NO REF	MOS HRS/MSC AFL	600	+25/-25			27-JUL-2020 3663.9 2882	4263.9	4288.9
243003	APU STARTER/GENERATOR 23080-023B Y01196 REF: AMM 49-40-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			10-JAN-2019 3193.1 2515		
243003A	OVERHAUL APU STARTER/GENERATOR AND BRUSH REPLACEMENT. (IRN # V4900021, V4900003) 23080-023B Y01196 REF: AMM 49-40-01	MOS HRS/MSC AFL APH	1200	+25/-25			10-JAN-2019 3193.1 2515 1088.42	2288.42	2313.42
243003B	VISUALLY INSPECT APU STARTER/GENERATOR GEAR BOX DRIVE SPLINE. (IRN # O4900006) 23080-023B Y01196 REF: AMM 05-10-00	MOS HRS/MSC AFL APH	1200	+25/-25			08-MAR-2019 3241.7 2541 1088.42	2288.42	2313.42

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243005	LEFT (GCU) GENERATOR CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
243006	RIGHT (GCU) GENERATOR CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
243019	NO. 1 MAIN SHIP BATTERY RG380E/40L 41031653 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-NOV-2019 3425.8 2707		
243019A	CHECK/SERVICE NO. 1 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD-ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID) RG380E/40L 41031653 REF: See Workcard	MOS HRS/MSC AFL	6	+1m/-1m		-36	11-DEC-2020 3751.9 2968	06-MAY-2021	06-JUN-2021
243019B	OVERHAUL NO. 1 MAIN SHIP BATTERY NI-CAD BATTERY PER RECOMMENDED MFG'S INSTRUCTIONS. RG380E/40L 41031653 REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A						
+ 243019C	NO. 1 BATTERY TEMPERATURE SWITCH PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			26-MAR-2007 0 0		
	<b>N/A EQUIPMENT NOT INSTALLED</b>								
243020	NO. 2 MAIN SHIP BATTERY RG-380E/40L 41031649 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-NOV-2019 3425.8 2707		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243020A	CHECK/SERVICE NO. 2 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD-ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID)								
	RG-380E/40L 41031649 REF: See Workcard	MOS HRS/MSC AFL	6	+1m/-1m		-36	11-DEC-2020 3751.9 2968	06-MAY-2021	06-JUN-2021
243020B	OVERHAUL NO. 2 MAIN SHIP BATTERY NI-CAD BATTERY PER RECOMMENDED MFG'S INSTRUCTIONS.								
	RG-380E/40L 41031649 REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A						
+ 243020C	NO. 1 BATTERY TEMPERATURE SWITCH								
	PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			26-MAR-2007 0 0		
	<b>N/A EQUIPMENT NOT INSTALLED</b>								
243037	EMERGENCY (IRN AB2431063 FOR RG-443) BATTERY								
	RG443 40854344 REF: See Workcard	MOS HRS/MSC AFL	60 5000	+14d/-14d +25/-25	N:11 N:286		21-MAR-2018 2931.7 2312	21-APR-2022 7645.7	05-MAY-2022 7670.7
243037A	PERFORM EMERGENCY (IRN AB2431063 FOR RG-443) BATTERY CAPACITY CHECK (P/N 7624308001, IRN O2431002), (P/N RG-443, IRN AB2431062)								
	RG443 40854344 REF: CMM 24-30-67	MOS HRS/MSC AFL	12 1000	+14d/-14d +25/-25		-314	29-JAN-2020 3544.5 2781	31-JAN-2021 4544.5	M 14-FEB-2021 4569.5
246001	LEFT FORWARD POWER DISTRIBUTION PANEL								
	650GC02Y03 462 REF: AMM 24-60-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		
246002	RIGHT FORWARD POWER DISTRIBUTION PANEL								
	655GC02Y03 424 REF: AMM 24-60-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246003	LEFT AFT POWER DISTRIBUTION PANEL 660GC02Y07 530 REF: AMM 24-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
246004	RIGHT AFT POWER DISTRIBUTION PANEL 665GC02Y07 529 REF: AMM 24-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
246101	LEFT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
246102	LEFT LOGIC PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
246104	RIGHT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
246105	RIGHT LOGIC PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
246106	APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
5-19-00-Y2431005	BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK. (REFER TO 24-31-00.). IRN Y2431005  REF: AMM 24-31-00	MOS HRS/MSC AFL	300	+25/-25			13-JAN-2021 3778.2 2986	4078.2	4103.2

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ AC2460002 (s)	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUSS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.						PKG		
	PKG 19	MOS	96	+14d/-14d			26-MAR-2007		
		HRS/MSC	2400	+25/-25			0		
	REF: AMM NO REF	AFL					0		
B2450002 (s)	PERFORM ** ELECTRICAL SYSTEM CONTROL - OPERATIONAL CHECK						PKG		
	PKG 13	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
<b>AIRWORTHINESS</b>	REF: AMM 24-00-00	AFL					2541		
H2450001 (s)	** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
<b>AIRWORTHINESS</b>	REF: AMM 24-00-00	AFL					2781		
H2450023 (s)	** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK.						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
<b>AIRWORTHINESS</b>	REF: AMM 24-00-00	AFL					2781		
Q2460001 (s)	PERFORM ** POWER DISTRIBUTION SYSTEM - SQUAT SWITCH CHECK.						PKG		
	PKG 17	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
<b>AIRWORTHINESS</b>	REF: AMM 24-60-00	AFL					2541		
R2431003 (s)	PERFORM ** BATTERY WARNING SYSTEM - FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT WITH NI-CAD BATTERIES INSTALLED)						PKG		
	PKG 19	MOS	96	+14d/-14d			10-APR-2015		
		HRS/MSC	2400	+25/-25			2017.3		
<b>AIRWORTHINESS</b>	REF: AMM 24-31-00	AFL							
W2450000 (s)	** GENERATOR FAIL INDICATION - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
<b>AIRWORTHINESS</b>	REF: AMM 24-00-00	AFL					2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2400001 (s)	PERFORM SWITCH AND CIRCUIT BREAKER PANELS - VISUAL INSPECTION PKG 13 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
Y2400002 (s)	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION PKG 7 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2400025 (s)	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION PKG 8 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2430005 (s)	STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK PKG 9 REF: AMM 24-30-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2430006 (s)	STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS PKG 9 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2431000 (s)	PERFORM BATTERY, GENERATOR, AND BUS-TIE CABLES - VISUAL INSPECTION. PKG 20 REF: AMM 05-10-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 10-APR-2015 2017.3		
Y2431001 (s)	EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION PKG 7 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2460000 (s)	PERFORM DC BUS ISOLATION - OPERATIONAL CHECK PKG 13 REF: AMM 24-60-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
<b>CHAPTER 25</b>	<b>EQUIPMENT/FURNISHINGS</b>								
250010	RELAY MODULE MSM9646-01-1 020700156 REF: GENERIC NO REF	MOS HRS/MSC AFL		O/C			N:0 N:0 N:0 26-MAR-2007 0 0		
252000-1	#1 PASSENGER SEAT M6613100-(001)-(T) 070212-12 REF: AMM 25-20-45	MOS HRS/MSC AFL		O/C			N:0 N:0 N:0 26-MAR-2007 0 0		
252000-2	#2 PASSENGER SEAT M6613100-(002)-(T) 070212-14 REF: AMM 25-20-45	MOS HRS/MSC AFL		O/C			N:0 N:0 N:0 26-MAR-2007 0 0		
252000-3	#3 PASSENGER SEAT M6613100-(001)-(T) 070212-13 REF: AMM 25-20-45	MOS HRS/MSC AFL		O/C			N:0 N:0 N:0 26-MAR-2007 0 0		
252000-4	#4 PASSENGER SEAT M6613100-(002)-(T) 070212-10 REF: AMM 25-20-45	MOS HRS/MSC AFL		O/C			N:0 N:0 N:0 26-MAR-2007 0 0		
252000-5	#5 PASSENGER SEAT M6613100-(001)-(T) 070212-09 REF: AMM 25-20-45	MOS HRS/MSC AFL		O/C			N:0 N:0 N:0 26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252000-6	#6 PASSENGER SEAT M6613100-(002)-(T) 070212-16 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252000-7	#7 PASSENGER SEAT M6613100-(001)-(T) 070212-11 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252000-8	#8 PASSENGER SEAT M6613100-(002)-(T) 070212-15 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252000-9	JUMP SEAT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252001-1	#1 PASSENGER SEAT PCU SP-45-54 050600861 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252001-2	#2 PASSENGER SEAT PCU PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252001-3	#3 PASSENGER SEAT PCU PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252001-4	#4 PASSENGER SEAT PCU PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252001-5	#5 PASSENGER SEAT PCU PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
252001-6	#6 PASSENGER SEAT PCU PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
252001-7	#7 PASSENGER SEAT PCU PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
252001-8	#8 PASSENGER SEAT PCU PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
252001-9	LAVATORY PASSENGER CONTROL UNIT PCU SP-45-55 080600106 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0				26-MAR-2007 0 0	
252003-1	BOX ASSEM, STORAGE RH FWD (#1) CHANGE PN SN-UNKNOWN REF: AMM 25-20-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
252003-2	BOX ASSEM, STORAGE, RH FWD MID (#2) CHANGE PN SN-UNKNOWN REF: AMM 25-20-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
252003-3	BOX ASSEM, STORAGE, RH AFT FWD (#3) CHANGE PN SN-UNKNOWN REF: AMM 25-20-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252003-4	BOX ASSEM, STORAGE, RH AFT (#4) CHANGE PN SN-UNKNOWN REF: AMM 25-20-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252003-5	BOX ASSEM, STORAGE, LH AFT (#5) CHANGE PN SN-UNKNOWN REF: AMM 25-20-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252003-6	BOX ASSEM, STORAGE, LH AFT MID (#6) CHANGE PN SN-UNKNOWN REF: AMM 25-20-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252003-7	BOX ASSEM, STORAGE LH FWD MID (#7) CHANGE PN SN-UNKNOWN REF: AMM 25-20-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252003-8	BOX ASSEM, STORAGE, LH FWD (#8) CHANGE PN SN-UNKNOWN REF: AMM 25-20-32	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252010	AIRSHOW COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252012	AIRSHOW SWITCH CHANGE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252015	IR SENSOR CHANGE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252020	CLOSET SWITCH PANEL ASSEMBLY SP-45-21 040700020 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252090	POWER PORT 110 VOLT OUTLET SP-45-26 010700613 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252091	POWER PORT 110 VOLT OUTLET SP-45-26 010700960 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252092	POWER PORT 110 VOLT OUTLET SP-45-26 010700614 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252095	POWER PORT 110 VOLT OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252097	NO. 1 AC OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252098	NO. 2 AC OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
252099	NO. 3 AC OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253001	MICROWAVE OVEN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
253075	NO. 1 HEATED WATER CONTAINER AR9061-3 0230 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-JUN-2008 357 277		
253076	NO. 2 HEATED WATER CONTAINER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
253077	HEATED WATER SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
253080	GALLEY DRAIN VALVE SOLENOID PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
256001	PILOT CREW SEAT TALJ2-14PM01-02 / 4525103038-007 864 REF: AMM 25-10-50	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
256002	COPILOT CREW SEAT TALJ2-14CM01-02 / 4525103038-008 827 REF: AMM 25-10-50	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256030	PILOT PROTECTIVE BREATHING (PBE), (IRN A3510008) EQUIPMENT UNIT PN SN-UNKNOWN <b>REF:</b> AMM 25-60-00	MOS HRS/MSC AFL	N/A						
<b>NOT INSTALLED</b>									
256032	COPILOT PROTECTIVE BREATHING (PBE), (IRN A3510008) EQUIPMENT UNIT PN SN-UNKNOWN <b>REF:</b> AMM 25-60-00	MOS HRS/MSC AFL	N/A						
<b>NOT INSTALLED</b>									
256061	PILOT LIFE VEST D21343-153 L959726 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256061A	INSPECT PILOT LIFE VEST (IRN # E2561002) D21343-153 L959726 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	
256062	COPILOT LIFE VEST D21343-153 L964032 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256062A	INSPECT COPILOT LIFE VEST (IRN # E2561002) D21343-153 L964032 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	
256063	NO. 1 LIFE VEST D21343-153 L959750 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256063A	INSPECT NO. 1 LIFE VEST (IRN # E2561002) D21343-153 L959750 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256064	NO. 2 LIFE VEST D21343-153 L964008 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256064A	INSPECT NO. 2 LIFE VEST (IRN # E2561002) D21343-153 L964008 REF: See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	
256065	NO. 3 LIFE VEST D21343-153 L964037 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256065A	INSPECT NO. 3 LIFE VEST (IRN # E2561002) D21343-153 L964037 REF: See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	
256066	NO. 4 LIFE VEST D21343-153 L964034 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256066A	INSPECT NO. 4 LIFE VEST (IRN # E2561002) D21343-153 L964034 REF: See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	
256067	NO. 5 LIFE VEST D21343-153 L964033 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256067A	INSPECT NO. 5 LIFE VEST (IRN # E2561002) D21343-153 L964033 REF: See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256068	NO. 6 LIFE VEST D21343-153 L964039 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256068A	INSPECT NO. 6 LIFE VEST (IRN # E2561002) D21343-153 L964039 REF: See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	
256069	NO. 7 LIFE VEST D21343-153 L964030 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256069A	INSPECT NO. 7 LIFE VEST (IRN # E2561002) D21343-153 L964030 REF: See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	
256070	NO. 8 LIFE VEST D21343-153 L964009 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2992 O:0			20-JAN-2021 3787.7 2992		
256070A	INSPECT NO. 8 LIFE VEST (IRN # E2561002) D21343-153 L964009 REF: See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	
256071	LAVATORY LIFE VEST D21343-153 L964036 REF: CMM 25-60-05	MOS HRS/MSC AFL	O/C	N:166 O:0 N:3787.7 O:0 N:2922 O:0			20-JAN-2021 3787.7 2992		
256071A	INSPECT LAVATORY LIFE VEST (IRN # E2561002) D21343-153 L964036 REF: See Workcard	MOS HRS/MSC AFL	60				19-JAN-2021	<b>19-JAN-2026</b>	



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256074	LIFE RAFT PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
+ 256074A	INSPECT LIFE RAFT IAW MANUFACTURERS INSTRUCTIONS PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	-					26-MAR-2007 0 0	
256074B	HYDROSTATIC TEST LIFE RAFT CO2 CYLINDER IAW MANUFACTURERS INSTRUCTIONS PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	A/R					26-MAR-2007 0 0	
256074C	REPLACE LIFE RAFT DAY/NIGHT FLARES IAW MANUFACTURERS INSTRUCTIONS PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	A/R					26-MAR-2007 0 0	
256080	INSPECT LIFE VESTS 05-19-00-E2561002 REF: CMM 25-60-05	MOS HRS/MSC AFL	A/R					26-MAR-2007 0 0	
256080A	RECERTIFY LIFE VEST FOR CONTINUED SERVICE PER MANUFACTURER'S INSTRUCTIONS REF: CMM 25-60-05	MOS HRS/MSC AFL	A/R					26-MAR-2007 0 0	
256109	(ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000-(366) 16082 REF: AMM 25-62-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0				18-APR-2008 310.2 240	
256109A	FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000-(366) 16082 REF: See Workcard	MOS HRS/MSC AFL	12					13-JAN-2021 3778.2 2986	13-JAN-2022

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256109B	INSPECT ELT BATTERIES (IF INSTALLED) 453-5000-(366) 16082 REF: See Workcard	MOS HRS/MSC AFL	12	+14d/-14d			13-JAN-2021 3778.2 2986	13-JAN-2022	27-JAN-2022
256109C	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER ELT BATTERY 453-5000-(366) 16082 REF: See Workcard  Expiry Date: 31-JAN-2022	MOS HRS/MSC AFL	DUE				12-APR-2017 2645 2085	31-JAN-2022 M	
256109D	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY ARTEX 110 SYSTEMS WITHOUT 406 MHZ CAPABILITIES. 453-5000-(366) 16082 REF: See Workcard	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
	<b>N/A EQUIPMENT NOT INSTALLED</b>								
256109E	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY (DORNE AND MARGOLIN ELT REMOTE CONTROL BATTERY (P/N U264-1). (ZONE/ACCESS 200 IRN # N2561004) 453-5000-(366) 16082 REF:	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
	<b>NOT INSTALLED</b>								
256109F	RENEW EMERGENCY LOCATOR TRANSMITTER ELT REGISTRATION  REF: MSC ELT REGISTRATION	MOS HRS/MSC AFL	A/R				26-MAR-2007 0 0		
256110	ELT NAV INTERFACE UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
256115	ELT ANTENNA 110-337 139146 REF: AMM 25-62-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256116	ELT REMOTE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
258001	CABIN AIRSHOW DISPLAY COMPUTER UNIT 30900228 090700106 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			04-NOV-2020 3723.1 2946		
259073	AUTOMATIC ELECTRONIC DEFIBRILLATOR BATTERIES PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
259074	AUTOMATIC ELECTRONIC DEFIBRILLATOR PADS PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
ST00909SE	INSPECT LIFEPORT INSTALLATION REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				26-MAR-2007 0 0		
Y2510000 (s)	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y2510001 (s)	CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2520000 (s)	CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG.  PKG 1  REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25				13-JAN-2021 3778.2 2986	PKG
Y2540000 (s)	ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.  PKG 7  REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25				29-JAN-2020 3544.5 2781	PKG
Y2540009 (s)	PERFORM AVIONICS EQUIPMENT AND WIRING LOCATED IN LAVATORY AREA - GENERAL VISUAL INSPECTION  PKG 25  REF: AMM 05-10-00	MOS HRS/MSC AFL	4800	+25/-25				26-MAR-2007 0 0	PKG
<b>CHAPTER 26</b>	<b>FIRE PROTECTION</b>								
261012	NO. 1 ENGINE FIREWALL FIRE DETECT ELEMENT  PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			26-MAR-2007 0 0	
261013	NO. 2 ENGINE FIREWALL FIRE DETECT ELEMENT  PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			26-MAR-2007 0 0	
261014	NO. 1 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT  PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			26-MAR-2007 0 0	
261015	NO. 2 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT  PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261016	NO. 1 ENGINE HOT SECTION FIRE DETECT ELEMENT PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
261017	NO. 2 ENGINE HOT SECTION FIRE DETECT ELEMENT PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
261057	NO. 1 FIRE DETECT CONTROL UNIT 877-01032 0643-179 REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
261058	NO. 2 FIRE DETECT CONTROL UNIT 877-01032 0729-322 REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
261069	NO. 1 BLEED AIR LEAK(A76) DETECTION UNIT 35009-39 1573 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
261070	NO. 2 BLEED AIR LEAK(A78) DETECTION UNIT 6626100000-003 1563 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C				25-SEP-2014 1849.9 1446		
261071	ANTI-ICE BLEED AIR LEAK(A77) DETECTION UNIT 6626100000-003 1572 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C				25-SEP-2014 1849.9 1446		
261075	APU FIRE/OVERHEAT DETECTOR 10-1093 06-0280 REF: AMM 26-13-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262001	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE 33100021-1 71696B1 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0				13-JAN-2021 3778.2 2986	
262001A	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006) 33100021-1 71696B1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			20-APR-2020	20-APR-2025	04-MAY-2025
<b>SCHEDULED MAINTENANCE TASKS AND INTERVALS</b>									
262002	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE 33100021-1 71805B1 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				13-JAN-2021 3778.2 2986	
262002A	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - HYDROSTATIC TEST (Q2620006) 33100021-1 71805B1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			20-APR-2020	20-APR-2025	04-MAY-2025
262013	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB 30903856 02553 REF: Manufacture Date: 01-SEP-2020	MOS HRS/MSC AFL	180	+14d/-14d	N:0 N:0 N:0			13-JAN-2021 3778.2 2986	01-SEP-2035 15-SEP-2035
+ 262013A	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT 30903856 02553 REF:	MOS HRS/MSC AFL	120	+14d/-14d			13-JAN-2021 3778.2 2986	13-JAN-2031	27-JAN-2031
<b>SERVICE LIFE LIMIT</b>									
262014	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB 30903856 02532 REF: Manufacture Date: 01-SEP-2020	MOS HRS/MSC AFL	180	+14d/-14d	N:0 N:0 N:0			13-JAN-2021 3778.2 2986	01-SEP-2035 15-SEP-2035
<b>REPLACE</b>									

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 262014A	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT 30903856 02532 <b>REF:</b>	MOS HRS/MSC AFL	120	+14d/-14d			13-JAN-2021 3778.2 2986	<b>13-JAN-2031</b>	27-JAN-2031
262015	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB M30903859 01709 <b>REF:</b> Manufacture Date: 01-MAR-2019	MOS HRS/MSC AFL	180	+14d/-14d	N:0 N:0 N:0		13-JAN-2021 3778.2 2986	<b>01-MAR-2034</b>	15-MAR-2034
+ 262015A	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB SERVICE LIFE LIMIT M30903859 01709 <b>REF:</b>	MOS HRS/MSC AFL	120	+14d/-14d			13-JAN-2021 3778.2 2986	<b>13-JAN-2031</b>	27-JAN-2031
262016	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB M30903859 01695 <b>REF:</b> Manufacture Date: 01-MAR-2019	MOS HRS/MSC AFL	180	+14d/-14d	N:0 N:0 N:0		13-JAN-2021 3778.2 2986	<b>01-MAR-2034</b>	15-MAR-2034
+ 262016A	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB SERVICE LIFE LIMIT M30903859 01695 <b>REF:</b>	MOS HRS/MSC AFL	120	+14d/-14d			13-JAN-2021 3778.2 2986	<b>13-JAN-2031</b>	27-JAN-2031
262040	APU FIRE WARNING HORN 430-M1 22579 <b>REF:</b> AMM 26-13-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		
262041	PILOT PORTABLE FIRE EXTINGUISHER A344T E68644511 <b>REF:</b> GENERIC CUSTOM	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-MAR-2018 2931.7 2312		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262041A (s)	VISUAL INSPECTION AND WEIGHT CHECK PILOT PORTABLE FIRE EXTINGUISHER PILOTS PORTABLE FIRE EXTINGUISHER IRN (Y2620009)						PKG		
	A344T PKG 1	MOS	12	+14d/-14d				13-JAN-2021	
	E68644511	HRS/MSC	300	+25/-25				3778.2	
	REF: AMM NO REF	AFL						2986	
262041B	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER (IRN # Q2510003).								
	A344T	MOS	144	+14d/-14d				21-MAR-2018	30-NOV-2023 M 14-DEC-2023
	E68644511	HRS/MSC							
	REF: AMM 26-23-00	AFL							
262042	COPILOT PORTABLE FIRE EXTINGUISHER								
	A344T	MOS			N:0			21-MAR-2018	
	E71098871	HRS/MSC	O/C		N:0			2931.7	
	REF: GENERIC CUSTOM	AFL			N:0			2312	
262042A (s)	VISUAL INSPECTION AND WEIGHT CHECK COPILOT PORTABLE FIRE EXTINGUISHER CO-PILOT'S PORTABLE FIRE EXTINGUISHER (IRN Y2620009)						PKG		
	A344T PKG 1	MOS	12	+14d/-14d				13-JAN-2021	
	E71098871	HRS/MSC	300	+25/-25				3778.2	
	REF: AMM NO REF	AFL						2986	
262042B	HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER (IRN # Q2510003).								
	A344T	MOS	144	+14d/-14d				21-MAR-2018	30-NOV-2023 M 14-DEC-2023
	E71098871	HRS/MSC							
	REF: AMM 26-23-00	AFL							
262051	CABIN PORTABLE FIRE EXTINGUISHER								
	C352TS	MOS			N:0			21-MAR-2018	
	E65820718	HRS/MSC	O/C		N:0			2931.7	
	REF: GENERIC CUSTOM	AFL			N:0			2312	
262051A (s)	VISUAL INSPECTION AND WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER (IRN Y2620009)						PKG		
	C352TS PKG 1	MOS	12	+14d/-14d				13-JAN-2021	
	E65820718	HRS/MSC	300	+25/-25				3778.2	
	REF: AMM 26-23-00	AFL						2986	





# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262051B	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER (IRN # Q2510003). C352TS E65820718 REF: AMM 26-23-00	MOS HRS/MSC AFL	144	+14d/-14d			21-MAR-2018	30-SEP-2023 M	14-OCT-2023
262075	APU FIRE EXTINGUISHER 51600-2 0445 REF: AMM 26-22-01	MOS HRS/MSC AFL	O/C				21-MAR-2018 2931.7 2312		
262075A	PERFORM APU FIRE EXTINGUISHER CONTAINER - ICC HYDROSTATIC TEST. (ZONE/ACCESS 310JL, 310QR) (IRN # Q4900014) 51600-2 0445 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			21-MAR-2018	21-MAR-2023	04-APR-2023
262076	REPLACE APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE 30600-22 LOT99 REF: AMM 26-21-02 LIFE LIMIT Manufacture Date: 01-MAY-2013	MOS HRS/MSC AFL	180	+14d/-14d			20-SEP-2013	01-MAY-2028	15-MAY-2028
+ 262076A	REPLACE APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE (SERVICE LIFE LIMIT) 30600-22 LOT99 REF: AMM NO REF	MOS HRS/MSC AFL	144	+14d/-14d			20-SEP-2013	20-SEP-2025	04-OCT-2025
5-19-00-O2610001-LEFT	VISUALLY INSPECT NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE REF: AMM 05-10-00	MOS HRS/MSC AFL	3000	+100/-100	-58.3		07-AUG-2018 3058.3 2403	6000	6100
5-19-00-O2610001-RIGHT	VISUALLY INSPECT NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE REF: AMM 05-10-00	MOS HRS/MSC AFL	3000	+100/-100	-58.3		07-AUG-2018 3058.3 2403	6000	6100

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
J2620000 (s)	PERFORM ** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - FUNCTIONAL TEST PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 26-21-00	HRS/MSC AFL	4800	+25/-25			0	0	
T2620001 (s)	PERFORM ** FIREWALL SHUTOFF VALVES - OPERATIONAL CHECK. PKG 13	MOS	48	+14d/-14d			PKG	08-MAR-2019	
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 26-21-00	HRS/MSC AFL	1200	+25/-25			3241.7	2541	
Y2610000 (s)	FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION PKG 9	MOS	24	+14d/-14d			PKG	29-JAN-2020	
	<b>REF:</b> AMM 05-10-00	HRS/MSC AFL	600	+14/-14			3544.5	2781	
Y2620002 (s)	ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION PKG 2	MOS	12	+14d/-14d			PKG	13-JAN-2021	
	<b>REF:</b> AMM 05-10-00	HRS/MSC AFL	300	+25/-25			3778.2	2986	
Y2620005 (s)	PERFORM ENGINE FIRE EXTINGUISHING SYSTEM - OPERATIONAL CHECK PKG 19	MOS	96	+14d/-14d			PKG	10-APR-2015	
	<b>REF:</b> AMM 26-21-00	HRS/MSC AFL	2400	+25/-25			2017.3		
Y2620009 (s)	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. PKG 1	MOS	12	+14d/-14d			PKG	13-JAN-2021	
	<b>REF:</b>	HRS/MSC AFL	300	+25/-25			3778.2	2986	
Z2620021 (s)	NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION PKG 2	MOS	12				PKG	13-JAN-2021	
	<b>REF:</b> AMM 26-21-00	HRS/MSC AFL	300				3778.2	2986	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z2620021 (s)	NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						PKG		
	PKG 2	MOS	12				13-JAN-2021		
		HRS/MSC	300				3778.2		
	REF: AMM 26-21-00	AFL					2986		
<b>CHAPTER 27 FLIGHT CONTROLS</b>									
270301	TRIM SWITCH PANEL ASSY								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-00-01	AFL		N:0			0		
271001	LEFTAILERON CONTROL SYSTEM CROSSOVER CABLE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-10-05	AFL		N:0			0		
271002	RIGHTAILERON CONTROL SYSTEM CROSSOVER CABLE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-10-05	AFL		N:0			0		
271003	LEFTAILERON CONTROL SYSTEM CABLE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-10-05	AFL		N:0			0		
271004	RIGHTAILERON CONTROL SYSTEM CABLE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-10-05	AFL		N:0			0		
271005	AILERON CONTROL SYSTEM AFT CABLE ASSEMBLY								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-10-05	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271045	ASSEMBLY, AILERON CONTROL INBOARD LEFT CABLE 4527103078-009 1053776-21 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
271046	ASSEMBLY, AILERON CONTROL INBOARD RIGHT CABLE 4527103078-009 1053776-25 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
271051	LEFT AILERON FORWARD OUTBOARD CONTROL CABLE 4527103077-011 1055403-2 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
271052	RIGHT AILERON FORWARD OUTBOARD CONTROL CABLE 4527103076-015 1055402-8 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
271053	LEFT AILERON OUTBOARD AFT CONTROL CABLE 4527103079-009 1054599-8 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
271054	RIGHT AILERON AFT OUTBOARD CONTROL CABLE 4527103079-009 1054599-21 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
271083	AILERON TRIM TAB ACTUATOR 4323338 0189 REF: AMM 27-10-09	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			09-APR-2009 599.6		
271095	PILOT ANGLE OF ATTACK (AOA) INDICATOR C-38805-1 83281 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271096	COPILOT ANGLE OF ATTACK (AOA) INDICATOR C-38805-1 83259 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
271220	TRIM, TOGGLE, AND PUSH BUTTON SWITCH PN SN-UNKNOWN REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
272001	FORWARD UPPER RUDDER CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
272002	FORWARD LOWER RUDDER CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
272003	LEFT AFT UPPER RUDDER CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
272004	RIGHT AFT UPPER RUDDER CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
272005	LEFT AFT LOWER RUDDER CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
272006	RIGHT AFT LOWER RUDDER CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272021	RUDDER TRIM TAB ACTUATOR 4323322 0441 REF: AMM 27-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
272031	PILOT RUDDER PEDAL ADJUST ACTUATOR 4389596 1015 REF: AMM 27-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
272032	COPILOT RUDDER PEDAL ADJUST ACTUATOR 4389596 1016 REF: AMM 27-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273001	FORWARD PILOT ELEVATOR CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273002	FORWARD COPILOT ELEVATOR CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273003	LEFT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273004	RIGHT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273005	LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273006	RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273015	LEFT ANGLE OF ATTACK (AOA) VANE PN SN-UNKNOWN REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273016	RIGHT ANGLE OF ATTACK (AOA) VANE PN SN-UNKNOWN REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273020	LH ANGLE OF ATTACK (AOA) SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273021	RH ANGLE OF ATTACK (AOA) SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273051	ELEVATOR DISCONNECT ACTUATOR PN SN-UNKNOWN REF: AMM 27-30-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273063	PILOT STICK SHAKER 72672-1 1639 REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273064	COPILOT STICK SHAKER 72672-1 1637 REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273075	LEFT ANGLE OF ATTACK (AOA) TRANSMITTER C-38817-1 1129 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273076	RIGHT ANGLE OF ATTACK (AOA) TRANSMITTER C-38817-1 1132 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273087	STALL WARNING COMPUTER C-38806-2 556 REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273201	ELEVATOR DISCONNECT (A83) CURRENT LIMITER PN SN-UNKNOWN REF: AMM 27-30-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273220	DISCONNECT ASSEM, ELEVATOR AFT CHANGE PN SN-UNKNOWN REF: AMM 27-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
273420	ELEVATOR OVERRIDE (L45) ACTUATOR PN SN-UNKNOWN REF: AMM 27-30-14	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
274011	HORIZONTAL STABILIZER ACTUATOR 6627401000-009 B0926 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			21-MAR-2018 2931.7 2312		
274011A	INSPECT HORIZONTAL STABILIZER ACTUATOR * (6627401000-009 - IRN P2740032). (6627401000-007 - IRN T2740002) 6627401000-009 B0926 REF: AMM 27-40-00	MOS HRS/MSC AFL	1200				21-MAR-2018 2931.7 2312	4131.7	



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274011B	* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION (6627401000-009 - IRN P2740033). (6627401000-007 - IRN N2740025) 6627401000-009 B0926 REF: GENERIC NO REF	MOS HRS/MSC AFL	2400	I:0			21-MAR-2018 2931.7 2312	4154	
274011C	REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME SCREW (P/N 2A94568008). EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740023) 6627401000-009 B0926 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				21-MAR-2018 2931.7 2312		
274011D	REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME NUT (P/N 2A94567005). (EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740024) 6627401000-009 B0926 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				21-MAR-2018 2931.7 2312		
274031	TRIM-IN-MOTION DETECTOR 1625-1-1 206450224 REF: AMM 27-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
274041	FORWARD INTERFACE UNIT PN SN-UNKNOWN REF: AMM 27-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
274051	HORIZONTAL STABILIZER ACTUATOR CONTROL BOX ASSEMBLY 6627401000-003 D0677 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			01-NOV-2019 3426.4 2708		
274210	PC BOARD ASSEM, WHEEL MASTER DISCONNECT REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275000	FLAP HYDRAULIC MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275020	LEFT FLAP, OUTBOARD ACTUATOR 6627503000-033 2009 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C				04-APR-2013 1524.5 1169		
275021	LEFT FLAP, INBOARD ACTUATOR 6627503000-031 1350 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			04-APR-2013 1524.5 1169		
275022	RIGHT FLAP, INBOARD ACTUATOR 6627503000-031 1532 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C				04-APR-2013 1524.5 1169		
275023	RIGHT FLAP, OUTBOARD ACTUATOR 6627503000-033 1539 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C				04-APR-2013 1524.5 1169		
275030	LEFT * INBOARD FLAP ACTUATOR JOINT REPLACE 159174-1 SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2013 0 0		
275031	LEFT * OUTBOARD FLAP ACTUATOR JOINT REPLACE PN SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2013 0 0		
275032	RIGHT * INBOARD FLAP ACTUATOR JOINT REPLACE PN SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2013 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275033	RIGHT * OUTBOARD FLAP ACTUATOR JOINT REPLACE PN SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2013 0 0		
275057	FLAP DRIVE POWER UNIT 6627503000-001 1471X REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			15-APR-2016 2324.4 1822		
275058	FLAP CONTROL UNIT C144486-3-003 1452 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			30-MAR-2012 1307.7 999		
275069	FLAP POSITION INDICATOR C145159-1 1529 REF: AMM 27-50-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275080	FLAP CONTROL MODULE 69013-17 463 REF: AMM 27-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275081	LEFT FLAP DRIVE RVDT C144489-2 A0868 REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275082	RIGHT FLAP DRIVE RVDT C144489-2 A0858 REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275110	LH IB FLAP TRACK ASSEMBLY REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275112	RH IB FLAP TRACK ASSEMBLY REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275114	LH OB FLAP TRACK ASSEMBLY REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275116	RH OB FLAP TRACK ASSEMBLY REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275120	CENTER LEFT FLAP TRACK ASSEMBLY REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275122	CENTER RIGHT FLAP TRACK ASSEMBLY REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275201	SHAFT, LH INBD FLAP DRIVE PN SN-UNKNOWN REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275202	SHAFT, RH INBD FLAP DRIVE PN SN-UNKNOWN REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
275203	SHAFT, LH OUTBD FLAP DRIVE PN SN-UNKNOWN REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275204	SHAFT, RH OUTBD FLAP DRIVE PN SN-UNKNOWN REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
276001	LEFT SPOILER ACTUATOR P455A0001-04 AAA018P455 REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
276002	RIGHT SPOILER ACTUATOR P455A0001-04 AAA026P455 REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
276005	SPOILER CONTROL MODULE 69014-9 458 REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
276010	SPOILERON CONTROLLER RESISTOR BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 27-60-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
276013	SPOILER SHUTOFF VALVE 100291000-003 0129TK REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
276020	SPOILER LOW PRESSURE ASSEMBLY (L41) SWITCH PN SN-UNKNOWN REF: AMM 27-60-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
276031	LEFT SPOILER RVDT 3A2-249A A8057 REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276032	RIGHT SPOILER RVDT 3A2-249A A0864 REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
276073	SPOILERON COMPUTER 402800-06-02 00787 REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
276076	CONTROL WHEEL RVDT 3G4-211A 04630639 REF: AMM 27-60-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
5-19-00-D2740003	** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740003)  REF: AMM 27-40-02	MOS HRS/MSC AFL	600	+25/-25		-246.5	13-JAN-2021 3778.2 2986	4131.7	4156.7
5-19-00-D2740004	** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST (IRN D2740004)  REF: AMM 27-40-02	MOS HRS/MSC AFL	600	+25/-25		-246.5	13-JAN-2021 3778.2 2986	4131.7	4156.7
5-19-00-K2700007	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700007)  REF: AMM 27-00-00	MOS HRS/MSC AFL	4800				26-MAR-2007 0 0	4800	
5-19-00-K2700008	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700008)  REF: AMM 27-00-00	MOS HRS/MSC AFL	4800				26-MAR-2007 0 0	4800	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700009)	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-00-00	HRS/MSC AFL	4800				0 0	<b>4800</b>	
5-19-00-K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700010)	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-00-00	HRS/MSC AFL	4800				0 0	<b>4800</b>	
5-19-00-K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (IRN K2700012)	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-00-00	HRS/MSC AFL	4800				0 0	<b>4800</b>	
5-19-00-K2700014	DETAILED VISUAL INSPECTION * AILERON CONTROL SYSTEM PRIMARY CABLES (IRN K2700014)	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-00-00	HRS/MSC AFL	4800				0 0	<b>4800</b>	
5-19-00-M5540022	RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION	MOS							
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 55-40-00	HRS/MSC AFL	N/A						
5-19-00-N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION	MOS	72	+14d/-14d			08-MAR-2019	<b>08-MAR-2025</b>	22-MAR-2025
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-20-01	HRS/MSC AFL					3241.7 2541		
5-19-00-S2750057	* FLAP ACTUATOR BALLNUT SLEEVE (FLAP ACTUATOR ASSEMBLY LEARJET P/N 6627503000-009, 6627503000-011, 6627503000-021, 6627503000-023, 6627503000-025, AND 6627503000-027, FLAP ACTUATOR ASSEMBLY MICROTECNICA P/N C144487-1, C144488-1, C144487-2, C144488-2, C144487-3, AND C144488-3) - PERFORM FLUORESCENT PENETRANT INSPECTION	MOS							
<b>NOT APPLICABLE</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	N/A						

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-W2750056	PERFORM * FLAP ACTUATOR JOINT (P/N 145673-1) - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 27-50-06.) APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT. (REFER TO 12-21-03.). IRN W2750056	MOS						06-NOV-2009	
<b>N/A BY PART NUMBER</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	N/A				717.1 549		
+ 5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE	MOS					29-JAN-2020		
	PN-UNKNOWN	HRS/MSC	1200	+25/-25		-20.1	3544.5	<b>4724.4</b>	4749.4
	SN-UNKNOWN	AFL					2781		
	<b>REF:</b> AMM NO REF								
+ 5-19-01-AA2760021-LEFT	LEFT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE	MOS					29-JAN-2020		
	PN-UNKNOWN	HRS/MSC	1200	+25/-25		-20.1	3544.5	<b>4724.4</b>	4749.4
	SN-UNKNOWN	AFL					2781		
	<b>REF:</b> AMM NO REF								
+ 5-19-01-AA2760021-RIGHT	RIGHT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE	MOS					29-JAN-2020		
	PN-UNKNOWN	HRS/MSC	1200	+25/-25		-20.1	3544.5	<b>4724.4</b>	4749.4
	SN-UNKNOWN	AFL					2781		
	<b>REF:</b> AMM NO REF								
+ 5-19-01-AA2760021-RIGHT	RIGHT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE	MOS					29-JAN-2020		
	PN-UNKNOWN	HRS/MSC	1200	+25/-25		-20.1	3544.5	<b>4724.4</b>	4749.4
	SN-UNKNOWN	AFL					2781		
	<b>REF:</b> AMM NO REF								
5-19-01-R2710041	REPLACE * AILERON SPINDLE (P/N 4527102103-001). (IRN R2710041)	MOS						26-MAR-2007	
<b>NOT APPLICABLE</b>	<b>REF:</b> AMM 27-10-07	HRS/MSC AFL	N/A						
5-19-01-W2750055	* FLAP ACTUATOR JOINT (P/N 145673-1) (IRN W2750055) REPLACEMENT	MOS						06-NOV-2009	
	159174-1	HRS/MSC	N/A				717.1		
<b>NOT APPLICABLE</b>	<b>REF:</b> AMM 27-50-06	AFL					549		
A2711001 (s)	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK	MOS	24	+14d/-14d				29-JAN-2020	
	PKG 7	HRS/MSC	600	+25/-25			3544.5		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 27-10-04	AFL					2781		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A2721001 (s)	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK PKG 7	MOS	24	+14d/-14d			PKG	29-JAN-2020	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-20-00</b>	HRS/MSC AFL	600	+25/-25			3544.5 2781		
A2731002 (s)	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK PKG 8	MOS	24	+14d/-14d			PKG	29-JAN-2020	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-30-00</b>	HRS/MSC AFL	600	+25/-25			3544.5 2781		
A2760001 (s)	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK PKG 10	MOS	24	+14d/-14d			PKG	29-JAN-2020	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-60-04</b>	HRS/MSC AFL	600	+25/-25			3544.5 2781		
A2760002 (s)	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK PKG 10	MOS	24	+14d/-14d			PKG	29-JAN-2020	
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-60-00</b>	HRS/MSC AFL	600	+25/-25			3544.5 2781		
AA2700000 (s)	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES PKG 7	MOS	24	+14d/-14d			PKG	29-JAN-2020	
	<b>REF: AMM 27-00-00</b>	HRS/MSC AFL	600	+25/-25			3544.5 2781		
AA2700001 (s)	RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES PKG 7	MOS	24	+14d/-14d			PKG	29-JAN-2020	
	<b>REF: AMM 27-00-00</b>	HRS/MSC AFL	600	+25/-25			3544.5 2781		
AA2700002 (s)	ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES PKG 7	MOS	24	+14d/-14d			PKG	29-JAN-2020	
	<b>REF: AMM 27-00-00</b>	HRS/MSC AFL	600	+25/-25			3544.5 2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G2710003 (s)	PERFORM AILERON CONTROL SYSTEM CABLES (LOCATED IN WING AREA) - CABLE TENSION CHECK. PKG 16 REF: AMM 27-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
G2710004 (s)	PERFORM AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE AREA) - CABLE TENSION CHECK. PKG 13 REF: AMM 27-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
G2720003 (s)	PERFORM RUDDER CONTROL CABLES - TENSION CHECK. PKG 14 REF: AMM 27-20-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
G2720004 (s)	PERFORM RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER. PKG 13 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
G2730003 (s)	PERFORM ELEVATOR CONTROL CABLES - TENSION CHECK. PKG 14 REF: AMM 27-30-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
V2712000 (s)	** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK. PKG 7 AIRWORTHINESS REF: AMM 27-60-09	MOS HRS/MSC AFL	24 600	+25d/-25d +14/-14			PKG 29-JAN-2020 3544.5 2781		
W2731001 (s)	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR PKG 8 AIRWORTHINESS REF: AMM 27-30-14	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2700003 (s)	AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING PKG 10 REF: AMM 27-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2700004 (s)	RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES PKG 8 REF: AMM 27-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2700005 (s)	ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES PKG 8 REF: AMM 27-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2700006 (s)	RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION PKG 9 REF: AMM 27-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2710000 (s)	AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION PKG 10 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2710001 (s)	PERFORM AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - VISUAL INSPECTION PKG 16 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
Y2710002 (s)	PERFORM AILERON CONTROL SYSTEM - OPERATIONAL CHECK PKG 16 REF: AMM 27-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
Y2710048 (s)	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK PKG 22 REF: See Workcard	MOS HRS/MSC AFL	9600	+25/-25			PKG 26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2720000 (s)	RUDDER - PERFORM VISUAL INSPECTION PKG 2	MOS	12	+14d/-14d			PKG	13-JAN-2021	
	REF: AMM 05-10-00	HRS/MSC AFL	300	+25/-25			3778.2 2986		
Y2720001 (s)	PERFORM RUDDER BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - VISUAL INSPECTION PKG 14	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
Y2720002 (s)	PERFORM RUDDER CONTROL SYSTEM - OPERATIONAL CHECK PKG 14	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	REF: AMM 27-20-00	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
Y2721000 (s)	RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION. NOTE: ON AIRCRAFT 45-005 THRU 45-364 NOT MODIFIED BY SB 45-27-34 AND AIRCRAFT 45-005 THRU 45-428 NOT MODIFIED PER SB 45-27-37, REPLACE THE RUDDER TRIM TAB HINGE LOWER COTTER PIN DURING THIS INSPECTION. PKG 2	MOS	12	+14d/-14d			PKG	13-JAN-2021	
	REF: AMM 05-10-00	HRS/MSC AFL	300	+25/-25			3778.2 2986		
Y2730000 (s)	PERFORM CONTROL COLUMNS - VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AILERON CONTROL WHEEL CABLE DRUM AND BOTTOM CROSSOVER PULLEYS PKG 13	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
Y2730001 (s)	ELEVATORS - PERFORM VISUAL INSPECTION PKG 2	MOS	12	+14d/-14d			PKG	13-JAN-2021	
	REF: AMM 05-10-00	HRS/MSC AFL	300	+25/-25			3778.2 2986		
Y2730002 (s)	PERFORM ELEVATOR CONTROL SYSTEM - OPERATIONAL CHECK PKG 14	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+25/-25			3241.7 2541		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2730004 (s)	PERFORM CONTROL COLUMNS - INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING PKG 19 REF: AMM 27-00-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 10-APR-2015 2017.3		
Y2730007 (s)	PERFORM AFT ELEVATOR DISCONNECT - DETAILED VISUAL INSPECTION PKG 20 REF: AMM 05-10-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 10-APR-2015 2017.3		
Y2740000 (s)	PERFORM PRIMARY PITCH TRIM SYSTEM - OPERATIONAL CHECK PKG 14 REF: AMM 27-40-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
Y2740001 (s)	PERFORM SECONDARY PITCH TRIM SYSTEM - OPERATIONAL CHECK PKG 14 REF: AMM 27-40-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
Y2750000 (s)	FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED PKG 10 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
Y2750001 (s)	FLAPS - PERFORM VISUAL INSPECTION PKG 4 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y2750053 (s)	FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS PKG 10 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2760000 (s)	SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED						PKG		
	PKG 10	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
	REF: AMM 05-10-00	AFL					2781		
<b>CHAPTER 28 FUEL</b>									
281001	LEFT NO. 1 FUEL, EJECTOR SCAVENGE PUMP								
	HTE230008	MOS					26-MAR-2007		
	41061844	HRS/MSC	O/C				0		
	REF: AMM 28-12-01	AFL					0		
281002	RIGHT NO. 1 FUEL, EJECTOR SCAVENGE PUMP								
	HTE230008	MOS					26-MAR-2007		
	41061861	HRS/MSC	O/C				0		
	REF: AMM 28-12-01	AFL					0		
281003	LEFT NO. 2 FUEL, EJECTOR SCAVENGE PUMP								
	HTE230008	MOS					26-MAR-2007		
	41061853	HRS/MSC	O/C				0		
	REF: AMM 28-12-01	AFL					0		
281004	RIGHT NO. 2 FUEL, EJECTOR SCAVENGE PUMP								
	HTE230008	MOS					26-MAR-2007		
	41061848	HRS/MSC	O/C				0		
	REF: AMM 28-12-01	AFL					0		
281005	LEFT NO. 3 FUEL, EJECTOR SCAVENGE PUMP								
	HTE230008	MOS					26-MAR-2007		
	41061870	HRS/MSC	O/C				0		
	REF: AMM 28-12-01	AFL					0		
281006	RIGHT NO. 3 FUEL, EJECTOR SCAVENGE PUMP								
	HTE230008	MOS					26-MAR-2007		
	41061849	HRS/MSC	O/C				0		
	REF: AMM 28-12-01	AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281007	LEFT NO. 4 FUEL, EJECTOR SCAVENGE PUMP HTE230008 41061872 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
281008	RIGHT NO. 4 FUEL, EJECTOR SCAVENGE PUMP HTE230008 41061851 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
281009	LEFT NO. 5 FUEL, EJECTOR SCAVENGE PUMP HTE230008 41061876 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
281010	RIGHT NO. 5 FUEL, EJECTOR SCAVENGE PUMP HTE230008 43061674 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
281031	FUEL, FUSELAGE CELL 506877 104864 REF: AMM 28-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
281051	FUEL CROSSFLOW SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
281401	SURGE TANK FLOAT VALVE PN SN-UNKNOWN REF: AMM 28-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
281501	LEFT FLEX FUEL HOSE ASSY PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
28.015									

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281502	RIGHT FLEX FUEL HOSE ASSY								
28.015	PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
281521	LEFT FUEL TRANSFER CHECK VALVE								
	HTE460072 43060148 REF: AMM 28-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
281522	RIGHT FUEL TRANSFER CHECK VALVE								
	HTE460072 43060146 REF: AMM 28-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282001	LEFT FUEL SHUTOFF VALVE								
	PN SN-UNKNOWN REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282003	RIGHT FUEL SHUTOFF VALVE								
	EM91-102-2 1546 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282011	SHUTOFF - REFUEL VALVE								
	980056-2 24060013 REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282031	LEFT NO. 1 FUEL SUPPLY CHECK VALVE								
	HTE460071 44061028 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282032	LEFT NO. 2 FUEL SUPPLY CHECK VALVE								
	HTE460071 44061022 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282033	RIGHT NO. 1 FUEL SUPPLY CHECK VALVE HTE460071 44061035 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282034	RIGHT NO. 2 FUEL SUPPLY CHECK VALVE HTE460071 44061029 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282037	RIGHT FUEL SUPPLY SHUT-OFF (L10) VALVE ASSEMBLY EM91-102-2 1548 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282038	LEFT FUEL SUPPLY SHUT-OFF (L11) VALVE ASSEMBLY EM91-102-2 1542 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282041	CONTROL - REFUELING PANEL 4528408000V5-001 06100940BA REF: AMM 28-20-14	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282051	LEFT CHECK, MOTIVE FLOW VALVE 6628200106-003 45068350 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282052	RIGHT CHECK, MOTIVE FLOW VALVE 6628200106-003 45060351 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282063	PRE-CHECK, SPPR VALVE HTE940032-1 2706223 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282064	PILOT, SPPR VALVE 61087-2 436 REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282075	LEFT ASSEMBLY, FUEL MAIN EJECTOR PUMP HTE230009 43061489 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282076	RIGHT ASSEMBLY, FUEL MAIN EJECTOR PUMP HTE230009 43061491 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282087	LEFT FUEL, STANDBY PUMP 1C12-39 10BB78 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282088	RIGHT FUEL, STANDBY PUMP 1C12-39 10BB79 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282601	DEFUEL (B24) SHUTOFF VALVE EM91-102-2 1413 REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282602	REFUEL CHECK VALVE PN SN-UNKNOWN REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
282603	SINGLE POINT PRESSURE REFUELING (SPPR) ADAPTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282815	APU FUEL SHUTOFF VALVE 7086048-1 072203000940C REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			18-APR-2008 310.2 240		
284001	ASSEMBLY, FUEL C1 PROBE 10665T01Y00 MN06435 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284002	FUEL C2 PROBE 10665T03Y00 MN07506 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284003	ASSEMBLY, FUEL C3 PROBE 10552T03Y00 MN05073 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284004	ASSEMBLY, FUEL C4 PROBE 10552T04Y00 MN03701 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284005	ASSEMBLY, FUEL C5 PROBE 10552T05Y00 MN06028 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284006	ASSEMBLY, FUEL C6 PROBE 10552T06Y00 MN05840 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284008	FUEL C8 PROBE 10665T01Y00 MN06438 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284009	ASSEMBLY, FUEL C9 PROBE 10665T03Y00 MN07512 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284010	ASSEMBLY, FUEL C10 PROBE 10552T03Y00 MN06114 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284011	ASSEMBLY, FUEL C11 PROBE 10552T04Y00 MN03703 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284012	ASSEMBLY, FUEL C12 PROBE 10552T05Y00 MN06034 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284013	ASSEMBLY, FUEL C13 PROBE 10552T06Y00 MN05845 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284014	ASSEMBLY, FUEL C14 PROBE 10552T01Y00 MN06093 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284015	FUEL C15 PROBE 10552T01Y00 MN06097 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
284016	ASSEMBLY, FUEL C16 PROBE 10552T06Y00 MN05842 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284017	FUEL C17 PROBE 10552T06Y00 MN05846 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
284033	FUSELAGE FUEL PROBE 10554T02Y00 DT44618 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
284035	NO. 1 FUEL, LOW PRESSURE (S21) SWITCH PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
284036	NO. 2 FUEL, LOW PRESSURE (S21) SWITCH PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
284041	LEFT FLOAT, FUEL (S19 & S20) SWITCH PN SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
284042	RIGHT FLOAT, FUEL (S19 & S20) SWITCH PN SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
284045	FUEL QUANTITY SIGNAL CONDITIONER 10551B08Y09 1042 REF: AMM 28-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
284047	LEFT FUEL, LOW LEVEL SENSOR PN SN-UNKNOWN REF: AMM 28-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284048	RIGHT FUEL, LOW LEVEL SENSOR								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-40-03	AFL		N:0			0		
5-19-00-D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW PRESSURE FUEL FILTERS. (NEW AIRCRAFT 50-FLIGHT HOUR CHECK) (ZONE/ACCESS 510AL IRN # D2820013)								
		MOS					27-JUN-2007		
		HRS/MSC	A/R				54.1		
	REF: AMM 28-20-15	AFL					48		
5-19-00-H2840001	* DUAL FUEL FLOW CONVERTOR (DFFC) (P/N 10540B06F07) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING (IRN H2840001)								
		MOS					26-MAR-2007		
		HRS/MSC	N/A				0		
<b>NOT INSTALLED</b>	REF: GENERIC NO REF	AFL					0		
F2840003 (s)	PERFORM ** FUEL QUANTITY SIGNAL CONDITIONER - FUNCTIONAL TEST TO VERIFY WEIGHT-ON-WHEELS (WOW) INPUTS. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-194 POST SB 45-28-5 AND 45-195 AND SUBSEQUENT.)						PKG		
	PKG 14	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
<b>AIRWORTHINESS</b>	REF: AMM 28-40-00	AFL					2541		
Y2810001 (s)	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						PKG		
	PKG 10	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
	REF: AMM 05-10-00	AFL					2781		
Y2810002 (s)	PERFORM WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						PKG		
	PKG 22	MOS	96	+14d/-14d			10-APR-2015		
		HRS/MSC	2400	+25/-25			2017.3		
	REF: AMM 05-10-00	AFL							
Y2820000 (s)	LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY						PKG		
	PKG 10	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
	REF: AMM 28-20-15	AFL					2781		

## CHAPTER 29 HYDRAULIC POWER

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291001	HYDRAULIC RESERVOIR PN SN-UNKNOWN REF: AMM 29-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291012	L8 HYDRAULIC SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 29-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291013	L9 HYDRAULIC SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 29-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291033	RESERVOIR PRESSURIZATION CONTROL MODULE ZVM11-2 06-100659 REF: AMM 29-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291034	RESERVOIR FLUID LEVEL SENSOR 3L14F-17 663A2Q06 REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291045	NO. 1 HYDRAULIC, ENGINE DRIVEN PUMP 848888 MX705239A REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291046	NO. 2 HYDRAULIC, ENGINE DRIVEN PUMP 848888 MX704169A REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291051	NO. 1 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH PN SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291052	NO. 2 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH PN SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291057	MAIN HYDRAULIC SYSTEM ACCUMULATOR 88746-1 426 REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291059	MAIN HYDRAULIC FILTER MANIFOLD PN SN-UNKNOWN REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
291069	THERMAL SHUTOFF VALVE 98050 0621 REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
292001	AUXILIARY FILTER MANIFOLD ASSEMBLY PN SN-UNKNOWN REF: AMM 29-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
292011	AUXILIARY HYDRAULIC PUMP ASSEMBLY 66157-02 K0481 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
292012	AUXILIARY HYDRAULIC PUMP PN SN-UNKNOWN REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
292013	AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR PN SN-UNKNOWN REF: AMM 29-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
292025	AUXILIARY PRESSURE, HYDRAULIC SYSTEM (S29) SWITCH PN SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
292401	AUXILIARY HUDRAULIC PRESSURE CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
293001	GROUND SERVICE CONTROL BOX 4529308000-013 A50153 REF: AMM 29-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
293003	LEFT HYDRAULIC LOW (S8, S9) PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
293004	RIGHT HYDRAULIC LOW (S8, S9) PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
293011	HYDRAULIC PRESSURE TRANSDUCER 7629301001-001 7200-5-212 REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
5-19-01-D2910017	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910017) REF: AMM 29-10-03	MOS HRS/MSC AFL	-				21-MAR-2018 2931.7 2312		
5-19-01-D2910018	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS (D2910018) REF: AMM 29-10-03	MOS HRS/MSC AFL	300	+25/-25			13-JAN-2021 3778.2 2986	4078.2	4103.2

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-01-O2910005	REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS. (REFER TO 29-20-02.) (IRN # O2910005)	MOS					15-APR-2016		
	REF: AMM 29-20-02	HRS/MSC AFL	2400	+25/-25			2324.4 1822	4724.4	4749.4
H2920002 (s)	PERFORM HYDRAULIC SYSTEM GROUND SERVICE LEDS - FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-194 PRE SB 45-29-6.)	MOS	48	+14d/-14d			08-MAR-2019		
	PKG 13	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
	REF: AMM 29-30-00								
T2910026 (s)	PERFORM RELIEF FUNCTION OF THE HYDRAULIC RESERVOIR PRESSURIZATION CONTROL MODULE - FUNCTIONAL TEST.	MOS	48	+14d/-14d			08-MAR-2019		
	PKG 14	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
	REF: AMM 29-10-06								
Y2910001 (s)	PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT OF FUSELAGE FUEL CELL, FS 495 TO FS 512) - VISUAL INSPECTION.	MOS	48	+14d/-14d			08-MAR-2019		
	PKG 14	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
	REF: AMM 05-10-00								
Y2910002 (s)	PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (WHEEL WELL AND FORWARD AREA OF REAR SPAR) - VISUAL INSPECTION	MOS	48	+14d/-14d			08-MAR-2019		
	PKG 17	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
	REF: AMM 05-10-00								
Y2910003 (s)	PERFORM HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - VISUAL INSPECTION	MOS	96	+14d/-14d			10-APR-2015		
	PKG 19	HRS/MSC AFL	2400	+25/-25			2017.3		
	REF: AMM 05-10-00								
Y2920001 (s)	PERFORM AUXILIARY HYDRAULIC SYSTEM - OPERATIONAL CHECK	MOS	48	+14d/-14d			08-MAR-2019		
	PKG 13	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
	REF: AMM 29-20-00								

## CHAPTER 30 ICE AND RAIN PROTECTION

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301006	RELAY (P40) - ANTI-ICE VERTICAL STABILIZER. PANEL ASSY PN SN-UNKNOWN REF: AMM 30-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301010	LEFT HORIZONTAL STABILIZER CONTROL (MT47) SENSOR PN SN-UNKNOWN REF: AMM 30-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301011	RIGHT HORIZONTAL STABILIZER CONTROL (MT46) SENSOR PN SN-UNKNOWN REF: AMM 30-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301051	LEFT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301052	RIGHT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301063	LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L12) VALVE 3215616-2 1052 REF: AMM 30-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301064	RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L13) VALVE 3215616-2 1053 REF: AMM 30-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301065	LEFT SHUTTLE, ANTI-ICE VALVE PN SN-UNKNOWN REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301066	RIGHT SHUTTLE, ANTI-ICE VALVE PN SN-UNKNOWN REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301240	ANTI-ICE MANIFOLD ASSEMBLY PN SN-UNKNOWN REF: AMM 30-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301401	RH WING OUTBD TUBE ASSEM (ANTI-ICE) CHANGE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301601	LH ANTI-ICE TUBE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301602	RH ANTI-ICE TUBE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301603	L/H SLIDE, FLEX, JOINT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301604	STAB, ANTI-ICE ELBOW DUCT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
301605	ANTI-ICE DUCT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301606	R/H FLEX, SLIDE JOINT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
302001	NO. 1 NACELLE INLET ANTI-ICE SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 30-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
302002	NO. 2 NACELLE INLET ANTI-ICE SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 30-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
302013	NO. 1 NACELLE ANTI-ICE PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 30-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
302014	NO. 2 NACELLE ANTI-ICE PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 30-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
303501	LEFT NOSE RELAY (P15) BOX PN SN-UNKNOWN REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
303510	RIGHT NOSE RELAY (P16) BOX PN SN-UNKNOWN REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
304021	WINDSHIELD ANTI-ICE CONTROLLER 90825-7 477 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304060	NO. 1 WING SURFACE TEMPERATURE (MT42) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
304061	NO. 2 WING SURFACE TEMPERATURE (MT43) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
304062	NO. 3 WING SURFACE TEMPERATURE (MT44) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
304063	NO. 4 WING SURFACE TEMPERATURE (MT45) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
308005	ICE DETECTION PROBE 0871HN2 0416 REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
5-19-00-Q3010006	BORESCOPE INSPECTION ANTI-ICE MANIFOLD ASSEMBLY. (ZONE/ACCESS 300 **IRN # Q3010006). REFER TO 30-10-07.  REF: AMM 30-10-07	MOS HRS/MSC AFL	1200	+25/-25			21-MAR-2018 2931.7 2312	4131.7	4156.7
5-19-00-Z3020005-LEFT	LEFT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION. PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.  REF: AMM 30-20-00	MOS HRS/MSC AFL	250				27-JUL-2020 3663.9 2882	3913.9	
<b>AIRWORTHINESS</b>									

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-Z3020005-RIGHT	RIGHT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.	MOS					27-JUL-2020		
<b>AIRWORTHINESS</b>	<b>REF: AMM 30-20-00</b>	HRS/MSC AFL	250				3663.9 2882	<b>3913.9</b>	
+ 5-19-00-Z3020006-LEFT	LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS	MOS					26-MAR-2007		
	<b>REF: GENERIC NO REF</b>	HRS/MSC AFL	N/A				0 0		
+ 5-19-00-Z3020006-RIGHT	RIGHT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS	MOS					26-MAR-2007		
	<b>REF: GENERIC NO REF</b>	HRS/MSC AFL	N/A				0 0		
A3020000 (s)	PERFORM ** NACELLE ANTI-ICE SYSTEM - FUNCTIONAL TEST						PKG		
	PKG 15	MOS	48	+14d/-14d			08-MAR-2019		
<b>AIRWORTHINESS</b>	<b>REF: AMM 30-20-00</b>	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
A3030000 (s)	PERFORM ** PITOT/STATIC HEAT SYSTEM - OPERATIONAL CHECK						PKG		
	PKG 19	MOS	96	+14d/-14d			10-APR-2015		
<b>AIRWORTHINESS</b>	<b>REF: AMM 30-30-00</b>	HRS/MSC AFL	2400	+25/-25			2017.3		
H3010000 (s)	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
<b>AIRWORTHINESS</b>	<b>REF: AMM 30-10-00</b>	HRS/MSC AFL	600	+25/-25			3544.5 2781		
T3040000 (s)	** PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
<b>AIRWORTHINESS</b>	<b>REF: AMM 30-40-00</b>	HRS/MSC AFL	600	+25/-25			3544.5 2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y3010007 (s)	WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176. PKG 10	MOS	24	+14d/-14d			PKG	29-JAN-2020	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			3544.5 2781		
Y3080000 (s)	PERFORM ICE DETECTION SYSTEM - FUNCTIONAL TEST PKG 13	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	REF: AMM 30-80-00	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
<b>CHAPTER 31 INDICATING/RECORDING SYSTEMS</b>									
311001	PILOT CIRCUIT BREAKER PANEL ASSY PN	MOS						26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	REF: AMM 24-60-01	AFL			N:0		0		
311005	COPILOT CIRCUIT BREAKER PANEL ASSY PN	MOS						26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	REF: AMM 24-60-01	AFL			N:0		0		
311601	GEAR UP/DOWN S47 SWITCH PN	MOS						26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	REF: AMM 32-30-02	AFL			N:0		0		
311606	PANEL, CENTER SWITCH REPLACE PN	MOS						26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	REF: AMM 31-11-03	AFL			N:0		0		
311805	ENGINE FUEL CONTROL (P7) PANEL ASSY PN	MOS						26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	REF: AMM 31-11-05	AFL			N:0		0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
311806	ENGINE/FUEL CONTROL PANEL OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
311906	FORWARD QUADRANT SWITCH PANEL (P6) OVERLAY PN SN-UNKNOWN REF: AMM 31-11-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
311906-1	RUDDER BOOST (DS48) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
312001	PILOT CLOCK M850-5V-LA 3691 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
312002	COPILOT CLOCK M850-5V-LA 3590 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
312011	PILOTS DIGITAL CLOCK BATTERY E90 12-2023 REF: AMM 31-21-02	MOS HRS/MSC AFL	12	+14d/-14d	N:0		18-JAN-2021 3787.7 2992	<b>18-JAN-2022</b>	01-FEB-2022
312012	COPILOTS DIGITAL CLOCK BATTERY PN-UNKNOWN SN-UNKNOWN REF: AMM 31-21-02	MOS HRS/MSC AFL	12	+14d/-14d	N:0 N:0 N:0		13-JAN-2021 3778.2 2986	<b>13-JAN-2022</b>	27-JAN-2022
312101	LEFT INCLINOMETER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
312104	RIGHT INCLINOMETER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
313001	FLIGHT DATA RECORDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
313001A	DOWNLOAD FLIGHT DATA RECORDER PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	N/R				26-MAR-2007 0 0		<b>CUSTOMER CODE</b>
313003	FDR ACCELEROMETER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
313005	FDR UNDERWATER LOCATOR BEACON PN SN-UNKNOWN REF: AMM 25-61-01	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			26-MAR-2007 0 0		<b>NOT INSTALLED</b>
313005A	PERFORM FDR UNDERWATER LOCATOR BEACON FUNCTIONAL TEST OF BEACON, CLEAN BEACON SWITCH AND PERFORM TEST OF ULB BATTERY. (IRN AA2560000) PN SN-UNKNOWN REF: AMM 25-61-01	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		<b>NOT INSTALLED</b>
313005B	REPLACE FDR UNDERWATER LOCATOR BEACON BATTERY ON OR BEFORE ULB BATTERY REPLACEMENT DATE. (ZONE/ACCESS 300 IRN # D2566001) PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		<b>NOT INSTALLED</b>

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313010	HOBBS METER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
313018	INERTIA, FDR SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			26-MAR-2007 0 0		
314001	SELCAL DECODER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
314011	NO. 1 DATA ACQUISITION (DAU) UNIT 7013348-938 06106368 REF: AMM 31-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
314012	NO. 2 DATA ACQUISITION (DAU) UNIT 7013348-938 06106369 REF: AMM 31-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
314023	NO. 1 INTEGRATED AVIONICS (IC-600) COMPUTER 7017000-82224 SN-UNKNOWN REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C				09-APR-2009 599.6		
314024	NO. 2 INTEGRATED AVIONICS (IC-600) COMPUTER 7017000-82224 SN-UNKNOWN REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C				09-APR-2009 599.6		
314051	NO. 1 CENTRAL COMPUTING IM-600 MEMORY MODULE 7025973-04214 06094342 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2007 10.9 11		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314052	NO. 2 CENTRAL COMPUTING IM-600 MEMORY MODULE 7025973-04214 06094343 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2007 10.9 11		
315001	CREW WARNING PANEL ASSEMBLY 90-42801-8 438 REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
315005	SWITCH, REVERSION, PILOT (V91812), (S135) REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316001	NO. 1 DU870 DISPLAY UNIT 7014300-901 0611F893 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316001-1	PILOT (#1) MFD CONTROLLER BEZEL PN SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316002	NO. 2 DU870 DISPLAY UNIT 7014300-901 0611F894 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316002-1	PILOT (#2) MFD CONTROLLER BEZEL PN SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316003	NO. 3 DU870 DISPLAY UNIT 7014300-901 0607F616 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	O:3 O:0 O:0			02-NOV-2016 2459.7 1944		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316003-1	COPILOT (#3) MFD CONTROLLER BEZEL PN SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316004	NO. 4 DU870 DISPLAY UNIT 7014300-901 0611F896 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316004-1	COPILOT (#4) MFD CONTROLLER BEZEL PN SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316005	PILOT EFIS DISPLAY CONTROLLER 7016986-733 06116614 REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316006	COPILOT EFIS DISPLAY CONTROLLER 7016986-733 06116615 REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
316091	DATA TRANSFER, AFIS UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
B3100000 (s)	** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK PKG 7 REF: AMM 31-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			29-JAN-2020 3544.5 2781	PKG	

**CHAPTER 32 LANDING GEAR**

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320041	* REPLACE LEFT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) IRN N3220101								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-10-01</b>	AFL	10000	N:0			0		<b>10000</b>
320042	* REPLACE RIGHT UPPER MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-10-01</b>	AFL	10000	N:0			0		<b>10000</b>
320043	* REPLACE LEFT LOWER MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 32-10-01</b>	AFL	10000	N:0			0		<b>10000</b>
320044	* REPLACE RIGHT LOWER MAIN LANDING GEAR LINK PIN (P/N 200-0214) (IRN N3220101)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 32-10-01</b>	AFL	10000	N:0			0		<b>10000</b>
320051	* REPLACE LEFT MAIN LANDING GEAR PISTON PIN (P/N 200-0215). (IRN N3220102)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	10000	N:0			0		<b>10000</b>
320052	* REPLACE RIGHT MAIN LANDING GEAR PISTON PIN (P/N 200-0215) (IRN N3220102) ASSEMBLY								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	10000	N:0			0		<b>10000</b>
320061	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-31-01</b>	AFL	17000	N:0			0		<b>17000</b>
320062	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-31-01</b>	AFL	17000	N:0			0		<b>17000</b>

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320071	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	17000	N:0			0		<b>17000</b>
320072	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	17000	N:0			0		<b>17000</b>
320081	* REPLACE LEFT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)								
	PN	MOS		N:0			27-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-31-01</b>	AFL	2387	N:0	734		0		<b>3121</b>
		APH							
320082	* REPLACE RIGHT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067)								
	200-0303-001	MOS		N:0			24-APR-2018		
	H2755	HRS/MSC		N:0			2992.4		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-31-01</b>	AFL	2387	N:0			2348		<b>4735</b>
320091	* REPLACE LEFT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-31-01</b>	AFL	17000	N:0			0		<b>17000</b>
320092	* REPLACE RIGHT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068)								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-31-01</b>	AFL	17000	N:0			0		<b>17000</b>
321001	* LEFT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY								
	200-0200-013	MOS		N:85			16-APR-2014		
	H0424	HRS/MSC		N:1734.5			1734.5		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-10-01</b>	AFL	10000	N:1346			1346		<b>10000</b>

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321001A	PERFORM SPECIAL DETAILED INSPECTION ON LEFT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)	MOS	96	+14d/-14d			16-APR-2014 1734.5	<b>16-APR-2022</b>	30-APR-2022
	REF: See Workcard	AFL	6600	+25/-25			1346	<b>7946</b>	7971
321002	* RIGHT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY	MOS		N:85			16-APR-2014 1734.5		
	200-0200-014	HRS/MSC		N:1734.5			1346	<b>10000</b>	
<b>LIFE LIMIT</b>	REF: AMM 32-10-01	AFL	10000	N:1346					
321002A	PERFORM SPECIAL DETAILED INSPECTION ON RIGHT MAIN LANDING GEAR SHOCK STRUTS (IRN AA3220018)	MOS	96	+14d/-14d			16-APR-2014 1734.5	<b>16-APR-2022</b>	30-APR-2022
	REF: See Workcard	AFL	6600	+25/-25			1346	<b>7946</b>	7971
321011	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128)	MOS		N:0			26-MAR-2007 0		
	SN-UNKNOWN	HRS/MSC		N:0			0	<b>6600</b>	
<b>LIFE LIMIT</b>	REF: AMM 32-10-01	AFL	6600	N:0			0		
321011A	ULTRASONIC-INSPECTION * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122)	MOS					26-MAR-2007 0		
	SN-UNKNOWN	HRS/MSC					0	<b>3300</b>	
<b>AIRWORTHINESS</b>	REF: See Workcard	AFL	3300				0		
321012	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128)	MOS		N:0			26-MAR-2007 0		
	SN-UNKNOWN	HRS/MSC		N:0			0	<b>6600</b>	
<b>LIFE LIMIT</b>	REF: AMM 32-10-01	AFL	6600	N:0			0		
321012A	ULTRASONIC-INSPECTION * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN'S N3220116, Q3220137, Q3220128) * MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122)	MOS					26-MAR-2007 0		
	SN-UNKNOWN	HRS/MSC					0	<b>3300</b>	
<b>AIRWORTHINESS</b>	REF: See Workcard	AFL	3300				0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321025	* LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY 200-0325-101 CPS01C-3651 <b>REF:</b> AMM 32-31-01	MOS HRS/MSC AFL	96	N:0 N:0 N:0			13-JAN-2021 3778.2 2986	<b>13-JAN-2029</b>	
<b>LIFE LIMIT</b>									
321025A	MAGNETIC PARTICLE INSPECT * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220024) 200-0325-101 CPS01C-3651 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48				13-JAN-2021 3778.2 2986	<b>13-JAN-2025</b>	
<b>AIRWORTHINESS</b>									
321025B	DETAILED VISUAL INSPECTION * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220135) 200-0325-101 CPS01C-3651 <b>REF:</b> AMM 05-10-00	MOS HRS/MSC AFL	48				13-JAN-2021 3778.2 2986	<b>13-JAN-2025</b>	
<b>AIRWORTHINESS</b>									
321026	* RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY 200-0325-101 CPS01C-3655 <b>REF:</b> AMM 32-31-01	MOS HRS/MSC AFL	96	N:0 N:0 N:0			13-JAN-2021 3778.2 2986	<b>13-JAN-2029</b>	
<b>LIFE LIMIT</b>									
321026A	MAGNETIC PARTICLE INSPECT * RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220024) 200-0325-101 CPS01C-3655 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48				13-JAN-2021 3778.2 2986	<b>13-JAN-2025</b>	
<b>AIRWORTHINESS</b>									
321026B	DETAILED VISUAL INSPECTION * RIGHT MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) ASSEMBLY * (IRN T3220135) 200-0325-101 CPS01C-3655 <b>REF:</b> AMM 05-10-00	MOS HRS/MSC AFL	48				13-JAN-2021 3778.2 2986	<b>13-JAN-2025</b>	
<b>AIRWORTHINESS</b>									
321037	* LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY 200-0217-101 CPS01C-4073 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	96	N:0 N:0 N:0			13-JAN-2021 3778.2 2986	<b>13-JAN-2029</b>	
<b>LIFE LIMIT</b>									

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321037A	MAGNETIC PARTICLE INSPECT * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220024)								
	200-0217-101	MOS	48				13-JAN-2021	13-JAN-2025	
	CPS01C-4073	HRS/MSC					3778.2		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	AFL					2986		
321037B	DETAILED VISUAL INSPECTION * LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220135)								
	200-0217-101	MOS	48				13-JAN-2021	13-JAN-2025	
	CPS01C-4073	HRS/MSC					3778.2		
<b>AIRWORTHINESS</b>	<b>REF: AMM 05-10-00</b>	AFL					2986		
321038	* RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY								
	200-0217-101	MOS	96	N:0			13-JAN-2021	13-JAN-2029	
	CPS01C-4084	HRS/MSC		N:0			3778.2		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	AFL		N:0			2986		
321038A	MAGNETIC PARTICLE INSPECT * RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220024)								
	200-0217-101	MOS	48				13-JAN-2021	13-JAN-2025	
	CPS01C-4084	HRS/MSC					3778.2		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	AFL					2986		
321038B	DETAILED VISUAL INSPECTION * RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) ASSEMBLY * (IRN T3220135)								
	200-0217-101	MOS	48				13-JAN-2021	13-JAN-2025	
	CPS01C-4084	HRS/MSC					3778.2		
<b>AIRWORTHINESS</b>	<b>REF: AMM 05-10-00</b>	AFL					2986		
321049	* LEFT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (N3220036) ASSEMBLY								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-10-01</b>	AFL	10000	N:0			0	10000	
321049A	INSPECTION * LEFT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007)								
		MOS	48				21-MAR-2018	21-MAR-2022	
		HRS/MSC					2931.7		
	<b>REF: AMM 32-10-01</b>	AFL					2312		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321050	* RIGHT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (N3220036) ASSEMBLY								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-10-01</b>	AFL	10000	N:0			0	<b>10000</b>	
321050A	INSPECTION * RIGHT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007)								
		MOS	48				21-MAR-2018	<b>21-MAR-2022</b>	
		HRS/MSC					2931.7		
	<b>REF: AMM 32-10-01</b>	AFL					2312		
321061	LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
321062	RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
321073	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
321074	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
321085	LEFT FORWARD TRUNNION ASSEMBLY								
	4532103011-011	MOS		N:0			26-MAR-2007		
	CMI-138	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
321086	RIGHT FORWARD TRUNNION ASSEMBLY								
	4532103011-012	MOS		N:0			26-MAR-2007		
	CMI-107	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321087	LEFT AFT TRUNNION ASSEMBLY 4532103021-009 CMI-102 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
321088	RIGHT AFT TRUNNION ASSEMBLY 4532103021-010 CMI-107 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
321101	* REPLACE LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213). (IRN N3220023) ASSEMBLY 200-0212-103 H1057 REF: See Workcard	MOS HRS/MSC AFL	10000	N:85 N:1734.5 N:1346			16-APR-2014 1734.5 1346		10000
321101A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN - (IRN V3220022) REF: See Workcard	MOS HRS/MSC AFL	96	+14d/-14d			16-APR-2014 1734.5 1346	16-APR-2022	30-APR-2022
321102	* REPLACE RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY 200-0212-103 H1015 REF: See Workcard	MOS HRS/MSC AFL	10000	N:85 N:1734.5 N:1346			16-APR-2014 1734.5 1346		10000
321102A	MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (IRN V3220022) REF: See Workcard	MOS HRS/MSC AFL	96	+14d/-14d			16-APR-2014 1734.5 1346	16-APR-2022	30-APR-2022
321103	* REPLACE LEFT MAIN LANDING GEAR TRUNNION AFT PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY 200-0213-103 H0842 REF: See Workcard	MOS HRS/MSC AFL	10000	N:85 N:1734.5 N:1346			16-APR-2014 1734.5 1346		10000

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321103A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION AFT PIN (IRN V3220022)	MOS HRS/MSC AFL	96	+14d/-14d			16-APR-2014 1734.5 1346	16-APR-2022	30-APR-2022
	REF: See Workcard								
321104	* REPLACE RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY	MOS HRS/MSC AFL		N:85 N:1734.5 N:1346			16-APR-2014 1734.5 1346		10000
	200-0213-103 H0853 REF: See Workcard		10000						
LIFE LIMIT									
321104A	MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (IRN V3220022)	MOS HRS/MSC AFL	96	+14d/-14d			16-APR-2014 1734.5 1346	16-APR-2022	30-APR-2022
	REF: See Workcard								
32111-2	BRAKE NO. 1 SWIVEL	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		
	PN SN-UNKNOWN REF: GENERIC NO REF		O/C						
321111	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		5000
	4532103201-001 CMI-1596 REF: AMM 57-10-05		5000						
LIFE LIMIT									
321111A	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC AFL		N/A					
NOT APPLICABLE	REF: AMM 57-10-05								
321112	RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		5000
	4532103201-001 CMI-1615 REF: AMM 57-10-05		5000						
LIFE LIMIT									

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321112A	RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION								
<b>NOT APPLICABLE</b>	<b>REF:</b> AMM 57-10-05	MOS HRS/MSC AFL	N/A						
321113	LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103201-001 CMI-1626	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		5000
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 57-10-05		5000						
321113A	LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION								
<b>NOT APPLICABLE</b>	<b>REF:</b> AMM 57-10-05	MOS HRS/MSC AFL	N/A						
321114	RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103201-001 CMI-1011	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		5000
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 57-10-05		5000						
321114A	RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION								
<b>NOT APPLICABLE</b>	<b>REF:</b> AMM 57-10-05	MOS HRS/MSC AFL	N/A						
321117	LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103202-001 CMI-333	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		5000
<b>LIFE LIMIT</b>	<b>REF:</b> AMM 57-10-05		5000						
321117A	LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION								
<b>NOT APPLICABLE</b>	<b>REF:</b> AMM 57-10-05	MOS HRS/MSC AFL	N/A						

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321118	RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103202-001 CMI-600	MOS HRS/MSC		N:0 N:0			26-MAR-2007 0		
<b>LIFE LIMIT</b>	<b>REF: AMM 57-10-05</b>	AFL	5000	N:0			0	<b>5000</b>	
321118A	RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC	N/A						
<b>NOT APPLICABLE</b>	<b>REF: AMM 57-10-05</b>	AFL							
321119	LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103203-001 CMI-828	MOS HRS/MSC		N:0 N:0			26-MAR-2007 0		
<b>LIFE LIMIT</b>	<b>REF: AMM 57-10-05</b>	AFL	5000	N:0			0	<b>5000</b>	
321119A	LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC	N/A						
<b>NOT APPLICABLE</b>	<b>REF: AMM 57-10-05</b>	AFL							
321120	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103203-001 CMI-738	MOS HRS/MSC		N:0 N:0			26-MAR-2007 0		
<b>LIFE LIMIT</b>	<b>REF: AMM 57-10-05</b>	AFL	5000	N:0			0	<b>5000</b>	
321120A	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION	MOS HRS/MSC	N/A						
<b>NOT APPLICABLE</b>	<b>REF: AMM 57-10-05</b>	AFL							
321201	LEFT MAIN LANDING GEAR OLEO ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			26-MAR-2007 0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321202	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
321215	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			26-MAR-2007 0 0	10000	
321216	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			26-MAR-2007 0 0	10000	
321227	* REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY PN SN-UNKNOWN REF: AMM 32-10-01	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			26-MAR-2007 0 0	10000	
321228	* REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY PN SN-UNKNOWN REF: AMM 32-10-01	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			26-MAR-2007 0 0	10000	
321301	LEFT MAIN LANDING GEAR OUTBOARD DOOR 4552803003-003 902124600404 REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
321302	LEFT MAIN LANDING GEAR INBOARD DOOR 4552803004-003 902135600405 REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
321303	RIGHT MAIN LANDING GEAR INBOARD DOOR 4552803004-004 902142500404 REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321304	RIGHT MAIN LANDING GEAR OUTBOARD DOOR 4552803003-004 266127100404 REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
322001 (s)	* REPLACE NOSE LANDING GEAR STRUT ASSEMBLY (O3220009) (JAA E3220069) 4532201000V14-005 348 REF: AMM 32-20-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			26-MAR-2007 0 0		
LIFE LIMIT									
322002	NOSE LANDING GEAR CYLINDER 2342102 T544 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
322003	NOSE LANDING GEAR PISTON 2342104 F292 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
322004	NOSE LANDING GEAR ACTUATOR BRACKET 2342111 R309 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
322005	NOSE LANDING GEAR FORK 2342116 R488 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
322011	* REPLACE NOSE LANDING GEAR ACTUATOR (P/N 6632201000) (O3220010) (JAA IRN E3220073) ASSEMBLY 30460-7 EFS519 REF: AMM 32-32-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			26-MAR-2007 0 0		20000
LIFE LIMIT									
322061	* REPLACE NOSE LANDING GEAR TRUNNION AXLE (P/N 2342110) (IRN O3220029 JAA IRN E3220072) ASSEMBLY 2342110-003 R559 REF: AMM 32-20-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			26-MAR-2007 0 0		20000
LIFE LIMIT									

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322071	* REPLACE LEFT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071) ASSEMBLY 2342108-003 E113	MOS HRS/MSC		N:0 N:0			26-MAR-2007 0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-20-01</b>	AFL	20000	N:0			0	<b>20000</b>	
322072	* REPLACE RIGHT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071) ASSEMBLY 2342108-003 E234	MOS HRS/MSC		N:0 N:0			26-MAR-2007 0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-20-01</b>	AFL	20000	N:0			0	<b>20000</b>	
322095	LEFT NOSE LANDING GEAR DOOR PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			26-MAR-2007 0		
	<b>REF: AMM 52-81-01</b>	AFL		N:0			0		
322096	RIGHT NOSE LANDING GEAR DOOR PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			26-MAR-2007 0		
	<b>REF: AMM 52-81-01</b>	AFL		N:0			0		
322098	AXLE, PISTON ASSEM, NOSE LANDING GEAR REPLACE PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			26-MAR-2007 0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
322111	NOSE LANDING GEAR CHASSIS ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			26-MAR-2007 0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
322121	NOSE LANDING GEAR UPLOCK MECHANISM 2269H000-003 1463	MOS HRS/MSC	O/C	N:0 N:0			26-MAR-2007 0		
	<b>REF: AMM 32-32-02</b>	AFL		N:0			0		
323001	LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE 200-0300-003 H0432	MOS HRS/MSC		N:85 N:1734.5			16-APR-2014 1734.5		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-31-01</b>	AFL	17000	N:1346			1346	<b>17000</b>	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323001A	INSPECT LH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111)	MOS	96	+14d/-14d			16-APR-2014	16-APR-2022	30-APR-2022
		HRS/MSC					1734.5		
	REF: GENERIC NO REF	AFL	10000	+25/-25			1346	11346	11371
323002	RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE	MOS					24-APR-2018		
	200-0300-004	HRS/MSC			R:0		2992.4		
	H1454	AFL	17000		R:0		2348	17036	
LIFE LIMIT	REF: AMM 32-31-01				N:2312 R:0				
323002A	INSPECT RH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN AA3220111)	MOS	96	+14d/-14d			16-APR-2014	16-APR-2022	30-APR-2022
		HRS/MSC					1734.5		
	REF: GENERIC NO REF	AFL	10000	+25/-25			1346	11346	11371
323037	MAIN LANDING GEAR UPLOCK INBD DOOR, LEFT MECHANISM	MOS					26-MAR-2007		
	3000H000-005	HRS/MSC	O/C		N:0		0		
	1882	AFL			N:0		0		
	REF: AMM 32-31-04				N:0				
323038	MAIN LANDING GEAR UPLOCK INBD DOOR, RIGHT MECHANISM	MOS					26-MAR-2007		
	3000H000-006	HRS/MSC	O/C		N:0		0		
	1941	AFL			N:0		0		
	REF: AMM 32-31-04				N:0				
323110	NOSE LANDING GEAR DOWN-LOCK (S139) SWITCH	MOS					26-MAR-2007		
	PN	HRS/MSC	O/C		N:0		0		
	SN-UNKNOWN	AFL			N:0		0		
	REF: AMM 32-60-05				N:0				
323220	DOWN AND LOCKED (S96) SWITCH	MOS					26-MAR-2007		
	PN	HRS/MSC	O/C		N:0		0		
	SN-UNKNOWN	AFL			N:0		0		
	REF: AMM 32-60-02				N:0				

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323221	DOWN AND LOCKED (S100) SWITCH PN SN-UNKNOWN REF: AMM 32-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
323225	UP, LOCKED (VU1605) (S98) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
323226	UP, LOCKED (VU1605), (S102), RH SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
323301	* REPLACE LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY 7469-1 0790 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
323302	* REPLACE RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) ASSEMBLY 7469-1 0830 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
323304	SWITCH ASSEM, ACTUATOR HYD, MLG DOOR REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
323305	LEFT MLG ACTUATOR GIMBAL ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323306	RIGHT MLG ACTUATOR GIMBAL ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
323307	LEFT MLG SHAFT GIMBAL ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
323308	RIGHT MLG SHAFT GIMBAL ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
323309	LEFT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
323310	RIGHT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
323311	LEFT HAND MAIN GEAR DOOR INBD ACTUATOR PN SN-UNKNOWN REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
323312	RIGHT HAND MAIN GEAR DOOR, INBD ACTUATOR PN SN-UNKNOWN REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
323735	CONTROL VALVE 2245H000-002 1451 REF: AMM 32-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324001	NO. 1 MAIN LANDING GEAR WHEEL 3-1545-1 2300 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				02-JUN-2020 3631.9 2849		
324001A	NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL 3-1545-1 2300 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				02-JUN-2020 3631.9 2849		
324002	NO. 2 MAIN LANDING GEAR WHEEL 3-1545-1 0788 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				02-JUN-2020 3631.9 2849		
324002A	NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL 3-1545-1 0788 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				02-JUN-2020 3631.9 2849		
324003	NO. 3 MAIN LANDING GEAR WHEEL 3-1545-1 0776 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			21-JUL-2020 3662.4 2879		
324003A	NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL 3-1545-1 0776 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				21-JUL-2020 3662.4 2879		
324004	NO. 4 MAIN LANDING GEAR WHEEL 3-1545-1 0102 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			21-JUL-2020 3662.4 2879		
324004A	NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL 3-1545-1 0102 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				21-JUL-2020 3662.4 2879		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324005	NOSE GEAR WHEEL ASSEMBLY 9544207-4 MAR11-11003 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C					27-JUL-2020 3663.9 2882	
324021	NO. 1 MAIN LANDING GEAR TIRE 226K08-4 72962868 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-MAR-2018 2931.7 2312	
324022	NO. 2 MAIN LANDING GEAR TIRE 226K08-4 72922881 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-MAR-2018 2931.7 2312	
324023	NO. 3 MAIN LANDING GEAR TIRE 226K08-4 7227S00496 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				17-SEP-2018 3085.3 2428	
324024	NO. 4 MAIN LANDING GEAR TIRE 226K08-4 SN-UNKNOWN REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C					06-JUN-2017 2689.7 2113	
324025	NOSE LANDING GEAR TIRE 031-613-8 9052S00346 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				27-JUL-2020 3663.9 2882	
324061	LEFT ANTI-SKID CONTROL VALVE 39-787 366 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
324062	RIGHT ANTI-SKID CONTROL VALVE 39-787 1000 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324066	LEFT ANTI-SKID SHUTOFF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324067	RIGHT ANTI-SKID SHUTOFF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324097	BRAKE CONTROL UNIT 42-933-3 548 REF: AMM 32-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324108	EMERGENCY PARKING BRAKE CHECK VALVE PN SN-UNKNOWN REF: AMM 32-42-09	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0			26-MAR-2007 0 0 0		
324109	EMERGENCY/PARK BRAKE VALVE 8196-5 0522 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324110	PRESSURE, EMERGENCY/PARK BRAKE TRANSDUCER 7629301001-001 7172-7-76 REF: AMM 32-42-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324111	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 2008 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324111-1	INBOARD BRAKE NO. 1 SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324111-2	OUTBOARD BRAKE NO. 1 SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324112	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 1981 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324112-1	INBOARD BRAKE NO. 2 SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324112-2	OUTBOARD BRAKE NO. 2 SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324113	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 2000 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324113-1	INBOARD BRAKE NO. 3 SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324113-2	OUTBOARD BRAKE NO. 3 SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324114	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 1983 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324114-1	INBOARD BRAKE NO. 4 SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324114-2	OUTBOARD BRAKE NO. 4 SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324201	NO. 1 BRAKE SHUTTLE VALVE 5116-1 1732 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324202	NO. 2 BRAKE SHUTTLE VALVE 5116-1 1723 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324203	NO. 3 BRAKE SHUTTLE VALVE 5116-1 1741 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324204	NO. 4 BRAKE SHUTTLE VALVE 5116-1 1739 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324205	BRAKE SHUTTLE MODULE PN SN-UNKNOWN REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324305	LEFT PILOT BRAKE TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324306	RIGHT PILOT BRAKE TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324307	LEFT CO-PILOT BRAKE TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324308	RIGHT CO-PILOT BRAKE TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324601	SHUTTLE MODULE, ANTI-SKID, BRAKE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324610-1	LEFT INBOARD BRAKE SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324610-2	LEFT OUTBOARD BRAKE SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324611-1	RIGHT INBOARD BRAKE SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324611-2	RIGHT OUTBOARD BRAKE SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324701	NO. 1 HYDRAULIC, BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324702	NO. 2 HYDRAULIC, BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324703	NO. 3 HYDRAULIC, BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324704	NO. 4 HYDRAULIC, BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324711	NO. 1 WHEEL SPEED - ANTI-SKID TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324712	NO. 2 WHEEL SPEED - ANTI-SKID TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
324713	NO. 3 WHEEL SPEED - ANTI-SKID TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324714	NO. 4 WHEEL SPEED - ANTI-SKID TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
324721	(MT56) PRESSURE BRAKE TRANSDUCER ASSEMBLY PN SN-UNKNOWN REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
324722	(MT57) PRESSURE BRAKE TRANSDUCER ASSEMBLY PN SN-UNKNOWN REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
324723	(MT58) PRESSURE BRAKE TRANSDUCER ASSEMBLY PN SN-UNKNOWN REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
324724	(MT59) PRESSURE BRAKE TRANSDUCER ASSEMBLY PN SN-UNKNOWN REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
324725	TRANSDUCER, PRESSURE BRAKE (M69) REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
324726	TRANSDUCER, PRESSURE BRAKE (M70) REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
324801	EMERGENCY/PARK BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-42-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324805	EMER/PARK BRAKE ACCUMULATOR 88744-1 468 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
325007	FILTER, NOSE WHEEL STEERING (P41) BOX PN SN-UNKNOWN REF: AMM 32-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
325011	NOSE WHEEL STEERING SERVO ACTUATOR JR5208C C0468 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
325021	NOSE WHEEL STEERING GEARBOX 2W3201D A0467 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
325031	NOSE WHEEL STEERING COMPUTER 498000-03-02 00582 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
325035	NOSE WHEEL STEERING POWER SUPPLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
325041	LEFT NOSE WHEEL STEERING TRANSDUCER 19710 / 3A1-279A A0905 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
325042	RIGHT NOSE WHEEL STEERING TRANSDUCER 19710 / 3A1-279A A0908 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325051	* NOSE LANDING GEAR ACTUATOR UPPER PIN (IRN O3220011 OR JAA IRN E3220070) 4532302043-007 595	MOS HRS/MSC		N:0 N:0			26-MAR-2007 0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-32-01</b>	AFL	20000	N:0			0	<b>20000</b>	
326000	NOSE LANDING GEAR WIRE HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		
326104	NOSE LANDING GEAR SQUAT/WOW (S178) SWITCH PN SN-UNKNOWN REF: AMM 32-50-09	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		
326105	NO. 1 MAIN GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-60-09	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		
326106	NO. 2 MAIN GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-60-09	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		
326107	NO. 3 MAIN GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-60-09	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		
326108	NO. 4 MAIN GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-60-09	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		
326115	SQUAT SWITCH P21 RELAY BOX PN SN-UNKNOWN REF: AMM 32-60-08	MOS HRS/MSC AFL		N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-D3260006	LUBRICATE NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY. EFFECTIVE ON AIRCRAFT 45-001 THRU 45-071 MODIFIED PER SB 45-32-3 AND AIRCRAFT 45-072 THROUGH 45-114 NOT MODIFIED PER SB 45-32-8. (ZONE/ACCESS 700 IRN # D3260006)	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
	REF: AMM 12-21-01								
5-19-00-J3220120	* MLG TRUNNION SHEAR PIN BUSHING - PERFORM VISUAL INSPECTION FOR BUSHING MIGRATION (IRN J3220120)	MOS HRS/MSC AFL	O/C				26-MAR-2007 0 0		
	REF: AMM 57-10-05								
5-19-00-L3220020	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-104]. PART 6, 32-11-00 (L3220020)	MOS HRS/MSC AFL					26-MAR-2007 0 0		
<b>AIRWORTHINESS</b>	REF: NDT PART 6/32-11-00		10000					<b>10000</b>	
5-19-00-P3231020	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
32.101	REF: NDT PART 6/32-13-00								
5-19-00-P3231021	MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
32.102	REF: NDT PART 8/32-13-02								
5-19-00-W3231022	MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
32.103	REF: NDT PART 6/32-13-01								
5-19-01-F3220045	REPLACE NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING (ZINC COATED)	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
<b>NOT INSTALLED</b>	REF: AMM 32-32-01								



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
571010	* REPLACE LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING								
	4532103041-009PP	MOS		N:0			26-MAR-2007		
57.010	17599 / 2-01	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-31-01</b>	AFL	20000	N:0			0	<b>20000</b>	
571011	* REPLACE RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING								
	4532103041-010PP	MOS		N:0			26-MAR-2007		
57.011	17560 / 2-01	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 32-31-01</b>	AFL	20000	N:0			0	<b>20000</b>	
A3230001 (s)	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST						PKG		
	PKG 11	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
<b>AIRWORTHINESS</b>	<b>REF: AMM 32-33-00</b>	AFL					2781		
A3240005 (s)	PERFORM ** BRAKE HYDRAULIC FUSES - FUNCTIONAL TEST						PKG		
	PKG 17	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
<b>AIRWORTHINESS</b>	<b>REF: AMM 32-41-09</b>	AFL					2541		
A3240006 (s)	PERFORM ** BRAKE SHUTTLE MODULE - FUNCTIONAL TEST						PKG		
	PKG 17	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
<b>AIRWORTHINESS</b>	<b>REF: AMM 32-41-04</b>	AFL					2541		
A3240007 (s)	PERFORM **BRAKE SHUTTLE VALVES - FUNCTIONAL TEST						PKG		
	PKG 23	MOS	96	+14d/-14d			10-APR-2015		
		HRS/MSC	2400	+25/-25			2017.3		
<b>AIRWORTHINESS</b>	<b>REF: AMM 32-42-04</b>	AFL							
A3240009 (s)	PERFORM ** BRAKE PRESSURE TRANSDUCERS - FUNCTIONAL TEST						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	4800	+25/-25			0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 32-41-08</b>	AFL					0		
AB3220016 (s)	PERFORM NOSE LANDING GEAR STRUT ASSEMBLY - SPECIAL DETAILED INSPECTION.						PKG		
	PKG 27	MOS					26-MAR-2007		
		HRS/MSC					0		
	<b>REF: See Workcard</b>	AFL	10000	+25/-25			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3220017 (s)	PERFORM NOSE LANDING GEAR TRUNNION AXLE - VISUAL INSPECTION. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION IS NOT FOUND, CONDUCT FLUORESCENT PENETRANT INSPECTION OF AXLE PORTION THAT IS EXPOSED FROM CYLINDER.						PKG		
	PKG 27	MOS						26-MAR-2007	
		HRS/MSC						0	
	REF: AMM 05-10-00	AFL	10000	+25/-25				0	
L3220019 (s)	PERFORM NOSE LANDING GEAR ACTUATOR ATTACHMENT PIN - REMOVE PIN AND PERFORM MAGNETIC PARTICLE INSPECTION.						PKG		
	PKG 27	MOS						26-MAR-2007	
		HRS/MSC						0	
	REF: NDT PART 7/32-30-02	AFL	10000	+25/-25				0	
L3220109 (s)	PERFORM NOSE LANDING GEAR ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.						PKG		
	PKG 27	MOS						26-MAR-2007	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	10000	+25/-25				0	
V3240004 (s)	** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT.						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
<b>AIRWORTHINESS</b>	REF: AMM 32-42-01	AFL						2781	
V3240008 (s)	** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
<b>AIRWORTHINESS</b>	REF: AMM 32-42-02	AFL						2781	
Y3220000 (s)	NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	REF: AMM 05-10-00	AFL						2781	
Y3220001 (s)	MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	REF: AMM 05-10-00	AFL						2781	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y3220002 (s)	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	REF: AMM 05-10-00	AFL						2781	
Y3220003 (s)	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	REF: GENERIC NO REF	AFL						2781	
Y3220004 (s)	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	REF: AMM 05-10-00	AFL						2781	
Y3220006 (s)	LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL)						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	REF: AMM 05-10-00	AFL						2781	
Y3220008 (s)	PERFORM NOSE LANDING GEAR AXLE - REMOVE NOSE LANDING GEAR WHEEL AND PERFORM INSPECTION. INSPECT BOTH INSIDE AND OUTSIDE OF AXLE.						PKG		
	PKG 17	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 32-40-01	AFL						2541	
Y3220124 (s)	NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	REF: AMM 05-10-00	AFL						2781	
Y3230002 (s)	MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS						PKG		
	PKG 5	MOS	12	+14d/-14d				13-JAN-2021	
		HRS/MSC	300	+25/-25				3778.2	
	REF: AMM 05-10-00	AFL						2986	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y3231023 (s)	MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469) END CAP SCREWS - PERFORM DETAILED INSPECTION. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-276 PRE SB 45-32-19)						PKG		
	PKG 5	MOS	12	+14d/-14d				13-JAN-2021	
		HRS/MSC	300	+25/-25				3778.2	
	REF: AMM 32-31-02	AFL						2986	
Y3240000 (s)	NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION						PKG		
	PKG 5	MOS	12	+14d/-14d				13-JAN-2021	
		HRS/MSC	300	+25/-25				3778.2	
	REF: AMM 12-10-04	AFL						2986	
Y3240001 (s)	BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS						PKG		
	PKG 11	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	REF: AMM 05-10-00	AFL						2781	
Y3240002 (s)	BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE						PKG		
	PKG 5	MOS	12	+14d/-14d				13-JAN-2021	
		HRS/MSC	300	+25/-25				3778.2	
	REF: AMM 32-41-01	AFL						2986	
Y3240003 (s)	PERFORM BRAKE CONTROL SYSTEM LINEAR VARIABLE DIFFERENTIAL TRANSFORMER (LVDT) - VISUAL INSPECTION						PKG		
	PKG 13	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 05-10-00	AFL						2541	
Y3260005 (s)	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-114 POST SB 45-32-8 AND AIRCRAFT 45-115 AND SUBSEQUENT)						PKG		
	PKG 5	MOS	12	+14d/-14d				13-JAN-2021	
		HRS/MSC	300	+25/-25				3778.2	
	REF: AMM 12-21-01	AFL						2986	
<b>CHAPTER 33</b>	<b>LIGHTS</b>								
330000	MODIFIED PULSE CONTROLLER								
	2401S	MOS						26-MAR-2007	
	AR01142	HRS/MSC	O/C					0	
	REF: GENERIC NO REF	AFL						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331001	NO. 1 LIGHTING CONTROL UNIT RDC4-1 0885 REF: AMM 33-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331002	NO. 2 LIGHTING CONTROL UNIT RDC4-1 0886 REF: AMM 33-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331003	PRESSURIZATION PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331010	PILOT FORWARD SWITCH PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331011	PILOT SWITCH PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331012	COPILOT FORWARD SWITCH PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331013	COPILOT FORWARD SWITCH PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331015	CENTER SWITCH (P5) PANEL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331016	CENTER SWITCH PANEL (P5) OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331017	THROTTLE QUADRANT OVERLAY PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331018	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331019	COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY 7624608502-031 754 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-APR-2009 599.6		
331020	DIMMER CONTROL BOX LT-48(G) 1984 REF: AMM 33-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331021	PILOT FWD CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331022	CO-PILOT FWD CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331023	GLARESHIELD FLOOR FLOODLIGHTS INVERTER 6900135-001 390 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331025	COCKPIT MISC RELAY BOX PN SN-UNKNOWN REF: AMM 33-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331030	CENTER SWITCH PANEL DIODE (P12) BOX PN SN-UNKNOWN REF: AMM 33-10-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331033	GLARESHIELD FLOODLIGHT POWER SUPPLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331040	PILOT REVERSION PANEL (DS55) OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331041	OVERLAY ASSEMBLY, COPILOT OUTBD SWITCH (DS58) PANEL 7631208503-019 599 REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-MAR-2012 1307.7 999		
331101	P35 FUSE PANEL ASSY PN SN-UNKNOWN REF: AMM 33-10-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331401-1	NO. 1 LEFT INVERTER (PS5009) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
331401-10	INVERTER SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331401-11	INVERTER SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
331401-2	NO. 1 RIGHT INVERTER (PS5003) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
331401-3	NO. 2 LEFT INVERTER (PS5008) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
331401-4	NO. 2 RIGHT INVERTER (PS5004) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
331401-5	NO. 3 LEFT INVERTER (PS5007) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
331401-6	NO. 3 RIGHT INVERTER (PS5005) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
331401-7	NO. 4 LEFT INVERTER (PS5006) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
331401-8	NO. 4 RIGHT INVERTER (PS5010) LAV SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331401-9	NO. 5 LEFT INVERTER (PS5011) LAV SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332001	RH FWD LIGHTING CONTROL (A5038) UNIT SP-45-53-2 080500272 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332002	RH MID FWD LIGHTING CONTROL (A5039) UNIT SP-45-53-2 120600678 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332003	RH MID AFT LIGHTING CONTROL (A5040) UNIT SP-45-53-2 120600676 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332004	RH AFT LIGHTING CONTROL (A5041) UNIT SP-45-53-2 120600039 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332005	L/H FWD LIGHTING CONTROL (A5045) UNIT SP-45-53-2 100601088 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332006	LH MID FWD LIGHTING CONTROL (A5044) UNIT SP-45-53-2 120600139 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332007	LH MID AFT LIGHTING CONTROL (A5043) UNIT SP-45-53-2 090600636 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332008	LH AFT LIGHTING CONTROL (A5042) UNIT PN SN-UNKNOWN REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332030	LAVATORY NO SMOKING / RETURN TO SEAT SIGN (DS138) CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332068	COPILOT LIGHTING CONTROL MODULE SP-45-01-6767 120600797 REF: AMM 33-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
332404	ENTRYWAY CONTROL LIGHT PANEL SP-45-52 110500886 REF: AMM 33-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
333004	TAIL CONE MAINTENANCE LIGHT CHANGE PN SN-UNKNOWN REF: AMM 33-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
334011	LANDING/TAXI, LEFT LIGHT PN SN-UNKNOWN REF: AMM 33-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
334012	LANDING/TAXI, RIGHT LIGHT PN SN-UNKNOWN REF: AMM 33-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
334020	LIGHT ASSEMBLY, NAV EMPENNAGE PN SN-UNKNOWN REF: AMM 33-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334021	LEFT NAVIGATION (DS37) LIGHT PN SN-UNKNOWN REF: AMM 33-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
334022	RIGHT NAVIGATION (DS38) LIGHT PN SN-UNKNOWN REF: AMM 33-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
334023	TAIL NAVIGATION (DS39) LIGHT 01-0771011-01 SN-UNKNOWN REF: AMM 33-40-02	MOS HRS/MSC AFL	O/C				15-APR-2016 2324.4 1822		
334041	COPILOT REVERSION PANEL (DS56) OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
334175	RELAY OPTIONS PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
334332	UPPER ANTI-COLLISION LIGHT PN SN-UNKNOWN REF: AMM 33-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
334333	LOWER ANTI-COLLISION LIGHT PN SN-UNKNOWN REF: AMM 33-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
335005	FWD ELS ACTIVATION ASSEMBLY (A81) MODULE PN SN-UNKNOWN REF: AMM 33-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335006	AFT ELS ACTIVATION ASSEMBLY (A82) MODULE PN SN-UNKNOWN REF: AMM 33-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
336001	PILOT CHART HOLDER 10-62-01 5170 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
336002	COPILOT CHART HOLDER 10-62-01 5171 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
336003	PILOT MAP LIGHT PN SN-UNKNOWN REF: AMM 33-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
336004	COPILOT MAP LIGHT PN SN-UNKNOWN REF: AMM 33-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
Y3310000 (s)	FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATION OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS. PKG 1 REF: AMM 33-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			13-JAN-2021 3778.2 2986		
Y3340000 (s)	EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS. PKG 2 REF: See Workcard	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			13-JAN-2021 3778.2 2986		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y3350003 (s)	EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK PKG 14	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	REF: AMM 33-50-00	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
<b>CHAPTER 34 NAVIGATION</b>									
34-00-FAR-91.171	CHECK VOR EQUIPMENT FOR IFR OPERATIONS FAR 91.171	MOS						26-MAR-2007	
	REF: FAR FAR 91.171	HRS/MSC AFL	O/C				0 0		
340001-RVSM	CHECK RVSM HEIGHT MONITORING	MOS	24					31-DEC-2020	31-DEC-2022
	REF: FAR AGHME	HRS/MSC AFL	1000				3776.6 2984		4776.6
341001	NO. 1 AIR DATA COMPUTER 7030700-71704 06101207	MOS						08-MAR-2019	
	REF: AMM 34-17-01	HRS/MSC AFL	O/C	N:144 N:3241.7 N:2541			3241.7 2541		
341001A	TEST/INSPECT NO. 1 AIR DATA COMPUTER 7030700-71704 06101207	MOS	24					13-JAN-2021	13-JAN-2023
	REF: See Workcard	HRS/MSC AFL							
341002	NO. 2 AIR DATA COMPUTER 7030700-71704 06101208	MOS						08-MAR-2019	
	REF: AMM 34-17-01	HRS/MSC AFL	O/C	N:144 N:3241.7 N:2541			3241.7 2541		
341002A	TEST/INSPECT NO. 2 AIR DATA COMPUTER 7030700-71704 06101208	MOS	24					13-JAN-2021	13-JAN-2023
	REF: See Workcard	HRS/MSC AFL							

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341013	STANDBY AIRSPEED INDICATOR 26240-1129 284367 REF: AMM 34-18-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
341025	STANDBY ALTIMETER 16650-1142 167465B REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C				08-MAR-2019 3241.7 2541		
341025A	TEST/INSPECT STANDBY ALTIMETER 16650-1142 167465B REF: See Workcard	MOS HRS/MSC AFL	24				13-JAN-2021	13-JAN-2023	
341037	LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001) 0856TJ1 239843 REF: AMM 34-11-01	MOS HRS/MSC AFL	15000	+25/-25	N:0 N:0 N:0		26-MAR-2007 0 0	15000	15025
LIFE LIMIT									
341037A	TEST/INSPECT LEFT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ1 OR P/N 6634100000-001) 0856TJ1 239843 REF: See Workcard	MOS HRS/MSC AFL	24				13-JAN-2021 3778.2 2986	13-JAN-2023	
341038	RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003) 0856TJ2 236383 REF: AMM 34-11-01	MOS HRS/MSC AFL	15000	+25/-25	N:0 N:0 N:0		26-MAR-2007 0 0	15000	15025
LIFE LIMIT									
341038A	TEST/INSPECT RIGHT PRIMARY PITOT/STATIC PROBE (P/N 0856TJ2 OR P/N 6634100000-003) 0856TJ2 236383 REF: See Workcard	MOS HRS/MSC AFL	24				13-JAN-2021 3778.2 2986	13-JAN-2023	
341049	STANDBY PITOT/STATIC PROBE 0856TJ4 241748 REF: AMM 34-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341049A	TEST/INSPECT STANDBY PITOT/STATIC PROBE	MOS	24				13-JAN-2021	13-JAN-2023	
	REF: See Workcard	HRS/MSC					3778.2		
		AFL					2986		
341061	RADAR ALTIMETER RECEIVER	MOS		N:0			26-MAR-2007		
	7001840-936	HRS/MSC	O/C	N:0			0		
	0609D004	AFL		N:0			0		
	REF: AMM 34-14-01								
341073	FORWARD RADAR ALTIMETER ANTENNA	MOS		N:0			26-MAR-2007		
	S67-2002-4	HRS/MSC	O/C	N:0			0		
	522-13832	AFL		N:0			0		
	REF: AMM 34-14-02								
341074	AFT RADAR ALTIMETER ANTENNA	MOS		N:0			26-MAR-2007		
	S67-2002-4	HRS/MSC	O/C	N:0			0		
	552-13830	AFL		N:0			0		
	REF: AMM 34-14-02								
3413-RVSM	FLIGHT CHECK ALTITUDE ALERTER FUNCTION. RVSM COMPLIANT AIRCRAFT.	MOS					26-MAR-2007		
		HRS/MSC	N/R				0		
	REF: GENERIC CUSTOM	AFL					0		
341901	(TAT) TOTAL AIR TEMPERATURE PROBE	MOS		N:0			26-MAR-2007		
	102AU1AG	HRS/MSC	O/C	N:0			0		
	A69116	AFL		N:0			0		
	REF: AMM 34-17-02								
342001	(AHR) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER	MOS		N:0			26-MAR-2007		
	142185-1102	HRS/MSC	O/C	N:0			0		
	1492	AFL		N:0			0		
	REF: AMM 34-26-01								
342002	(AHR) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER	MOS					16-AUG-2019		
	142185-1102	HRS/MSC	O/C				3378.9		
	1263	AFL					2673		
	REF: AMM 34-26-01								

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342003	(AHR) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN 140691-0000 3819 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
342004	(AHR) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN 140691-0000 3820 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
342037	LEFT FLUX VALVE 7010133 0609H115 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
342038	RIGHT FLUX VALVE 7010133 0609H126 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
342101	DUAL ANGLE OF ATTACK INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
342103	STANDBY COMPASS PAI700-5V 62257 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
342103A	CALIBRATION CHECK STANDBY COMPASS PAI700-5V 62257 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	A/R				26-MAR-2007 0 0		
342701	LEFT ATTITUDE HEADING REFERENCE SYSTEM (AHR) MEMORY MODULE PN SN-UNKNOWN REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342702	RIGHT ATTITUDE HEADING REFERENCE SYSTEM (AHRS) MEMORY MODULE PN SN-UNKNOWN REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
342801	STANDBY ATTITUDE INDICATOR 501-1648-02 1582 REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
343005	MARKER BEACON ANTENNA DMN27-3 15747 REF: AMM 34-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
343008	UPPER GLIDESCOPE (E11) ANTENNA PN SN-UNKNOWN REF: AMM 34-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
343009	LOWER GLIDESCOPE (E12) ANTENNA PN SN-UNKNOWN REF: AMM 34-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
343030	MARKER BEACON ANTENNA SPLITTER DMH21-1 31484 REF: AMM 34-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344101	AIRSERVE COMPUTER CHANGE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344102	RS-232 CONVERTER CHANGE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344111	UPPER TCAS ANTENNA 7514081-913 ANE25975 REF: AMM 34-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344112	LOWER TCAS ANTENNA 7514081-913 ANE25435 REF: AMM 34-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344143	TCAS PROCESSOR 7517900-55012 20008332 REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C				04-APR-2013 1524.5 1169		
344155	TCAS RELAY BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 34-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344167	TCAS CONFIGURATION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344171	NO. 1 TCAS UPPER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344172	NO. 2 TCAS UPPER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344173	NO. 3 TCAS UPPER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344174	NO. 4 TCAS UPPER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344176	UPPER TCAS ADAPTER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344177	LOWER TCAS ADAPTER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344181	NO. 1 TCAS LOWER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344182	NO. 2 TCAS LOWER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344183	NO. 3 TCAS LOWER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344184	NO. 4 TCAS LOWER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344201	GPS / XM WEATHER ANTENNA CI401-460 568530 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C				12-JUN-2018 3014.9		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA 7021450-601 06016059 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344207	WEATHER RADAR TRANSCEIVER PN SN-UNKNOWN REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344209	WEATHER RADAR LIGHTNING SENSOR ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344221	WEATHER RADAR CONTROLLER 7008471-667 06078997 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344223	LIGHTNING DETECTION PROCESSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344513	TERRAIN AWARENESS WARNING (TAWS) COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344514	TERRAIN AWARENESS WARNING (TAWS) CONFIGURATION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
344515	TAWS RELAY BOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345000 (s)	UPDATE NAVIGATION DATA BASE	MOS							
<b>CUSTOMER CODE</b>	<b>REF: GENERIC CUSTOM</b>	HRS/MSC AFL	DUE						
345001	NO. 1 INTEGRATED NAVIGATION UNIT								
	7510100-631	MOS		N:0			26-MAR-2007		
	0609A772	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
345002	NO. 2 INTEGRATED NAVIGATION UNIT								
	7510100-633	MOS		N:0			26-MAR-2007		
	0607A701	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
345011	NO. 1 NAVIGATION RECEIVER MODULE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
345012	NO. 2 NAVIGATION RECEIVER MODULE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
345013	NO. 1 ADF ANTENNA								
	7510300-901	MOS		N:0			26-MAR-2007		
	0603A338	HRS/MSC	O/C	N:0			0		
	<b>REF: AMM 34-57-01</b>	AFL		N:0			0		
345014	NO. 2 ADF ANTENNA								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: AMM 34-57-01</b>	AFL		N:0			0		
345024	GPWS CONTROL PANEL								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345025	ENHANCED GROUND PROXIMITY WARNING (EGPWS) COMPUTER 965-0976-040-208-208 24818 REF: AMM 34-45-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345037	FORWARD ATC ANTENNA DMN150-2-2 108716 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345038	AFT ATC ANTENNA DMN150-2-2 111232 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345049	AFT (NO. 1) DME ANTENNA DMN150-2-2 111222 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345050	FORWARD (NO. 2) DME ANTENNA DMN150-9-2 7582 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345083	LEFT VOR/LOCALIZER ANTENNA DMN4-17-1/N 23737 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345084	RIGHT VOR/LOCALIZER ANTENNA DMN4-17-1/N 23738 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345201	NAV VHF (A42) DUPLEXER PN SN-UNKNOWN REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345260	PHASING COUPLER DMN4-17-2 20039 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345501	DME INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345605	LEFT UPPER MODE S ATC ANTENNA DMN150-2-2 111406 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
345606	RIGHT UPPER MODE S ATC ANTENNA DMN150-2-2 111248 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
346001	PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU 2017-41-201 1260 REF: AMM 34-60-01	MOS HRS/MSC AFL	O/C	O:0 N:588.7 O:0 O:0			09-APR-2009 599.6		
346001A	NO.1 FMS BATTERY REPLACE PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			26-MAR-2007 0 0		
346002	COPILLOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU 2017-41-201 1280 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:25 O:0 N:599.6 O:0 N:0			09-APR-2009 599.6		
346002A	NO.2 FMS BATTERY REPLACE PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346021	FMS DATA (DTU) TRANSFER UNIT 1406-01-1 4126 REF: AMM 34-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
346025	NO. 1 FLIGHT MANAGEMENT CONFIGURATION MODULE 10171 4584 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
346026	NO. 2 FLIGHT MANAGEMENT CONFIGURATION MODULE 10171 4698 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
346027	NO. 1 WAAS FMS LH ANNUNCIATOR PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
346031	NO. 1 FMS ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
346032	NO. 2 FMS ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
346090	AFIS DATA MANAGEMENT UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
346092	AFIS (FLIGHT INFORMATION SYSTEM) ANTENNA REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
347510	NO. 1 GPS ANTENNA 10706 11551 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
347511	NO. 2 GPS ANTENNA 10706 11428 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
5-19-02-RVSM-L3411062	DETAILED VISUAL INSPECTION OF PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT(ZONE/ACCESS 220 IRN # L3411062)	MOS HRS/MSC AFL	24	+14d/-14d			13-JAN-2021 3778.2 2986	<b>13-JAN-2023</b>	27-JAN-2023
<b>RVSM</b>	REF: AMM 34-11-01								
5-19-02-RVSM-M3411052	VERIFY PITCH, ROLL, AND YAW ALIGNMENT OF THE PRIMARY PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT (IRN # M3411052)	MOS HRS/MSC AFL	24	+14d/-14d			13-JAN-2021 3778.2 2986	<b>13-JAN-2023</b>	27-JAN-2023
<b>RVSM</b>	REF: AMM 34-11-01								
5-19-02-RVSM-U3411060	PERFORM FUNCTIONAL TEST - AIR DATA SYSTEM (EFFECTIVE ON AIRCRAFT CERTIFIED & MAINTAINED FOR RVSM) (REFER TO 34-17-00) (IRN U3411060)	MOS HRS/MSC AFL	24	+14d/-14d			13-JAN-2021 3778.2 2986	<b>13-JAN-2023</b>	27-JAN-2023
<b>RVSM</b>	REF: AMM 34-17-00								
A3400000 (s)	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK PKG 7	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
<b>AIRWORTHINESS</b>	REF: AMM 34-00-00								
+ ICA-4519-560(21190F)	INSPECT UAT ANTENNA (ANTENNA CONNECTOR HOLES)	MOS HRS/MSC AFL					26-MAR-2007 0 0		<b>21190</b>
<b>ICA</b>	REF: AMM NO REF		21190						

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ ICA-4519-560(4409F)	INSPECT GPS ANTENNA (INSTALLATION FASTENER HOLES)	MOS					26-MAR-2007		
ICA	REF: AMM NO REF	HRS/MSC AFL	4409				0 0		4409
+ ICA-4519-560(7269F)	INSPECT UAT ANTENNA (INSTALLATION FASTENER HOLES)	MOS					26-MAR-2007		
ICA	REF: AMM NO REF	HRS/MSC AFL	7296				0 0		7296
+ ICA-4519-560(9232F)	INSPECT GPS ANTENNA (ANTENNA CONNECTOR HOLES)	MOS					26-MAR-2007		
ICA	REF: AMM NO REF	HRS/MSC AFL	9232				0 0		9232
ST01509WI-D	INSTALL UPDATED HONEYWELL MARK V ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS W/RAAS)	MOS					26-MAR-2007		
STC-SUPPLEMENTAL TYPE CERTIFICATE	REF: GENERIC NO REF	HRS/MSC AFL	O/C				0 0		
V3420000 (s)	ATTITUDE HEADING REFERENCE UNIT (AHRU) MOUNTING TRAY FAN FILTER - PERFORM VISUAL INSPECTION. ENSURE FILTER IS FREE OF OBSTRUCTIONS.						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			3544.5 2781		
Y3411000 (s)	PITOT-STATIC PROBE - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
	REF: See Workcard	HRS/MSC AFL	600	+25/-25			3544.5 2781		
Y3440000 (s)	PERFORM RADOME STRUCTURE AND ANTENNA INSTALLATION - VISUAL INSPECTION						PKG		
	PKG 13	MOS	48	+14d/-14d			08-MAR-2019		
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			3241.7 2541		

## CHAPTER 35 OXYGEN

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350001	OXYGEN CYLINDER 6635000000-119 ALT280-6727 REF: AMM 35-00-01	MOS HRS/MSC AFL	180	+14d/-14d	N:0 N:0 N:0		08-MAR-2019 3241.7 2541	08-MAR-2034	22-MAR-2034
350001A	HYDROSTATIC TEST OXYGEN CYLINDER ** (IRN Q3510005 - STANDARD CAPACITY; Q3510018 - INCREASED CAPACITY) 6635000000-119 ALT280-6727 REF: GENERIC NO REF	MOS HRS/MSC AFL	60 5000	+14d/-14d +25/-25			08-MAR-2019 3241.7 2541	08-MAR-2024 8241.7 M	22-MAR-2024 8266.7
350001C	FUNCTIONAL TEST OXYGEN CYLINDER ** LOW PRESSURE RELIEF VALVE (IRN Q3510005 - STANDARD CAPACITY; Q3510018 - INCREASED CAPACITY) 6635000000-119 ALT280-6727 REF: GENERIC NO REF	MOS HRS/MSC AFL	60 5000	+14d/-14d +25/-25			08-MAR-2019 3241.7 2541	08-MAR-2024 8241.7	22-MAR-2024 8266.7
350013	OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		
350201	TEMP/PRESSURE TRANSDUCER PN SN-UNKNOWN REF: AMM 35-00-03	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		
350225	OXYGEN FILL (POST SB 45-12-1) VALVE P21010 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-AUG-2014 1835 1435		
350230	REMOTE OXYGEN PRESSURE INDICATOR PN SN-UNKNOWN REF: AMM 35-00-05	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351001	PILOT OXYGEN MASK MC10-15-166 SE09664 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			29-JAN-2020 3544.5 2781		
351001A	OVERHAUL PILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006) MC10-15-166 SE09664 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d			29-JAN-2020	29-JAN-2026	12-FEB-2026
351002	COPILOT OXYGEN MASK MC10-15-166 SE09682 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			04-JAN-2016		
351002A	OVERHAUL COPILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006) MC10-15-166 SE09682 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d			04-JAN-2016	04-JAN-2022	18-JAN-2022
351003	PASSENGER OXYGEN MASK (OVHL/SCRAP) - 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01) REPLACE PN SN-UNKNOWN REF: SI 833-35-01	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			26-MAR-2007 0 0		
351003A	INSPECTION PASSENGER OXYGEN MASK (INSPECTION) - PERFORM VISUAL INSPECTION OF 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01). REF: SI 833-35-01	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
351005	PILOT CREW OXYGEN OUTLET PN SN-UNKNOWN REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351006	COPILOT CREW-OXYGEN OUTLET 6635000000-047 SN-UNKNOWN REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C				28-AUG-2014 1835 1435		
352002	ALTITUDE COMPENSATING REGULATOR 112053-16 00296M REF: AMM 35-20-06	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			16-APR-2014 1734.5 1346		
352011	OXYGEN CONTROL VALVE P21081 0483 REF: AMM 35-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
352025	OXYGEN CYLINDER REGULATOR 806370-07 892 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			08-MAR-2019 3241.7 2541		
353001	PORTABLE OXYGEN CYLINDER PN SN-UNKNOWN REF: AMM 35-00-01	MOS HRS/MSC AFL	-						
<b>NOT INSTALLED</b>									
353001A (s)	HYDROSTATIC CHECK PORTABLE OXYGEN CYLINDER (IRN Q3500024) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d					
353001B (s)	VISUALLY INSPECT PORTABLE OXYGEN CYLINDER PER MANUFACTURER'S INSTRUCTIONS PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	12	+14d/-14d					
<b>CUSTOMER CODE</b>									
355111	OXYGEN PRESSURE INDICATOR P24071-3 469 REF: AMM 35-00-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-K3500021	** OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES - PERFORM OPERATIONAL CHECK. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS.	MOS					26-MAR-2007		
	REF: AMM 35-00-00	HRS/MSC AFL	N/A				0 0		
5-19-00-N3510013	PERFORM ** PERIODIC CHECK OF OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES (IRN N3510013)	MOS					24-DEC-2017		
INSPECT	REF: AMM 35-00-01	HRS/MSC AFL	1500	+25/-25		-44.8	2852.5 2261	4307.7	4332.7
5-19-00-N3510019	PERFORM ** PERIODIC CHECK OF THE OXYGEN CYLINDER AND REMOTE FILL VALVES. EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM. (IRN N3510019)	MOS							
	REF: AMM 35-00-01	HRS/MSC AFL	N/A						
5-19-00-Q3510022	PERFORM OXYGEN CYLINDER REGULATOR - OVERHAUL	MOS	60	+14d/-14d			08-MAR-2019	08-MAR-2024	22-MAR-2024
	REF: AMM 35-00-01	HRS/MSC AFL	5000	+25/-25			3241.7 2541	8241.7	8266.7
5-19-00-Q3510023	PERFORM OXYGEN CYLINDER REGULATOR - OVERHAUL (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM)	MOS							
	REF: AMM 35-00-01	HRS/MSC AFL	N/A						
03510003 (s)	** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST.						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
AIRWORTHINESS	REF: AMM 35-20-00	HRS/MSC AFL	600	+25/-25			3544.5 2781		
S3510014 (s)	** OXYGEN SYSTEM ALTITUDE COMPENSATING REGULATOR - PERFORM FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-170 AND SUBSEQUENT AND PRIOR AIRCRAFT MODIFIED BY SB 45-35-1)						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
AIRWORTHINESS	REF: AMM 35-20-00	HRS/MSC AFL	600	+25/-25			3544.5 2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
W3510002 (s)	** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
<b>AIRWORTHINESS</b>	<b>REF: AMM 35-00-00</b>	HRS/MSC	600	+25/-25			3544.5		
		AFL					2781		
Y3510000 (s)	PERFORM OXYGEN CYLINDER INSTALLATION - VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION						PKG		
	PKG 13	MOS	48	+14d/-14d			08-MAR-2019		
	<b>REF: AMM 05-10-00</b>	HRS/MSC	1200	+25/-25			3241.7		
		AFL					2541		
Y3510001 (s)	CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR						PKG		
	PKG 1	MOS	12	+14d/-14d			13-JAN-2021		
	<b>REF: AMM 05-10-00</b>	HRS/MSC	300	+25/-25			3778.2		
		AFL					2986		
Y3510017 (s)	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION. (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM.)						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
	<b>REF: AMM 05-10-00</b>	HRS/MSC	600	+25/-25			3544.5		
		AFL					2781		

CHAPTER	PNEUMATIC								
361001	LEFT ASSEMBLY, HP TAILCONE OUTBOARD MANIFOLD								
	PN	MOS			N:0		26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	<b>REF: GENERIC NO REF</b>	AFL			N:0		0		
361002	LEFT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD								
	PN	MOS			N:0		26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	<b>REF: AMM 30-10-07</b>	AFL			N:0		0		
361004	LEFT INBOARD HPBA MANIFOLD ASSEMBLY								
	PN	MOS			N:0		26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	<b>REF: AMM 36-10-07</b>	AFL			N:0		0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361005	RIGHT INBOARD HPBA MANIFOLD ASSEMBLY PN SN-UNKNOWN REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361015	MANIFOLD ASSEM, CENTER REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361016	RIGHT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD PN SN-UNKNOWN REF: AMM 30-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361017	RIGHT ASSEMBLY, HP TAILCONE OUTBOARD MANIFOLD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361020	LEFT HP OVER-TEMP SWITCH 641179-4 SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361021	RIGHT HP OVER-TEMP SWITCH 641179-4 1086 REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-APR-2007 10.9 11		
361031	ECS CONTROLLER 1165-1-6 206490303 REF: AMM 36-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361040	VALVE, APU BLEED AIR CHECK REPLACE 4011-14 0235 REF: AMM 36-10-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361050	LOAD CONTROL (SHUTOFF (L5003) VALVE PN SN-UNKNOWN REF: AMM 36-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361053	NO. 1 ECS SHUTOFF (L37) VALVE 3215468-1 943 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361054	NO. 2 ECS SHUTOFF (L38) VALVE 3215468-1 884 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361055	ECS SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361056	ECS SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361065	LEFT TAILCONE HIGH PRESSURE SHUT-OFF (L39) VALVE 3291216-2 1034 REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361066	RIGHT TAILCONE HIGH PRESSURE SHUT-OFF (L40) VALVE 3291216-2 1036 REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361120	NO. 1 PRESSURE (S79) SWITCH 642019-3 1038 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361121	NO. 2 PRESSURE (S88) SWITCH 642019-3 1041 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361122	LEFT HAND HP BLEED AIR TUBE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361123	RIGHT HAND HP BLEED AIR TUBE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361125	LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361126	RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361127	LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361128	RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
361215	ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD LJ01212-001 120107-001 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361215A	BORESCOPE ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD BRACKET LJ01212-001 120107-001 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C					26-MAR-2007 0 0	
361216	ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD LJ01212-002 120107-002 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
361216A	BORESCOPE ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD BRACKET LJ01212-002 120107-002 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C					26-MAR-2007 0 0	
361301	APU SERVO AIR CHECK VALVE. EFFECTIVE ON CHECK VALVE S/N 001 THRU 1486. (IRN # K3610013) REPLACE 6C1005 3029 REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
361302	LEFT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE 6C1005 2914 REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
361303	RIGHT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE 6C1005 2920 REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
362005	LEFT FORWARD PYLON OVERHEAT THERMOSTAT (S145) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
362006	LEFT AFT PYLON OVERHEAT THERMOSTAT (S146) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
362007	RIGHT FORWARD PYLON OVERHEAT THERMOSTAT (S147) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
362008	RIGHT AFT PYLON OVERHEAT THERMOSTAT (S148) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
5-19-00-D3610002	BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD.(IRN D3610002)  REF: AMM 36-10-07	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
5-19-00-P3610048-LEFT	PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY".  REF: AMM 36-10-07	MOS HRS/MSC AFL	3000	+100/-100	-58.3		07-AUG-2018 3058.3 2403	6000	6100
5-19-00-P3610048-RIGHT	PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY".  REF: AMM 36-10-07	MOS HRS/MSC AFL	3000	+100/-100	-58.3		07-AUG-2018 3058.3 2403	6000	6100
A3610000 (s)	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST PKG 7 REF: AMM 36-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		
A3610001 (s)	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST PKG 8 REF: AMM 36-20-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U3610075 (s)	BORESCOPE INSPECTION ECS BLEED AIR "Y" MANIFOLD (P/N 12945-054-019, 12945-054-025, 12945-054-031, 129-054-037, 12945-054V1-001, 12945-054V2-001, 12945-054V6-001, 4536102027-001) (EFFECTIVE ON AIRCRAFT 45-002 THRU 45-448)						PKG		
	PKG 25	MOS						26-MAR-2007	
	REF: AMM 36-10-00	HRS/MSC AFL	4800	+25/-25				0	0
Y3610061 (s)	HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES.						PKG		
	PKG 8	MOS	24	+14d/-14d				29-JAN-2020	
	REF: AMM 36-10-02	HRS/MSC AFL	600	+25/-25				3544.5	2781
<b>CHAPTER 38</b>	<b>WATER/WASTE</b>								
380001	TOILET SERVICE PANEL								
	PN	MOS						26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C					0	
	REF: AMM 38-30-05	AFL						0	
381009	TOILET HEATED DRAIN MAST ASSY								
	PN	MOS						26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C					0	
	REF: GENERIC NO REF	AFL						0	
383001	TOILET								
	9600-1B	MOS						26-MAR-2007	
	U3286	HRS/MSC	O/C					0	
	REF: AMM 38-30-01	AFL						0	
383002	TOILET TIMER								
	9600-12D	MOS						26-MAR-2007	
	T4911	HRS/MSC	O/C					0	
	REF: AMM 38-30-02	AFL						0	
383005	WATER TANK ASSEMBLY								
	PN	MOS						26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C					0	
	REF: GENERIC NO REF	AFL						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
383010	TANK FLOAT SWITCH, TOILET REPLACE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
<b>CUSTOMER CODE</b>	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
383011	LAVATORY SINK SHUT OFF VALVE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
384025	TOILET PUMP								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
384051	TOILET MACERATOR								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
389050	TOILET CLEAN WATER PUMP								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
<b>CHAPTER 49</b>	<b>AIRBORNE AUXILIARY POWER</b>								
490060	ELECTRONIC CONTROL, APU ECU								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: AMM 49-60-04</b>	AFL		N:0			0		
491011	MAINTENANCE CONTROL, APU PANEL								
	7088001-2	MOS		N:0			26-MAR-2007		
	DC338	HRS/MSC	O/C	N:0			0		
	<b>REF: AMM 49-60-02</b>	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
491020	APU, COCKPIT CONTROL PANEL 7088000-1 DB305 REF: AMM 49-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
495001	COOLING, TAILCONE APU (B31) FAN 011809500 106466503 REF: AMM 49-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
495002	TAILCONE ACCESS DOOR COOLING (B30) FAN 011809500 106466500 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
495040	APU THERMOSTAT (S175) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
495041	APU THERMOSTAT (S176) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
495201	STRUT SUPPORT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
495202	STRUT SUPPORT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
497001	APU BITE INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49APU1	APU								
49.APU1	3800726-1 P-366 REF: AMM NO REF	MOS HRS/MSC AFL	E/C						
5-19-01-AA4900039	APU FUEL LINE (P/N 4549058032-001) REPLACE								
	PN	MOS		N:0			27-DEC-2006		
	SN-UNKNOWN	HRS/MSC	4800	+25/-25	N:0		0	4800	4825
	REF: GENERIC NO REF	AFL		N:0			0		
		APH		N:0			0		
H4900011 (s)	PERFORM **APU GENERATOR - OVERVOLTAGE PROTECTION CHECK.						PKG		
	PKG 13	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
<b>AIRWORTHINESS</b>	REF: AMM 49-40-01	AFL					2541		
Y4900000 (s)	AUXILIARY POWER UNIT - PERFORM VISUAL INSPECTION OF EXTERNAL FIREBOX INSTALLATION AND ATTACHING COMPONENTS						PKG		
	PKG 2	MOS	12	+14d/-14d			13-JAN-2021		
		HRS/MSC	300	+25/-25			3778.2		
	REF: AMM 05-10-00	AFL					2986		
Y4900002 (s)	AUXILIARY POWER UNIT - FIRE EXTINGUISHER CONTAINER - PERFORM FUNCTIONAL TEST OF WIRING.						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
	REF: AMM 26-22-00	AFL					2781		
Y4900010 (s)	APU ENGINE FIRE EXTINGUISHER CONTAINER - CHECK CONTAINER PRESSURE GAUGE FOR PROPER PRESSURE.						PKG		
	PKG 2	MOS	12	+14d/-14d			13-JAN-2021		
		HRS/MSC	300	+25/-25			3778.2		
	REF: AMM 26-22-00	AFL					2986		
Y4900012 (s)	APU INLET SCREEN AND OPENING - PERFORM VISUAL INSPECTION						PKG		
	PKG 2	MOS	12	+14d/-14d			13-JAN-2021		
		HRS/MSC	300	+25/-25			3778.2		
	REF: AMM 05-10-00	AFL					2986		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y4900013 (s)	APU EXHAUST DUCT AREA, INCLUDING FORWARD AND AFT APU EXHAUST FAIRINGS - PERFORM VISUAL INSPECTION						PKG		
	PKG 2	MOS	12	+14d/-14d				13-JAN-2021	
		HRS/MSC	300	+25/-25				3778.2	
	REF: AMM 05-10-00	AFL						2986	
APU Model : RE100 (CIMMS) Serial # P-366 Part # 3800726-1									
+ 4900018	APU - AUXILIARY POWER UNIT TURBINE ROTOR								
	PN	MOS		N:0				27-DEC-2006	
	SN-UNKNOWN	HRS/MSC		N:0				0	
<b>LIFE LIMIT</b>	REF: AMM 49-10-01	APUS	4000	N:0				0	<b>4000</b>
+ 4900020	APU - AUXILIARY POWER UNIT COMPRESSOR ROTOR								
	PN	MOS		N:0				27-DEC-2006	
	SN-UNKNOWN	HRS/MSC		N:0				0	
<b>LIFE LIMIT</b>	REF: AMM 49-10-01	APUS	12000	N:0				0	<b>12000</b>
+ 491000	APU - DOWNLOAD APU ECU (TIMES/CYCLES)								
		MOS						27-DEC-2006	
		HRS/MSC	A/R					0	
	REF:	APUS						0	
492001	APU - APU COMPRESSOR ROTOR. (P/N 3822523-2 - IRN H4900019) (P/N 3822523-003 - IRN H4900020) ROTOR								
	3822523-003	MOS		N:0				27-DEC-2006	
	060350105712	HRS/MSC		N:0				0	
<b>LIFE LIMIT</b>	REF: AMM 49-10-01	APUS	12000	N:0				0	<b>12000</b>
492005	APU - APU TURBINE ROTOR (P/N 3842340 - IRN H4900018) CHANGE								
	3842340-2	MOS		N:0				27-DEC-2006	
	060134512612	HRS/MSC		N:0				0	
<b>LIFE LIMIT</b>	REF: AMM 49-10-01	APUS	4000	N:0				0	<b>4000</b>
492006	APU - COMPRESSOR MATCHED SEAL SET								
	PN	MOS		N:0				27-DEC-2006	
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0	
	REF:	APUS		N:0				0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
492007	APU - GENERATOR MATCHED SEAL SET PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
493011	APU - APU PRESSURIZING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
493021	APU - APU FILTER BYPASS VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
493031	APU - APU PRESSURE RELIEF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
493041	APU - APU DIFFERENTIAL PRESSURE VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
493051	APU - APU FUEL PUMP PN SN-UNKNOWN REF: AMM 49-30-04	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
493061	APU - APU DIFFERENTIAL PRESSURE INDICATOR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
493071	APU - APU ASSEMBLY, FUEL CONTROL 3883900-1 0600979 REF: AMM 49-30-04	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
494001	APU - (LOW VOLTAGE) IGNITION UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
494011	APU - APU IGNITION EXCITER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
494021	APU - APU LOW VOLTAGE IGNITER PLUG PN SN-UNKNOWN REF: AMM 49-40-02	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
494031	APU - APU IGNITION LEAD PN SN-UNKNOWN REF: AMM 49-40-03	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
494060	APU - APU GROUND CONTROL UNIT CHANGE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
495001	APU - APU ISOLATION VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
496001	APU - APU REMOTELY LOCATED (ECU) CONTROLLER 2119560-3 116-M0003 REF: AMM 49-60-04	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
496010	APU - APU FUEL LINE REPLACE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
496011	APU - APU FUEL SHUTOFF VALVE 3876322-1 0328 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
496021	APU - APU FLOW DIVIDER VALVE PN SN-UNKNOWN REF: AMM 49-30-06	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
496031	APU - APU FUEL SOLENOID VALVE PN SN-UNKNOWN REF: AMM 49-30-01	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
496041	APU - APU - BLEED AIR SHUTOFF VALVE 3876322-1 0135 REF:	MOS HRS/MSC APUS	O/C	O:0 O:0 O:0			30-MAR-2012		
497001	APU - APU SPEED SENSOR PN SN-UNKNOWN REF: AMM 49-70-04	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
497011	APU - APU EGT THERMOCOUPLE PN SN-UNKNOWN REF: AMM 49-70-07	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
499025	APU - APU ASSEMBLY, LUBE OIL-PUMP 3881825-1 P-1082 REF: AMM 49-90-03	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
499037	APU - APU LOW OIL PRESSURE SENSOR PN SN-UNKNOWN REF: AMM 49-90-02	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
499048	APU - INLET TEMP SENSOR MS28034-1 308979 REF:	MOS HRS/MSC APUS	O/C				30-SEP-2019		
499049	APU - APU OIL TEMPERATURE BULB PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
499061	APU - APU OIL LEVEL SENSOR PN SN-UNKNOWN REF: AMM 49-90-01	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
499071	APU - APU ULTIMATE RELIEF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
499081	APU - APU MANIFOLD AND PRIMARY ATOMIZER PN SN-UNKNOWN REF: AMM 49-30-05	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
499082	APU - APU MANIFOLD AND SECONDARY ATOMIZER PN SN-UNKNOWN REF: AMM 49-30-05	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			27-DEC-2006 0 0		
5-19-00-O4900008	APU - INSPECT APU CHIP DETECTOR - FOR CONTAMINATION. (ZONE/ACCESS 310JL, 310RR IRN # O4900008)  REF: AMM 49-90-05	MOS HRS/MSC APUS	750				16-APR-2014 714.9 1259	1464.9	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-P4900009	APU - CHANGE APU OIL. (ZONE/ACCESS 310JL, 310RR). (IRN # P4900009). (REFER TO 12-10-10.) NOTE: THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49).	MOS HRS/MSC 750 APUS					16-APR-2014 714.9 1259	1464.9	
	REF: AMM 12-10-10								
5-19-01-K4900005	APU - REPLACE APU ENGINE FUEL FILTER. IRN # K4900005	MOS HRS/MSC 750 APUS					16-APR-2014 714.9 1259	1464.9	
	REF: AMM 49-30-03								
5-19-01-T4900004	APU - REPLACE APU OIL FILTER. THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49 (ZONE/ACCESS 310JR, 310QR) (IRN # T4900004)	MOS HRS/MSC 750 APUS					16-APR-2014 714.9 1259	1464.9	
	REF: AMM 49-90-04								
<b>CHAPTER 52 DOORS</b>									
5-19-02-RVSM-M5240004	INSPECT AVIONIC ACCESS DOOR GAP AND MISMATCH FOR RVSM COMPLIANT AIRCRAFT (IRN # M5240004)	MOS HRS/MSC AFL	24	+14d/-14d			13-JAN-2021 3778.2 2986	13-JAN-2023	27-JAN-2023
	RVSM REF: AMM 52-40-01								
521001	UPPER CABIN DOOR 4552101000-003 W404 REF: AMM 52-10-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		
521002	LOWER CABIN DOOR 4552100050V107-001 W391 REF: AMM 52-10-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		26-MAR-2007 0 0		
+ 5210053	CABIN DOOR HANDLE - REPLACE  REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25		5	21-MAR-2019 3252.9 2553	26-MAR-2031 8553	09-APR-2031 8578

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521010	LOWER ENTRY DOOR FORWARD GAS DAMPER ASSEMBLY 662102002-003 SN-UNKNOWN REF: AMM 52-10-11	MOS HRS/MSC AFL	O/C				18-JUN-2007 41.5 37		
521011	LOWER ENTRY DOOR AFT GAS DAMPER ASSEMBLY PN SN-UNKNOWN REF: AMM 52-10-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
522001	EMERGENCY EXIT DOOR ASSEMBLY 4552200076-V43-001 L330 REF: AMM 52-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
522010	DOOR ASSY PN SN-UNKNOWN REF: AMM 52-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
523001	TAILCONE BAGGAGE DOOR ASSEMBLY 12045-558V2-001 0424 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
524001	TAILCONE ACCESS DOOR 4552405151-009 0430 REF: AMM 52-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
524010	SPPR DOOR ASSY PN SN-UNKNOWN REF: AMM 52-40-03	MOS HRS/MSC AFL	O/C						
A5210009 (s)	PERFORM * EMERGENCY EXIT DOOR RETAINERS - VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (FS 374 AND 394) PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				26-MAR-2007 0 0		
<b>AIRWORTHINESS</b>									

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A5210012 (s)	PERFORM * LOWER PASSENGER DOOR HINGE - VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS						PKG		
	PKG 26	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL						0	
A5210014 (s)	PERFORM * UPPER PASSENGER DOOR TENSION FITTINGS - VISUAL INSPECTION. INSPECT THE FOLLOWING: A. TENSION STUDS AT RETAINING FLANGES. B. RADII AROUND FLANGE PERIPHERY.						PKG		
	PKG 26	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL						0	
+ AA5210055 (s)	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION						PKG		
	PKG 18	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	<b>REF:</b> AMM 12-21-02	AFL						2541	
D5210015 (s)	PERFORM * EMERGENCY EXIT DOOR - VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS.						PKG		
	PKG 25	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL						0	
E5210013 (s)	PERFORM * UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - VISUAL INSPECTION.						PKG		
	PKG 25	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL						0	
F5210016 (s)	PERFORM * UPPER PASSENGER DOOR HINGE - VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERS AT BASE OF LUG.						PKG		
	PKG 26	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL						0	
N5210010 (s)	PERFORM * LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - VISUAL INSPECTION.						PKG		
	PKG 24	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF:</b>	AFL						0	



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5210011 (s)	PERFORM * UPPER AND LOWER PASSENGER DOOR LATCH PINS - VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS.						PKG		
	PKG 24	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF:</b>	AFL						0	
N5210017 (s)	PERFORM * UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - VISUAL INSPECTION.						PKG		
	PKG 24	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF:</b>	AFL						0	
T5210003 (s)	PERFORM EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA						PKG		
	PKG 18	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	<b>REF:</b> AMM 05-10-00	AFL						2541	
Y5210000 (s)	PERFORM AVIONICS COMPARTMENT ACCESS DOORS AND SEALS - VISUAL INSPECTION						PKG		
	PKG 13	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	<b>REF:</b> AMM 05-10-00	AFL						2541	
Y5210001 (s)	TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES						PKG		
	PKG 12	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	<b>REF:</b> AMM 05-10-00	AFL						2781	
Y5210002 (s)	BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES						PKG		
	PKG 12	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	<b>REF:</b> AMM 05-10-00	AFL						2781	
Y5210004 (s)	PERFORM UPPER AND LOWER PASSENGER/CREW DOOR - VISUAL INSPECTION OF DOOR STRUCTURE, TENSION FITTINGS, AND HINGE AREA FOR CRACKS AND CORROSION						PKG		
	PKG 18	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	<b>REF:</b> AMM 05-10-00	AFL						2541	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5210005 (s)	PERFORM INTERNAL LOWER PASSENGER/CREW DOOR CABLES - VISUAL INSPECTION. REMOVE STEP SKIN TO GAIN ACCESS TO CABLES						PKG		
	PKG 18	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
	REF: AMM 05-10-00	AFL					2541		
Y5210006 (s)	UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION						PKG		
	PKG 12	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
	REF: AMM 05-10-00	AFL					2781		
Y5210008 (s)	EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM - PERFORM OPERATIONAL CHECK						PKG		
	PKG 12	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
	REF: AMM 52-20-07	AFL					2781		
Y5240000 (s)	PERFORM OXYGEN SYSTEM SERVICING DOOR AND LATCHES - VISUAL INSPECTION FOR CONDITION AND SECURITY. CHECK DECAL FOR CONDITION AND LEGIBILITY						PKG		
	PKG 13	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
	REF: AMM 05-10-00	AFL					2541		
Y5240003 (s)	PERFORM SINGLE POINT REFUELING ACCESS DOOR - VISUAL INSPECTION.						PKG		
	PKG 14	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
	REF: AMM 05-10-00	AFL					2541		

## CHAPTER 53 FUSELAGE

5-19-00-H5323032	* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323032)								
		MOS	24				05-MAR-2019	<b>05-MAR-2021</b>	
		HRS/MSC	2400				3241.7	<b>5641.7</b>	
<b>AIRWORTHINESS</b>	REF: NDT PART 6/56-20-01	AFL					2541		
5-19-00-H5323092	* EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION (IRN H5323092)								
		MOS					26-MAR-2007		
		HRS/MSC	N/A				0		
	REF: NDT PART 6/56-20-01	AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-T5323166	PERFORM * EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES AND WING INSPECTION LIGHT. (REFER TO 5-10-00.) IRN T5323166	MOS	144				08-MAR-2019	08-MAR-2031	
<b>MANDATORY</b>	REF: GENERIC NO REF	HRS/MSC	9600				3241.7	12841.7	
		AFL					2541		
5-19-00-V5323168	EDDY CURRENT INSPECTION * LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH (P/N'S 4553130001-802 THRU 4553130001-809)	MOS					26-MAR-2007		
<b>NOT APPLICABLE</b>	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
5-19-01-U5323167-LEFT	* REPLACE LEFT COUPE RAIL (P/N 4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY	PN							
<b>NOT APPLICABLE</b>	REF: AMM 53-10-04	MOS		N:0					
		SN-UNKNOWN		N:0					
		AFL		N:0					
		APH		N:0					
5-19-01-U5323167-RIGHT	* REPLACE RIGHT COUPE RAIL (4553002003V7000-001, 4553002003V7001-002) (IRN U5323167) ASSEMBLY	PN							
<b>NOT APPLICABLE</b>	REF: AMM 53-10-04	MOS		N:0					
		SN-UNKNOWN		N:0					
		AFL		N:0					
		APH		N:0					
5-19-02-RVSM-M5313001	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK OF THE FORWARD FUSELAGE SKIN FOR RVSM COMPLIANT AIRCRAFT (IRN # M5313001)	MOS	24	+14d/-14d			13-JAN-2021	13-JAN-2023	27-JAN-2023
<b>RVSM</b>	REF: AMM 53-00-01	HRS/MSC					3778.2		
		AFL					2986		
530001	FUSELAGE ASSEMBLY	MOS					26-MAR-2007		
	4553020010-001	HRS/MSC	O/C				0		
	L0330	AFL					0		
	REF: GENERIC NO REF						0		
531001	AFT PRESSURE BULKHEAD	PN					26-MAR-2007		
	SN-UNKNOWN	MOS		N:0			0		
	REF: AMM 53-10-01	HRS/MSC	O/C	N:0			0		
		AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
531040	LEFT TIE ROD END PN SN-UNKNOWN REF: AMM 53-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
531041	RIGHT TIE ROD END PN SN-UNKNOWN REF: AMM 53-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
531042	LEFT COUPE RAIL PN SN-UNKNOWN REF: AMM 53-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
531043	RIGHT COUPE RAIL PN SN-UNKNOWN REF: AMM 53-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
+ 5323172 EMP	* SKIN CUT-OUT FOR IRIDIUM ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION								
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				26-MAR-2007 0 0		
535001	RADOME H0601-5 0487 REF: AMM 53-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
535601	LEFT DELTA FIN 4555501000-015 S7549A0169 REF: AMM 53-56-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
535602	RIGHT DELTA FIN 4555501000-016 S7549A0174 REF: AMM 53-56-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A5310005 (s)	PERFORM * FUSELAGE FUEL CELL CANTED BULKHEAD (FS 495) - VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSSMEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING.						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	9600				0		0
A5310007 (s)	PERFORM * AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT.						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	9600				0		0
A5323022 (s)	PERFORM * NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (FS 150 TO FS 162) - VISUAL INSPECTION. INSPECT THE FOLLOWING: A. PANEL B. CHANNEL STIFFENERS. C. SUPPORT ANGLE. D. ANGLE STIFFENER. E. ZEE STIFFENER.						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	9600				0		0
A5323023 (s)	PERFORM * DRAG LINK ATTACHMENT LUG - VISUAL INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	9600				0		0
A5360001 (s)	PERFORM DELTA FINS - WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING: A. DELTA FIN AFT SPAR. B. DELTA FIN SUPPORT ANGLE. C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS.						PKG		
	PKG 26	MOS					26-MAR-2007		
	<b>REF:</b> AMM 05-10-00	HRS/MSC AFL	9600	+25/-25			0		0
D5323039 (s)	PERFORM * MACHINED FUSELAGE FRAME AT FS 466 - DETAILED VISUAL INSPECTION BETWEEN STRINGER 13 LEFT AND RIGHT, PAYING PARTICULAR ATTENTION TO THE BL 10 SPLICES. CONFIRM ANY CRACK INDICATIONS WITH THE EDDY CURRENT PROCEDURES						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	9600				0		0
E5310001 (s)	PERFORM * LONGERON, INTERNAL (BETWEEN FS 384 AND FS 433) - VISUAL INSPECTION.						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	9600				0		0

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5310002 (s)	PERFORM * FLIGHT DECK LONGERON (FS 149 - FS 196) - VISUAL INSPECTION. INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS.						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
E5310017 (s)	PERFORM * AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (FS 457) - DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT FS 457 FLANGE AT ATTACHMENT TO PRESSURE FLOOR.						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
E5310018 (s)	PERFORM * AFT PRESSURE BULKHEAD PANEL FACING SHEETS (FS 457) - VISUAL INSPECTION. INSPECT BOTH FRONT AND AFT OF FACING SHEETS.						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
E5323025 (s)	PERFORM * FORWARD/AFT WHEELBOX JOINT (FS 150) - VISUAL INSPECTION. INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON.						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
E5323050 (s)	PERFORM * AFT POST/WINDSHIELD RETAINER ATTACHMENT - WITH HEADLINER REMOVED, EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-04	HRS/MSC	9600					0	
		AFL						0	
E5323053 (s)	PERFORM * FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (FS 171 TO FS 204) - VISUAL INSPECTION. INSPECT THE FOLLOWING: A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT FS 171, FS 182, FS 196, AND FS 204. B. FRAME ATTACHMENTS TO UPPER COUPE RAILS AT FS 196 AND FS 204. C. GUSSETS AT FASTENER HOLES.						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
E5323054 (s)	PERFORM * TIE-ROD ASSEMBLY (FS 162) (ALUMINUM ENDS) - VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						PKG		
	PKG 25	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC	4800					0	
		AFL						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5323055 (s)	PERFORM * TIE-ROD ASSEMBLY (FS 162) (TITANIUM ENDS) - VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 53-10-04	HRS/MSC	9600					0	
		AFL						0	
E5323068 (s)	PERFORM * STRINGER 1 RH BETWEEN FS 533 AND FS 543 - VISUAL INSPECTION. INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN FS 533 AND FS 543.						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
E5323073 (s)	PERFORM * FUSELAGE BOTTOM SKIN PANEL - VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (FS 435)						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
E5323074 (s)	PERFORM * AUXILIARY SKIN PANEL - VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (FS 466).						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
E5350000 (s)	PERFORM * BOTTOM KEELBEAM END PADS (FS 384 - FS 486) - VISUAL INSPECTION. INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT FS 433.						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
F5323056 (s)	PERFORM * TIE-ROD FORK ENDS (ALUMINUM) - FLOURESCENT PENETRANT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-058)						PKG		
	PKG 25	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC	4800					0	
		AFL						0	
F5323081 (s)	PERFORM * TIE-ROD FORK ENDS (TITANIUM, P/N R24889) - FLUORESCENT PENETRANT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-059 AND SUBSEQUENT AND PRIOR AIRCRAFT WITH TITANIUM ROD ASSEMBLY INSTALLED.)						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 8/53-10-01	HRS/MSC	9600					0	
		AFL						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
F5331021 (s)	PERFORM * FORWARD CANTED BULKHEAD (FS 630) - VISUAL INSPECTION. INSPECT AT FRONT SPAR ATTACHMENT FASTENERS.						PKG		
	PKG 25	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF: AMM NO REF</b>	AFL						0	
F5331022 (s)	PERFORM * MID CANTED BULKHEAD (FS 657) - VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS.						PKG		
	PKG 26	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF: AMM NO REF</b>	AFL						0	
F5331023 (s)	PERFORM * AFT CANTED BULKHEAD (FS 682) - VISUAL INSPECTION. INSPECT AT REAR SPAR ATTACHMENT FASTENERS.						PKG		
	PKG 26	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF: AMM NO REF</b>	AFL						0	
F5331024 (s)	PERFORM * VERTICAL STABILIZER FRONT ROOT BULKHEAD ATTACHMENT (FS 630) - VISUAL INSPECTION. INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						PKG		
	PKG 26	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL						0	
F5331025 (s)	PERFORM * VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (FS 657) - VISUAL INSPECTION. INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						PKG		
	PKG 26	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL						0	
F5331026 (s)	PERFORM * VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (FS 682) - VISUAL INSPECTION. INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						PKG		
	PKG 26	MOS						26-MAR-2007	
		HRS/MSC	9600					0	
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL						0	
L5311002 (s)	PERFORM * NOSE LANDING GEAR ACTUATOR ATTACHMENT ON FORWARD PRESSURE BULKHEAD - EDDY CURRENT INSPECTION. INSPECT ACTUATOR ATTACHMENT BRACKET LUGS, RADII, AND FASTENER HOLES.						PKG		
	PKG 27	MOS						26-MAR-2007	
		HRS/MSC						0	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/32-12-00</b>	AFL	10000					0	



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
L5311004 (s)	PERFORM * NOSE LANDING GEAR TRUNNION FITTINGS - VISUAL INSPECTION OF THE TRUNNION FITTINGS AND ATTACHMENT BOLTS. PKG 27	MOS HRS/MSC					PKG	26-MAR-2007	0
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL	10000				0		0
L5311005 (s)	PERFORM * NOSE LANDING GEAR TRUNNION FITTINGS AND SUPPORT STRUCTURE - EDDY CURRENT INSPECTION OF THE TRUNNION SUPPORT STRUCTURE AT THE FORWARD PRESSURE BULKHEAD FLANGE. PKG 27	MOS HRS/MSC					PKG	26-MAR-2007	0
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/32-12-05	AFL	10000				0		0
M5323021 (s)	PERFORM * EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - VISUAL INSPECTION. INSPECT LONGERON BETWEEN FS 398 AND FS 486, STRINGER 13 LHS & RHS. PKG 26	MOS HRS/MSC	9600				PKG	26-MAR-2007	0
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		0
M5323034 (s)	PERFORM * UPPER AND LOWER COUPE RAIL AND CENTER POST/ WINDSHIELD RETAINER ATTACHMENT - EDDY CURRENT INSPECTION. PKG 26	MOS HRS/MSC	9600				PKG	26-MAR-2007	0
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-03	AFL					0		0
N5314000 (s)	PERFORM * EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (FS 370 TO FS 398) - PERFORM EDDY CURRENT INSPECTION. PKG 19	MOS HRS/MSC	4800				PKG	26-MAR-2007	0
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-01	AFL					0		0
N5323026 (s)	PERFORM * UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (F.S. 224 - F.S. 256) -EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/CREW DOOR CUTOUT PKG 19	MOS HRS/MSC	4800				PKG	26-MAR-2007	0
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-02	AFL					0		0
P5310003 (s)	PERFORM * AFT PRESSURE BULKHEAD SUPPORT POST (FS 457) - EDDY CURRENT INSPECTION. PKG 26	MOS HRS/MSC	9600				PKG	26-MAR-2007	0
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-18	AFL					0		0

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5310004 (s)	PERFORM * AFT PRESSURE BULKHEAD FRAME PERIPHERY - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-21	HRS/MSC AFL	9600				0 0		
P5310006 (s)	PERFORM * FORWARD PRESSURE BULKHEAD - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-07	HRS/MSC AFL	9600				0 0		
P5320001 (s)	PERFORM * FUSELAGE PRESSURE FLOOR STEP (FS 433 - FS 457) - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-20-01	HRS/MSC AFL	9600				0 0		
P5323024 (s)	PERFORM * FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-12	HRS/MSC AFL	9600				0 0		
P5323027 (s)	PERFORM * FUSELAGE FRAME AT FS 412 - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-20	HRS/MSC AFL	9600				0 0		
P5323029 (s)	PERFORM * MACHINED SPAR FRAMES SYSTEMS CUTOUTS (FS 398, FS 412, FS 432, FS 466) - EDDY CURRENT INSPECTION PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-15	HRS/MSC AFL	9600				0 0		
P5323033 (s)	PERFORM * FUSELAGE SKIN AT EMERGENCY DOOR EGRESS-LIGHT AND WING INSPECTION LIGHT - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-40-02	HRS/MSC AFL	9600				0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5323037 (s)	PERFORM * WINDSHIELD COUPE RAIL TIE ROD BRACKET - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-09	HRS/MSC AFL	9600				0 0		
P5323038 (s)	PERFORM * WINDSHIELD CENTERPOST TO UPPER COUPE RAIL JOINT ATTACHMENT - EDDY CURRENT INSPECTION PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-22	HRS/MSC AFL	9600				0 0		
P5323047 (s)	PERFORM * PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION. PKG 19	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-10-04	HRS/MSC AFL	9600				0 0		
P5323049 (s)	PERFORM * FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-11	HRS/MSC AFL	9600				0 0		
P5323057 (s)	PERFORM * PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - EDDY CURRENT INSPECTION. PKG 19	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-06	HRS/MSC AFL	9600				0 0		
P5323058 (s)	PERFORM * FUSELAGE SKIN AT F.S. 504 - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-13	HRS/MSC AFL	9600				0 0		
P5323069 (s)	PERFORM * CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-08	HRS/MSC AFL	9600				0 0		
P5323164 (s)	PERFORM * FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-40-01	HRS/MSC AFL	9600				0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5323165 (s)	PERFORM * WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-10	AFL					0		
P5360006 (s)	PERFORM DELTA FIN ATTACH BOLT - LIQUID PENETRANT INSPECTION.						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600	+25/-25			0		
	<b>REF:</b> NDT PART 8/53-10-02	AFL					0		
Q5310023 (s)	PERFORM FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH - DETAILED VISUAL INSPECTION OF HI-LITE COLLARS						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600	+25/-25			0		
	<b>REF:</b>	AFL					0		
Q5310025 (s)	PERFORM AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LH THRU BL 9.55 RH) - DETAILED VISUAL INSPECTION OF HI-LITE COLLARS						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600	+25/-25			0		
	<b>REF:</b>	AFL					0		
Q5323048 (s)	PERFORM * FUSELAGE (PRESSURE CABIN) - EDDY CURRENT INSPECTION. INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING)						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-05	AFL					0		
Q5323051 (s)	PERFORM * LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (FS 220- FS 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LH AND RH AND STRINGER 2 RH AND STRINGER 18 RH.						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
Q5323059 (s)	PERFORM * STRINGER TO FRAME JOINTS (FS 162 TO FS 213) - EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS.						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T5310027 (s)	PERFORM * AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - EDDY CURRENT INSPECTION						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/53-30-17</b>	HRS/MSC	9600				0		
		AFL					0		
T5321089 (s)	SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING						PKG		
	PKG 7	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
	<b>REF: AMM 53-20-01</b>	AFL					2781		
T5323028 (s)	PERFORM * FUSELAGE TO WING ATTACH FITTINGS - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/53-30-16</b>	HRS/MSC	9600				0		
		AFL					0		
Y5311001 (s)	PERFORM NOSE LANDING GEAR ACTUATOR ATTACH FITTING AND SURROUNDING STRUCTURE - VISUAL INSPECTION						PKG		
	PKG 17	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
	<b>REF: AMM 05-10-00</b>	AFL					2541		
Y5311003 (s)	PERFORM NOSE LANDING GEAR TRUNNION FITTING AND SURROUNDING STRUCTURE - VISUAL INSPECTION						PKG		
	PKG 17	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
	<b>REF: AMM 05-10-00</b>	AFL					2541		
Y5320000 (s)	CENTER PEDESTAL - PERFORM VISUAL INSPECTION						PKG		
	PKG 1	MOS	12	+14d/-14d			13-JAN-2021		
		HRS/MSC	300	+25/-25			3778.2		
	<b>REF: AMM 05-10-00</b>	AFL					2986		
Y5321010 (s)	FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION						PKG		
	PKG 1	MOS	12	+14d/-14d			13-JAN-2021		
		HRS/MSC	300	+25/-25			3778.2		
	<b>REF: AMM 53-20-01</b>	AFL					2986		
Y5321011 (s)	TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION						PKG		
	PKG 8	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
	<b>REF: AMM 05-10-00</b>	AFL					2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5321088 (s)	PERFORM SEAT RAILS - REMOVE FLOORBOARD 230AL AND PERFORM VISUAL INSPECTION OF SEAT RAILS. IF CORROSION IS DETECTED, REMOVE ALL FLOORBOARDS AND INSPECT ALL SEAT RAILS.						PKG		
	PKG 13	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM NO REF	AFL						2541	
Y5323020 (s)	PERFORM EXTERNAL FUSELAGE (PRESSURE CABIN) - VISUAL INSPECTION OF ALL CABIN SKINS FROM F.S. 100 TO F.S.458. PAY PARTICULAR ATTENTION TO ALL CUTOUTS AND SKIN JOINTS. NO FAIRING ACCESS REQUIRED.						PKG		
	PKG 13	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 05-10-00	AFL						2541	
Y5323031 (s)	PERFORM EXTERIOR CABIN WINDOW COAMINGS AND SURROUNDING FUSELAGE SKIN - VISUAL INSPECTION USING 10X MAGNIFICATION AND ADEQUATE LIGHTING						PKG		
	PKG 13	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 05-10-00	AFL						2541	
Y5340007 (s)	PERFORM WING ATTACH FITTINGS - VISUAL INSPECTION						PKG		
	PKG 19	MOS	96	+14d/-14d				10-APR-2015	
		HRS/MSC	2400	+25/-25				2017.3	
	REF: AMM 05-10-00	AFL							
Y5360000 (s)	DELTA FINS - PERFORM VISUAL INSPECTION						PKG		
	PKG 8	MOS	24	+14d/-14d				29-JAN-2020	
		HRS/MSC	600	+25/-25				3544.5	
	REF: AMM 05-10-00	AFL						2781	
Z5323172 (s)	*SKIN CUT-OUT FOR IRIDIUM ANTENNAS FS283.88 TO FS308.39 - PERFORM EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS						26-MAR-2007	
		HRS/MSC	N/A					0	
<b>AIRWORTHINESS</b>	REF: AMM NO REF	AFL						0	
<b>CHAPTER 54</b>	<b>NACELLES/PYLONS</b>								
5-19-01-A5450028	REPLACE AFT ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500201-001/-002)								
		MOS						26-MAR-2007	
		HRS/MSC	N/A					0	
<b>N/A BY SERIAL NUMBER</b>	REF: AMM 53-40-02	AFL						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-01-M5450027	REPLACE FORWARD ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500101-003/4)	MOS					26-MAR-2007		
	REF: AMM 53-40-02	HRS/MSC	10000	+25/-25			0	10000	10025
		AFL					0		
		APH					0		
5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.	MOS					26-MAR-2007		
	REF: AMM 05-10-00	HRS/MSC	6000	+100/-100			0	6000	6100
		AFL					0		
		APH					0		
5450054	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.	MOS					26-MAR-2007		
	REF: AMM 05-10-00	HRS/MSC	6000	+100/-100			0	6000	6100
		AFL					0		
		APH					0		
545019	* REPLACE LEFT AFT ENGINE BEAM TO FRAME ATTACHMENT (IRN P5450020) BOLT	MOS					26-MAR-2007		
	PN			N:0			0	9600	
	SN-UNKNOWN	HRS/MSC	9600				0		
<b>LIFE LIMIT</b>	REF: NDT PART 8/54-30-01	AFL		N:0			0		
545020	* REPLACE RIGHT AFT ENGINE BEAM TO FRAME ATTACHMENT (IRN P5450020) BOLT	MOS					26-MAR-2007		
	PN			N:0			0	9600	
	SN-UNKNOWN	HRS/MSC	9600				0		
<b>LIFE LIMIT</b>	REF: NDT PART 8/54-30-01	AFL		N:0			0		
545021	* REPLACE LEFT AFT ENGINE MOUNT TO END FITTING ATTACH (IRN A5450022) BOLT	MOS					26-MAR-2007		
	PN			N:0			0	9600	
	SN-UNKNOWN	HRS/MSC	9600				0		
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
545022	* REPLACE RIGHT AFT ENGINE MOUNT TO END FITTING ATTACH (IRN A5450022) BOLT								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	9600	N:0			0	9600	
<b>LIFE LIMIT</b>	<b>REF:</b> GENERIC NO REF	AFL		N:0			0		
545023	* REPLACE LEFT ENGINE TO AFT ENGINE MOUNT ATTACH (IRN P5450023) BOLT								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	9600	N:0			0	9600	
<b>LIFE LIMIT</b>	<b>REF:</b> NDT PART 8/54-30-02	AFL		N:0			0		
545024	*REPLACE RIGHT ENGINE TO AFT ENGINE MOUNT ATTACH (IRN P5450023) BOLT								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	9600	N:0			0	9600	
<b>LIFE LIMIT</b>	<b>REF:</b> NDT PART 8/54-30-02	AFL		N:0			0		
A5450026 (s)	PERFORM * ENGINE DRAG STRUT - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/54-50-01	AFL					0		
E5450029 (s)	PERFORM * AFT ENGINE BEAM - VISUAL INSPECTION. INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE.						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
F5450019 (s)	PERFORM * AFT ENGINE BEAM ATTACHMENT TO FRAMES - VISUAL INSPECTION. INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES.						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	AFL					0		
H5450012 (s)	PERFORM * FRAMES 39/40 (FS 512/518) AT ENGINE BEAM ATTACHMENT - EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT.						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/54-50-03	AFL					0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
M5450015 (s)	PERFORM * FORWARD ENGINE BEAM, SPAR CAP, AND WEB - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/54-50-05	HRS/MSC	9600				0		
		AFL					0		
M5450018 (s)	PERFORM * FORWARD ENGINE MOUNT ATTACHMENT BOLTS - FLUORESCENT LIQUID PENETRANT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 8/71-20-01	HRS/MSC	9600				0		
		AFL					0		
P5450011 (s)	PERFORM * DRAG STRUT ATTACHMENT FITTINGS - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-10-03	HRS/MSC	9600				0		
		AFL					0		
P5450016 (s)	PERFORM * FORWARD ENGINE BEAM END FITTING - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/54-50-02	HRS/MSC	9600				0		
		AFL					0		
P5450017 (s)	PERFORM * FORWARD ENGINE BEAM TO FRAME ATTACH BOLTS - LIQUID PENETRANT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 8/53-40-01	HRS/MSC	9600				0		
		AFL					0		
P5450021 (s)	PERFORM * ENGINE AFT ISOLATOR MOUNT FITTINGS - LIQUID PENETRANT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 8/71-20-03	HRS/MSC	9600				0		
		AFL					0		
P5450024 (s)	PERFORM * FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT BEAM ATTACHMENT - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/53-30-14	HRS/MSC	9600				0		
		AFL					0		
P5450025 (s)	PERFORM * FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/54-50-03	HRS/MSC	9600				0		
		AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5450030 (s)	PERFORM * AFT ENGINE BEAM END FITTING - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG 26-MAR-2007		
<b>AIRWORTHINESS</b>	REF: NDT PART 6/54-50-04	HRS/MSC AFL	9600				0 0		
Y5410002 (s)	PERFORM PYLONS - VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE PKG 14	MOS	48	+14d/-14d			PKG 08-MAR-2019		
	REF: AMM 54-00-01	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
<b>CHAPTER 55 STABILIZERS</b>									
5-19-00-M5510010	EDDY CURRENT INSPECTION * HORIZONTAL STABILIZER AFT ROOT RIB. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS. (REFER TO NDI MANUAL {NDI-104}, PART 6, 55-10-03.)	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	REF: NDT PART 6/55-10-03	HRS/MSC AFL	4800				0 0	<b>4800</b>	
5-19-00-W5510091	PERFORM * HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 55-10-00.)	MOS					29-JAN-2020		
<b>MANDATORY</b>	REF: AMM 55-10-00	HRS/MSC AFL	625				3544.5 2781	<b>4169.5</b>	
+ 5510034	HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION	MOS							
	REF: AMM 55-10-00	HRS/MSC AFL	4800	+25/-25			(EBT)	<b>4800</b>	4825
551005	HORIZONTAL STABILIZER ASSEMBLY 4555101002-(033) S7549A0149	MOS			N:0		26-MAR-2007		
	REF: AMM 27-40-01	HRS/MSC AFL	O/C		N:0 N:0		0 0		
552031	LEFT ELEVATOR ASSEMBLY 4555201005-(007) S7549A0153	MOS			N:0		26-MAR-2007		
	REF: AMM 27-30-01	HRS/MSC AFL	O/C		N:0 N:0		0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
552032	RIGHT ELEVATOR ASSEMBLY 4555201005-(008) S7549A0153 REF: AMM 27-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
553000	TAILCONE/VERTICAL STABILIZER ASSEMBLY 4555301001-001 A0146 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
554005	RUDDER ASSEMBLY 4555401000-019 S7549A0160 REF: AMM 27-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
A5510014 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING. PKG 26	MOS HRS/MSC AFL	9600				26-MAR-2007 0 0		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF								
A5510021 (s)	PERFORM * HORIZONTAL MID SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - DETAILED VISUAL INSPECTION. PKG 26	MOS HRS/MSC AFL	9600				26-MAR-2007 0 0		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF								
A5540000 (s)	PERFORM * RUDDER ROOT RIB CAP (FS 698) - VISUAL INSPECTION. INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES. PKG 26	MOS HRS/MSC AFL	9600				26-MAR-2007 0 0		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF								
E5510074 (s)	PERFORM * HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - VISUAL INSPECTION. INSPECT REAR SPAR CAP AND FASTENERS. PKG 26	MOS HRS/MSC AFL	9600				26-MAR-2007 0 0		
<b>AIRWORTHINESS</b>	REF: GENERIC NO REF								

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5510075 (s)	PERFORM * HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB #3 - VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS.						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL					0		
E5510076 (s)	PERFORM * HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - VISUAL INSPECTION. INSPECT FRONT SPAR CAP AND FASTENERS.						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL					0		
E5520003 (s)	PERFORM * ELEVATOR FRONT SPAR - VISUAL INSPECTION. INSPECT SPAR CAP AT FASTENER HOLES.						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL					0		
E5520004 (s)	PERFORM * ELEVATOR RIB #1 CAP - VISUAL INSPECTION OF RIB #1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE.						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL					0		
G5510000 (s)	PERFORM * HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	4800				0		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/55-10-01</b>	AFL					0		
G5510023 (s)	PERFORM * HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	4800				0		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/55-30-01</b>	AFL					0		
H5510033 (s)	PERFORM * HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - LIQUID PENETRANT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	4800				0		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 8/27-40-01</b>	AFL					0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5510005 (s)	PERFORM * HORIZONTAL STABILIZER REAR SPAR CAP - EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE.						PKG		
	PKG 20	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-10-05	HRS/MSC	4800				0		
		AFL					0		
N5510015 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING TOP PLATE - EDDY CURRENT INSPECTION.						PKG		
	PKG 20	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-30-02	HRS/MSC	4800				0		
		AFL					0		
N5510016 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS						PKG		
	PKG 20	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-30-03	HRS/MSC	4800				0		
		AFL					0		
N5510069 (s)	PERFORM * HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - EDDY CURRENT INSPECTION						PKG		
	PKG 20	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-10-02	HRS/MSC	4800				0		
		AFL					0		
N5510082 (s)	PERFORM * HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - EDDY CURRENT INSPECTION						PKG		
	PKG 20	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-10-04	HRS/MSC	4800				0		
		AFL					0		
P5510006 (s)	PERFORM * VERTICAL STABILIZER FRONT SPAR AND MID SPAR - RADIOGRAPHIC INSPECTION.						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 2/55-30-01	HRS/MSC	9600				0		
		AFL					0		
P5510008 (s)	PERFORM * HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - MAGNETIC PARTICLE INSPECTION.						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC	9600				0		
		AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5510009 (s)	PERFORM * HORIZONTAL STABILIZER MID SPAR CAP B.L. 0.0 TO B.L. 4.0 - X-RAY INSPECTION. PKG 20	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 2/55-10-03</b>	HRS/MSC AFL	9600				0 0		
P5510011 (s)	PERFORM * HORIZONTAL STABILIZER MID-SPAR AND REAR-SPAR UPPER FLANGE AT ROOT RIB - RADIOGRAPHIC INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 2/55-10-01</b>	HRS/MSC AFL	9600				0 0		
P5510017 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - EDDY CURRENT INSPECTION PKG 20	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/55-30-05</b>	HRS/MSC AFL	9600				0 0		
P5510018 (s)	PERFORM * VERTICAL STABILIZER PIVOT FITTING LUGS - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/55-30-04</b>	HRS/MSC AFL	9600				0 0		
P5510019 (s)	PERFORM * ELEVATOR HINGES ON HORIZONTAL STABILIZER - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/55-20-02</b>	HRS/MSC AFL	9600				0 0		
P5510020 (s)	PERFORM * HORIZONTAL MID-SPAR UPPER CAP - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/55-10-07</b>	HRS/MSC AFL	9600				0 0		
P5510024 (s)	PERFORM * ELEVATOR CONTROL HORN - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/55-20-01</b>	HRS/MSC AFL	9600				0 0		
P5510070 (s)	PERFORM * HORIZONTAL STABILIZER FRONT SPAR - RADIOGRAPHIC INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 2/55-10-02</b>	HRS/MSC AFL	9600				0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5510073 (s)	PERFORM * HORIZONTAL REAR SPAR UPPER CAP - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-10-07	HRS/MSC AFL	9600				0 0		
P5510092 (s)	PERFORM * HORIZONTAL STABILIZER UPPER-SPAR-SPLICE DOUBLER - EDDY CURRENT INSPECTION. PKG 20	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-10-06	HRS/MSC AFL	9600				0 0		
P5520001 (s)	PERFORM * ELEVATOR HINGE ATTACH BOLT - MAGNETIC PARTICLE INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 7/27-30-01	HRS/MSC AFL	9600				0 0		
P5520002 (s)	PERFORM * ELEVATOR HINGE PIN - LIQUID PENETRANT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-014) PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 8/55-30-01	HRS/MSC AFL	9600				0 0		
P5520021 (s)	PERFORM * ELEVATOR HINGE FITTINGS - EDDY CURRENT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-015 AND SUBSEQUENT.) PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-30-07	HRS/MSC AFL	9600				0 0		
P5520022 (s)	PERFORM * ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - LIQUID PENETRANT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	9600				0 0		
P5540001 (s)	PERFORM * RUDDER SPAR - DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC AFL	9600				0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5540002 (s)	PERFORM * RUDDER ATTACH BOLT - LIQUID PENETRANT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 8/55-30-02	HRS/MSC AFL	9600				0 0		
Q5510007 (s)	PERFORM * VERTICAL STABILIZER SKIN AND LOWER AFT SPAR CAP - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-30-06	HRS/MSC AFL	9600				0 0		
Q5530011 (s)	PERFORM * VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - EDDY CURRENT INSPECTION. PKG 20	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/55-30-06	HRS/MSC AFL	9600				0 0		
T5510004 (s)	PERFORM * RUDDER HINGE FITTINGS - VISUAL INSPECTION. CONTROL SURFACE REMOVAL NOT REQUIRED. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b>	HRS/MSC AFL	9600				0 0		
Y5510001 (s)	PERFORM HORIZONTAL STABILIZER - EXTERNAL VISUAL INSPECTION PKG 14	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	<b>REF:</b> AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
Y5510002 (s)	PERFORM ELEVATOR HINGES ON HORIZONTAL STABILIZER - VISUAL INSPECTION. INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE PKG 14	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	<b>REF:</b> AMM 55-10-01	HRS/MSC AFL	1200	+25/-25			3241.7 2541		
Y5510003 (s)	PERFORM VERTICAL STABILIZER PIVOT FITTING - VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET). PKG 14	MOS	48	+14d/-14d			PKG	08-MAR-2019	
	<b>REF:</b> AMM 55-00-01	HRS/MSC AFL	1200	+25/-25			3241.7 2541		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5510093 (s)	PERFORM HORIZONTAL STABILIZER - VISUAL INSPECTION OF HILITE COLLARS IN THE FOLLOWING AREAS:- FORWARD SPAR TO BL 0.0 RIB.- CENTER SPAR TO BL 0.0 RIB.- CENTER SPAR SPLICE PLATE.- AFT SPAR SPLICE PLATE.- ROOT RIBS AT BL 3.70 (RIGHT AND LEFT).- UPPER DOUBLER SPAR SPLICE, BL 0.0.- HSTA UPPER ATTACH FITTING STRUCTURE						PKG		
	PKG 14	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 55-00-01	AFL						2541	
Y5510094 (s)	PERFORM LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - BORESCOPE INSPECTION OF HILITE COLLARS COMMON TO RIB # 6 AND MID SPAR						PKG		
	PKG 14	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 55-10-00	AFL						2541	
Y5540012 (s)	RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION. NOTE: PERFORM BONDING CHECK OF CLAMP AND BONDING JUMPERS AFTER REINSTALLATION OF CLAMP.						PKG		
	PKG 2	MOS	12	+14d/-14d				13-JAN-2021	
		HRS/MSC	300	+25/-25				3778.2	
	REF: AMM 27-20-01	AFL						2986	
<b>CHAPTER 56</b>	<b>WINDOWS</b>								
5-19-00-W5600002	** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST (IRN W5600002)								
		MOS	12	+14d/-14d				29-JAN-2020	29-JAN-2021 12-FEB-2021
		HRS/MSC						3544.5	
<b>AIRWORTHINESS</b>	REF: See Workcard	AFL						2781	
561001	LEFT WINDSHIELD ASSEMBLY								
	6656100001-001	MOS		N:0				23-FEB-2010	
	0931	HRS/MSC	O/C	N:0				777.3	
	REF: See Workcard	AFL		N:0				595	
+ 561001A	ULTRASONIC-INSPECTION LEFT WINDSHIELD ASSEMBLY STRUCTURAL PLIES (IRN N5600003)								
	6656100001-001	MOS						26-MAR-2007	
	0931	HRS/MSC	4800					0	4800
<b>AIRWORTHINESS</b>	REF: NDT PART 4/56-10-01	AFL						0	
		APH						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561001B	PERFORM INSPECTION LEFT WINDSHIELD ASSEMBLY BOLT HOLES (IRN N5600012)	MOS					23-FEB-2010		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 56-10-01	HRS/MSC AFL	4800				777.3 595		<b>5577.3</b>
561002	RIGHT WINDSHIELD ASSEMBLY	MOS					31-AUG-2010		
	6656100001-002	HRS/MSC	O/C	N:0			906.8		
	1014	AFL		N:0			693		
	<b>REF:</b> See Workcard			N:0					
+ 561002A	ULTRASONIC-INSPECTION RIGHT WINDSHIELD ASSEMBLY STRUCTURAL PLIES (IRN N5600003)	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 4/56-10-01	HRS/MSC AFL APH	4800				0 0 0		<b>4800</b>
561002B	PERFORM INSPECTION RIGHT WINDSHIELD ASSEMBLY BOLT HOLE (IRN N5600012)	MOS					31-AUG-2010		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 56-10-01	HRS/MSC AFL	4800				906.8 693		<b>5706.8</b>
562010-1	LEFT NO.1 WINDOW CABIN	MOS					26-MAR-2007		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	<b>REF:</b> AMM 56-20-01			N:0					
562010-10	RIGHT NO.5 WINDOW CABIN	MOS					26-MAR-2007		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	<b>REF:</b> AMM 56-20-01			N:0					
562010-11	LEFT NO.6 WINDOW CABIN	MOS					26-MAR-2007		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	<b>REF:</b> AMM 56-20-01			N:0					

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562010-12	RIGHT NO.6 EMERGENCY EXIT WINDOW PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-13	LEFT NO.7 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-14	RIGHT NO.7 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-15	LEFT NO.8 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-16	EMERGENCY EXIT WINDOW CABIN PN SN-UNKNOWN REF: AMM 52-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-2	RIGHT NO.1 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-3	LEFT NO.2 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-4	RIGHT NO.2 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562010-5	LEFT NO.3 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-6	RIGHT NO.3 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-7	LEFT NO.4 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-8	RIGHT NO.4 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
562010-9	LEFT NO.5 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
L5600010 (s)	PERFORM * CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - DETAILED VISUAL INSPECTION PKG 25 REF: GENERIC NO REF	MOS HRS/MSC AFL	4800				PKG 26-MAR-2007 0 0		
Y5600000 (s)	WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR) PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
Y5600001 (s)	CABIN WINDOWS - PERFORM VISUAL INSPECTION PKG 7 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 29-JAN-2020 3544.5 2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5600013 (s)	WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL. IF REPAIRS TO THE SEAL ARE NEEDED, REFER TO 56-10-01.						PKG		
	PKG 1	MOS	12	+14d/-14d				13-JAN-2021	
		HRS/MSC	300	+25/-25				3778.2	
	REF: See Workcard	AFL						2986	
<b>CHAPTER 57 WINGS</b>									
5-19-00-E5750051	VISUALLY INSPECT * FLAP MAIN TRACK ROLLERS WITH FLAPS REMOVED (IRN E5750051)								
		MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	REF: AMM 05-10-00	HRS/MSC	10000					0	<b>10000</b>
		AFL						0	
5-19-00-E5750052	VISUALLY INSPECT * FLAP NOSE ROLLERS WITH FLAPS REMOVED (IRN E5750052)								
		MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	REF: AMM 05-10-00	HRS/MSC	7200					0	<b>7200</b>
		AFL						0	
5-19-00-N5710002	VISUALLY INSPECT * WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIBS 7 AND 8. N5710002 (PRE SB 45-11-5)								
		MOS							
<b>AIRWORTHINESS</b>	REF: AMM 05-10-00	HRS/MSC	9600					0	<b>9600</b>
		AFL							
5-19-00-N5710008	NON DESTRUCTIVE INSPECT * WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. N5710008 (PRE SB 45-11-5)								
		MOS							
<b>AIRWORTHINESS</b>	REF: NDT PART 4/57-30-03	HRS/MSC	9600					0	<b>9600</b>
		AFL							
5-19-00-N5710009	NON DESTRUCTIVE TEST * WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM NDI INSPECTION. N5710009 (PRE SB 45-11-5)								
		MOS							
<b>AIRWORTHINESS</b>	REF: NDT PART 2/57-10-02	HRS/MSC	9600					0	<b>9600</b>
		AFL							
5-19-00-N5710010	NON DESTRUCTIVE INSPECT * WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT WS 81 - PERFORM NDI INSPECTION. N5710010 (PRE SB 45-11-5)								
		MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	REF: NDT PART 4/57-30-01	HRS/MSC	9600					0	<b>9600</b>
		AFL						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710012	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB #6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (REFER TO 5-10-00.) (EFFECTIVE ON AIRCRAFT NOT MODIFIED BY SB 45-11-5, "INCREASE MAXIMUM ZERO FUEL WEIGHT (16,500 POUNDS).")	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> AMM 05-10-00	HRS/MSC	9600				0	<b>9600</b>	
		AFL					0		
5-19-00-N5710013	NON DESTRUCTIVE INSPECT * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM NDI INSPECTION. N5710013 (PRE SB 45-11-5)	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-20-04	HRS/MSC	10000				0	<b>10000</b>	
		AFL					0		
5-19-00-N5710026	NON DESTRUCTIVE INSPECT * WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. N5710026 (PRE SB 45-11-5)	MOS							
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 4/57-30-03	HRS/MSC	10000					<b>10000</b>	
		AFL							
5-19-00-N5710123	EDDY CURRENT INSPECT * WING BOX MID SPAR LOWER CAP AT TRUNNION FITTING - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. N5710123 (PRE SB 45-11-5)	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-01	HRS/MSC	9600				0	<b>9600</b>	
		AFL					0		
5-19-00-N5710148	EDDY CURRENT INSPECTION * WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION, INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33 N5710148 (POST SB 45-11-5)	MOS					26-MAR-2007		
	<b>REF:</b> NDT PART 6/57-20-02	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
5-19-00-N5710149	EDDY CURRENT INSPECTION * WING CENTER SECTION FORWARD AND AFT RIBS AT WS6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION. N5710149 (POST SB 45-11-5)	MOS					26-MAR-2007		
	<b>REF:</b> NDT PART 6/57-10-06	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710150	ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION, INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS99 AND WS137. N5710150 (POST SB 45-11-5)	MOS						26-MAR-2007	
	REF: NDT PART 4/57-30-03	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	
5-19-00-N5710151	X-RAY INSPECTION * WING BOX MID SPAR LOWER CAP JOINT AT WS137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT. N5710151 (POST SB 45-11-5)	MOS						26-MAR-2007	
	REF: NDT PART 2/57-10-02	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	
5-19-00-N5710152	ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS81 - PERFORM ULTRASONIC INSPECTION, INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 CLOSING RIB AT WS 60. N5710152 (POST SB 45-11-5)	MOS						26-MAR-2007	
	REF: NDT PART 4/57-30-01	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	
5-19-00-N5710153	X-RAY INSPECTION * WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90. N5710153 (POST SB 45-11-5)	MOS						26-MAR-2007	
	REF: NDT PART 2/57-10-03	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	
5-19-00-N5710155	EDDY CURRENT INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS33 AND WS 48. N5710155 (POST SB 45-11-5)	MOS						26-MAR-2007	
	REF: NDT PART 6/57-20-04	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710158	EDDY CURRENT INSPECTION * CENTER SECTION FRONT SPAR LOWER CAP - PEFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS31 LEFT TO WS31 RIGHT) N5710158 (POST SB 45-11-5)	MOS						26-MAR-2007	
	REF: NDT PART 6/57-10-03	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	
5-19-00-N5710159	ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. N5710159 (POST SB 45-11-5)	MOS						26-MAR-2007	
	REF: NDT PART 4/57-30-03	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	
5-19-00-N5710160	EDDY CURRENT INSPECTION * WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. N5710160 (POST SB 45-11-5)	MOS						26-MAR-2007	
	REF: NDT PART 6/57-10-11	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	
5-19-00-N5710163	EDDY CURRENT INSPECTION * CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP. N5710163 (POST SB 45-11-5)	MOS						26-MAR-2007	
NOT APPLICABLE	REF: See Workcard	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	
5-19-00-N5710164	EDDY CURRENT INSPECTION * CENTER SECTION MID SPAR LOWER CAP - PEFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33. N5710164 (POST SB 45-11-5)	MOS						26-MAR-2007	
	REF: NDT PART 6/57-10-02	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710165	EDDY CURRENT INSPECTION * WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS65, WS 126 AND WS184 ON REAR SPAR. N5710165 (POST SB 45-11-5)	MOS					26-MAR-2007		
	REF: NDT PART 6/57-20-01	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
5-19-00-N5710168	EDDY CURRENT INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. N5710168 (POST SB 45-11-5)	MOS					26-MAR-2007		
	REF: NDT PART 6/57-10-01	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
5-19-00-N5710169	EDDY CURRENT INSPECTION * MID SPAR AT RIB #2 NEAR WS48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710169 (POST SB 45-11-5)	MOS					26-MAR-2007		
	REF: NDT PART 6/57-10-11	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
5-19-00-N5710170	EDDY CURRENT INSPECTION * MID SPAR AT RIB #3 NEAR WS60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710170 (POST SB 45-11-5)	MOS					26-MAR-2007		
	REF: NDT PART 6/57-10-11	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
5-19-00-N5710171	EDDY CURRENT INSPECTION * FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. N5710171 (POST SB 45-11-5)	MOS					26-MAR-2007		
	REF: NDT PART 6/57-20-03	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
5-19-00-N5710172	ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. N5710172 (PRE SB 45-11-5)	MOS							
	REF: NDT PART 4/57-10-00	HRS/MSC	9600				0	9600	
		AFL							

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710173	ULTRASONIC-INSPECTION * WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. N5710173 (POST SB 45-11-5)	MOS					26-MAR-2007		
	REF: NDT PART 4/57-10-00	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
5-19-00-N5710174	ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT WS 48 - PEFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. N5710174 (PRE SB 45-11-5)	MOS					0	10000	
	REF: NDT PART 4/57-30-04	HRS/MSC	10000				0		
		AFL							
5-19-00-N5710175	ULTRASONIC-INSPECTION * WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. N5710175 (POST SB 45-11-5)	MOS					26-MAR-2007		
	REF: NDT PART 4/57-30-04	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
5-19-00-N5710177	ULTRASONIC-INSPECTION * WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION. N5710177 (POST SB 45-11-5)	MOS					26-MAR-2007		
	REF: NDT PART 4/57-30-05	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
571001	WING ASSEMBLY	MOS		N:0			26-MAR-2007		
	4557000004-001	HRS/MSC	O/C	N:0			0		
	953676600404	AFL		N:0			0		
	REF: AMM 57-10-00	APH		N:0			0		
+ 5710190	LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.	MOS	96	+14d/-14d		-322	13-JAN-2021	26-FEB-2028	11-MAR-2028
	REF: GENERIC NO REF	HRS/MSC					3778.2		
		AFL					2986		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5710190	RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.	MOS HRS/MSC AFL	96	+14d/-14d		-322	13-JAN-2021 3778.2 2986	26-FEB-2028	11-MAR-2028
	REF: GENERIC NO REF								
571066	REAR TRUNNION BREAK OUT BLOCK REPLACE								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
573001	LEFT WINGLET FILLER								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
573002	RIGHT WINGLET FILLER								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
573089	RIGHT WING WINGLET								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-30-01	AFL		N:0			0		
573090	LEFT WING WINGLET								
	4557300006-001/00	MOS		N:0			26-MAR-2007		
	931618100404	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-30-01	AFL		N:0			0		
573091	LEFT WINGLET LEADING EDGE ASSEMBLY								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-30-01	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
573092	RIGHT WING WINGLET 4557300006-002/00 540638200404 REF: AMM 57-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
573093	RIGHT WINGLET LEADING EDGE ASSEMBLY PN SN-UNKNOWN REF: AMM 57-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
574005	LEFT INBOARD LEADING EDGE 4557400005-039 902192100404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
574007	RIGHT INBOARD LEADING EDGE 4557400005-040 902200800404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
574011	LEFT INBOARD LEADING EDGE ACCESS SECTION 4557400005-037 768103400404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
574013	RIGHT INBOARD LEADING EDGE ACCESS SECTION 4557400005-038 749469600404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
574033	LEFT CENTER LEADING EDGE 4557400005-041 902207400404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
574035	RIGHT CENTER LEADING EDGE 4557400005-042 772553300404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
574039	LEFT OUTBOARD LEADING EDGE ACCESS SECTION 4557400005-045 902233700404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
574041	RIGHT OUTBOARD LEADING EDGE ACCESS SECTION 4557400005-044 738762000404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
574050	LEFT OUTBOARD LEADING EDGE 4557400005-043 738758800404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
574051	RIGHT OUTBOARD LEADING EDGE 4557400005-046 916104100404 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
575001	LEFT FLAP ASSEMBLY 4557500006-007 953662200404 REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
575002	RIGHT FLAP ASSEMBLY 4557500006-008 953665300404 REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
576001	LEFT AILERON 4557600003-001 953679200404 REF: AMM 27-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
576002	RIGHT AILERON 4557600003-002 953682200404 REF: AMM 27-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
576003	UPPER AILERON QUADRANT ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
576004	LOWER AILERON QUADRANT ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
576010	LEFT AILERON BALANCE TAB ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
576011	RIGHT AILERON BALANCE TAB ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
+ 576037	REPLACE LEFT AILERON (ZONE/ACCESS 540/640 *IRN # A5760004) BOLTS PN SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			26-MAR-2007 0 0	9600	
+ 576038	REPLACE RIGHT AILERON (ZONE/ACCESS 540/640 *IRN # A5760004) BOLTS PN SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			26-MAR-2007 0 0	9600	
577001	LEFT SPOILER 4557700003-021 661703600382 REF: AMM 27-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
577002	RIGHT SPOILER 4557700003-022 712271700397 REF: AMM 27-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5710005 (s)	PERFORM * WING CENTER SECTION SPAR UPPER CAPS - VISUAL INSPECTION. INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION AT WS 33.						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL					0		
E5710019 (s)	PERFORM * WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - VISUAL INSPECTION. INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL					0		
E5710020 (s)	PERFORM * WING BOX RIBS - VISUAL INSPECTION. INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR.						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL					0		
E5760006 (s)	PERFORM * AILERON BASIC STRUCTURE - VISUAL INSPECTION						PKG		
	PKG 26	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: GENERIC NO REF</b>	AFL					0		
L5710124 (s)	PERFORM * AILERON DRIVE SUPPORT - ULTRASONIC INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	4800				0		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 4/27-10-01</b>	AFL					0		
N5710004 (s)	PERFORM * WING CENTER SECTION REAR SPAR - EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-20-02</b>	AFL					0		
N5710006 (s)	PERFORM * WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - EDDY CURRENT INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	9600				0		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-06</b>	AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5710011 (s)	PERFORM * WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 2/57-10-03	HRS/MSC	9600					0	
		AFL						0	
N5710014 (s)	PERFORM * WING BOX REAR SPAR FLAP TRACK CUTOUTS - EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUTOUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-20-01	HRS/MSC	9600					0	
		AFL						0	
N5710016 (s)	PERFORM * WING BOX BASIC SKIN/STRINGER, LOWER SKIN - VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
N5710017 (s)	PERFORM * WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS. (PRE SB 45-11-5)						PKG		
	PKG 26	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600					0	
		AFL						0	
N5710021 (s)	PERFORM * CENTER SECTION MID SPAR LOWER CAP - EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33 (PRE SB 45-11-5)						PKG		
	PKG 22	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-02	HRS/MSC	9600					0	
		AFL						0	
N5710022 (s)	PERFORM * CENTER SECTION MID SPAR CENTERLINE JOINT - EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> See Workcard	HRS/MSC	9600					0	
		AFL						0	
N5710023 (s)	PERFORM * CENTER SECTION FRONT SPAR LOWER CAP - EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS(W/31 LEFT TO W/31 RIGHT). (PRE SB 45-11-5)						PKG		
	PKG 22	MOS						26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-03	HRS/MSC	9600					0	
		AFL						0	



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5710028 (s)	PERFORM * WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-11	HRS/MSC	9600				0		
		AFL					0		
N5710031 (s)	PERFORM * WING BOX SKIN ACCESS COVER HOLES - EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-30-01	HRS/MSC	9600				0		
		AFL					0		
N5710037 (s)	PERFORM * WING BOX FRONT SPAR LOWER CAP - VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION(MS) 55. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600				0		
		AFL					0		
N5710084 (s)	PERFORM SPOILER, CENTER HINGE SPOILER SIDE - NDI INSPECTION.						PKG		
	PKG 22	MOS					26-MAR-2007		
		HRS/MSC	4800	+25/-25			0		
	<b>REF:</b> NDT PART 6/57-40-01	AFL					0		
N5710121 (s)	PERFORM * WING BOX MID SPAR, OUTBOARD OF RIB #8 - VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600				0		
		AFL					0		
N5710122 (s)	PERFORM * WING BOX REAR SPAR, OUTBOARD OF RIB #6 - VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600				0		
		AFL					0		
N5710137 (s)	PERFORM * MID SPAR AT RIB #2 NEAR WS 48 - BOLT HOLE EDDY CURRENT INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-11	HRS/MSC	9600				0		
		AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5710138 (s)	PERFORM * MID SPAR AT RIB #3 NEAR WS 60 - BOLT HOLE EDDY CURRENT INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-11	HRS/MSC	9600				0		
		AFL					0		
N5710139 (s)	PERFORM * FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - BOLT HOLE EDDY CURRENT INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-20-03	HRS/MSC	9600				0		
		AFL					0		
N5710157 (s)	PERFORM * WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS. (POST SB 45-11-5)						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>NOT APPLICABLE</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
N5710161 (s)	PERFORM *WING BOX SKIN ACCESS COVER HOLES - EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS. (POST SB 45-11-5)						PKG		
	PKG 22	MOS					26-MAR-2007		
<b>NOT APPLICABLE</b>	<b>REF:</b> NDT PART 6/57-30-01	HRS/MSC	N/A				0		
		AFL					0		
N5710176 (s)	PERFORM * WING MID-SPAR (CENTER SECTION) LOWER CAP AND CENTER-JOINT FITTING - ULTRASONIC INSPECTION. (PRE SB 45-11-5)						PKG		
	PKG 22	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 4/57-30-05	HRS/MSC	9600				0		
		AFL					0		
N5750005 (s)	PERFORM * FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES.						PKG		
	PKG 22	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> GENERIC NO REF	HRS/MSC	9600				0		
		AFL					0		
P5710001 (s)	PERFORM * WING DRAG LINK ATTACH FITTING - MAGNETIC PARTICLE INSPECTION						PKG		
	PKG 22	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 7/57-30-02	HRS/MSC	9600				0		
		AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5710007 (s)	PERFORM * WING TO FUSELAGE ATTACH FITTINGS AND LINKS - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-12</b>	HRS/MSC	9600				0		
		AFL					0		
P5710015 (s)	PERFORM * WING REAR SPAR ATAILERON HINGE - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-20</b>	HRS/MSC	9600				0		
		AFL					0		
P5710018 (s)	PERFORM * WING LOWER SKIN AT MID-SPAR SPAN-WISE JOINT - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-09</b>	HRS/MSC	9600				0		
		AFL					0		
P5710024 (s)	PERFORM * WING REAR-SPAR SIDE-STAY-FITTING SUPPORT STRUCTURE - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-20-06</b>	HRS/MSC	9600				0		
		AFL					0		
P5710025 (s)	PERFORM * WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - RADIOGRAPHIC INSPECTION.						PKG		
	PKG 22	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 2/57-10-01</b>	HRS/MSC	9600				0		
		AFL					0		
P5710029 (s)	PERFORM * WING MID-SPAR VERTICAL WEB - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-07</b>	HRS/MSC	9600				0		
		AFL					0		
P5710030 (s)	PERFORM * WING REAR SPAR VERTICAL WEB - EDDY CURRENT INSPECTION.						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-20-05</b>	HRS/MSC	9600				0		
		AFL					0		
P5710032 (s)	PERFORM * WING RIB UPPER-AFT-FLANGE FILLET RADIUS AT WS 33.0 - ULTRASONIC INSPECTION						PKG		
	PKG 25	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 4/57-30-02</b>	HRS/MSC	9600				0		
		AFL					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5710033 (s)	PERFORM * WING ACCESS HOLE IN CLOSING RIB BETWEEN MID SPAR AND REAR SPAR - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-05	HRS/MSC AFL	9600				0 0		
P5710034 (s)	PERFORM * WING BOX JOINT TO WINGLET - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-13	HRS/MSC AFL	9600				0 0		
P5710035 (s)	PERFORM * WING LOWER SKIN AT DRAIN HOLE - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-30-02	HRS/MSC AFL	9600				0 0		
P5710083 (s)	PERFORM * FLAP BOX BASIC STRUCTURE - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-40-02	HRS/MSC AFL	9600				0 0		
P5710085 (s)	PERFORM SPOILER UPPER SKIN - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-16	HRS/MSC AFL	9600	+25/-25			0 0		
P5710086 (s)	PERFORM SPOILER BOLTS AND HINGE PINS - MAGNETIC PARTICLE INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 7/27-10-01	HRS/MSC AFL	9600	+25/-25			0 0		
P5710181 (s)	PERFORM * WING DRAG LINK TUBE - MAGNETIC PARTICLE INSPECTION. PKG 22	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 7/57-30-01	HRS/MSC AFL	9600				0 0		
P5710182 (s)	PERFORM * WING DRAG LINK ATTACH BOLTS - LIQUID PENETRANT INSPECTION PKG 22	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 8/57-10-01	HRS/MSC AFL	9600				0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5710183 (s)	PERFORM * WING DRAG-LINK CLEVIS - MAGNETIC PARTICLE INSPECTION. PKG 22	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 7/57-10-01</b>	HRS/MSC AFL	9600				0 0		
P5710184 (s)	PERFORM * WING ATTACH BOLTS - FLUORESCENT PENETRANT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 8/57-10-02</b>	HRS/MSC AFL	9600				0 0		
P5710185 (s)	PERFORM * WING ATTACH LINKS - MAGNETIC PARTICLE INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 7/57-10-03</b>	HRS/MSC AFL	9600				0 0		
P5710186 (s)	PERFORM * WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - MAGNETIC PARTICLE INSPECTION PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 7/57-10-02</b>	HRS/MSC AFL	9600				0 0		
P5750002 (s)	PERFORM * FLAP FRONT-SPAR CUTOUTS - EDDY CURRENT INSPECTION. PKG 22	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-15</b>	HRS/MSC AFL	9600				0 0		
P5750003 (s)	PERFORM * FLAP NOSE-ROLLER RIBS - EDDY CURRENT INSPECTION. PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-14</b>	HRS/MSC AFL	9600				0 0		
P5750004 (s)	PERFORM * FLAP ACTUATOR SUPPORT RIBS - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-21</b>	HRS/MSC AFL	9600				0 0		
P5750048 (s)	PERFORM * FLAP TRACKS - MAGNETIC PARTICLE INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 7/57-71-01</b>	HRS/MSC AFL	9600				0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5750049 (s)	PERFORM * FLAP NOSE ROLLER TRACKS - MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 7/57-10-04</b>	HRS/MSC AFL	9600				0 0		
P5750053 (s)	PERFORM * FLAP TRACK SUPPORT RIBS - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-17</b>	HRS/MSC AFL	9600				0 0		
P5750068 (s)	PERFORM * FLAP FRONT-SPAR RIB SUPPORT STRUCTURE - EDDY CURRENT INSPECTION PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-26</b>	HRS/MSC AFL	9600				0 0		
P5760000 (s)	PERFORM * AILERON ACTUATOR HINGE FITTING - EDDY CURRENT INSPECTION. PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-25</b>	HRS/MSC AFL	9600				0 0		
P5760001 (s)	PERFORM * AILERON SKIN - EDDY CURRENT INSPECTION PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-19</b>	HRS/MSC AFL	9600				0 0		
P5760002 (s)	PERFORM * AILERON BALANCE TAB HINGE FITTINGS - EDDY CURRENT INSPECTION PKG 22	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-60-01</b>	HRS/MSC AFL	9600				0 0		
P5760003 (s)	PERFORM * AILERON TRIM AND BALANCE TAB FRONT SPARS - RADIOGRAPHIC INSPECTION PKG 25	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 2/57-60-01</b>	HRS/MSC AFL	9600				0 0		
P5760005 (s)	PERFORM * AILERON HINGE LUGS AND FITTINGS - EDDY CURRENT INSPECTION PKG 26	MOS					PKG	26-MAR-2007	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6/57-10-24</b>	HRS/MSC AFL	9600				0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5760014 (s)	PERFORM * AILERON HINGE SUPPORT STRUCTURE - EDDY CURRENT INSPECTION						PKG		
	PKG 26	MOS					26-MAR-2007		
<b>AIRWORTHINESS</b>	<b>REF:</b> NDT PART 6/57-10-23	HRS/MSC	9600				0		
		AFL					0		
P5770000 (s)	PERFORM SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS					26-MAR-2007		
	<b>REF:</b> NDT PART 6/57-10-22	HRS/MSC	9600	+25/-25			0		
		AFL					0		
Q5710156 (s)	PERFORM * WING BOX BASIC SKIN/STRINGER, LOWER SKIN - VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS. (POST SB 45-11-5)						PKG		
	PKG 22	MOS					10-APR-2015		
	<b>REF:</b> GENERIC NO REF	HRS/MSC	N/A				2017.3		
		AFL							
Q5710162 (s)	PERFORM * WING BOX FRONT SPAR LOWER CAP - VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55. (POST SB 45-11-5)						PKG		
	PKG 22	MOS					10-APR-2015		
<b>NOT APPLICABLE</b>	<b>REF:</b> AMM 05-10-00	HRS/MSC	N/A				2017.3		
		AFL							
Q5710166 (s)	PERFORM * WING BOX MID SPAR, OUTBOARD OF RIB #8 - VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260. (POST SB 45-11-5)						PKG		
	PKG 22	MOS					10-APR-2015		
<b>NOT APPLICABLE</b>	<b>REF:</b> AMM 05-10-00	HRS/MSC	N/A				2017.3		
		AFL							
Q5710167 (s)	PERFORM * WING BOX REAR SPAR, OUTBOARD OF RIB #6 - VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260. (POST SB 45-11-5)						PKG		
	PKG 22	MOS					10-APR-2015		
<b>NOT APPLICABLE</b>	<b>REF:</b> AMM 05-10-00	HRS/MSC	N/A				2017.3		
		AFL							
U5710147 (s)	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB #7 AND #8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS. (POST SB 45-11-5)						PKG		
	PKG 10	MOS					29-JAN-2020		
<b>NOT APPLICABLE</b>	<b>REF:</b>	HRS/MSC	N/A				3544.5		
		AFL					2781		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U5710154 (s)	* WING BOX REAR SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 81 TO RIB #6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (POST SB 45-11-5)						PKG		
	PKG 10	MOS					29-JAN-2020		
		HRS/MSC	N/A				3544.5		
<b>NOT APPLICABLE</b>	<b>REF:</b>	AFL					2781		
V5710039 (s)	PERFORM WINGLET SKIN - EDDY CURRENT INSPECTION						PKG		
	PKG 25	MOS					26-MAR-2007		
		HRS/MSC	9600	+25/-25			0		
	<b>REF:</b> NDT PART 6/57-10-18	AFL					0		
Y5700001 (s)	WINGLET - PERFORM VISUAL INSPECTION						PKG		
	PKG 4	MOS	12	+14d/-14d			13-JAN-2021		
		HRS/MSC	300	+25/-25			3778.2		
	<b>REF:</b> AMM 05-10-00	AFL					2986		
Y5700002 (s)	FLUX VALVE BRACKET - VISUALLY INSPECT FOR CRACKS. (EFFECTIVE ON AIRCRAFT 45-006 THRU 45-131 PRE SB 45-57-4)						PKG		
	PKG 4	MOS	12	+14d/-14d			13-JAN-2021		
		HRS/MSC	300	+25/-25			3778.2		
	<b>REF:</b> GENERIC NO REF	AFL					2986		
Y5710000 (s)	PERFORM WING - EXTERNAL VISUAL INSPECTION FROM BL 0.00 TO WS 260						PKG		
	PKG 16	MOS	48	+14d/-14d			08-MAR-2019		
		HRS/MSC	1200	+25/-25			3241.7		
	<b>REF:</b> AMM 05-10-00	AFL					2541		
Y5710180 (s)	EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION.						PKG		
	PKG 10	MOS	24	+14d/-14d			29-JAN-2020		
		HRS/MSC	600	+25/-25			3544.5		
	<b>REF:</b> AMM 05-10-00	AFL					2781		
Y5730013 (s)	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION.						PKG		
	PKG 4	MOS	12	+14d/-14d			13-JAN-2021		
		HRS/MSC	300	+25/-25			3778.2		
	<b>REF:</b> AMM 57-60-01	AFL					2986		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y5750067 (s)	PERFORM FLAP BRACKETS (P/N A159019-1 AND A159022-1) - DETAILED VISUAL INSPECTION. PKG 22	MOS	96	+14d/-14d			PKG 10-APR-2015 2017.3		
	REF: AMM 05-10-00	HRS/MSC AFL	2400	+25/-25					
Y5750069 (s)	FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS. PKG 4	MOS	12	+14d/-14d			PKG 13-JAN-2021 3778.2 2986		
	REF: AMM 05-10-00	HRS/MSC AFL	300	+25/-25					
Y5750071 (s)	PERFORM FLAPS - WITH FLAPS REMOVED, DETAILED VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS. PKG 16	MOS	48	+14d/-14d			PKG 08-MAR-2019 3241.7 2541		
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25					
<b>CHAPTER 71 POWER PLANT</b>									
5-19-00-Q7110004-LEFT	TAP TEST NO. 1 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)	MOS					07-AUG-2018 3058.3 2403	6058.3	6158.3
	REF: AMM 71-10-01	HRS/MSC AFL	3000	+100/-100					
5-19-00-Q7110004-RIGHT	TAP TEST NO. 2 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)	MOS					07-AUG-2018 3058.3 2403	6058.3	6158.3
	REF: AMM 71-10-01	HRS/MSC AFL	3000	+100/-100					
5-19-00-R7100032	L/H ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION.	MOS					08-MAR-2019 3241.7 2541		
<b>NOT APPLICABLE</b>	REF: AMM 71-10-03	HRS/MSC AFL	N/A		-33.4				
5-19-01-V7120074L	LEFT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (REFER TO 71-00-01.)	MOS					07-AUG-2018 3058.3 2403		
<b>AIRWORTHINESS</b>	REF: AMM 71-20-00	HRS/MSC AFL	E/C		N:0 N:0 N:0				



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-01-V7120074R	RIGHT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (REFER TO 71-00-01.)								
	4571408525-003	MOS		N:0			07-AUG-2018		
<b>AIRWORTHINESS</b>	SN-UNKNOWN	HRS/MSC	E/C	N:0			3058.3		
	REF: AMM 71-20-00	AFL		N:0			2403		
711001	NO. 1 ENGINE FORWARD MOUNT								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-20-00	AFL		N:0			0		
711002	NO. 2 ENGINE FORWARD MOUNT								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120002	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS					26-MAR-2007		
		HRS/MSC	N/A				0		
	REF: AMM 71-20-00	AFL					0		
7120002	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS								
		MOS					26-MAR-2007		
		HRS/MSC	N/A				0		
	REF: AMM 71-20-00	AFL					0		
+ 7120002	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS					26-MAR-2007		
		HRS/MSC	N/A				0		
	REF: AMM 71-20-00	AFL					0		
+ 7120002	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS					26-MAR-2007		
		HRS/MSC	N/A				0		
	REF: AMM 71-20-00	AFL					0		
+ 7120002	NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS								
		MOS					26-MAR-2007		
		HRS/MSC	N/A				0		
	REF: AMM 71-20-00	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7120002	NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC	N/A				0		
		AFL					0		
+ 7120002	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC	N/A				0		
		AFL					0		
+ 7120002	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC	N/A				0		
		AFL					0		
7120004	REPLACE ALL FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSINGS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC	15000	+25/-25			0	15000	15025
<b>LIFE LIMIT</b>		AFL					0		
+ 7120004	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING	MOS					26-MAR-2007		
	PN			N:0			0	15000	
	SN-UNKNOWN	HRS/MSC	15000	N:0			0		
<b>LIFE LIMIT</b>	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120004	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING	MOS					26-MAR-2007		
	PN			N:0			0	15000	
	SN-UNKNOWN	HRS/MSC	15000	N:0			0		
<b>LIFE LIMIT</b>	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120004	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING	MOS					26-MAR-2007		
	PN			N:0			0	15000	
	SN-UNKNOWN	HRS/MSC	15000	N:0			0		
<b>LIFE LIMIT</b>	REF: AMM 71-20-00	AFL		N:0			0		
+ 7120004	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING	MOS					26-MAR-2007		
	PN			N:0			0	15000	
	SN-UNKNOWN	HRS/MSC	15000	N:0			0		
<b>LIFE LIMIT</b>	REF: AMM 71-20-00	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120004	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	15000	N:0			0	15000	
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
+ 7120004	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	15000	N:0			0	15000	
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
+ 7120005	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
7120005	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
		MOS					26-MAR-2007		
		HRS/MSC	N/A				0		
	<b>REF: AMM 71-20-00</b>	AFL					0		
+ 7120005	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
+ 7120005	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
+ 7120005	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	N/A	N:0			0		
	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7120005	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS						26-MAR-2007	
	REF: AMM 71-20-00	HRS/MSC	N/A					0	
		AFL						0	
		APH						0	
+ 7120005	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS		N:0				26-MAR-2007	
	PN	HRS/MSC	N/A	N:0				0	
	SN-UNKNOWN	AFL		N:0				0	
	REF: AMM 71-20-00								
+ 7120005	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS		N:0				26-MAR-2007	
	PN	HRS/MSC	N/A	N:0				0	
	SN-UNKNOWN	AFL		N:0				0	
	REF: AMM 71-20-00								
+ 7120006	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS	MOS		N:0				26-MAR-2007	
	PN	HRS/MSC	N/A	N:0				0	
	SN-UNKNOWN	AFL		N:0				0	
	REF: AMM 71-20-00								
+ 7120006	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS	MOS		N:0				26-MAR-2007	
	PN	HRS/MSC	N/A	N:0				0	
	SN-UNKNOWN	AFL		N:0				0	
	REF: AMM 71-20-00								
+ 7120006	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS		N:0				26-MAR-2007	
	PN	HRS/MSC	N/A	N:0				0	
	SN-UNKNOWN	AFL		N:0				0	
	REF: AMM 71-20-00								
+ 7120006	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS		N:0				26-MAR-2007	
	PN	HRS/MSC	N/A	N:0				0	
	SN-UNKNOWN	AFL		N:0				0	
	REF: AMM 71-20-00								

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120006	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			26-MAR-2007 0 0		
+ 7120006	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			26-MAR-2007 0 0		
+ 7120006	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			26-MAR-2007 0 0		
+ 7120006	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			26-MAR-2007 0 0		
712005	NO. 1 ENGINE AFT MOUNT ISOLATOR ASSEMBLY LM-833-SA18 LK1347 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
712006	NO. 2 ENGINE AFT MOUNT ISOLATOR ASSEMBLY LM-833-SA18 LK1126 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
+ 7120069	NO. 1 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS REF: AMM 71-20-00	MOS HRS/MSC AFL	3000	+100/-100			07-AUG-2018 3058.3 2403	6058.3	6158.3
7120069	NO. 1 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS REF: AMM 71-20-00	MOS HRS/MSC AFL	3000	+100/-100	-58.3		07-AUG-2018 3058.3 2403	6000	6100

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120069	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-AUG-2018		
	REF: AMM 71-20-00	HRS/MSC AFL	3000	+100/-100			3058.3 2403	6058.3	6158.3
+ 7120069	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-AUG-2018		
	REF: AMM 71-20-00	HRS/MSC AFL	3000	+100/-100			3058.3 2403	6058.3	6158.3
+ 7120069	NO. 2 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-AUG-2018		
	REF: AMM 71-20-00	HRS/MSC AFL	3000	+100/-100			3058.3 2403	6058.3	6158.3
7120069	NO. 2 ENGINE ALL ISOLATORS - PERFORM VISUAL INSPECTION OF ISOLATORS AND ASSOCIATED PARTS	MOS					07-AUG-2018		
	REF: AMM 71-20-00	HRS/MSC AFL	3000	+100/-100		-58.3	3058.3 2403	6000	6100
+ 7120069	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-AUG-2018		
	REF: AMM 71-20-00	HRS/MSC AFL	3000	+100/-100			3058.3 2403	6058.3	6158.3
+ 7120069	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-AUG-2018		
	REF: AMM 71-20-00	HRS/MSC AFL	3000	+100/-100			3058.3 2403	6058.3	6158.3
712007	NO. 1 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY	MOS					26-MAR-2007		
	LM-833-45	HRS/MSC	O/C				0		
	LK3401	AFL					0		
	REF: AMM 71-20-00						0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120070	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0	6000	6100
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
7120070	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
		MOS					26-MAR-2007		
		HRS/MSC	6000	+100/-100			0	6000	6100
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL							
+ 7120070	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0	6000	6100
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
+ 7120070	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0	6000	6100
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
+ 7120070	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0	6000	6100
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
7120070	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
		MOS					26-MAR-2007		
		HRS/MSC	6000	+100/-100			0	6000	6100
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL							
+ 7120070	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0	6000	6100
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		
+ 7120070	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS								
	PN	MOS		N:0			26-MAR-2007		
	SN-UNKNOWN	HRS/MSC	6000	+100/-100	N:0		0	6000	6100
<b>LIFE LIMIT</b>	<b>REF: AMM 71-20-00</b>	AFL		N:0			0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120073	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
7120073	NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC AFL APH	6000	+100/-100			0 0 0	6000	6100
+ 7120073	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
7120073	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
+ 7120073	NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
7120073	NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS	MOS					26-MAR-2007		
	REF: AMM 71-20-00	HRS/MSC AFL APH	6000	+100/-100			0 0 0	6000	6100
+ 7120073	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-AUG-2018		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			3058.3 2403	9058.3	9158.3

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7120073	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS  REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+100/-100			26-MAR-2007 0 0	6000	6100
712008	NO. 2 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY  LM-833-45 LK3294 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
712009	NO. 1 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY  LM-833-45 LK3283 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
712010	NO. 2 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY  LM-833-45 LK3395 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
712045	NO. 1 ENGINE AFT MOUNT  4571200011-003 CDF 961 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
712046	NO. 2 ENGINE AFT MOUNT  4571200011-003 CDF 918 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
716005	NO. 1 ENGINE INLET NACELLE  PN SN-UNKNOWN REF: AMM 71-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
716006	NO. 2 ENGINE INLET NACELLE  2652000V25-003 406RH REF: AMM 71-10-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			24-APR-2018 2992.4 2348		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN1	NO. 1 ENGINE								
71.EN1	3060082-6 P-116817C REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C						
71EN2	NO. 2 ENGINE								
71.EN2	3060082-6 P-116818C REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C						
P7120001 (s)	PERFORM * FORWARD ENGINE MOUNT - EDDY CURRENT INSPECTION.						PKG		
	PKG 25	MOS HRS/MSC AFL	9600				26-MAR-2007 0 0		
<b>AIRWORTHINESS</b>	REF: NDT PART 6/71-10-01								
Y7100002 (s)	LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING.						PKG		
	PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			29-JAN-2020 3544.5 2781		
REF: AMM 05-10-00									
Y7110000 (s)	ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION.						PKG		
	PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			29-JAN-2020 3544.5 2781		
REF: AMM 05-10-00									
Y7110001 (s)	ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION.						PKG		
	PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			29-JAN-2020 3544.5 2781		
REF: AMM 05-10-00									
Y7110002 (s)	ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION.						PKG		
	PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			29-JAN-2020 3544.5 2781		
REF: AMM 05-10-00									
Y7110003 (s)	ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION.						PKG		
	PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			29-JAN-2020 3544.5 2781		
REF: AMM 05-10-00									

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y7120000 (s)	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION. PKG 3 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 13-JAN-2021 3778.2 2986		
<b>ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116817C Part # 3060084-2</b>									
710100	NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC			N:0 N:0 N:0		19-DEC-2006 0 0		
+ 710130 (s)	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS. PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50/-300			PKG 27-JUL-2020 3663.9 2882		
+ 710140 (s)	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B) PKG 0 REF: See Workcard	MOS HRS/MSC ENC	800	+50/-300			PKG 27-JUL-2020 3663.9 2882		
+ 714010 (s)	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50/-300			PKG 27-JUL-2020 3663.9 2882		
+ 715010 (s)	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50/-300			PKG 27-JUL-2020 3663.9 2882		
<b>ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116818C Part # 3060084-2</b>									
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC			N:0 N:0 N:0		19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710130 (s)	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.						PKG		
	PKG 0	MOS						27-JUL-2020	
		HRS/MSC	800	+50/-300				3663.9	
	REF: LMM 72-00-00	ENC						2882	
+ 710140 (s)	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)						PKG		
	PKG 0	MOS						27-JUL-2020	
		HRS/MSC	800	+50/-300				3663.9	
	REF: See Workcard	ENC						2882	
+ 714010 (s)	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE						PKG		
	PKG 0	MOS						27-JUL-2020	
		HRS/MSC	800	+50/-300				3663.9	
	REF: LMM 72-00-00	ENC						2882	
+ 715010 (s)	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING						PKG		
	PKG 0	MOS						27-JUL-2020	
		HRS/MSC	800	+50/-300				3663.9	
	REF: LMM 72-00-00	ENC						2882	

CHAPTER 72		ENGINE	
ENGINE NO. 1	Model : TFE731-20BR-1B	Serial # P-116817C	Part # 3060084-2
72-00-00-200-006	NO. 1 ENGINE - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION		
		MOS	
		HRS/MSC	A/R
	REF: LMM 72-00-00	ENC	
			19-DEC-2006
			0
			0
72-00-00-200-007	NO. 1 ENGINE - ACCIDENT OR INCIDENT		
		MOS	
		HRS/MSC	A/R
	REF: LMM 72-00-00	ENC	
			19-DEC-2006
			0
			0
72-00-00-200-008	NO. 1 ENGINE - LIGHTING STRIKE		
		MOS	
		HRS/MSC	A/R
	REF: LMM 72-00-00	ENC	
			19-DEC-2006
			0
			0

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-009	NO. 1 ENGINE - OVERTEMPERATURE	MOS					19-DEC-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-010	NO. 1 ENGINE - SEVERE HAILSTORM, FOD, AND/OR BIRD STRIKE	MOS					19-DEC-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-011	NO. 1 ENGINE - OVERSPEED	MOS					19-DEC-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-012	NO. 1 ENGINE - LPC1 BLADE BORESCOPE	MOS					19-DEC-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-013	NO. 1 ENGINE - HP IMPELLER BORESCOPE	MOS					19-DEC-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-014	NO. 1 ENGINE - NO. 4 AND NO.5 BEARING/SEAL RUNNER FAILURE	MOS					19-DEC-2006		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 72-00-00-550-005-A01-1	NO. 1 ENGINE - PERFORM STORAGE OF UNINSTALLED ENGINE IN AN UNSEALED PACKING STORED IN A CONTROLLED ENVIRONMENT FOR UP TO 60 DAYS.	MOS					19-DEC-2006		
<b>STORAGE &amp; PRESERVATION</b>	REF:	HRS/MSC	A/R				0		
		ENC					0		
+ 72-00-00-550-005-A01-10	NO. 1 ENGINE - PERFORM PRESERVATION EXTENSION OR PRESERVATION AFTER EXPIRED PERIODS	MOS					19-DEC-2006		
<b>STORAGE &amp; PRESERVATION</b>	REF:	HRS/MSC	A/R				0		
		ENC					0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-550-005-A01-2	NO. 1 ENGINE - PERFORM STORAGE OF UNINSTALLED ENGINE IN SEALED PACKING STORED IN A CONTROLLED ENVIRONMENT FOR UP TO 2 YEARS.							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-3	NO. 1 ENGINE - PERFORM STORAGE OF UNINSTALLED ENGINE IN A SEALED/PRESSURIZED PACKING IN A CONTROLLED OR AN UNCONTROLLED ENVIRONMENT FOR INDEFINITE TIME.							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-4	NO. 1 ENGINE - PERFORM STORAGE OF INSTALLED ENGINE STORED IN AN UNCONTROLLED ENVIRONMENT FOR INDEFINITE TIME.							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-5	NO. 1 ENGINE - PERFORM STORAGE OF INSTALLED ENGINE STORED IN AN UNCONTROLLED ENVIRONMENT FOR UP TO 2 YEARS							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-6	NO. 1 ENGINE - DISASSEMBLE ENGINE TO INSPECT ALL INTERNAL BEARINGS, GEARS AND HOUSING FOR CORROSION AND REPLACE/SCRAP BEARINGS AS NECESSARY							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-7	NO. 1 ENGINE - SUBMIT SOAP SAMPLE USING OIL OBTAINED FROM TGB OR AGB BEFORE OPERATING ENGINE							04-MAY-2020	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						3603.5	
		HRS/MSC	A/R					2824	
		ENC							
+ 72-00-00-550-005-A01-8	NO. 1 ENGINE - PRESERVATION VALIDATION REQUIREMENTS FOR CONTINUED STORAGE							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-550-005-A01-9	NO. 1 ENGINE - RE-ACTIVATE ENGINE AND RETURN TO SERVICE OR EXTEND STORAGE	MOS						19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-009-A01	NO. 1 ENGINE - PERFORM AIRCRAFT AND ENGINE FOR EXTERNALS AND COMPRESSOR RINSE	MOS						19-DEC-2006	
	<b>REF:</b>	HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-808-A01	NO. 1 ENGINE - PERFORM DEPRESERVATION OF ENGINE	MOS						03-AUG-2018	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	HRS/MSC	A/R					3058.3	
		ENC						2403	
+ 72-00-00-550-809-A01	NO. 1 ENGINE - PERFORM STORAGE OF ENGINE	MOS						19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	HRS/MSC	A/R					0	
		ENC						0	
72-70-04-900-801-A01	NO. 1 ENGINE - NO. 1 FAN STATOR VANE ASSEMBLY	MOS						03-AUG-2018	
	3060378-1	HRS/MSC	O/C	N:0				3058.3	
	SN-UNKNOWN	ENC		N:0				2403	
	<b>REF:</b> See Workcard								
72-70-04-900-801-A02	NO. 1 ENGINE - NO. 2 FAN STATOR VANE ASSEMBLY	MOS						03-AUG-2018	
	3060378-1	HRS/MSC	O/C	N:0				3058.3	
	SN-UNKNOWN	ENC		N:0				2403	
	<b>REF:</b>								
72-70-04-900-801-A03	NO. 1 ENGINE - NO. 3 FAN STATOR VANE ASSEMBLY	MOS						03-AUG-2018	
	3060378-1	HRS/MSC	O/C	N:0				3058.3	
	SN-UNKNOWN	ENC		N:0				2403	
	<b>REF:</b>								
72-70-04-900-801-A04	NO. 1 ENGINE - NO. 4 FAN STATOR VANE ASSEMBLY	MOS						03-AUG-2018	
	3060378-1	HRS/MSC	O/C	N:0				3058.3	
	SN-UNKNOWN	ENC		N:0				2403	
	<b>REF:</b>								



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A05	NO. 1 ENGINE - NO. 5 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A06	NO. 1 ENGINE - NO. 6 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A07	NO. 1 ENGINE - NO. 7 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A08	NO. 1 ENGINE - NO. 8 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A09	NO. 1 ENGINE - NO. 9 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A10	NO. 1 ENGINE - NO. 10 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A11	NO. 1 ENGINE - NO. 11 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A12	NO. 1 ENGINE - NO. 12 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A13	NO. 1 ENGINE - NO. 13 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A14	NO. 1 ENGINE - NO. 14 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A15	NO. 1 ENGINE - NO. 15 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A16	NO. 1 ENGINE - NO. 16 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A17	NO. 1 ENGINE - NO. 17 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A18	NO. 1 ENGINE - NO. 18 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A19	NO. 1 ENGINE - NO. 19 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A20	NO. 1 ENGINE - NO. 20 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A21	NO. 1 ENGINE - NO. 21 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A22	NO. 1 ENGINE - NO. 22 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A23	NO. 1 ENGINE - NO. 23 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A24	NO. 1 ENGINE - NO. 24 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A25	NO. 1 ENGINE - NO. 25 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A26	NO. 1 ENGINE - NO. 26 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A27	NO. 1 ENGINE - NO. 27 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A28	NO. 1 ENGINE - NO. 28 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A29	NO. 1 ENGINE - NO. 29 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A30	NO. 1 ENGINE - NO. 30 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A31	NO. 1 ENGINE - NO. 31 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A32	NO. 1 ENGINE - NO. 32 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A33	NO. 1 ENGINE - NO. 33 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A34	NO. 1 ENGINE - NO. 34 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A35	NO. 1 ENGINE - NO. 35 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
72-70-04-900-801-A36	NO. 1 ENGINE - NO. 36 FAN STATOR VANE ASSEMBLY 3060378-1 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A37	NO. 1 ENGINE - NO. 37 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A38	NO. 1 ENGINE - NO. 38 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A39	NO. 1 ENGINE - NO. 39 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A40	NO. 1 ENGINE - NO. 40 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-AS-720005	NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	3000	+100			03-AUG-2018 3058.3 2403	(6058.3) 6058.3	6158.3
72-AS-720006 (s)	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS REF: GENERIC NO REF	MOS HRS/MSC ENC	3000	+100/-100			06-AUG-2018 3058.3 0		
72-AS-720007	NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200			19-DEC-2006 0 0	(6000) 6000	6200
72-AS-720008 (s)	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS REF: See Workcard	MOS HRS/MSC ENC	6000	+200/-200			19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-AS-720010	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)  REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R					17-SEP-2018 3085.3 2428	
72-AS-720011	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)  REF: LMM 73-21-02	MOS HRS/MSC ENC	A/R					27-JUL-2020 3663.9 2882	
720110	NO. 1 ENGINE - ACCESSORY GEARBOX 3060827-2 S-2485 REF: LMM 72-60-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
720244	NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
720245	NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
722001	NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY 70060157-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				03-AUG-2018 3058.3 2403	
723002	NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
+ 723010 (s)	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50/-100				PKG 03-AUG-2018 3058.3 2403	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723011	NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723012	NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723013	NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723014	NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723081	NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723090	NO. 1 ENGINE - LOW PRESSURE 3RD STAGE AXIAL COMPRESSOR ROTOR PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725007	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 72-50-07	MOS HRS/MSC ENC	A/R	N:0 N:0 N:0			19-DEC-2006 0 0		
725010	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060625-1 060322901955 LIFE LIMIT	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		(12000) 12000

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725017	NO. 1 ENGINE - HPT SHROUD SLEEVE								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
<b>CUSTOMER CODE</b>	<b>REF: LMM 72-50-07</b>	ENC		N:0			0		
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								
	3060611-1	MOS		N:0			19-DEC-2006		
	060322900770	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: LMM 72-50-04</b>	ENC	12000	N:0			0	(12000)	12000
725021	NO. 1 ENGINE - 2ND-STAGE LPT NOZZLE RETAINER								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
<b>CUSTOMER CODE</b>	<b>REF: LMM 72-50-04</b>	ENC		N:0			0		
725022	NO. 1 ENGINE - 2ND-STAGE LPT NOZZLE SHROUD								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
<b>CUSTOMER CODE</b>	<b>REF: LMM 72-50-04</b>	ENC		N:0			0		
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								
	3060671-2	MOS		N:0			19-DEC-2006		
	060322901728	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: LMM 72-50-04</b>	ENC	12000	N:0			0	(12000)	12000
725031	NO. 1 ENGINE - 3RD-STAGE LTP BLADES								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
<b>CUSTOMER CODE</b>	<b>REF: LMM 72-50-04</b>	ENC		N:0			0		
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								
	3060841-1	MOS		N:0			19-DEC-2006		
	061217200167	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: LMM 72-50-07</b>	ENC	10000	N:0			0	(10000)	10000
725044	NO. 1 ENGINE - FIRST-STAGE LOW PRESSURE TURBINE NOZZLE ASSEMBLY - AFT DEFLECTOR								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF:</b>	ENC		N:0			0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725050	NO. 1 ENGINE - FAN DISC 3060287-2 061365106779 LIFE LIMIT	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			19-DEC-2006 0 0	(20000) 20000	
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060372-1 060316002121 LIFE LIMIT	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			19-DEC-2006 0 0	(10000) 10000	
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060373-1 060316001475 LIFE LIMIT	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			19-DEC-2006 0 0	(10000) 10000	
725071	NO. 1 ENGINE - COMBUSTION LINER 3060766-1 SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-AUG-2018 3058.3 2403		
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060374-1 060316002084 LIFE LIMIT	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			19-DEC-2006 0 0	(10000) 10000	
725081	NO. 1 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075326-5 060350106524 LIFE LIMIT	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			19-DEC-2006 0 0	(20000) 20000	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 06P30656 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER 3060371-1 060322903631 REF: LMM 72-50-06	MOS HRS/MSC ENC	8000	N:0 N:0 N:0			19-DEC-2006 0 0	(8000) 8000	
725130	NO. 1 ENGINE - FAN SPINNER 3060156-2 062784300443 REF: LMM 72-70-01	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			19-DEC-2006 0 0	(20000) 20000	
725140	NO. 1 ENGINE - FAN DRIVE SHAFT 3060180-2 061366304325 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725141	NO. 1 ENGINE - FAN ROLLER BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725155-01	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 1 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-02	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 2 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-03	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 3 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725155-04	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 4 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C					03-AUG-2018 3058.3 2403	
725155-05	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 5 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-06	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 6 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-07	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 7 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-08	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 8 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-09	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 9 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-10	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 10 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-11	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 11 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725155-12	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 12 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-13	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 13 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-14	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 14 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-15	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 15 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-16	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 16 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-17	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 17 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-18	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 18 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-19	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 19 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725155-20	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 20 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-21	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 21 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-22	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 22 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-23	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 23 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-24	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 24 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-25	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 25 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-26	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 26 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
725155-27	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 27 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725155-28	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 28 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-29	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 29 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C				03-AUG-2018 3058.3 2403		
725155-30	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 30 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C				03-AUG-2018 3058.3 2403		
725155-31	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 31 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-32	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 32 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-33	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 33 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-34	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 34 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		
725155-35	NO. 1 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 35 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL 3060698-1 060350103636	MOS HRS/MSC		N:0 N:0			19-DEC-2006 0		
<b>LIFE LIMIT</b>	<b>REF: LMM 72-70-03</b>	ENC	7000	N:0			0	<b>(7000) 7000</b>	
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3060366-3 06P34663	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2006 0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE 3060534-4 06P29337	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2006 0		
	<b>REF: See Workcard</b>	ENC		N:0			0		
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE 3060514-1 060322904214	MOS HRS/MSC		N:0 N:0			19-DEC-2006 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	10000	N:0			0	<b>(10000) 10000</b>	
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-6 06P28690	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2006 0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT 3060693-1 061756501416	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2006 0		
	<b>REF: LMM 72-50-04</b>	ENC		N:0			0		
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY 3060666-7 06P33821	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2006 0		
	<b>REF: LMM 72-50-04</b>	ENC		N:0			0		
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING 3060502-2 06P35423	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2006 0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING 3060599-2 06P32727 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL 3073765-12 061756501858 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726005	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY 3070093-16 06P35133 REF: LMM 72-60-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726010	NO. 1 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726011	NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726012	NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726013	NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726014	NO. 1 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726015	NO. 1 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726016	NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726017	NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727001	NO. 1 ENGINE - BYPASS FAN STATOR PN SN-UNKNOWN REF: LMM 72-70-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727005	NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727010 (s)	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. PKG 0 REF: See Workcard	MOS HRS/MSC ENC	1200	+100/-200			PKG 03-AUG-2018 3058.3 2403		
727101	NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY 3075675-2 16-152826-43028 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727102	NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727103	NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727105	NO. 1 ENGINE - HELICAL RING GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727107	NO. 1 ENGINE - SUN GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727203	NO. 1 ENGINE - NO. 3 BALL BEARING PN SN-UNKNOWN REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727210	NO. 1 ENGINE - PLANET HOUSING ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727210-1	NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727210-2	NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727210-3	NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
727210-4	NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
727210-5	NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
<b>ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116818C Part # 3060084-2</b>									
72-00-00-200-006	NO. 2 ENGINE - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R					19-DEC-2006 0 0	
72-00-00-200-007	NO. 2 ENGINE - ACCIDENT OR INCIDENT REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R					19-DEC-2006 0 0	
72-00-00-200-008	NO. 2 ENGINE - LIGHTING STRIKE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R					19-DEC-2006 0 0	
72-00-00-200-009	NO. 2 ENGINE - OVERTEMPERATURE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R					19-DEC-2006 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-010	NO. 2 ENGINE - SEVERE HAILSTORM, FOD, AND/OR BIRD STRIKE	MOS						19-DEC-2006	
	REF: LMM 72-00-00	HRS/MSC	A/R					0	
		ENC						0	
72-00-00-200-011	NO. 2 ENGINE - OVERSPEED	MOS						19-DEC-2006	
	REF: LMM 72-00-00	HRS/MSC	A/R					0	
		ENC						0	
72-00-00-200-012	NO. 2 ENGINE - LPC1 BLADE BORESCOPE	MOS						19-DEC-2006	
	REF: LMM 72-00-00	HRS/MSC	A/R					0	
		ENC						0	
72-00-00-200-013	NO. 2 ENGINE - HP IMPELLER BORESCOPE	MOS						19-DEC-2006	
	REF: LMM 72-00-00	HRS/MSC	A/R					0	
		ENC						0	
72-00-00-200-014	NO. 2 ENGINE - NO. 4 AND NO.5 BEARING/SEAL RUNNER FAILURE	MOS						19-DEC-2006	
	REF: LMM 72-00-00	HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-1	NO. 2 ENGINE - PERFORM STORAGE OF UNINSTALLED ENGINE IN AN UNSEALED PACKING STORED IN A CONTROLLED ENVIRONMENT FOR UP TO 60 DAYS.	MOS						19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	REF:	HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-10	NO. 2 ENGINE - PERFORM PRESEREVATION EXTENSION OR PRESERVATION AFTER EXPIRED PERIODS	MOS						19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	REF:	HRS/MSC	A/R					0	
		ENC						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-550-005-A01-2	NO. 2 ENGINE - PERFORM STORAGE OF UNINSTALLED ENGINE IN SEALED PACKING STORED IN A CONTROLLED ENVIRONMENT FOR UP TO 2 YEARS.							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-3	NO. 2 ENGINE - PERFORM STORAGE OF UNINSTALLED ENGINE IN A SEALED/PRESSURIZED PACKING IN A CONTROLLED OR AN UNCONTROLLED ENVIRONMENT FOR INDEFINITE TIME.							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-4	NO. 2 ENGINE - PERFORM STORAGE OF INSTALLED ENGINE STORED IN AN UNCONTROLLED ENVIRONMENT FOR INDEFINITE TIME.							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-5	NO. 2 ENGINE - PERFORM STORAGE OF INSTALLED ENGINE STORED IN AN UNCONTROLLED ENVIRONMENT FOR UP TO 2 YEARS							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-6	NO. 2 ENGINE - DISASSEMBLE ENGINE TO INSPECT ALL INTERNAL BEARINGS, GEARS AND HOUSING FOR CORROSION AND REPLACE/SCRAP BEARINGS AS NECESSARY							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-7	NO. 2 ENGINE - SUBMIT SOAP SAMPLE USING OIL OBTAINED FROM TGB OR AGB BEFORE OPERATING ENGINE							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-005-A01-8	NO. 2 ENGINE - PRESERVATION VALIDATION REQUIREMENTS FOR CONTINUED STORAGE							19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-550-005-A01-9	NO. 2 ENGINE - RE-ACTIVATE ENGINE AND RETURN TO SERVICE OR EXTEND STORAGE	MOS						19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-009-A01	NO. 2 ENGINE - PERFORM AIRCRAFT AND ENGINE FOR EXTERNALS AND COMPRESSOR RINSE	MOS						19-DEC-2006	
	<b>REF:</b>	HRS/MSC	A/R					0	
		ENC						0	
+ 72-00-00-550-808-A01	NO. 2 ENGINE - PERFORM DEPRESERVATION OF ENGINE	MOS						06-AUG-2018	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	HRS/MSC	A/R					3058.3	
		ENC						2403	
+ 72-00-00-550-809-A01	NO. 2 ENGINE - PERFORM STORAGE OF ENGINE	MOS						19-DEC-2006	
<b>STORAGE &amp; PRESERVATION</b>	<b>REF:</b>	HRS/MSC	A/R					0	
		ENC						0	
72-50-07-900-801-A01	NO. 2 ENGINE - HPT NOZZLE ASSEMBLY	MOS						06-AUG-2018	
	3060840-3	HRS/MSC	O/C	O:0				3058.3	
	SN-UNKNOWN	ENC		O:0				2403	
	<b>REF:</b> See Workcard								
72-70-04-900-801-A02	NO. 2 ENGINE - NO. 2 FAN STATOR VANE ASSEMBLY	MOS						19-DEC-2006	
	PN	HRS/MSC	O/C	N:0				0	
	SN-UNKNOWN	ENC		N:0				0	
	<b>REF:</b>			N:0				0	
72-70-04-900-801-A03	NO. 2 ENGINE - NO. 3 FAN STATOR VANE ASSEMBLY	MOS						19-DEC-2006	
	PN	HRS/MSC	O/C	N:0				0	
	SN-UNKNOWN	ENC		N:0				0	
	<b>REF:</b>			N:0				0	
72-70-04-900-801-A04	NO. 2 ENGINE - NO. 4 FAN STATOR VANE ASSEMBLY	MOS						19-DEC-2006	
	PN	HRS/MSC	O/C	N:0				0	
	SN-UNKNOWN	ENC		N:0				0	
	<b>REF:</b>			N:0				0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A05	NO. 2 ENGINE - NO. 5 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A06	NO. 2 ENGINE - NO. 6 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A07	NO. 2 ENGINE - NO. 7 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A08	NO. 2 ENGINE - NO. 8 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A09	NO. 2 ENGINE - NO. 9 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A10	NO. 2 ENGINE - NO. 10 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A11	NO. 2 ENGINE - NO. 11 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A12	NO. 2 ENGINE - NO. 12 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A13	NO. 2 ENGINE - NO. 13 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A14	NO. 2 ENGINE - NO. 14 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A15	NO. 2 ENGINE - NO. 15 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A16	NO. 2 ENGINE - NO. 16 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A17	NO. 2 ENGINE - NO. 17 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A18	NO. 2 ENGINE - NO. 18 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A19	NO. 2 ENGINE - NO. 19 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A20	NO. 2 ENGINE - NO. 20 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A21	NO. 2 ENGINE - NO. 21 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A22	NO. 2 ENGINE - NO. 22 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A23	NO. 2 ENGINE - NO. 23 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A24	NO. 2 ENGINE - NO. 24 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A25	NO. 2 ENGINE - NO. 25 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A26	NO. 2 ENGINE - NO. 26 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A27	NO. 2 ENGINE - NO. 27 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A28	NO. 2 ENGINE - NO. 28 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A29	NO. 2 ENGINE - NO. 29 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A30	NO. 2 ENGINE - NO. 30 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A31	NO. 2 ENGINE - NO. 31 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A32	NO. 2 ENGINE - NO. 32 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A33	NO. 2 ENGINE - NO. 33 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A34	NO. 2 ENGINE - NO. 34 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A35	NO. 2 ENGINE - NO. 35 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
72-70-04-900-801-A36	NO. 2 ENGINE - NO. 36 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-70-04-900-801-A37	NO. 2 ENGINE - NO. 37 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A38	NO. 2 ENGINE - NO. 38 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A39	NO. 2 ENGINE - NO. 39 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-70-04-900-801-A40	NO. 2 ENGINE - NO. 40 FAN STATOR VANE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
72-AS-720005	NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	3000	+100			06-AUG-2018 3058.3 2403	(6058.3) 6058.3	6158.3
72-AS-720006 (s)	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS REF: GENERIC NO REF	MOS HRS/MSC ENC	3000	+100/-100			06-AUG-2018 3058.3 0		
72-AS-720007	NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200			19-DEC-2006 0 0	(6000) 6000	6200
72-AS-720008 (s)	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS REF: See Workcard	MOS HRS/MSC ENC	6000	+200/-200			19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-AS-720010	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)  REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R					17-SEP-2018 3085.3 2428	
72-AS-720011	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)  REF: LMM 73-21-02	MOS HRS/MSC ENC	A/R					27-JUL-2020 3663.9 2882	
720110	NO. 2 ENGINE - ACCESSORY GEARBOX 3060827-2 S-2489 REF: LMM 72-60-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
720244	NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
720245	NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
722001	NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY 70060157-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				06-AUG-2018 3058.3 2403	
723002	NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
+ 723010 (s)	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50/-100				PKG 06-AUG-2018 3058.3 2403	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723011	NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723012	NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723013	NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723014	NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723081	NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
723090	NO. 2 ENGINE - LOW PRESSURE 3RD STAGE AXIAL COMPRESSOR ROTOR PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725007	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY 3060840-3 SN-UNKNOWN REF: LMM 72-50-07	MOS HRS/MSC ENC	A/R	O:0 O:0 O:0			06-AUG-2018 3058.3 2403		
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060625-1 060322901413 REF: LMM 72-50-04	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		
LIFE LIMIT		ENC	12000	N:0			0	(12000) 12000	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725017	NO. 2 ENGINE - HPT SHROUD SLEEVE								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
<b>CUSTOMER CODE</b>	<b>REF: LMM 72-50-07</b>	ENC		N:0			0		
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								
	3060611-1	MOS		N:0			19-DEC-2006		
	060322901341	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: LMM 72-50-04</b>	ENC	12000	N:0			0	(12000)	12000
725021	NO. 2 ENGINE - 2ND-STAGE LPT NOZZLE RETAINER								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
<b>CUSTOMER CODE</b>	<b>REF: LMM 72-50-04</b>	ENC		N:0			0		
725022	NO. 2 ENGINE - 2ND-STAGE LPT NOZZLE SHROUD								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
<b>CUSTOMER CODE</b>	<b>REF: LMM 72-50-04</b>	ENC		N:0			0		
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								
	3060671-2	MOS		N:0			19-DEC-2006		
	060322901729	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: LMM 72-50-04</b>	ENC	12000	N:0			0	(12000)	12000
725031	NO. 2 ENGINE - 3RD-STAGE LTP BLADES								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
<b>CUSTOMER CODE</b>	<b>REF: LMM 72-50-04</b>	ENC		N:0			0		
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								
	3060841-1	MOS		N:0			19-DEC-2006		
	061217200212	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: LMM 72-50-07</b>	ENC	10000	N:0			0	(10000)	10000
725044	NO. 2 ENGINE - FIRST-STAGE LOW PRESSURE TURBINE NOZZLE ASSEMBLY - AFT DEFLECTOR								
	PN	MOS		N:0			19-DEC-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF:</b>	ENC		N:0			0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725050	NO. 2 ENGINE - FAN DISC 3060287-2 061365106769 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			19-DEC-2006 0 0	(20000) 20000	
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060599-2 06P35551 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			19-DEC-2006 0 0	(10000) 10000	
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060373-1 060316001476 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			19-DEC-2006 0 0	(10000) 10000	
725071	NO. 2 ENGINE - COMBUSTION LINER 3060766-1 06P14100 REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			06-AUG-2018 3058.3 2403		
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060374-1 060316002673 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			19-DEC-2006 0 0	(10000) 10000	
725081	NO. 2 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075326-5 060350104300 REF: LMM 72-30-04	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			19-DEC-2006 0 0	(20000) 20000	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 06P27000 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER 3060371-1 060322905594 REF: LMM 72-50-06	MOS HRS/MSC ENC	8000	N:0 N:0 N:0			19-DEC-2006 0 0	(8000) 8000	
725130	NO. 2 ENGINE - FAN SPINNER 3060156-2 062784300391 REF: LMM 72-70-01	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			19-DEC-2006 0 0	(20000) 20000	
725140	NO. 2 ENGINE - FAN DRIVE SHAFT 3060180-2 061366304328 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725141	NO. 2 ENGINE - FAN ROLLER BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725155-01	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 1 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-02	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 2 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-03	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 3 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725155-04	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 4 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-05	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 5 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-06	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 6 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-07	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 7 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-08	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 8 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-09	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 9 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-10	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 10 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-11	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 11 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725155-12	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 12 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-13	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 13 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-14	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 14 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-15	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 15 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-16	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 16 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-17	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 17 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-18	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 18 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-19	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 19 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725155-20	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 20 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-21	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 21 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-22	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 22 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-23	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 23 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-24	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 24 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-25	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 25 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-26	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 26 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-27	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 27 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725155-28	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 28 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-29	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 29 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-30	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 30 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-31	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 31 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-32	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 32 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-33	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 33 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-34	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 34 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
725155-35	NO. 2 ENGINE - 3RD STAGE LOW PRESSURE TURBINE ROTOR - NO. 35 BLADE 3061823-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL 3060698-1 060350108340 <b>REF:</b> LMM 72-70-03	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		(7000) 7000
<b>LIFE LIMIT</b>			7000						
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3060366-3 06P33214 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		
			O/C						
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE 3060534-4 06P32218 <b>REF:</b> See Workcard	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		
			O/C						
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE 3060514-1 060322904257 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		(10000) 10000
<b>LIFE LIMIT</b>			10000						
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-6 06P28141 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		
			O/C						
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT 3060693-1 061756501696 <b>REF:</b> LMM 72-50-04	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		
			O/C						
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY 3060666-7 06P33824 <b>REF:</b> LMM 72-50-04	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		
			O/C						
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING 3060502-2 06P35442 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			19-DEC-2006 0 0		
			O/C						

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING 3060372-1 060316002115 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL 3073765-12 061756501922 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726005	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY 3070093-16 06P35134 REF: LMM 72-60-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726010	NO. 2 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726011	NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726012	NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726013	NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
726014	NO. 2 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726015	NO. 2 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
726016	NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
726017	NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
727001	NO. 2 ENGINE - BYPASS FAN STATOR PN SN-UNKNOWN REF: LMM 72-70-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
727005	NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
727010 (s)	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. PKG 0 REF: See Workcard	MOS HRS/MSC ENC	1200	+100/-200				PKG 06-AUG-2018 3058.3 2403	
727101	NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY 3060457-1 16-152826-43037 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				06-AUG-2018 3058.3 2403	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727102	NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727103	NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727105	NO. 2 ENGINE - HELICAL RING GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727107	NO. 2 ENGINE - SUN GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727203	NO. 2 ENGINE - NO. 3 BALL BEARING PN SN-UNKNOWN REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727210	NO. 2 ENGINE - PLANET HOUSING ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727210-1	NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
727210-2	NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727210-3	NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
727210-4	NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
727210-5	NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
<b>CHAPTER 73 ENGINE FUEL AND CONTROL</b>									
733001	NO. 1 ENGINE FUEL FLOW TRANSDUCER PN SN-UNKNOWN REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
733002	NO. 2 ENGINE FUEL FLOW TRANSDUCER PN SN-UNKNOWN REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
733013	DUAL FUEL FLOW (DFFC) CONVERTER 10540B08F07 06121004A REF: AMM 73-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
733031	LEFT ENGINE FUEL TEMPERATURE BULB MS28034-3 N8930 REF: AMM 73-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733032	RIGHT ENGINE FUEL TEMPERATURE BULB MS28034-3 N8918 REF: AMM 73-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116817C Part # 3060084-2									
730110	NO. 1 ENGINE - FUEL CONTROL UNIT 3070800-37 18557 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
730120 (s)	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600				PKG 27-JUL-2020 3663.9 2882		
730130	NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY 3060760-4 2071 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
731001	NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY 3060759-1 1245 REF: LMM 73-21-02	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-AUG-2018 3058.3 2403		
731005-1	NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 000137100528 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-AUG-2018 3058.3 2403		
731005-10	NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 96-01371-464 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-AUG-2018 3058.3 2403		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-11	NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 980137100894 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				03-AUG-2018 3058.3 2403	
731005-12	NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 000137102779 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				03-AUG-2018 3058.3 2403	
731005-2	NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137102695 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				03-AUG-2018 3058.3 2403	
731005-3	NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 000137100532 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				03-AUG-2018 3058.3 2403	
731005-4	NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 000137102126 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				03-AUG-2018 3058.3 2403	
731005-5	NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 000137102140 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				03-AUG-2018 3058.3 2403	
731005-6	NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 10-163498-00103 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				03-AUG-2018 3058.3 2403	
731005-7	NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 000137102767 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				03-AUG-2018 3058.3 2403	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-8	NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137102159 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-AUG-2018 3058.3 2403		
731005-9	NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 96-01371-418 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-AUG-2018 3058.3 2403		
731015	NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR PN SN-UNKNOWN REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
731110	NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE 3070685-11 17078 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 2293 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
732102	NO. 1 ENGINE - RELIEF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
732120 (s)	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			PKG 27-JUL-2020 3663.9 2882		

ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116818C Part # 3060084-2

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
730110	NO. 2 ENGINE - FUEL CONTROL UNIT 3070800-47 18772 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	R:0 R:0 R:0				14-DEC-2018 3181.8 2505	
730120 (s)	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600					PKG 27-JUL-2020 3663.9 2882	
730130	NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY 3060760-4 2107 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
731001	NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY 3060759-1 0345 REF: LMM 73-21-02	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				06-AUG-2018 3058.3 2403	
731005-1	NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 980137101403 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				06-AUG-2018 3058.3 2403	
731005-10	NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137100248 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				06-AUG-2018 3058.3 2403	
731005-11	NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137100268 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				06-AUG-2018 3058.3 2403	
731005-12	NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137101536 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0				06-AUG-2018 3058.3 2403	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-2	NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137101132 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	0:0 0:0 0:0			06-AUG-2018 3058.3 2403		
731005-3	NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137101490 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	0:0 0:0 0:0			06-AUG-2018 3058.3 2403		
731005-4	NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137101533 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	0:0 0:0 0:0			06-AUG-2018 3058.3 2403		
731005-5	NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137101135 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	0:0 0:0 0:0			06-AUG-2018 3058.3 2403		
731005-6	NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137101501 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	0:0 0:0 0:0			06-AUG-2018 3058.3 2403		
731005-7	NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137101131 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	0:0 0:0 0:0			06-AUG-2018 3058.3 2403		
731005-8	NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137101115 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	0:0 0:0 0:0			06-AUG-2018 3058.3 2403		
731005-9	NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 010137101461 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	0:0 0:0 0:0			06-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731015	NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR PN SN-UNKNOWN REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
731110	NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE 3070685-11 17080 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 2285 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
732102	NO. 2 ENGINE - RELIEF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
732120 (s)	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100				PKG 27-JUL-2020 3663.9 2882	
<b>CHAPTER 74</b>	<b>IGNITION</b>								
743001	TAIL CONE RELAY (P13) PANEL PN SN-UNKNOWN REF: AMM 74-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
743001-1	EMERGENCY LIGHTING (P-51) RELAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
743005-1	K22 RELAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
743005-2	K61 RELAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
<b>ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116817C Part # 3060084-2</b>									
740110	NO. 1 ENGINE - IGNITION UNIT PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
+ 740140 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 0 REF: See Workcard	MOS HRS/MSC ENC	1600	+50/-100				PKG 03-AUG-2018 3058.3 2403	
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				03-AUG-2018 3058.3 2403	
+ 740160 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 0 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50/-100				PKG 03-AUG-2018 3058.3 2403	



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742011	NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
742012	NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
742020	NO. 1 ENGINE - IGNITION EXCITER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
<b>ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116818C Part # 3060084-2</b>									
740110	NO. 2 ENGINE - IGNITION UNIT PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		
+ 740140 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 0 REF: See Workcard	MOS HRS/MSC ENC	1600	+50/-100			PKG 06-AUG-2018 3058.3 2403		
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			06-AUG-2018 3058.3 2403		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 740160 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 0 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50/-100			PKG 06-AUG-2018 3058.3 2403		
742011	NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
742012	NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
742020	NO. 2 ENGINE - IGNITION EXCITER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
<b>CHAPTER 75 AIR</b>									
<b>ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116817C Part # 3060084-2</b>									
754210	NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
761310	NO. 1 ENGINE - SURGE BLEED VALVE 978812-7-1 12777 REF: See Workcard	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-AUG-2018 3058.3 2403		
<b>ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116818C Part # 3060084-2</b>									
754210	NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761310	NO. 2 ENGINE - SURGE BLEED VALVE 978812-7-1 12790 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:140 O:0 N:3058.3 O:0 N:2403 O:0			06-AUG-2018 3058.3 2403		
<b>CHAPTER 76</b>	<b>ENGINE CONTROLS</b>								
761013	THROTTLE CONTROL MODULE 69011-17 508 REF: AMM 76-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
761201	AFT LEFT THROTTLE CABLE 6676101001-041 SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-APR-2009 599.6		
761202	AFT RIGHT THROTTLE CABLE PN SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
761203	LEFT FORWARD THROTTLE CABLE PN SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
761204	RIGHT FORWARD THROTTLE CABLE PN SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
Y7600000 (s)	PERFORM ENGINE DEEC WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS - VISUAL INSPECTION PKG 15 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			08-MAR-2019 3241.7 2541		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y760001 (s)	PERFORM THRUST LEVER CONTROL MODULE - FUNCTIONAL TEST PKG 13 REF: AMM 76-10-02	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
Y7610007 (s)	PERFORM ENGINE CONTROL CABLES - VISUAL INSPECTION OF FORWARD AND AFT CABLE CONNECTION. PKG 14 REF: AMM 05-10-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 08-MAR-2019 3241.7 2541		
<b>ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116817C Part # 3060084-2</b>									
761001	NO. 1 ENGINE - NO. 1 SOLENOID ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
761002	NO. 1 ENGINE - NO. 2 SOLENOID ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE 109696-6-1 12405 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
761330	NO. 1 ENGINE - ENGINE (DEEC) COMPUTER 2118882-1008 116-AW0291 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
761330A	NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM 2118882-1008 116-AW0291 CUSTOMER CODE	MOS HRS/MSC ENC	1				31-DEC-2020 3776.6 2984	<b>31-JAN-2021</b>	
<b>ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116818C Part # 3060084-2</b>									

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761001	NO. 2 ENGINE - NO. 1 SOLENOID ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
761002	NO. 2 ENGINE - NO. 2 SOLENOID ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE 109696-6-1 12419 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
761330	NO. 2 ENGINE - ENGINE (DEEC) COMPUTER 2118882-1008 116-AW0293 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
761330A	NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM 2118882-1008 116-AW0293 REF: See Workcard	MOS HRS/MSC ENC	1				31-DEC-2020 3776.6 2984	31-JAN-2021	
<b>CUSTOMER CODE</b>									
<b>CHAPTER 77</b>	<b>ENGINE INDICATING</b>								
774001	ENGINE VIBRATION MONITOR BOX 241-241-000-501 AC19724 REF: AMM 77-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
774010	P36 RELAY BOX PN SN-UNKNOWN REF: AMM 77-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
774011	LEFT ENGINE VIBRATION ACCELEROMETER PN SN-UNKNOWN REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
774012	RIGHT ENGINE VIBRATION ACCELEROMETER PN SN-UNKNOWN REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
Y7741000 (s)	PERFORM ENGINE VIBRATION MONITORING SYSTEM - FUNCTIONAL TEST. PKG 21 REF: AMM 77-41-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 10-APR-2015 2017.3		

**ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116817C Part # 3060084-2**

770101	NO. 1 ENGINE - N1 MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
770110	NO. 1 ENGINE - N1 LEAD MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
771210	NO. 1 ENGINE - N1 COMPENSATOR 3060735-4 061309701027 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
771220	NO. 1 ENGINE - N2 MONOPOLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
772210	NO. 1 ENGINE - ITT HARNESS ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
<b>ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116818C Part # 3060084-2</b>									
770101	NO. 2 ENGINE - N1 MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
770110	NO. 2 ENGINE - N1 LEAD MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
771210	NO. 2 ENGINE - N1 COMPENSATOR 3060735-3 061309700940 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
771220	NO. 2 ENGINE - N2 MONOPOLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
772210	NO. 2 ENGINE - ITT HARNESS ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
<b>CHAPTER 78 EXHAUST</b>									
5-19-00-R7830007	PERFORM - THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RH THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST  REF: NDT PART 6/78-30-01	MOS HRS/MSC AFL APH	1200	+25/-25			30-MAR-2012  500.75	1700.75	1725.75

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783001	LEFT THRUST REVERSER LJ7830101-5 A30040414 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783002	RIGHT THRUST REVERSER LJ7830101-6 A30040414 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783025	TRANSFORMER/RECTIFIER ELECTRONIC CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783037	NO. 1 GPM HYDRAULIC CONTROL VALVE PN SN-UNKNOWN REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783038	NO. 2 GPM HYDRAULIC CONTROL VALVE PN SN-UNKNOWN REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783051	LEFT OUTBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783052	LEFT INBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783053	RIGHT INBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783054	RIGHT OUTBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783061	NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE PN SN-UNKNOWN REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783062	NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE PN SN-UNKNOWN REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783101	LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE R-9045-9 0955 REF: AMM 78-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783102	RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE R-9045-9 0960 REF: AMM 78-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783150	LEFT HAND INBOARD LATCHBOX ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-30	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783150A	LEFT HAND OUTBOARD LATCHBOX ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-30	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783151	RIGHT HAND INBOARD LATCHBOX ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-30	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783151A	RIGHT HAND OUTBOARD LATCHBOX ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-30	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783210	LEFT THRUST REVERSER CONTROL VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783211	RIGHT THRUST REVERSER CONTROL VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783220	NO. 1 ENGINE THROTTLE RETARD ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-40	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783221	NO. 2 ENGINE THROTTLE RETARD ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-40	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783301	LEFT THRUST REVERSER CONTROL BOX LJ7836706-3 00066 REF: AMM 78-33-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783302	RIGHT THRUST REVERSER CONTROL BOX LJ7836706-3 00218 REF: AMM 78-33-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783320	LEFT OUTBOARD THRUST REVERSER WIRE HARNESS PN SN-UNKNOWN REF: AMM 78-33-20	MOS HRS/MSC AFL	C/C	N:0 N:0 N:0			26-MAR-2007 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783321	LEFT INBOARD THRUST REVERSER WIRE HARNESS PN SN-UNKNOWN REF: AMM 78-33-20	MOS HRS/MSC AFL	C/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783322	RIGHT INBOARD THRUST REVERSER WIRE HARNESS PN SN-UNKNOWN REF: AMM 78-33-20	MOS HRS/MSC AFL	C/C	N:0 N:0 N:0			26-MAR-2007 0 0		
783323	RIGHT OUTBOARD THRUST REVERSER WIRE HARNESS PN SN-UNKNOWN REF: AMM 78-33-20	MOS HRS/MSC AFL	C/C	N:0 N:0 N:0			26-MAR-2007 0 0		
D7830078 (s)	PERFORM ** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - OPERATIONAL CHECK PKG 21 REF: AMM 78-32-40	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 10-APR-2015 2017.3		
H7830081 (s)	PERFORM THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION. PKG 21 REF: NDT PART 778-30-01	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 10-APR-2015 2017.3		
H7830082 (s)	PERFORM THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES. PKG 21 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-APR-2015 2017.3		
Y7830000 (s)	PERFORM EXHAUST NOZZLE - VISUAL INSPECTION PKG 21 REF: AMM 05-10-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 10-APR-2015 2017.3		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y7830001 (s)	PERFORM THRUST REVERSER INNER FAN DUCT ASSEMBLY - VISUAL INSPECTION. INSPECT FROM EXHAUST END ONLY						PKG		
	PKG 15	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 05-10-00	AFL						2541	
Y7830002 (s)	PERFORM THRUST REVERSER DOOR AND HINGE FITTINGS - VISUAL INSPECTION						PKG		
	PKG 15	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 05-10-00	AFL						2541	
Y7830003 (s)	PERFORM THRUST REVERSER PRIMARY ACTUATOR AND LATCH ASSEMBLY - VISUAL INSPECTION						PKG		
	PKG 15	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 05-10-00	AFL						2541	
Y7830004 (s)	PERFORM THRUST REVERSER HYDRAULIC CONTROL VALVE (HCV), THROTTLE RETARD ACTUATOR, AND ASSOCIATED PLUMBING - VISUAL INSPECTION						PKG		
	PKG 15	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 05-10-00	AFL						2541	
Y7830005 (s)	PERFORM THRUST REVERSER DOOR SEALS AND RETAINERS - VISUAL INSPECTION						PKG		
	PKG 15	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 05-10-00	AFL						2541	
Y7830006 (s)	PERFORM THRUST REVERSER WIRE HARNESS - VISUAL INSPECTION.						PKG		
	PKG 15	MOS	48	+14d/-14d				08-MAR-2019	
		HRS/MSC	1200	+25/-25				3241.7	
	REF: AMM 05-10-00	AFL						2541	
<b>CHAPTER 79</b>	<b>OIL</b>								
792037	NO. 1 OIL PRESSURE SWITCH								
	PN	MOS						26-MAR-2007	
	SN-UNKNOWN	HRS/MSC	O/C					0	
	REF: AMM 79-30-02	AFL						0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792038	NO. 2 OIL PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
793001	NO. 1 ENGINE OIL PRESSURE TRANSDUCER PN SN-UNKNOWN REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
793002	NO. 2 ENGINE OIL PRESSURE TRANSDUCER PN SN-UNKNOWN REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
793011	LEFT TEMPERATURE OIL BULB MS28034-3 N8937 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
793012	RIGHT TEMPERATURE OIL BULB MS28034-3 N8920 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
793013	APU TEMPERATURE OIL BULB PN SN-UNKNOWN REF: AMM 49-70-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				26-MAR-2007 0 0	
ENGINE NO. 1 Model : TFE731-20BR-1B Serial # P-116817C Part # 3060084-2									
790110	NO. 1 ENGINE - OIL PUMP 3060785-3 051405701047 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0				05-DEC-2016 2499.2 1974	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790130 (s)	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP) PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			PKG 27-JUL-2020 3663.9 2882		
790140 (s)	NO. 1 ENGINE - PERFORM OIL CHANGE PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200			PKG 07-AUG-2018 3058.3 2403		
790150 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600				PKG 27-JUL-2020 3663.9 2882		
790160 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION PKG 0 REF: See Workcard	MOS HRS/MSC ENC	150	+100			PKG 27-JUL-2020 3663.9 2882		
791001	NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR PN SN-UNKNOWN REF: LMM 79-10-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2006 0 0		
792002	NO. 1 ENGINE - AIR BREATHER VALVE ASSEMBLY CHANGE PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2006 0 0		
792005	NO. 1 ENGINE - OIL TANK ASSEMBLY PN SN-UNKNOWN REF: LMM 79-10-02	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2006 0 0		
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE PN SN-UNKNOWN REF: LMM 79-20-08	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792011	NO. 1 ENGINE - FUEL/OIL VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792012	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR PN SN-UNKNOWN REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792020	NO. 1 ENGINE - OIL CHECK VALVE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792220	NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY 160552-3 1575 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792230	NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY 160554-5 2276 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792240	NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY 160554-6 2252 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792260	NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE 158465-6 12341 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793064	NO. 1 ENGINE - TEMP BULB PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
+ 793315 (s)	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH PKG 0 REF: LMM 79-30-01	MOS HRS/MSC ENC	600	+50/-100			PKG 27-JUL-2020 3663.9 2882		
793316	NO. 1 ENGINE - THERMO LOCKOUT VALVE SWITCH ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
793320	NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY 3060709-4 2341 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2006 0 0		
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116818C Part # 3060084-2									
790110	NO. 2 ENGINE - OIL PUMP 3060785-3 071405700563 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			06-AUG-2018 3058.3 2403		
790130 (s)	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP) PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			PKG 27-JUL-2020 3663.9 2882		



# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790140 (s)	NO. 2 ENGINE - PERFORM OIL CHANGE PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200			PKG 07-AUG-2018 3058.3 2403		
790150 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600				PKG 27-JUL-2020 3663.9 2882		
790160 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION PKG 0 REF: See Workcard	MOS HRS/MSC ENC	150	+100			PKG 27-JUL-2020 3663.9 2882		
791001	NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR PN SN-UNKNOWN REF: LMM 79-10-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2006 0 0		
792002	NO. 2 ENGINE - AIR BREATHER VALVE ASSEMBLY CHANGE PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2006 0 0		
792005	NO. 2 ENGINE - OIL TANK ASSEMBLY PN SN-UNKNOWN REF: LMM 79-10-02	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2006 0 0		
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE 3060769-1 060645106911 REF: LMM 79-20-08	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2006 0 0		
792011	NO. 2 ENGINE - FUEL/OIL VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2006 0 0		

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792012	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR PN SN-UNKNOWN REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792020	NO. 2 ENGINE - OIL CHECK VALVE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792220	NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY 160552-3 1496 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792230	NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY 160554-5 2303 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792240	NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY 160554-6 2242 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
792250	NO. 2 ENGINE - PRESSURE BREATHER VALVE PN-UNKNOWN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C					29-JAN-2020 3544.5 2781	
792260	NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE 158465-6 12344 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
793064	NO. 2 ENGINE - TEMP BULB PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	

# Status Report

LEARJET 45 S/N 45-330 (N36GL): 3787.7 HRS, 2992 AFL as of 20-Jan-2021

Owner: GURLEY LEEP OLDSMOBILE-CADILLAC, INC. Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 27-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
+ 793315 (s)	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH PKG 0 REF: LMM 79-30-01	MOS HRS/MSC ENC	600	+50/-100				PKG 27-JUL-2020 3663.9 2882	
793316	NO. 2 ENGINE - THERMO LOCKOUT VALVE SWITCH ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
793320	NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY 3060709-4 2347 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				19-DEC-2006 0 0	
<b>CHAPTER 85</b>	<b>FUEL CELL SYSTEMS</b>								
859000	SUBMIT LOGBOOK ENTRIES FOR ELOGBOOK REF: GENERIC CUSTOM	MOS HRS/MSC AFL	A/R					26-MAR-2007 0 0	
<b>CHAPTER --</b>	<b>GENERAL</b>								
14CFR PART 47	PERFORM RECURRENT AIRCRAFT REGISTRATION REF: CFR 14 CFR PART 47	MOS HRS/MSC AFL	DUE					30-APR-2023 M	
Expiry Date: 30-APR-2023									