



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
052506A	INSPECT ELT SARSAT BEACON REGISTRATION				MTH 12-Mar-2015 HRS 972.4 LDG 613		24		31-Mar-2017	-29 m 5 d
										Over Due
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK						A/R			
055002	ACCOMPLISH OVERSPEED CHECK						A/R			
055003	ACCOMPLISH DANGEROUS AIR TURBULANCE CHECK						A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK						A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK						A/R			
055006	ACCOMPLISH TOWING WITH FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK						A/R			
055007	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK ENGAGED CHECK						A/R			
055008	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK DISENGAGED CHECK						A/R			
5-12-01 <i>051201</i>	INSPECTION DOCUMENT 01 KGYG				MTH 21-Jun-2018 HRS 1712.1 LDG 1025		450		2162.1	375.3
5-12-02 <i>051202</i>	INSPECTION DOCUMENT 02 KGYG				MTH 12-Mar-2015 HRS 972.4 LDG 613		900		1872.4	85.6
5-12-03 <i>051203</i>	INSPECTION DOCUMENT 03 KGYG				MTH 13-Jan-2017 HRS 1373.5 LDG 846		1350		2723.5	936.7
5-12-04 <i>051204</i>	INSPECTION DOCUMENT 04 UNK				MTH 18-Dec-2018 HRS 1786.8 LDG 1071		1800		3586.8	1800
5-12-05 <i>051205</i>	INSPECTION DOCUMENT 05 *CF				MTH 10-Jun-2009 HRS 0		3150		3150	1363.2
5-12-06 <i>051206</i>	INSPECTION DOCUMENT 06 KGYG				MTH 21-Jun-2018 HRS 1712.1 LDG 1025		12		30-Jun-2019	-2 m 5 d
										Over Due
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK): INSPECTION DOCUMENT 06 KGYG	C352 X-465737			MTH 21-Jun-2018 HRS 1712.1 LDG 1025		12		30-Jun-2019	-2 m 5 d
										Over Due
5-12-07 <i>051207</i>	INSPECTION DOCUMENT 07 GYG				MTH 21-Nov-2017 HRS 1569.9 LDG 950		24		30-Nov-2019	2 m 25 d
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) UNK				MTH 18-Dec-2018 HRS 1786.8 LDG 1071		60			



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262004 <i>051210 : FB</i>	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST): INSPECTION DOCUMENT 10	UNK		30401102-2 61140B1	MTH 18-Dec-2018	-42	60		30-Nov-2023	50 m 25 d
5-12-11 <i>051211</i>	INSPECTION DOCUMENT 11	KGYY			MTH 22-Jul-2015 HRS 1065.7 LDG 667		72		31-Jul-2021	22 m 26 d
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION): INSPECTION DOCUMENT 11	KGYY		C352 X-465737	MTH 22-Jul-2015 HRS 1065.7 LDG 667		72		31-Jul-2021	22 m 26 d
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 10-Jun-2009		144			
B262101 <i>051212</i>	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST): INSPECTION DOCUMENT 12	*CF		C352 X-465737	MTH 10-Jun-2009		144		30-Jun-2021	21 m 25 d
5-12-13 <i>051213</i>	INSPECTION DOCUMENT 13	KGYY			MTH 21-Jun-2018 HRS 1712.1 LDG 1025		12 450		30-Jun-2019 2162.1	-2 m 5 d 375.3
										Over Due
5-12-14 <i>051214</i>	INSPECTION DOCUMENT 14	KGYY			MTH 21-Jun-2018 HRS 1712.1 LDG 1025		12 900		30-Jun-2019 2612.1	-2 m 5 d 825.3
										Over Due
5-12-15 <i>051215</i>	INSPECTION DOCUMENT 15	GY			MTH 21-Nov-2017 HRS 1569.9 LDG 950		24 1350		30-Nov-2019 2919.9	2 m 25 d 1133.1
5-12-16 <i>051216</i>	INSPECTION DOCUMENT 16	UNK			MTH 18-Dec-2018 HRS 1786.8 LDG 1071		36 1350		31-Dec-2021 3136.8	27 m 26 d 1350
5-12-17 <i>051217</i>	INSPECTION DOCUMENT 17	UNK			MTH 18-Dec-2018 HRS 1786.8 LDG 1071		36 1800		31-Dec-2021 3586.8	27 m 26 d 1800
5-12-18 <i>051218</i>	INSPECTION DOCUMENT 18	UNK			MTH 18-Dec-2018 HRS 1786.8 LDG 1071		36 2250		31-Dec-2021 4036.8	27 m 26 d 2250
5-12-20 <i>051220</i>	INSPECTION DOCUMENT 20	GY			MTH 21-Nov-2017 HRS 1569.9 LDG 950		48 2700		30-Nov-2021 4269.9	26 m 25 d 2483.1
5-12-21 <i>051221</i>	INSPECTION DOCUMENT 21	KGYY			MTH 21-Jun-2018 HRS 1712.1 LDG 1025		12		30-Jun-2019	-2 m 5 d
										Over Due
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KGYY			MTH 15-Feb-2017 HRS 1389.8 LDG 854		24			
B341001 AIRSPEED <i>051222 : A/S</i>	CALIBRATION TEST INDICATOR 14 CFR PART 91.411: INSPECTION DOCUMENT 22	KGYY		261440-1143 298581A	MTH 15-Feb-2017	-31	24		31-Jan-2019	-7 m 5 d
										Over Due
B341001 NO. 1 <i>051222 : ADC</i>	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411: INSPECTION DOCUMENT 22	KGYY		011-01110-00 43805487	MTH 15-Feb-2017	-31	24		31-Jan-2019	-7 m 5 d
										Over Due
B341001 NO. 2 <i>051222 : ADC#2</i>	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411: INSPECTION DOCUMENT 22	KGYY		011-01110-00 43805498	MTH 15-Feb-2017	-31	24		31-Jan-2019	-7 m 5 d
										Over Due

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
B341001 STANDBY <i>051222 : STDBY</i>	CALIBRATION TEST ALTIMETER	14 CFR PART 91.411: INSPECTION DOCUMENT 22	MTH	15-Feb-2017	-31	24	31-Jan-2019	-7 m 5 d	Over Due	
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01) : INSPECTION DOCUMENT 22	MTH	15-Feb-2017	-20	24	31-Jan-2019	-7 m 5 d	Over Due		
B345000 LEFT <i>051222 : XPDR1</i>	CALIBRATION TEST TRANSPONDER	14 CFR PART 91.413 : INSPECTION DOCUMENT 22	MTH	15-Feb-2017	-31	24	31-Jan-2019	-7 m 5 d	Over Due	
B345000 RIGHT <i>051222 : XPDR2</i>	CALIBRATION TEST TRANSPONDER	14 CFR PART 91.413 : INSPECTION DOCUMENT 22	MTH	15-Feb-2017	-31	24	31-Jan-2019	-7 m 5 d	Over Due	
5-12-23 <i>051223</i>	INSPECTION DOCUMENT 23 (NOT USED)	MTH	21-Sep-2012			N/R				
B324000 LEFT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL	SPECIAL (NDI): INSPECTION DOCUMENT 28	MTH			A/R				
B324000 RIGHT	DETAILED INSPECTION MAIN LANDING GEAR WHEEL	SPECIAL (NDI): INSPECTION DOCUMENT 28				A/R				
B324000	DETAILED INSPECTION NOSE LANDING GEAR WHEEL	SPECIAL (NDI): INSPECTION DOCUMENT 28	MTH	21-Oct-2015		A/R				
5-12-30 <i>051230</i>	INSPECTION DOCUMENT 30	MTH	12-Feb-2018			48	28-Feb-2022	29 m 23 d		
5-12-31 <i>051231</i>	INSPECTION DOCUMENT 31	MTH	21-Jun-2018			450	2162.1	375.3		
5-12-32 <i>051232</i>	INSPECTION DOCUMENT 32	MTH	24-Jun-2015			72	30-Jun-2021	21 m 25 d		
5-12-34	INSPECTION DOCUMENT 34	MTH	01-Aug-2018			N/A				
B243003	FUNCTIONAL CHECK MAIN SHIP BATTERY	TELEDYNE GILL LEAD-ACID BATTERY (CAPACITY CHECK): INSPECTION DOCUMENT 34	MTH	01-Aug-2018		N/R				
5-12-35	INSPECTION DOCUMENT 35	MTH	18-Dec-2018			6	30-Jun-2019	-2 m 5 d		
5-12-37	INSPECTION DOCUMENT 37	MTH	21-Jun-2018			7200	8912.1	7125.3		
5-12-MA <i>0512MA</i>	INSPECTION DOCUMENT MA	MTH	21-Nov-2017			500	2057.1	270.3		



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-MB <i>0512MB</i>	INSPECTION DOCUMENT MB	KGYY	MTH HRS LDG	12-Mar-2015 972.4 613	-22.4	950		1900	113.2
5-12-MC <i>0512MC</i>	INSPECTION DOCUMENT MC	*CF	MTH HRS	10-Jun-2009 0		4000		4000	2213.2
5-12-MD <i>0512MD</i>	INSPECTION DOCUMENT MD	KGYY	MTH HRS LDG	21-Jun-2018 1712.1 1025		12		30-Jun-2019	-2 m 5 d
5-12-ME <i>0512ME</i>	INSPECTION DOCUMENT ME	KGYY	MTH HRS LDG	21-Jun-2018 1712.1 1025		36 1400		30-Jun-2021 3112.1	21 m 25 d 1325.3
5-12-MF <i>0512MF</i>	INSPECTION DOCUMENT MF	*CF	MTH HRS	10-Jun-2009 0		12000		12000	10213.2
5-12-MG <i>0512MG</i>	INSPECTION DOCUMENT MG	*CF	MTH HRS	10-Jun-2009 0		5000		5000	3213.2
5-12-MH <i>0512MH</i>	INSPECTION DOCUMENT MH	*CF	MTH HRS	10-Jun-2009 0		8250		8250	6463.2
5-12-MI <i>0512MI</i>	INSPECTION DOCUMENT MI	*CF	MTH HRS	10-Jun-2009 0		12000		12000	10213.2
5-12-MJ <i>0512MJ</i>	INSPECTION DOCUMENT MJ	*CF	MTH HRS	10-Jun-2009 0		10600		10600	8813.2
5-12-MK <i>0512MK</i>	INSPECTION DOCUMENT MK	*CF	MTH HRS	10-Jun-2009 0		10400		10400	8613.2
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH		DAYS	10-Jun-2009		A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH		DAYS	10-Jun-2009		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH		DAYS	10-Jun-2009		A/R			
B243005	FUNCTIONAL CHECK MAIN SHIP BATTERY		GILL TELEDYNE ICA TD14-8-01 LT VALVE-REGULATED BATTERY						
			7639-30LT	MTH	01-Aug-2018	18		29-Feb-2020	5 m 24 d
			G03003567	HRS	1741.2	1800		3541.2	1754.4
262003A LEFT <i>262003 : L</i>	REPLACE FIRE EXT CARTRIDGE	*CF	13083-5 14G540-001	MTH	12-Mar-2015	72		31-Jul-2020	10 m 26 d
262003A RIGHT <i>262003 : R</i>	REPLACE FIRE EXT CARTRIDGE	*CF	13083-5 14H543-001	MTH	12-Mar-2015	72		31-Aug-2020	11 m 26 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)		MTH	10-Jun-2009		A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)		MTH	10-Jun-2009		A/R			
B323001 <i>051208 : LG</i>	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST)	KGYY	40005369-2 6859	MTH	21-Jun-2018	36		30-Jun-2021	21 m 25 d
B324002 <i>051208 : EB</i>	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST)	KGYY	40005399-1 7011	MTH	21-Jun-2018	36		30-Jun-2021	21 m 25 d
B351001 <i>051210 : OXY</i>	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST	UNK	4441073-040 0802-295	MTH	18-Dec-2018	-42	60	30-Nov-2023	50 m 25 d



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION	MTH HRS LDG	21-Jun-2018 1712.1 1025	-88.9	12 450		30-Jun-2019 (2073.2)2073.2	-2 m 5 d 286.4		
		KGYY						Over Due		
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION	MTH HRS LDG	21-Jun-2018 1712.1 1025	-88.9	12 450		30-Jun-2019 (2073.2)2073.2	-2 m 5 d 286.4		
		KGYY						Over Due		
710010 E1	COMPRESSOR WASH	MTH HRS LDG	23-Jan-2018 1594.5 962		A/R					
		GYG								
	SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.									
710010 E2	COMPRESSOR WASH	MTH HRS LDG	23-Jan-2018 1594.5 962		A/R					
		GYG								
	SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.									
720000 E1	PERFORM ENGINE OVERHAUL	MTH HRS	10-Jun-2009 0		3500		(3500)3500	1713.2		
720000 E2	PERFORM ENGINE OVERHAUL	MTH HRS	10-Jun-2009 0		3500		(3500)3500	1713.2		
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION	MTH HRS LDG	18-Dec-2018 1786.8 1071	-36.8	1750		(3500)3500	1713.2		
		KGYY								
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION	MTH HRS LDG	18-Dec-2018 1786.8 1071	-36.8	1750		(3500)3500	1713.2		
		UNK								
720003 E1	INSPECT LOW UTILIZATION ENGINE	MTH	10-Jun-2009		144		30-Jun-2021	21 m 25 d		
		*CF								
720003 E2	INSPECT LOW UTILIZATION ENGINE	MTH	10-Jun-2009		144		30-Jun-2021	21 m 25 d		
		*CF								
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER	MTH HRS LDG	18-Dec-2018 1786.8 1071	-36.8	1750		(3500)3500	1713.2		
		KGYY								
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER	MTH HRS LDG	18-Dec-2018 1786.8 1071	-36.8	1750		(3500)3500	1713.2		
		UNK								
731020 E1	CHECK/REPLACE FUEL FILTER ELEMENT	MTH HRS LDG	21-Jun-2018 1712.1 1025		12 900		30-Jun-2019 (2612.1)2612.1	-2 m 5 d 825.3		
		KGYY						Over Due		
731020 E2	CHECK/REPLACE FUEL FILTER ELEMENT	MTH HRS LDG	21-Jun-2018 1712.1 1025		12 900		30-Jun-2019 (2612.1)2612.1	-2 m 5 d 825.3		
		KGYY						Over Due		
731055 E1	REPLACE FUEL MANIFOLD	PN MTH HRS LDG	18-Dec-2018 1786.8 1071	-36.8	1750		(3500)3500	1713.2		
		KGYY								
731055 E2	REPLACE FUEL MANIFOLD	PN MTH HRS LDG	18-Dec-2018 1786.8 1071	-36.8	1750		(3500)3500	1713.2		
		UNK								
733020 E1	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH	PN MTH HRS LDG	18-Dec-2018 1786.8 1071	-36.8	1750		(3500)3500	1713.2		
		KGYY								



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
733020 E2	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH	UNK		PN SN-UNKNOWN	MTH 18-Dec-2018 HRS 1786.8 LDG 1071	-36.8	1750		(3500)3500	1713.2
772001 E1	FUNCTIONAL TEST OF THE T6 THERMOCOUPLE WIRING HARNESS AND ASSEMBLY	KGYG			MTH 18-Dec-2018 HRS 1786.8 LDG 1071	-36.8	1750		(3500)3500	1713.2
772001 E2	FUNCTIONAL TEST OF THE T6 THERMOCOUPLE WIRING HARNESS AND ASSEMBLY	UNK			MTH 18-Dec-2018 HRS 1786.8 LDG 1071	-36.8	1750		(3500)3500	1713.2
790015 E1	REPLACE OIL FILTER ELEMENT	MKE			MTH 26-Jan-2015 HRS 929.7 LDG 571		900		(1829.7)1829.7	42.9
790015 E2	REPLACE OIL FILTER ELEMENT	MKE			MTH 26-Jan-2015 HRS 929.7 LDG 571		900		(1829.7)1829.7	42.9
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	KGYG		PN SN-UNKNOWN	MTH 18-Dec-2018 HRS 1786.8 LDG 1071		6 100		30-Jun-2019 (1886.8)1886.8	-2 m 5 d 100
										Over Due
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	UNK		35C0412-01 SN-UNKNOWN	MTH 18-Dec-2018 HRS 1786.8 LDG 1071		6 100		30-Jun-2019 (1886.8)1886.8	-2 m 5 d 100
										Over Due
794020 E1	REPLACE NO. 4 BEARING FRONT CARBON SEAL	KGYG			MTH 18-Dec-2018 HRS 1786.8 LDG 1071		1750		(3536.8)3536.8	1750
794020 E2	REPLACE NO. 4 BEARING FRONT CARBON SEAL	UNK			MTH 18-Dec-2018 HRS 1786.8 LDG 1071		1750		(3536.8)3536.8	1750



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
212002	UNDER FLOOR BLOWER ASSY. *CF	0113-12 1766	MTH 10-Jun-2009		O/C			
213001	KAPS II CONTROLLER 9912661-6 *CF	52811-102 989	MTH 10-Jun-2009		O/C			
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7 *CF	52812-102 1157	MTH 10-Jun-2009		O/C			
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7 *CF	52812-102 1161	MTH 10-Jun-2009		O/C			
215001	AIR CONDITIONING COMPRESSOR MODULE 9912660-14 *CF	1133610-4 307	MTH 10-Jun-2009		O/C			
215002	CONDENSOR ASSEMBLY 9912660-3 *CF	1134620-5 319	MTH 10-Jun-2009		O/C			
215003	RECEIVER DRYER ASSY 9912583-3 *CF	1134275-1 2282	MTH 10-Jun-2009		O/C			
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7 *CF	1133300-1 551	MTH 10-Jun-2009		O/C			
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7 *CF	1133300-1 552	MTH 10-Jun-2009		O/C			
215005	VANE AXIAL BLOWER ASSY. PN SN-UNKNOWN		MTH 10-Jun-2009		O/C	0		
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD PN SN-UNKNOWN		MTH 10-Jun-2009 ACH		800	0	800	627.8
221001 AILERON	GSA 80 TORQUE SERVO *CF	011-00877-00 10905186	MTH 10-Jun-2009		O/C			
221001 RUDDER	GSA 80 TORQUE SERVO *CF	011-00877-00 66306214	MTH 10-Jun-2009		O/C			
221002 ELEVATOR	GSA 81 TORQUE SERVO *CF	011-00878-10 71306644	MTH 10-Jun-2009		O/C			
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO KGY	011-00878-10 71306692	MTH 12-May-2017 HRS 1435.6 LDG 877		O/C	1435.6 877		
221003 AILERON	GSM 85A SERVO MOUNT KGY	011-01436-A2 10905186	MTH 21-Jun-2018 HRS 1712.1 LDG 1025		O/C			
221003 ELEVATOR	GSM 85A SERVO MOUNT KGY	011-01436-A0 11205195	MTH 21-Jun-2018 HRS 1712.1 LDG 1025		O/C	1712.1 1025		
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT KGY	011-01436-A1 11305175	MTH 21-Jun-2018 HRS 1712.1 LDG 1025		O/C	1712.1 1025		
221003 RUDDER	GSM 85 SERVO MOUNT KGY	011-01436-A3 11005169	MTH 21-Jun-2018 HRS 1712.1 LDG 1025		O/C	1712.1 1025		
221004	GMC 710 AFCS CONTROLLER *CF	011-01020-10 22005329	MTH 10-Jun-2009		O/C			
231002 NO. 1	GMA 1347D AUDIO PANEL *CF	011-01257-00 48405292	MTH 10-Jun-2009		O/C			
231002 NO. 2	GMA 1347D AUDIO PANEL *CF	011-01257-00 48405302	MTH 10-Jun-2009		O/C			
231003 NO. 1	VHF COMM ANTENNA *CF	VHF10-829 518	MTH 10-Jun-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
231003 NO. 2	VHF COMM ANTENNA *CF	VHF10-829 0532	MTH 10-Jun-2009		O/C			
231011	SAT PHONE ANTENNA *CF	S67-1575-109 N/A	MTH 10-Jun-2009		O/C			
231101	HIGH FREQUENCY CONTROLLER S3100-470 *CF	071-01605-0201 N/A	MTH 10-Jun-2009		O/C			
231102	HIGH FREQUENCY RECEIVER/ EXCITER S3100-449 *CF	064-01073-0102 N/A	MTH 10-Jun-2009		O/C			
231103	HIGH FREQUENCY ANTENNA *CF	16390 N/A	MTH 10-Jun-2009		O/C			
231104	HIGH FREQUENCY POWER AMPLIFER *CF	064-01072-0101 N/A	MTH 10-Jun-2009		O/C			
243001 LEFT	DIGITAL GCU 9912682-3 *CF	GCSG550-5 08409035	MTH 10-Jun-2009		O/C			
243001 RIGHT	DIGITAL GCU 9912682-3 *CF	GCSG550-5 08421209	MTH 10-Jun-2009		O/C			
243002	EMER INST BATTERY KGYG	CBS24 0177	MTH 21-Jun-2018 HRS 1712.1 LDG 1025		O/C			
243007	MAIN SHIP BATTERY KGYG	7639-30LT G03003567	MTH 01-Aug-2018 HRS 1741.2		O/C	0 0		
243015	RELAY DISCONNECT BATTERY S3155-1 KGYG	A-931F CU-14612	MTH 01-Aug-2018 HRS 1741.2		O/C	0 0		
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY *CF	7018920-5 0572	MTH 10-Jun-2009		O/C			
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY *CF	7018920-5 0569	MTH 10-Jun-2009		O/C			
245003	FLAP CONTROL MODULE *CF	7018916-9 0372	MTH 10-Jun-2009		O/C			
245005 LEFT	ICE PROTECTION CONTROL *CF	7018917-9 0336	MTH 10-Jun-2009		O/C			
245005 RIGHT	ICE PROTECTION CONTROL *CF	7018918-13 0348	MTH 10-Jun-2009		O/C			
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL *CF	7018919-13 0451	MTH 10-Jun-2009		O/C			
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL *CF	7018919-13 0470	MTH 10-Jun-2009		O/C			
245008	DOOR MONITOR- *CF	7018921-8 0291	MTH 10-Jun-2009		O/C			
245009	LANDING GEAR MONITOR- *CF	7018923-12 0302	MTH 10-Jun-2009		O/C			
245010 LEFT	START CONTROL *CF	7018924-5 0571	MTH 10-Jun-2009		O/C			
245010 RIGHT	START CONTROL *CF	7018924-5 0570	MTH 10-Jun-2009		O/C			
245011	FLAP MONITOR- *CF	7018925-11 0342	MTH 10-Jun-2009		O/C			
245012 LEFT	SPEEDBRAKE ASSY *CF	7018926-1 0610	MTH 10-Jun-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245012	SPEEDBRAKE ASSY *CF	7018926-1	MTH 10-Jun-2009		O/C			
	RIGHT	0595						
245013	DIAGNOSTIC UNIT *CF	7018927-7	MTH 10-Jun-2009		O/C			
		0366						
245014	FUEL FLOW SIGNAL PCB UNIT *CF	85-230-2	MTH 10-Jun-2009		O/C			
	9912417-3	748-720M2						
245015	MASTER INTERIOR SSR UNIT *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	UZ100	08034038						
245016	AVN BUS #1 SENSOR *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	RIGHT	08094755						
245017	AVN SENSOR *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	LEFT	08094778						
245018	AVN BUS #2 SENSOR *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	RIGHT	08034054						
245019	IGN #1 SENSOR *CF	10747P03E10	MTH 10-Jun-2009		O/C			
	LEFT	09015306						
245019	IGN #1 SENSOR *CF	10747P03E10	MTH 10-Jun-2009		O/C			
	RIGHT	08033927						
245020	IGN #2 SENSOR *CF	10747P03E10	MTH 10-Jun-2009		O/C			
	LEFT	08084540						
245020	IGN #2 SENSOR *CF	10747P03E10	MTH 10-Jun-2009		O/C			
	RIGHT	09025400						
245021	COCKPIT FAN SENSOR *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	LEFT	08094754						
245022	CABIN FAN SENSOR *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	LEFT	08094777						
245023	LH BOOST PUMP SENSOR *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	LEFT	08094753						
245023	RH BOOST PUMP SENSOR *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	RIGHT	08034088						
245024	CONDENSER FAN SENSOR *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	RIGHT	08034079						
245025	DC-DC CONVERTER *CF	10747P03E10	MTH 10-Jun-2009		O/C			
	LEFT	08033924						
245026	AVN EMERG SENSOR *CF	10747P03E25	MTH 10-Jun-2009		O/C			
	LEFT	08034047						
251001	GLARESHIELD ASSEMBLY *CF	4319027-17	MTH 10-Jun-2009		O/C			
		129957-1						
256001	LIFE VEST	P01224-205	MTH 26-Jan-2015		120	71	28-Feb-2019	-6 m 5 d
	NO. 1	319242	HRS 929.7		O/C	0		
			LDG 571			0		
								Over Due
256001	LIFE VEST	P01224-205	MTH 26-Jan-2015		120	71	28-Feb-2019	-6 m 5 d
	NO. 2	319369	HRS 929.7		O/C	0		
			LDG 571			0		
								Over Due
256001	LIFE VEST	P01224-205	MTH 26-Jan-2015		120	71	28-Feb-2019	-6 m 5 d
	NO. 3	319215	HRS 929.7		O/C	0		
			LDG 571			0		
								Over Due
256001	LIFE VEST	P01224-205	MTH 26-Jan-2015		120	71	28-Feb-2019	-6 m 5 d
	NO. 4	319368	HRS 929.7		O/C	0		
			LDG 571			0		
								Over Due



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
256001 NO. 5	LIFE VEST MKE	P01224-205 319318	MTH 26-Jan-2015 HRS 929.7 LDG 571		120 O/C	71 0 0	28-Feb-2019	-6 m 5 d
								Over Due
256001 NO. 6	LIFE VEST MKE	P01224-205 319317	MTH 26-Jan-2015 HRS 929.7 LDG 571		120 O/C	71 0 0	28-Feb-2019	-6 m 5 d
								Over Due
256002	ELT BATTERY KMKE	452-0133 DEC 2018	MTH 20-Nov-2013 HRS 796.1 LDG 476	1	60	0 0 0	31-Dec-2018	-8 m 5 d
								Over Due
256004	ELT ANTENNA *CF	110-340 241187	MTH 10-Jun-2009		O/C			
256007 256001	ELT PROCESSOR C406N KMKE	453-5060 14249	MTH 20-Nov-2013 HRS 796.1 LDG 476		O/C	0 0 0		
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1 *CF	3001-212-1004/455-9 210276	MTH 10-Jun-2009		O/C			
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1 *CF	3001-212-1004/455-9 210281	MTH 10-Jun-2009		O/C			
262001	FIRE EXTINGUISHER BOTTLE 9912048-6 *CF	30401102-2 61140B1	MTH 10-Jun-2009		O/C	0		
262003 LEFT	FIRE EXT CARTRIDGE KGYG	13083-5 14G540-001	MTH 12-Mar-2015 HRS 972.4 LDG 613		72	8	31-Jul-2020	10 m 26 d
Manufacture Date: 01-Jul-2014								
262003 RIGHT	FIRE EXT CARTRIDGE KGYG	13083-5 14H543-001	MTH 12-Mar-2015 HRS 972.4 LDG 613		72	7	31-Aug-2020	11 m 26 d
Manufacture Date: 01-Aug-2014								
262004	PORTABLE FIRE EXTINGUISHER	C352 X-465737	MTH 10-Jun-2009		O/C	0		
271001 LEFT	CONTROL WHEEL ASSY *CF	4319065-1 1531	MTH 10-Jun-2009		O/C			
271001 RIGHT	CONTROL WHEEL ASSY *CF	4319065-2 1520	MTH 10-Jun-2009		O/C			
273001	RUDDER TRIM ACTUATOR 9912639-2 *CF	SYLC-53361-1 290	MTH 10-Jun-2009		O/C			
273002	AILERON TRIM ACTUATOR 9912639-2 *CF	SYLC-53361-1 0366	MTH 10-Jun-2009		O/C			
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1 *CF	MP50Y-1 251	MTH 10-Jun-2009		O/C			
275002 LEFT	FLAP ACTUATOR 9912640-1 *CF	41013930-105 0635	MTH 10-Jun-2009		O/C			
275002 RIGHT	FLAP ACTUATOR 9912640-2 *CF	41013930-106 0546	MTH 10-Jun-2009		O/C			
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY 9914344-52 *CF	140527-5200 0487	MTH 10-Jun-2009		O/C			
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY VYS	9914344-59 0375	MTH 21-Sep-2012 HRS 647.4 LDG 366		O/C	0 0 0		
276001 LEFT	SPEED BRAKE ACTUATOR 9912641-2 *CF	41014070-103 0497	MTH 10-Jun-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
276001 RIGHT	SPEED BRAKE ACTUATOR 9912641-2 *CF	41014070-103 0613	MTH 10-Jun-2009		O/C			
282001 LEFT	PRIMARY EJECTOR 9912190-5 *CF	LR45300A C1590	MTH 10-Jun-2009		O/C			
282001 RIGHT	PRIMARY EJECTOR 9912190-5 *CF	LR45300A C1460	MTH 10-Jun-2009		O/C			
282002	TRANSFER VALVE 9914103-6 *CF	ZSV57 09-011571	MTH 10-Jun-2009		O/C			
282003 LEFT	DC FUEL PUMP 9912553-1 *CF	1C7-23 8BD353	MTH 10-Jun-2009		O/C			
282003 RIGHT	DC FUEL PUMP 9912553-1 *CF	1C7-23 9BD355	MTH 10-Jun-2009		O/C			
282004 L1	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 C1500	MTH 10-Jun-2009		O/C			
282004 L2	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 C1526	MTH 10-Jun-2009		O/C			
282004 R1	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 C1548	MTH 10-Jun-2009		O/C			
282004 R2	SCAVENGE EJECTOR 9912190-2 *CF	RG45310 C1549	MTH 10-Jun-2009		O/C			
282005 LEFT	VALVE-FUEL MOTOR 9912014-3 *CF	AV24B1507 AA187359	MTH 10-Jun-2009		O/C			
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3 *CF	AV24B1507 AA187358	MTH 10-Jun-2009		O/C			
284001 L1	FUEL PROBE 9912664-1 *CF	020-251-001 622	MTH 10-Jun-2009		O/C			
284001 L2	FUEL PROBE 9912664-2 *CF	020-251-002 622	MTH 10-Jun-2009		O/C			
284001 L3	FUEL PROBE 9912664-3 *CF	020-251-003 616	MTH 10-Jun-2009		O/C			
284001 L4	FUEL PROBE 9912664-4 *CF	020-251-004 283	MTH 10-Jun-2009		O/C			
284001 L5	FUEL PROBE 9912664-5 *CF	020-251-005 619	MTH 10-Jun-2009		O/C			
284001 R1	FUEL PROBE 9912664-1 *CF	020-251-001 620	MTH 10-Jun-2009		O/C			
284001 R2	FUEL PROBE 9912664-2 *CF	020-251-002 621	MTH 10-Jun-2009		O/C			
284001 R3	FUEL PROBE 9912664-3 *CF	020-251-003 618	MTH 10-Jun-2009		O/C			
284001 R4	FUEL PROBE 9912664-4 *CF	020-251-004 280	MTH 10-Jun-2009		O/C			
284001 R5	FUEL PROBE 9912664-5 *CF	020-251-005 612	MTH 10-Jun-2009		O/C			
284002	SIGNAL CONDITIONER 9912664-6 *CF	367-350-001 1192	MTH 10-Jun-2009		O/C			
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2 *CF	HM50C-3 287B	MTH 10-Jun-2009					
291002	HYDRAULIC CHECK VALVE *CF	4001-20 5139A	MTH 10-Jun-2009		O/C			
291003	HYDRAULIC SYS PRESSURE GAUGE *CF	19940933-1 026002	MTH 10-Jun-2009		O/C			
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4 *CF	80665 0241	MTH 10-Jun-2009		O/C			
291007	HYDRAULIC MANIFOLD 9912657-14 *CF	8257-3 0235	MTH 10-Jun-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
291008	HYDRAULIC RELIEF VALVE 9912657-2 *CF	2672 0232	MTH 10-Jun-2009		O/C			
291009	BRAKE PRESSURE SWITCH 9912657-3 *CF	80664 0241	MTH 10-Jun-2009		O/C			
291010	HYD SOLENOID CONTROL VALVE EXTEND 9912657-5 *CF	4251 0244	MTH 10-Jun-2009		O/C			
291010	HYD SOLENOID CONTROL VALVE RETRACT 9912657-7 *CF	4252 0244	MTH 10-Jun-2009		O/C			
291011	HYDRAULIC DUMP VALVE 9912657-15 *CF	9625-1 0242	MTH 10-Jun-2009		O/C			
291012	HYDRAULIC RESERVOIR ASSEMBLY *CF	7017005-28 7017005-28	MTH 10-Jun-2009		O/C			
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2 *CF	7550-2 0465	MTH 10-Jun-2009		O/C			
301001	WING DE-ICE BOOT LEFT 9912662-17	MKE P35-4D5317-17 NCJ9680	MTH 26-Jan-2015 HRS 929.7 LDG 571		O/C	0 0 0		
301001	WING DE-ICE BOOT RIGHT 9912662-18	MKE P35-4D5317-18 NCW0160	MTH 25-Oct-2015 HRS 1032.5 LDG 711 ACH 83		O/C	0 0 0		
301003	HORIZONTAL STAB DE-ICE BOOT LEFT 9912662-3 *CF	P29S4D5317-05 MBAQ040	MTH 10-Jun-2009		O/C			
301003	HORIZONTAL STAB DE-ICE BOOT RIGHT 9912662-4 *CF	P29S4D5317-06 MBAQ470	MTH 10-Jun-2009		O/C			
301004	DE-ICE PRESSURE SWITCH L1 *CF	1106P55-1 7436A	MTH 10-Jun-2009		O/C			
301004	DE-ICE PRESSURE SWITCH L2 *CF	1106P55-1 7437A	MTH 10-Jun-2009		O/C			
301004	DE-ICE PRESSURE SWITCH L3 *CF	1106P55-1 7420A	MTH 10-Jun-2009		O/C			
301004	DE-ICE PRESSURE SWITCH R1 *CF	1106P55-1 7416A	MTH 10-Jun-2009		O/C			
301004	DE-ICE PRESSURE SWITCH R2 *CF	1106P55-1 7422A	MTH 10-Jun-2009		O/C			
301004	DE-ICE PRESSURE SWITCH R3 *CF	1106P55-1 7419A	MTH 10-Jun-2009		O/C			
301004	VERT DE-ICE BOOT 9912662-13 *CF	P29S4D5317-13 MAZW330	MTH 10-Jun-2009		O/C			
302001	PRESS REG/SHUTOFF VALVE ASSY LEFT KGY	5285-00-3 1993	MTH 08-Sep-2016 HRS 1292.9 LDG 804 ACH 126.6		O/C	4 0 0		
302001	PRESS REG/SHUTOFF VALVE ASSY RIGHT *CF	5285-00-3 2184	MTH 10-Jun-2009		O/C			
302002	TEMP SWITCH LEFT *CF	1173T0759 5456	MTH 10-Jun-2009		O/C			
302002	TEMP SWITCH RIGHT *CF	1173T0759 5663	MTH 10-Jun-2009		O/C			
304001	DE-ICE VALVE L1 *CF	3D2353-06 N090739	MTH 10-Jun-2009		O/C			
304001	DE-ICE VALVE L2 *CF	3D2353-06 N091094	MTH 10-Jun-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
304002 LEFT	WINDSHIELD CONTROLLER KGYG	7018108-30 0160	MTH HRS LDG	11-Apr-2016 1213 755	O/C	0 0 0		
304002 RIGHT	WINDSHIELD CONTROLLER KGYG	7018108-30 0152	MTH HRS LDG	11-Apr-2016 1213 755	O/C	0 0 0		
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY *CF	7041020-5 215	MTH LDG	10-Jun-2009 0		20000 0	20000	18929
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY *CF	7041020-6 216	MTH LDG	10-Jun-2009 0		20000 0	20000	18929
321001	NOSE LANDING GEAR TRUNNION *CF	7042020-1 213	MTH	10-Jun-2009	O/C			
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY *CF	7041050-4 299	MTH LDG	10-Jun-2009 0		12000 0	12000	10929
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY *CF	7041050-4 297	MTH LDG	10-Jun-2009 0		12000 0	12000	10929
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY *CF	7041030-1 218	MTH LDG	10-Jun-2009 0		20000 0	20000	18929
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY *CF	7041030-2 217	MTH LDG	10-Jun-2009 0		20000 0	20000	18929
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK *CF	6327504-6 2656	MTH	10-Jun-2009	O/C			
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK *CF	6327504-6 2624	MTH	10-Jun-2009	O/C			
322002	NOSE GEAR FORK & PISTON ASSEMBLY *CF	7042040-1 215	MTH	10-Jun-2009	O/C			
322003 NOSE GEAR	UPLOCK ACTUATOR *CF	6327504-7 1324	MTH	10-Jun-2009	O/C			
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR 9912655-1 *CF	FA100036-001 FA100036-1-0247	MTH LDG	10-Jun-2009 0		12000 0	12000	10929
322010 LEFT	MAIN LANDING GEAR HYDRAULIC ACTUATOR 9912653-5 *CF	FA100104-001 FA100104-1-0205	MTH LDG	10-Jun-2009 0		12000 0	12000	10929
322010 RIGHT	MAIN LANDING GEAR HYDRAULIC ACTUATOR 9912653-6 *CF	FA100105-001 FA100105-1-0268	MTH LDG	10-Jun-2009 0		12000 0	12000	10929
322011	NOSE LANDING GEAR ACTUATOR 9912654-2 *CF	FA100087-001 FA100087-1-0270	MTH LDG	10-Jun-2009 0		12000 0	12000	10929
322202	SHIMMY DAMPER *CF	7042030-2 MTM00220	MTH	10-Jun-2009	O/C			
322205 NOSE	LANDING GEAR STRUT ASSEMBLY *CF	7042010-4 210	MTH LDG	10-Jun-2009 0		20000 0	20000	18929
322206 NOSE	LANDING GEAR DRAG BRACE ASSY *CF	DDA05645-1 139	MTH LDG	10-Jun-2009 0		20000 0	20000	18929
323001 LEFT	LANDING GEAR ASSEMBLY *CF	7041010-5 NSN	MTH	10-Jun-2009	O/C			
323001 RIGHT	LANDING GEAR ASSEMBLY *CF	7041010-6 NSN	MTH	10-Jun-2009	O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE	MTH	21-Jun-2018							?
	9914678-3	KGYY		40005369-2	HRS 1712.1		288			
				6859	LDG 1025					
MISSING "MANUFACTURE DATE" TO INSTALLED "OVERHAULED" UNIT. PLEASE SUPPLY MISSING INFORMATION TO CLEAR (?)										
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE	MTH	21-Jun-2018							?
	9914678-4	KGYY		40005399-1	HRS 1712.1		288			
				7011	LDG 1025					
MISSING "MANUFACTURE DATE" TO INSTALLED "OVERHAULED" UNIT. PLEASE SUPPLY MISSING INFORMATION TO CLEAR (?)										
323003	EMER BLOW DOWN BTL PRESSURE GAUGE	MTH	10-Jun-2009				O/C			
	*CF			19940931-1						
				026073						
324001	MAIN LANDING GEAR TIRE	MTH	20-Mar-2018				O/C	0		
LEFT	9912646-1	KGYY		021-523-0	HRS 1648.73			0		
				7129S00271						
324001	MAIN LANDING GEAR TIRE	MTH	20-Mar-2018				O/C	0		
RIGHT	9912646-1	KGYY		021-523-0	HRS 1648.73			0		
				7131S00350						
324002	NOSE LANDING GEAR TIRE	MTH	20-Mar-2018				O/C	0		
	9912649-1	KGYY		079-606-0	HRS 1648.73			0		
				7074S00253						
324003	MAIN LANDING GEAR WHEEL	MTH	08-Sep-2016				O/C	0		
LEFT	9912645-1	KGYY		3-1640	HRS 1292.9			0		
				0561	LDG 804			0		
					ACH 126.6					
324003	MAIN LANDING GEAR WHEEL	MTH	08-Sep-2016				O/C	0		
RIGHT	9912645-1	KGYY		3-1640	HRS 1292.9			0		
				0627	LDG 804			0		
					ACH 126.6					
324004	NOSE LANDING GEAR WHEEL	MTH	21-Oct-2015				O/C			
	9912648-1	KGYY		3-1642	HRS 1132.5					
				0285	LDG 711			711		
					ACH 83					
324005	MAIN LANDING GEAR BRAKE ASSY	MTH	21-Oct-2015				O/C			
LEFT	9912645-3	KGYY		2-1706-1	HRS 1132.5					
				0451	LDG 711					
					ACH 83					
324005	MAIN LANDING GEAR BRAKE ASSY	MTH	24-Jun-2015				O/C	1		
RIGHT	9912645-3	KGYY		2-1706-1	HRS 1044.9			0		
				0585	LDG 652			0		
324006	SHUTTLE VALVE	MTH	10-Jun-2009				O/C			
LEFT	9914689-4	*CF		5145-1						
				0313						
324006	SHUTTLE VALVE	MTH	10-Jun-2009				O/C			
RIGHT	9914689-4	*CF		5145-1						
				0318						
324007	BRAKE METERING VALVE	MTH	10-Jun-2009				O/C			
	9912650-9	*CF		84-75						
				0155						
324101	WHEEL SPEED SENSOR	MTH	10-Jun-2009				O/C			
LEFT	9912650-5	*CF		466-23-1						
				0457						
324101	WHEEL SPEED SENSOR	MTH	10-Jun-2009				O/C			
RIGHT	9912650-5	*CF		466-23-1						
				0511						
324101	PARKING BRAKE VALVE	MTH	10-Jun-2009				O/C			
	9912388-10	*CF		98433-1						
				0151						
324102	ANTISKID CONTROL UNIT	MTH	10-Jun-2009				O/C			
	9912650-1	*CF		556-3						
				302820266						



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
324103	ANTISKID CONTROL VALVE 9912650-6 *CF	211-134-1 0155	MTH 10-Jun-2009		O/C			
324104	EMERGENCY BRAKE VALVE 9912651-1 *CF	72298 0266	MTH 10-Jun-2009		O/C			
324105	EMER BRAKE BOTTLE PRESSURE GAUGE *CF	19940931-1 029361	MTH 10-Jun-2009		O/C			
325001	BUNGE ASSEMBLY *CF	7042072-9 NSN	MTH 10-Jun-2009		O/C			
334001 LEFT	POWER SUPPLY *CF 9912677-3	82004-1 000215	MTH 10-Jun-2009		O/C			
334001 RIGHT	POWER SUPPLY *CF 9912677-3	82004-1 000356	MTH 10-Jun-2009		O/C			
334002	GROUND RECOGNITION LIGHT 9912679-3 *CF	84003-2 000304	MTH 10-Jun-2009		O/C			
334003 LEFT	ANTI-COLLISION LIGHT 9912679-1 *CF	84005-1 000436	MTH 10-Jun-2009 HRS 0		8000	0	8000	6213.2
334003 RIGHT	ANTI-COLLISION LIGHT 9912679-2 *CF	84005-2 000369	MTH 10-Jun-2009 HRS 0		8000	0	8000	6213.2
341001	SWAAT UNIT *CF 9912689-1	0863B2 155	MTH 10-Jun-2009		O/C			
341002 NO. 1	GDC 74B AIRDATA SYSTEM *CF	011-01110-00 43805487	MTH 10-Jun-2009		O/C			
341002 NO. 2	GDC 74B AIRDATA SYSTEM *CF	011-01110-00 43805498	MTH 10-Jun-2009		O/C			
341003 NO. 1	GTP 59 OAT PROBE SYSTEM *CF	011-00978-00 47912635	MTH 10-Jun-2009		O/C			
341003 NO. 2	GTP 59 OAT PROBE SYSTEM *CF	011-00978-00 47912636	MTH 10-Jun-2009		O/C			
341004 LEFT	PITOT PROBE *CF 9912678-1	0851LN 261230	MTH 10-Jun-2009		O/C			
341004 RIGHT	PITOT PROBE *CF 9912678-1	0851LN 264607	MTH 10-Jun-2009		O/C			
342001 STANDBY	ALTIMETER *CF S3100-465	162350-1161 177833C	MTH 10-Jun-2009		O/C			
342002 AIRSPEED	INDICATOR MKE	261440-1143 298581A	MTH 26-Jan-2015 HRS 929.7 LDG 571		O/C			
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE *CF	011-00831-00 46710092	MTH 10-Jun-2009		O/C			
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE *CF	011-00831-00 46710111	MTH 10-Jun-2009		O/C			
342003	MAGNETIC COMPASS *CF	S2800-821 NSN	MTH 10-Jun-2009		O/C			
342004 NO. 1	GDU 1040A DISPLAY *CF	011-00916-00 86801505	MTH 10-Jun-2009		O/C			
342004 NO. 2	GDU 1040A DISPLAY *CF	011-00916-00 86801502	MTH 10-Jun-2009		O/C			
342005 NO. 1	GRS 77 AHRS UNIT *CF S3100-483/S3100-517	011-00868-10 42011538	MTH 10-Jun-2009		O/C			
342005 NO. 2	GRS 77 AHRS UNIT *CF S3100-483/S3100-517	011-00868-10 42011539	MTH 10-Jun-2009		O/C			
342006 NO. 1	GMU 44 MAGNETOMETER *CF	011-00870-00 47513280	MTH 10-Jun-2009		O/C			
342006 NO. 2	GMU 44 MAGNETOMETER *CF	011-00870-00 47513270	MTH 10-Jun-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
342007	GDU 1500 MFD UNIT *CF	011-01108-00 43201259	MTH 10-Jun-2009		O/C			
342008	ATTITUDE INDICATOR S3100-513 *CF	4200-21 C09-10212	MTH 10-Jun-2009		O/C			
344001	GWX 68 WEATHER RADAR *CF	011-00883-20 47202746	MTH 10-Jun-2009		O/C			
344002	GDL 69 WEATHER DATA LINK *CF	011-00987-00 47759471	MTH 10-Jun-2009		O/C			
345001	GPS/WAAS/XM ANTENNA *CF	013-00245-00 6362	MTH 10-Jun-2009		O/C			
345002 RIGHT	TRANSPONDER *CF	011-00779-01 84805544	MTH 10-Jun-2009		O/C			
345003 LEFT	TRANSPONDER *CF	011-00779-01 84805540	MTH 10-Jun-2009		O/C			
345004	GCU 475 FLIGHT MGMT CONTROL UNIT *CF	011-01054-10 21805247	MTH 10-Jun-2009		O/C			
345005	ADF RECEIVER *CF	013-00166-00 N/A	MTH 10-Jun-2009		O/C			
345006	ADF ANTENNA *CF	013-00165-00 N/A	MTH 10-Jun-2009		O/C			
345007	MARKER BEACON ANTENNA *CF	MB10-754-2 161	MTH 10-Jun-2009		O/C			
345008	GLIDE SLOPE ANTENNA *CF	RGS10-48 14334	MTH 10-Jun-2009		O/C			
345009 LEFT	L-BAND TRANSPONDER ANTENNA *CF	L10-611-14 1807	MTH 10-Jun-2009		O/C			
345009 RIGHT	L-BAND TRANSPONDER ANTENNA *CF	L10-611-14 1810	MTH 10-Jun-2009		O/C			
345009 UPPER	L-BAND TRANSPONDER ANTENNA *CF	L10-611-14 1822	MTH 10-Jun-2009		O/C			
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA *CF	L10-611-14 1858	MTH 10-Jun-2009		O/C			
345010	VOR/LOC ANTENNA *CF	VT10-767-3 0871	MTH 10-Jun-2009		O/C			
345011	KN63 DME TRANSCEIVER *CF	066-01070-0001 33042	MTH 10-Jun-2009		O/C			
345013	RMI CONVERTER *CF	013-00167-00 N/A	MTH 10-Jun-2009		O/C			
345014	GPS/WAAS/ ANTENNA *CF	013-00244-00 6225	MTH 10-Jun-2009		O/C			
345015	DME ANTENNA *CF	L10-611-14 1805	MTH 10-Jun-2009		O/C			
346010	TAS PROCESSOR KMKE	066-01152-0101 KTA810-2715	MTH 20-Nov-2013 HRS 796.1 LDG 476		O/C			
346011 BOTTOM	TAS ANTENNA *CF	L10-611-14 1825	MTH 10-Jun-2009		O/C			
346011 TOP	TAS ANTENNA *CF	071-01599-0100 21008	MTH 10-Jun-2009		O/C			
346012	CONFIGURATION MODULE *CF	071-00112-0200 14439	MTH 10-Jun-2009		O/C			
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT *CF	011-01105-01 15W008708	MTH 10-Jun-2009		O/C			
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT *CF	011-01105-01 15W008690	MTH 10-Jun-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
350001	OXYGEN BOTTLE *CF	4441073-040 0802-295	MTH 10-Jun-2009		180	5	31-Jan-2024	52 m 26 d
Manufacture Date: 31-Jan-2009								
350002	OXYGEN PRESSURE GAUGE C668512-0101 *CF	MD97-1 J07-10127	MTH 10-Jun-2009		O/C			
351001 LEFT	CREW OXYGEN MASK 9914067-41 KGY Y	MC10-16-101 SE27818	MTH 24-Jun-2015 HRS 1044.9 LDG 652		72	0	30-Jun-2021	21 m 25 d
351001 RIGHT	CREW OXYGEN MASK 9914067-41 KGY Y	MC10-16-101 SE27823	MTH 24-Jun-2015 HRS 1044.9 LDG 652		72	0	30-Jun-2021	21 m 25 d
361001 LEFT	PRECOOLER 9914402-7 *CF	8315-2 TO451	MTH 10-Jun-2009		O/C			
361001 RIGHT	PRECOOLER 9914402-7 *CF	8315-2 TO458	MTH 10-Jun-2009		O/C			
361002 LEFT	VARIABLE VENTURI VALVE ASSY *CF	2601-34 0319A	MTH 10-Jun-2009		O/C			
361002 RIGHT	VARIABLE VENTURI VALVE ASSY *CF	2601-34 0278A	MTH 10-Jun-2009		O/C			
361003	SERVICE AIR REGULATOR ASSY 9912510-2 *CF	1H75-23 3BE8	MTH 10-Jun-2009		O/C			
361004 LEFT	B/A SHUTOFF VALVE *CF	5253-00-3 2679	MTH 10-Jun-2009		O/C			
361004 RIGHT	B/A SHUTOFF VALVE *CF	5253-00-3 2710	MTH 10-Jun-2009		O/C			
361101 R1	DE-ICE VALVE *CF	3D2353-06 N090719	MTH 10-Jun-2009		O/C			
361101 R2	DE-ICE VALVE *CF	3D2353-06 N090902	MTH 10-Jun-2009		O/C			
522001	CABIN DOOR SEAL 9912674-3 *CF	S-22560-3 225	MTH 10-Jun-2009		O/C			
522002	ESCAPE HATCH SEAL 9912675-1 *CF	S-22561 273	MTH 10-Jun-2009		O/C			
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY *CF	7013022-3 218	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY *CF	7013022-4 218	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY *CF	7013022-11 218	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY *CF	7013022-10 218	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
534101 FWD	ENGINE BEAM *CF	7012061-3 227	MTH 10-Jun-2009		O/C			
535005	RADOME GY Y	7013010-802-1 21076750	MTH 14-Sep-2017 HRS 1526		O/C			
552001 LEFT	ELEVATOR ASSEMBLY *CF	7034001-11 142	MTH 10-Jun-2009		O/C			
552001 RIGHT	ELEVATOR ASSEMBLY *CF	7034001-12 143	MTH 10-Jun-2009		O/C			
553001	VERTICAL STABILIZER ASSY *CF	7031001-1 181	MTH 10-Jun-2009		O/C			
561001 LEFT	WINDSHIELD ASSY, (LH) 9912745-9 *CF	NP-188601-1 09024H7792	MTH 10-Jun-2009		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
561001 RIGHT	WINDSHIELD ASSY, (LH) 9912745-10 *CF	NP-188601-2 09033H8842	MTH 10-Jun-2009		O/C			
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-1 *CF	93310-1 1549	MTH 10-Jun-2009		O/C			
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-2 *CF	93310-2 1536	MTH 10-Jun-2009		O/C			
562003 L1	CABIN WINDOW 9912747-10 *CF	93320-10 2046	MTH 10-Jun-2009		O/C			
562003 L2	CABIN WINDOW 9912747-10 *CF	93320-10 2132	MTH 10-Jun-2009		O/C			
562003 L3	CABIN WINDOW 9912747-10 *CF	93320-10 2215	MTH 10-Jun-2009		O/C			
562003 R1	CABIN WINDOW 9912747-10 *CF	93320-10 2195	MTH 10-Jun-2009		O/C			
562003 R2	CABIN (ESCAPE HATCH) WINDOW 9912747-10 *CF	93320-10 2602	MTH 10-Jun-2009		O/C			
562003 R3	CABIN WINDOW 9912747-10 *CF	93320-10 2155	MTH 10-Jun-2009		O/C			
572001 LEFT WING	FWD SPAR *CF	7022022-1 88295	MTH 10-Jun-2009		O/C			
572001 RIGHT WING	FWD SPAR *CF	7022022-2 88296	MTH 10-Jun-2009		O/C			
572002 LEFT WING	REAR SPAR *CF	7022032-3 87934	MTH 10-Jun-2009		O/C			
572002 RIGHT WING	REAR SPAR *CF	7022032-4 87935	MTH 10-Jun-2009		O/C			
572003 LEFT WING	MAIN SPAR *CF	7022027-1 87874	MTH 10-Jun-2009		O/C			
572003 RIGHT WING	MAIN SPAR *CF	7022027-2 87875	MTH 10-Jun-2009		O/C			
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF	7041165-5 156	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF	7041165-6 210	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF	7041155-9 214	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF	7041155-10 210	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY *CF	7041175-5 216	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY *CF	7041175-6 206	MTH 10-Jun-2009 LDG 0		20000	0	20000	18929
712001 LEFT	ENG CHANNEL-FWD MOUNT 7051001-1 *CF	7051001-1 52	MTH 10-Jun-2009		O/C			
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1 *CF	LM-471-SA12 1231	MTH 10-Jun-2009 HRS 0		4000	0	4000	2213.2
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1 *CF	LM-471-SA12 1198	MTH 10-Jun-2009 HRS 0		4000	0	4000	2213.2
712001 RIGHT	ENG CHANNEL-FWD MOUNT *CF	7051001-2 108	MTH 10-Jun-2009		O/C			
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1 *CF	LM-471-SA12 1265	MTH 10-Jun-2009 HRS 0		4000	0	4000	2213.2
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1 *CF	LM-471-SA12 1136	MTH 10-Jun-2009 HRS 0		4000	0	4000	2213.2
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3 *CF	LM-471-SA4 LK2057	MTH 10-Jun-2009 HRS 0		8000	0	8000	6213.2
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3 *CF	LM-471-SA4 LK2052	MTH 10-Jun-2009 HRS 0		8000	0	8000	6213.2

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
712003 AFT	ENGINE BEAM *CF	7012066-2 0218	MTH 10-Jun-2009		O/C			
712003 LEFT	AFT ENGINE MOUNT CHANNEL *CF	7051001-3 74	MTH 10-Jun-2009		O/C			
712003 RIGHT	AFT ENGINE MOUNT CHANNEL *CF	7051001-4 251	MTH 10-Jun-2009		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE *CF	35C0510-01 LB0455	MTH 10-Jun-2009		E/C			
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE *CF	35C0510-01 LB0456	MTH 10-Jun-2009		E/C			
720010 E1	FAN ROTOR *CF	35C1940-01 TXA1B9329	MTH 10-Jun-2009 LDG 0		10500	0	(10500)10500	9429
720010 E2	FAN ROTOR *CF	35C1940-01 TXA1B9443	MTH 10-Jun-2009 LDG 0		10500	0	(10500)10500	9429
721010 E1	HP TURBINE DISK *CF	35C2311-01 A002HX75	MTH 10-Jun-2009 LDG 0		5250	0	(5250)5250	4179
721010 E2	HP TURBINE DISK *CF	35C2311-01 A002H9AX	MTH 10-Jun-2009 LDG 0		5250	0	(5250)5250	4179
721020 E1	LP TURBINE DISK *CF	35C2372-01 A002HLH9	MTH 10-Jun-2009 LDG 0		10500	0	(10500)10500	9429
721020 E2	LP TURBINE DISK *CF	35C2372-01 CRAZADLQ034	MTH 10-Jun-2009 LDG 0		10500	0	(10500)10500	9429
723010 E1	IMPELLER AND SHAFT ASSEMBLY *CF	35C4888-01 AAPPIAAS2030	MTH 10-Jun-2009 LDG 0		10500	0	(10500)10500	9429
723010 E2	IMPELLER AND SHAFT ASSEMBLY *CF	35C4888-01 AAPPIAGV2079	MTH 10-Jun-2009 LDG 0		10500	0	(10500)10500	9429
725010 E1	HP COMPRESSOR ROTOR *CF	35C3661-01 TXA1B6034	MTH 10-Jun-2009 LDG 0		10500	0	(10500)10500	9429
725010 E2	HP COMPRESSOR ROTOR *CF	35C3661-01 TXA1B9324	MTH 10-Jun-2009 LDG 0		10500	0	(10500)10500	9429
726010 E1	AGB STARTER MAGNETIC SEAL KGY	3059712 N/A	MTH 18-Dec-2018 HRS 1786.8 LDG 1071		1750	0	(3536.8)3536.8	1750
726010 E2	AGB STARTER MAGNETIC SEAL UNK	35C1022-01 N/A	MTH 18-Dec-2018 HRS 1786.8 LDG 1071		1750	0	(3536.8)3536.8	1750
726030 E1	REAR BYPASS DUCT C56	35C2967-01 FDA8781420	MTH 21-Sep-2012 HRS 647.4 LDG 366		O/C	0		
730001 LEFT	ENGINE FUEL PRESSURE SWITCH 9912033-2 *CF	1103P0448 8858	MTH 10-Jun-2009		O/C			
730001 RIGHT	ENGINE FUEL PRESSURE SWITCH 9912033-2 *CF	1103P0448 8883	MTH 10-Jun-2009		O/C			
733001 LEFT	FUEL FLOW TRANSMITTER 9912417-1 *CF	TFF1573-4 0909-021	MTH 10-Jun-2009		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER 9912417-1 *CF	TFF1573-4 0909-026	MTH 10-Jun-2009		O/C			
732101 E1	FUEL METERING UNIT *CF	35C0794-04 16470017	MTH 10-Jun-2009		O/C			
732101 E2	FUEL METERING UNIT *CF	35C0794-04 16459652	MTH 10-Jun-2009		O/C			
741001 E1	IGNITION EXCITER *CF	35C5472-01 WDA108110	MTH 10-Jun-2009		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
741001 E2	IGNITION EXCITER	C56		35C5472-01 WDA116201	MTH 21-Sep-2012 HRS 647.4 LDG 366		O/C	0		
741002 E1 LEFT	IGNITER CABLE	*CF		35C0844-01 NSN	MTH 10-Jun-2009		O/C			
741002 E2 LEFT	IGNITER CABLE	*CF		35C0844-01 NSN	MTH 10-Jun-2009		O/C			
741003 E1 RIGHT	IGNITER CABLE	*CF		35C0799-01 NSN	MTH 10-Jun-2009		O/C			
741003 E2 RIGHT	IGNITER CABLE	*CF		35C0799-01 NSN	MTH 10-Jun-2009		O/C			
741004 E1 INBOARD	SPARK IGNITER	*CF		35C2353-01 NSN	MTH 10-Jun-2009		O/C			
741004 E2 INBOARD	SPARK IGNITER	*CF		35C2353-01 NSN	MTH 10-Jun-2009		O/C			
741005 E1 OUTBOARD	SPARK IGNITER	KGYY		35C2353-02 NSN	MTH 21-Jun-2018 HRS 1712.1 LDG 1025		O/C	0		
741005 E2 OUTBOARD	SPARK IGNITER	*CF		35C2353-01 NSN	MTH 10-Jun-2009		O/C			
751003 E1	BLEED VALVE ACTUATOR	*CF		35C2851-02 16419369	MTH 10-Jun-2009		O/C			
751003 E2	BLEED VALVE ACTUATOR	*CF		35C2851-02 16453557	MTH 10-Jun-2009		O/C			
761001 E1	FADEC 9912637-2	*CF		35C4035-04 09-617	MTH 10-Jun-2009		O/C			
761001 E2	FADEC 9912637-2	*CF		35C4035-04 09-623	MTH 10-Jun-2009		O/C			
791001 E1	FUEL TO OIL HEAT EXCHANGER	*CF		35C3778-02 WA35690	MTH 10-Jun-2009		O/C			
791001 E2	FUEL TO OIL HEAT EXCHANGER	*CF		35C3778-02 WA35687	MTH 10-Jun-2009		O/C			
793001 E1	OIL TEMP SENSOR	*CF		102-00083 07217	MTH 10-Jun-2009		O/C			
793001 E2	OIL TEMP SENSOR	*CF		102-00083 07247	MTH 10-Jun-2009		O/C			
793002 E1	OIL PRESSURE TRANSMITER	*CF		APTE-304A-250G 7512-7-310	MTH 10-Jun-2009		O/C			
793002 E2	OIL PRESSURE TRANSMITER	*CF		APTE-304A-250G 7512-7-292	MTH 10-Jun-2009		O/C			
793010 E1	CHIP COLLECTOR			PN SN-UNKNOWN	MTH 10-Jun-2009		O/C	0		
793010 E2	CHIP COLLECTOR	KGYY		35C0412-01 SN-UNKNOWN	MTH 05-Feb-2016 HRS 1173.2 LDG 735		O/C	0		
801000 LEFT	STARTER GENERATOR 9912676-1	KGYY		MG94E-1 242D	MTH 12-May-2017 HRS 1435.6 LDG 877		1500	0	2935.6	1148.8
801000 RIGHT	STARTER GENERATOR 9912676-1	KGYY		MG94E-1 0622D	MTH 12-May-2017 HRS 1435.6 LDG 877		1500	0	2935.6	1148.8



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2)			INFORMATIONAL						
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED						
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01)			RECOMMENDED						
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL						
	MOC :									
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01)			INFORMATIONAL						
	MOC :									
SL 510-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 510-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-99-01 REV 01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 02)			INFORMATIONAL						
	MOC :									
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL						
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 01)			INFORMATIONAL						
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH						
	MOC :			RECOMMENDED						
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)			INFORMATIONAL						
	MOC :									
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL						
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 01)			INFORMATIONAL						
	MOC :									
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05)			INFORMATIONAL			A/R			
	MOC :									
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL						
	MOC :									
SL 510-21-02 REV 01	CABIN ALTITUDE MODULE INSPECTION			MANDATORY			A/R			N/A
	MOC :			NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO -0061 THRU -0181.						



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT									
				RECOMMENDED	MTH		-			New Req
MOC :										
SL 510-21-05	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT									
				OPTIONAL			-			
MOC :										
SB 510-23-02	COMMUNICATIONS - ENABLE XM RADIO IN THE COCKPIT						A/R			
				OPTIONAL						
MOC :										
SL 510-24-08 REV 01	STARTER/GENERATOR INSPECTION			MANDATORY	MTH	30-Jun-2010		A/R		Complete
		MKE			HRS	82.1				
					LDG	51				
MOC : COMPLIED WITH - COMPLIED WITH SL510-24-08,REVISION 1,STARTER/GENERATOR INSPECTION,DATED: 03/10/2010.										
SL 510-24-10	CONTROL WHEEL ELECTRICAL CONNECTOR INSPECTION			MANDATORY	MTH			A/R		N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0226 THRU 510-0256 ONLY.										
SL 510-24-11 REV 01	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION			MANDATORY	MTH	29-Jul-2011		A/R		Complete
		MKE			HRS	370.2				
					LDG	210				
MOC : COMPLIED WITH - COMPLIED WITH SL510-24-11,REVISION 1, RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION,DATED: 10-28-2010.										
SL 510-24-11	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION (SUPERSEDED BY SL510-24-11 REV 01)			MANDATORY				A/R		N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SL 510-24-12	CONTROL COLUMN TIE STRAP INSPECTION			MANDATORY	MTH			A/R		N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0253 THRU 510-0323 ONLY.										
SL 510-24-13	ELECTRICAL POWER - THROTTLE QUADRANT WIRE BUNDLE INSPECTION			MANDATORY	MTH	29-Jul-2011		A/R		Complete
		MKE			HRS	370.2				
					LDG	210				
MOC : COMPLIED WITH - COMPLIED WITH SL510-24-13, THROTTLE QUADRANT WIRE BUNDLE INSPECTION,DATED: 6-30-2011.										
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION			MANDATORY	DAYS			180	12-Mar-2017	-29 m 24 d
					HRS			300	1596.15	-190.65
MOC :										
SL 510-24-14	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION (SUPERSEDED BY SL510-24-14 REV 01)			MANDATORY	DAYS			-		
MOC :										
SB 510-25-02	EQUIPMENT/FURNISHINGS - AFT CABIN CURTAIN IMPROVEMENT			OPTIONAL				A/R		
MOC :										
SB 510-25-03	EQUIPMENT/FURNISHINGS - REMOVAL OF THE CABIN SIDEWALL AIR DIFFUSER			DISCRETIONARY				A/R		
MOC :										
SB 510-25-04	EQUIPMENT/FURNISHINGS - CABIN COMFORT IMPROVEMENTS			OPTIONAL				-		
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-25-02	CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION	MKE	MANDATORY		DAYS 30-Jun-2010 HRS 82.1 LDG 51		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-25-02,CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION,DATED: 05/12/2010.										
SB 510-27-02	SPEED BRAKE MECHANICAL SWITCH CONVERSION	KMKE	RECOMMENDED		MTH 20-Nov-2013 HRS 796.1 LDG 476		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-27-02 SPEED BRAKE MECHANICAL SWITCH CONVERSION DATED 02/27/2013.										
SB 510-28-02 28SB-02	LOCKING FUEL CAP INSTALLATION		OPTIONAL		MTH		A/R			
MOC :										
SB 510-30-02 REV 01	PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT	KGYY	DISCRETIONARY		MTH 11-Apr-2016 HRS 1213 LDG 755		-			Complete
MOC : COMPLIED WITH - PERFORMED CESSNA SB510-30-02 REV 1 DATED JUNE 2, 2015 PER THE ACCOMPLISHMENT INSTRUCTIONS. INSTALLED KITS SB510-30-02-0 AND SB510-30-02-2.										
SB 510-30-02	ICE AND RAIN PROTECTION - PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT (SUPERSEDED BY 510-30-02 REV 01)		DISCRETIONARY				-			
MOC :										
SB 510-30-03 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT		DISCRETIONARY				A/R			
MOC :										
SB 510-30-03	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT (SUPERSEDED BY 510-30-03 REV 01)		DISCRETIONARY				A/R			
MOC :										
SB 510-30-04	ICE AND RAIN PROTECTION - WINDSHIELD CONTROLLER CONTACT REPLACEMENT		MANDATORY		MTH		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE C/W IN PRODUCTION SERIAL NUMBERS -0041 AND ON.										
SB 510-30-05	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION	KMKE	MANDATORY		MTH 20-Nov-2013 HRS 796.1 LDG 476		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-30-05 ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION DATED 04/04/2012.										
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT		RECOMMENDED		MTH		-			
MOC :										
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01)	KGYY	RECOMMENDED		MTH 11-Apr-2016 HRS 1213 LDG 755		-			Complete
MOC : COMPLIED WITH - PERFORMED SB510-30-06, DATED NOVEMBER 16, 2015 PER THE ACCOMPLISHMENT INSTRUCTIONS. INSTALLED KIT SB510-30-06-1. REMOVED THE RIGHT WINDSHIELD CONTROLLER P/N 7018108-25 S/N 0524A AND REPLACED WITH A NEW CONTROLLER P/N 7018108-30 S/N 0152. REMOVED THE LEFT WINDSHIELD CONTROLLER P/N 7018108-25 S/N 0523A AND REPLACED WITH A NEW CONTROLLER P/N 7018108-30 S/N 0160.										
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL				-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)			INFORMATIONAL				A/R		
MOC :										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL						
MOC :										
SL 510-31-03	COCKPIT SWITCH WIRE BUNDLE ASSEMBLY (WBA) INSPECTION	MKE	MANDATORY		MTH 30-Jun-2010 HRS 82.1 LDG 51			A/R		Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-31-03,COCKPIT SWITCH WIRE BUNDLE ASSEMBLY (WBA) INSPECTION,DATED: 12/14/2009.										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL						
MOC :										
SL 510-32-02 REV 01	EMERGENCY GEAR RELEASE INSPECTION	MKE	MANDATORY		MTH 30-Jun-2010 HRS 82.1 LDG 51			A/R		Complete
<i>32SL-02 : 510R1</i>										
MOC : COMPLIED WITH - COMPLIED WITH SL510-32-02,REVISION 1,EMERGENCY GEAR RELEASE INSPECTION,DATED: NOVEMBER 13,2009.										
SL 510-32-05	LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION	KMKE	RECOMMENDED		MTH 20-Nov-2013 HRS 796.1 LDG 476			-		Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-32-05 LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION DATED 04/20/2012.										
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION	GYG	MANDATORY		DAYS 21-Nov-2017 HRS 1569.9 LDG 950			-		N/A
MOC : NOT APPLICABLE										
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY	GYG	MANDATORY		DAYS 21-Nov-2017 HRS 1569.9 LDG 950			-		Complete
MOC : COMPLIED WITH										
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT			OPTIONAL						
MOC :										
SB 510-34-10	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION	*CF	OPTIONAL		MTH			A/R		
<i>34SB-10</i>										
MOC :										
SB 510-34-11 REV 01	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE	VYS	MANDATORY		MTH 21-Sep-2012 HRS 647.4 LDG 366			A/R		Complete
MOC : COMPLIED WITH - BY COMPLIANCE WITH -24 UPGRADE.										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-34-11	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE (SUPERSEDED BY 510-34-11 REV 01)	MKE		MANDATORY	MTH 29-Jul-2011 HRS 370.2 LDG 210		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-34-11, GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE, DATED: 7-13-2011.										
SB 510-34-12 REV 01	GARMIN DISPLAY IMPROVEMENT	KMKE		MANDATORY	MTH 20-Nov-2013 HRS 796.1 LDG 476		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-34-12 R1 GARMIN DISPLAY IMPROVEMENT DATED 02/13/2012.										
SB 510-34-12	GARMIN DISPLAY IMPROVEMENT (SUPERSEDED BY 510-34-12 REV 01)			MANDATORY	MTH		-			
MOC :										
SB 510-34-14	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE	VYS		MANDATORY	MTH 21-Sep-2012 HRS 647.4 LDG 366		-			Complete
MOC : COMPLIED WITH - C/W BY AVIONICS PLACE (CRS # FQ5R866M) 0N W.O. 14901										
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHSR SOFTWARE UPDATE			MANDATORY	MTH HRS		6 300		31-Mar-2017 1607.22	-29 m 5 d -179.58 Over Due
MOC :										
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)			OPTIONAL			-			
MOC :										
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03)			OPTIONAL			-			
MOC :										
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE			OPTIONAL			-			
MOC :										
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE			RECOMMENDED	MTH		-			
MOC :										
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE			INFORMATIONAL			-			
MOC :										
SL 510-34-11	STORED FLIGHT PLAN DELETION PER GARMIN SERVICE ADVISORY 0929 REV A			INFORMATIONAL			A/R			
MOC :										
SL 510-34-15	TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX 68 WEATHER RADAR MOD 1	MKE		RECOMMENDED	MTH 29-Jul-2011 HRS 370.2 LDG 210		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL510-34-15, TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX 68 WEATHER RADAR MOD 1, DATED: 10-28-										
SL 510-34-16	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1041 - GDL 69/69A NEXRAD WEATHER REPORTING ISSUE			INFORMATIONAL			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-34-17	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1101 - GDL 69/69A TFR (TEMPORARY FLIGHT RESTRICTIONS) REPORTING ISSUE			INFORMATIONAL						
	MOC :									
SL 510-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1107 - ANOMALIES IN GREENLAND TERRAIN DATA MAY INHIBIT OPERATIONAL CAPABILITY AND GARMIN TERRAIN DATA ALERT - ANOMALIES IN GREENLAND TERRAIN DATA			INFORMATIONAL						
	MOC :									
SL 510-34-19	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1118 - MOMENTARY FAILURE INDICATIONS (RED X) CAN OCCUR WHEN SORTING STORED FLIGHT PLANS			INFORMATIONAL						
	MOC :									
SL 510-34-20	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1129 - MOMENTARY LOSS OF GRS 77/77H AND GDC 74A/74B/74H FUNCTIONS			INFORMATIONAL						
	MOC :									
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION			INFORMATIONAL						
	MOC :									
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL			INFORMATIONAL						
	MOC :									
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT			RECOMMENDED						
	MOC :									
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS			INFORMATIONAL						
	MOC :									
SL 510-34-25	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1838 EMERGENCY DESCENT MODE (EDM)			INFORMATIONAL						
	MOC :									
SL 510-34-26	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG			INFORMATIONAL						
	MOC :									
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KGYY		MANDATORY	MTH 05-Feb-2016					Complete
					DAYS 1173.2					
					HRS 735					
					LDG					
	MOC :									
SL 510-35-01 REV 01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL510-35-01 REV 02)			MANDATORY						
	MOC :									
SL 510-35-01 REV 02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	KMKE		MANDATORY	MTH 20-Nov-2013					Complete
					HRS 796.1					
					LDG 476					
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-35-01	INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY (SUPERSEDED BY SL510-35-01REV 01)									
	MANDATORY									
	MOC :									
SB 510-52-05	AFT BAGGAGE DOOR MODIFICATION		DISCRETIONARY				A/R			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE C/W AT PRODUCTION ON -0095 AND ON.									
SL 510-52-01 REV 01	CABIN ENTRY DOOR HINGE FASTENER INSPECTION		MANDATORY		MTH		A/R			Complete
	MOC : COMPLIED WITH - PARTIALLY AT MFG THIS SL IS COMPLIED WITH IN PRODUCTION ON SERIAL NUMBERS -0200 AND ON.									
SL 510-52-04	DOORS - CABIN ENTRY DOOR PIN REPAIR		INFORMATIONAL				A/R			
	MOC :									
SL 510-53-03	FUSELAGE - DRAIN HOLE INSPECTION		MANDATORY		MTH 30-Jun-2010		A/R			Complete
	MKE				HRS 82.1					
					LDG 51					
	MOC : COMPLIED WITH - COMPLIED WITH SL510-53-03,DRAIN HOLE INSPECTION,DATED: 03/05/2010.									
SB 510-54-01 REV 01	PYLON SKIN IMPROVEMENTS		DISCRETIONARY		MTH 20-Nov-2013		-			Complete
	KMKE				HRS 796.1					
					LDG 476					
	MOC : COMPLIED WITH - COMPLIED WITH SB510-54-01 R1 PYLON SKIN IMPROVEMENTS DATED 06/04/2012.									
SL 510-55-02 REV 01	HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 02)		MANDATORY		DAYS 29-Jul-2011		A/R			Complete
	MKE				HRS 370.2					
					LDG 210					
	MOC : COMPLIED WITH - COMPLIED WITH SL510-55-02,REVISION 1, HORIZONTAL STABILIZER SEALANT INSPECTION,DATED: 4-28-2011.									
SL 510-55-02	STABILIZERS - HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 01)		MANDATORY				A/R			
	MOC :									
SB PW600-72-63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS		CATEGORY 5		MTH 16-Mar-2009		-			Complete
	*CF									
	MOC : COMPLIED WITH									
SB PW600-72-63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS		CATEGORY 5		MTH 19-Mar-2009		-			Complete
	*CF									
	MOC : COMPLIED WITH									
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE		CATEGORY 9		MTH 16-Mar-2009		-			Complete
	*CF									
	MOC : COMPLIED WITH									
SB PW600-72-63003 E2	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE		CATEGORY 9		MTH 19-Mar-2009		-			Complete
	*CF									
	MOC : COMPLIED WITH									
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING		CATEGORY 5		MTH 16-Mar-2009		-			Complete
	*CF									
	MOC : COMPLIED WITH									
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING		CATEGORY 5		MTH 19-Mar-2009		-			Complete
	*CF									
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE *CF			CATEGORY 9	MTH 16-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE *CF			CATEGORY 9	MTH 19-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY *CF			CATEGORY 7	MTH 16-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63007 E2	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY *CF			CATEGORY 7	MTH 19-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY *CF			CATEGORY 8	MTH 16-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63010 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY *CF			CATEGORY 8	MTH 19-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63012 R01 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63012 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01) *CF			CATEGORY 6	MTH 16-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63012 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01) *CF			CATEGORY 6	MTH 19-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63013 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) *CF			CATEGORY 7	MTH 16-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63013 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01) *CF			CATEGORY 7	MTH 19-Mar-2009		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY *CF	CATEGORY 7	MTH	16-Mar-2009	-					Complete
MOC : COMPLIED WITH										
SB PW600-72-63016 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY *CF	CATEGORY 7	MTH	19-Mar-2009	-					Complete
MOC : COMPLIED WITH										
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS	CATEGORY 7			-					
MOC :										
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS	CATEGORY 7			-					
MOC :										
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01) *CF	CATEGORY 7	MTH	16-Mar-2009	-					Complete
MOC : COMPLIED WITH										
SB PW600-72-63017 E2	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01) *CF	CATEGORY 7	MTH	19-Mar-2009	-					Complete
MOC : COMPLIED WITH										
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY	CATEGORY 6			-					
MOC :										
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY	CATEGORY 6			-					
MOC :										
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01) *CF	CATEGORY 9	MTH	16-Mar-2009	-					Complete
MOC : COMPLIED WITH										
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01) *CF	CATEGORY 9	MTH	19-Mar-2009	-					Complete
MOC : COMPLIED WITH										
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)	CATEGORY 7			-					
MOC :										
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)	CATEGORY 7			-					
MOC :										
SB PW600-72-63022 R2 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY	CATEGORY 7			-					
MOC :										
SB PW600-72-63022 R2 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY	CATEGORY 7			-					
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)	*CF	CATEGORY 7	MTH	16-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63022 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)	*CF	CATEGORY 7	MTH	19-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING	*CF	CATEGORY 7	MTH	16-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63024 E2	REPLACEMENT OF NO. 4 ROLLER BEARING	*CF	CATEGORY 7	MTH	19-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER	*CF	CATEGORY 7	MTH	16-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63025 E2	REPLACEMENT OF SEAL RUNNER	*CF	CATEGORY 7	MTH	19-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY	*CF	CATEGORY 9	MTH	16-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63026 E2	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY	*CF	CATEGORY 9	MTH	19-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63027 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01)	*CF	CATEGORY 8	MTH	16-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63027 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63027 R01)	*CF	CATEGORY 8	MTH	19-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63028 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01)	*CF	CATEGORY 5	MTH	16-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63028 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01)	*CF	CATEGORY 5	MTH	19-Mar-2009	-				Complete
MOC : COMPLIED WITH										
SB PW600-72-63031 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY		CATEGORY 7					A/R		
MOC :										
SB PW600-72-63031 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY		CATEGORY 7					A/R		
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63031 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01)	*CF	CATEGORY 7	MTH	16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63031 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01)	*CF	CATEGORY 7	MTH	19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING	*CF	CATEGORY 7	MTH	16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63032 E2	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING	*CF	CATEGORY 7	MTH	19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE	*CF	CATEGORY 8	MTH	16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63034 E2	REPLACEMENT OF OIL PUMP PLATE	*CF	CATEGORY 8	MTH	19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY	*CF	CATEGORY 7	MTH	16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63035 E2	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY	*CF	CATEGORY 7	MTH	19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63037 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01)	*CF	CATEGORY 7	MTH	16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63037 E2	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63037 R01)	*CF	CATEGORY 7	MTH	19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY	*CF	CATEGORY 7	MTH	16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63039 E2	REPLACEMENT OF LPT VANE RING ASSEMBLY	*CF	CATEGORY 7	MTH	19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY	*CF	CATEGORY 7	MTH	16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63040 E2	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY	*CF	CATEGORY 7	MTH	19-Mar-2009		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY *CF	CATEGORY 7	MTH	16-Mar-2009	-				Complete	
MOC : COMPLIED WITH										
SB PW600-72-63041 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY *CF	CATEGORY 7	MTH	19-Mar-2009	-				Complete	
MOC : COMPLIED WITH										
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY *CF	CATEGORY 7	MTH	16-Mar-2009	-				Complete	
MOC : COMPLIED WITH										
SB PW600-72-63042 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY *CF	CATEGORY 7	MTH	19-Mar-2009	-				Complete	
MOC : COMPLIED WITH										
SB PW600-72-63043 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01) *CF	CATEGORY 6	MTH	16-Mar-2009	-				Complete	
MOC : COMPLIED WITH										
SB PW600-72-63043 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01) *CF	CATEGORY 6	MTH	19-Mar-2009	-				Complete	
MOC : COMPLIED WITH										
SB PW600-72-63044 E1	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY	CATEGORY 6			-					
MOC :										
SB PW600-72-63044 E2	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY	CATEGORY 6			-					
MOC :										
SB PW600-72-63045 R01 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY				-					
MOC :										
SB PW600-72-63045 R01 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY				-					
MOC :										
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01) *CF	CATEGORY 7	MTH	16-Mar-2009	-				Complete	
MOC : COMPLIED WITH										
SB PW600-72-63045 E2	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01) *CF	CATEGORY 7	MTH	19-Mar-2009	-				Complete	
MOC : COMPLIED WITH										
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES	CATEGORY 6			-					
MOC :										
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES	CATEGORY 6			-					
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63051 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01) *CF MOC : COMPLIED WITH	CATEGORY 7	MTH	16-Mar-2009		-				Complete
SB PW600-72-63051 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R01) *CF MOC : COMPLIED WITH	CATEGORY 7	MTH	19-Mar-2009		-				Complete
SB PW600-72-63052 R01 E1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF MOC :	CATEGORY 7				A/R				
SB PW600-72-63052 R01 E2	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF MOC :	CATEGORY 7				A/R				
SB PW600-72-63052 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01) *CF MOC : COMPLIED WITH	CATEGORY 7	MTH	16-Mar-2009		-				Complete
SB PW600-72-63052 E2	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01) *CF MOC : COMPLIED WITH	CATEGORY 7	MTH	19-Mar-2009		-				Complete
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS MOC :	CATEGORY 7				-				
SB PW600-72-63053 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS MOC :	CATEGORY 7				-				
SB PW600-72-63053 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01) *CF MOC : COMPLIED WITH	CATEGORY 7	MTH	16-Mar-2009		-				Complete
SB PW600-72-63053 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01) *CF MOC : COMPLIED WITH	CATEGORY 7	MTH	19-Mar-2009		-				Complete
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER *CF MOC : COMPLIED WITH	CATEGORY 7	MTH	16-Mar-2009		-				Complete
SB PW600-72-63057 E2	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER *CF MOC : COMPLIED WITH	CATEGORY 7	MTH	19-Mar-2009		-				Complete
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST MOC :	CATEGORY 9				-				
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST MOC :	CATEGORY 9				-				



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY									
	MOC :									
SB PW600-72-63059 R02 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY									
	MOC :									
SB PW600-72-63059 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)	*CF	CATEGORY 6	MTH	16-Mar-2009	-				Complete
	MOC : COMPLIED WITH									
SB PW600-72-63059 E2	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)	*CF	CATEGORY 6	MTH	19-Mar-2009	-				Complete
	MOC : COMPLIED WITH									
SB PW600-72-63062 R01 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL									
	MOC :									
SB PW600-72-63062 R01 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL									
	MOC :									
SB PW600-72-63062 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)	*CF	CATEGORY 7	MTH		-				
	MOC :									
SB PW600-72-63062 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)	*CF	CATEGORY 7	MTH		-				
	MOC :									
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)		CATEGORY 6				A/R			
	MOC :									
SB PW600-72-63064 R01 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02)		CATEGORY 6				A/R			
	MOC :									
SB PW600-72-63064 R02 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY									
	MOC :									
SB PW600-72-63064 R02 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY									
	MOC :									
SB PW600-72-63064 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)		CATEGORY 6	MTH		-				
	MOC :									
SB PW600-72-63064 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01)		CATEGORY 6	MTH		-				
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF	CATEGORY 7								
	MOC :									
SB PW600-72-63065 R01 E2	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF	CATEGORY 7								
	MOC :									
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER	CATEGORY 7	MTH							
	MOC :									
SB PW600-72-63066 E2	REPLACEMENT OF IGNITER	CATEGORY 7	MTH							
	MOC :									
SB PW600-72-63068 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY	CATEGORY 6					A/R			
	MOC :									
SB PW600-72-63068 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY	CATEGORY 6					A/R			
	MOC :									
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY	CATEGORY 6	MTH				A/R			
	MOC :									
SB PW600-72-63070 E2	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY	CATEGORY 6	MTH				A/R			
	MOC :									
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING	CATEGORY 7								
	MOC :									
SB PW600-72-63072 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING	CATEGORY 7								
	MOC :									
SB PW600-72-63072 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)	CATEGORY 7					A/R			
	MOC :									
SB PW600-72-63072 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01)	CATEGORY 7					A/R			
	MOC :									
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY	CATEGORY 7								
	MOC :									
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY	CATEGORY 7								
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63077 R01 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02)	CATEGORY 6								
	MOC :									
SB PW600-72-63077 R01 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02)	CATEGORY 6								
	MOC :									
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR	CATEGORY 6								
	MOC :									
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR	CATEGORY 6								
	MOC :									
SB PW600-72-63077 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01)	CATEGORY 6								
	MOC :									
SB PW600-72-63077 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01)	CATEGORY 6								
	MOC :									
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER	CATEGORY 7								
	MOC :									
SB PW600-72-63078 E2	REPLACEMENT OF HIGH PRESSURE IMPELLER	CATEGORY 7								
	MOC :									
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)	CATEGORY 6								
	MOC :									
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)	CATEGORY 6								
	MOC :									
SB PW600-72-63081 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL	CATEGORY 5								
	MOC :									
SB PW600-72-63081 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL	CATEGORY 5								
	MOC :									
SB PW600-72-63081 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)	CATEGORY 5								
	MOC :									
SB PW600-72-63081 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)	CATEGORY 5								
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63083 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7						
	MOC :									
SB PW600-72-63083 R01 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7						
	MOC :									
SB PW600-72-63083 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63083 E2	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63084 E2	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63085 E2	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63086 E2	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	KMKE		CATEGORY 3	MTH 20-Nov-2013 HRS 796.1 LDG 476		-			Complete
	MOC :									
SB PW600-72-63087 R02 E2	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL	KMKE		CATEGORY 3	MTH 20-Nov-2013 HRS 796.1 LDG 476		-			Complete
	MOC :									
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63088 E2	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY									
				CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63089 R01 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)									
				CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63089 R01 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)									
				CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF						-			
				CATEGORY 6						
	MOC :									
SB PW600-72-63089 R02 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF						-			
				CATEGORY 6						
	MOC :									
SB PW600-72-63089 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)						-			
				CATEGORY 6						
	MOC :									
SB PW600-72-63089 E2	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)						-			
				CATEGORY 6						
	MOC :									
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
				CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63090 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
				CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)									
				CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 R01 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)									
				CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS									
				CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS									
				CATEGORY 6			-			
	MOC :									
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)									
				CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63091 E2	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)	CATEGORY 6								
MOC :										
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT	CATEGORY 7								
MOC :										
SB PW600-72-63092 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT	CATEGORY 7								
MOC :										
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET	CATEGORY 6					A/R			
MOC :										
SB PW600-72-63093 E2	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET	CATEGORY 6					A/R			
MOC :										
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS	CATEGORY 7								
MOC :										
SB PW600-72-63094 R01 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS	CATEGORY 7								
MOC :										
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01)	CATEGORY 7								
MOC :										
SB PW600-72-63094 E2	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01)	CATEGORY 7								
MOC :										
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF	CATEGORY 7								
MOC :										
SB PW600-72-63095 E2	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF	CATEGORY 7								
MOC :										
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY	CATEGORY 7								
MOC :										
SB PW600-72-63096 E2	REPLACEMENT OF OIL NOZZLE ASSEMBLY	CATEGORY 7								
MOC :										
SB PW600-72-63097 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63097 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)									
	MOC :									
SB PW600-72-63097 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)									
	MOC :									
SB PW600-72-63097 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01)									
	MOC :									
SB PW600-72-63098 E1	INSPECTION OF - HP DIFFUSER CASE ASSY									
				CATEGORY 5						
	MOC :									
SB PW600-72-63098 E2	INSPECTION OF - HP DIFFUSER CASE ASSY									
				CATEGORY 5						
	MOC :									
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET									
				CATEGORY 7						
	MOC :									
SB PW600-72-63099 E2	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET									
				CATEGORY 7						
	MOC :									
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT									
	MOC :									
SB PW600-72-63100 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT									
	MOC :									
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY									
				RECOMMENDED				MTH		
	MOC :									
SB PW600-72-63101 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY									
				RECOMMENDED				MTH		
	MOC :									
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL									
				RECOMMENDED						
	MOC :									
SB PW600-72-63102 R01 E2	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL									
				RECOMMENDED						
	MOC :									
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63103 E2	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH									
	MOC :									
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7						
	MOC :									
SB PW600-72-63104 E2	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7						
	MOC :									
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7						
	MOC :									
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7						
	MOC :									
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01)			CATEGORY 7						
	MOC :									
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01)			CATEGORY 7						
	MOC :									
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5						
	MOC :									
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5						
	MOC :									
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01)			CATEGORY 5						
	MOC :									
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01)			CATEGORY 5						
	MOC :									
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7						
	MOC :									
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7						
	MOC :									
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE			CATEGORY 5						
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE									
		CATEGORY 5								
	MOC :									
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE									
		CATEGORY 5								
	MOC :									
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE									
		CATEGORY 5								
	MOC :									
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING									
		CATEGORY 3		MTH			12		20-Nov-2019	2 m 15 d
				HRS			600		(2394.17)2394.17	607.37
	MOC :									
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING									
		CATEGORY 3		MTH			12		20-Nov-2019	2 m 15 d
				HRS			600		(2394.17)2394.17	607.37
	MOC :									
ASB PW600-72-A63071 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02)									
		MKE		CATEGORY 3	MTH	21-Feb-2011		A/R		Complete
					HRS	255				
					LDG	141				
	MOC :									
	COMPLIED WITH - COMPLIED WITH ASB63071 BY COMPLETING ASL510-73-02 . ASL WAS DONE ON JUNE 30, 2010, WITH 82.1 HOURS AND 51 CYCLES.									
ASB PW600-72-A63071 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02)									
		MKE		CATEGORY 3	MTH	21-Feb-2011		A/R		Complete
					HRS	255				
					LDG	141				
	MOC :									
	COMPLIED WITH - COMPLIED WITH ASB A63071 R1 BY COMPLETING ASL510-73-02. ASL WAS DONE ON JUNE 30, 2010, WITH 82.1 HOURS AND 51 CYCLES.									
ASB PW600-72-A63071 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
				CATEGORY 3						
	MOC :									
ASB PW600-72-A63071 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
				CATEGORY 3						
	MOC :									
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS									
				CATEGORY 7				A/R		
	MOC :									
SB PW600-73-63030 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS									
				CATEGORY 7				A/R		
	MOC :									
ASL 510-73-01 LEFT 73ASL01 : L	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
				MANDATORY	HRS			-25		A/R
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
ASL 510-73-01 RIGHT <i>73ASL01 : R</i>	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE					175				
				MANDATORY	HRS					
MOC :										
ASL 510-73-02 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFANENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE				MTH 30-Jun-2010 HRS 82.1 LDG 51		A/R			Complete
		MKE		MANDATORY						
MOC : COMPLIED WITH - COMPLIED WITH ASL510-73-02,TRANSMITTAL OF PWC SERVICE BULLETIN A63071,DATED: 01/07/2010.										
ASL 510-73-02 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE				MTH 30-Jun-2010 HRS 82.1 LDG 51		A/R			Complete
		MKE		MANDATORY						
MOC : COMPLIED WITH - COMPLIED WITH ASL510-73-02,TRANSMITTAL OF PWC SERVICE BULLETIN A63071,DATED: 01/07/2010.										
SB PW600-1007-63009 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY				MTH 16-Mar-2009		-			Complete
		*CF		CATEGORY 8						
MOC : COMPLIED WITH										
SB PW600-1007-63009 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY				MTH 19-Mar-2009		-			Complete
		*CF		CATEGORY 8						
MOC : COMPLIED WITH										
SB PW600-72-63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE							A/R		
				CATEGORY 6						
MOC :										
SB PW600-72-63073 E2	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE							A/R		
				CATEGORY 6						
MOC :										
SB PW600-72-63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE)							A/R		
				CATEGORY 7						
MOC :										
SB PW600-72-63075 E2	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE)							A/R		
				CATEGORY 7						
MOC :										
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY							A/R		
				CATEGORY 7						
MOC :										
SB PW600-72-63079 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY							A/R		
				CATEGORY 7						
MOC :										
SB PW600-72-63080 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02)							A/R		
				CATEGORY 6						
MOC :										
SB PW600-72-63080 R01 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02)							A/R		
				CATEGORY 6						
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-72-63080 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01)			CATEGORY 6						
MOC :										
SB PW600-72-63080 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01)			CATEGORY 6						
MOC :										
SB PW600-72-63082 E1	INSPECTION OF BYPASS-DUCT FUEL FAIRING			CATEGORY 5	MTH			A/R		
MOC :										
SB PW600-72-63082 E2	INSPECTION OF BYPASS-DUCT FUEL FAIRING			CATEGORY 5	MTH			A/R		
MOC :										
ASB PW600-72-A63061 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)			CATEGORY 3						
MOC :										
ASB PW600-72-A63061 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02)			CATEGORY 3						
MOC :										
ASB PW600-72-A63061 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 3				A/R		Complete
MOC : COMPLIED WITH - AT MANUFACTURE COMPLIED WITH AT PRODUCTION ON ENGINE SERIAL NUMBERS PCE-LB0366 AND UP.										
ASB PW600-72-A63061 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 3				A/R		Complete
MOC : COMPLIED WITH - AT MANUFACTURE COMPLIED WITH AT PRODUCTION ON ENGINE SERIAL NUMBERS PCE-LB0366 AND UP.										
ASB PW600-72-A63061 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)	*CF		CATEGORY 3	MTH	16-Mar-2009		-		Complete
MOC : COMPLIED WITH										
ASB PW600-72-A63061 E2	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01)	*CF		CATEGORY 3	MTH	19-Mar-2009		-		Complete
MOC : COMPLIED WITH										
ASB PW600-72-A63069 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R02)			CATEGORY 3	MTH			A/R		
MOC :										
ASB PW600-72-A63069 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R02)			CATEGORY 3	MTH			A/R		
MOC :										
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN			CATEGORY 7	MTH	16-Mar-2009		-		Complete
MOC : COMPLIED WITH										
SB PW600-73-63004 E2	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN			CATEGORY 7	MTH	19-Mar-2009		-		Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-73-63011 R01 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) *CF	CATEGORY 8	MTH	16-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63011 R01 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) *CF	CATEGORY 8	MTH	19-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF	CATEGORY 7	MTH	16-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63014 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF	CATEGORY 7	MTH	19-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT *CF	CATEGORY 8	MTH	16-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT *CF	CATEGORY 8	MTH	19-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY *CF	CATEGORY 7	MTH	16-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63023 E2	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY *CF	CATEGORY 7	MTH	19-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF	CATEGORY 7	MTH	16-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63029 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY *CF	CATEGORY 7	MTH	19-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63030 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) *CF	CATEGORY 8	MTH	16-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63030 E2	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) *CF	CATEGORY 8	MTH	19-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER *CF	CATEGORY 7	MTH	16-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-73-63036 E2	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER *CF	CATEGORY 7	MTH	19-Mar-2009		-				Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED -
BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) *CF			CATEGORY 7	MTH 16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) *CF			CATEGORY 7	MTH 19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT *CF			CATEGORY 7	MTH 16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63048 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT *CF			CATEGORY 7	MTH 19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT *CF			CATEGORY 7	MTH 16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-73-63049 E2	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT *CF			CATEGORY 7	MTH 19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER *CF			CATEGORY 7	MTH 16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER *CF			CATEGORY 7	MTH 19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS *CF			CATEGORY 6	MTH 16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS *CF			CATEGORY 6	MTH 19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-75-63054 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01) *CF			CATEGORY 7	MTH 16-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB PW600-75-63054 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA) (SUPERSEDED BY PW600-75-63054 R01) *CF			CATEGORY 7	MTH 19-Mar-2009		-			Complete
MOC : COMPLIED WITH										
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETN PW600-72-63087 KMKE			MANDATORY	MTH 20-Nov-2013 HRS 796.1 LDG 476		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB510-76-01 R2 TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW600-72-63087 DATED 09/04/2012.										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED -
BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS	*CF		CATEGORY 8	MTH 16-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS	*CF		CATEGORY 8	MTH 19-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB 510-79-03	OIL - OIL PRESSURE TRANSDUCER REPLACEMENT			OPTIONAL			-			
	MOC :									
SL 510-79-02	OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION	MKE		MANDATORY	DAYS 29-Jul-2011 HRS 370.2 LDG 210		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-79-02, OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION, DATED: 3-17-2011.									
SB PW600-72-63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER	*CF		CATEGORY 7	MTH 16-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER	*CF		CATEGORY 7	MTH 19-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)						-			
	MOC :									
SB PW600-72-63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)						-			
	MOC :									
SB PW600-79-63008 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)	*CF			MTH 16-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79-63008 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)	*CF			MTH 19-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79-63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER	*CF		CATEGORY 7	MTH 16-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79-63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER	*CF		CATEGORY 7	MTH 19-Mar-2009		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79-63018 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER	*CF		CATEGORY 7	MTH		-			
	MOC :									
SB PW600-79-63018 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER	*CF		CATEGORY 7	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED -
BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW600-79-63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH *CF	CATEGORY 7	MTH	16-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-79-63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH *CF	CATEGORY 7	MTH	19-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-79-63047 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01) *CF		MTH	16-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SB PW600-79-63047 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01) *CF		MTH	19-Mar-2009		-				Complete
MOC : COMPLIED WITH										
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM RECOMMENDED		MTH			-				
MOC :										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS CANCELLED					-				
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS CANCELLED					-				
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) CANCELLED					-				
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW CANCELLED					-				
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	KGYY	MANDATORY	MTH	22-Jul-2015	-				N/A
					HRS 1065.7					
					LDG 667					
	MOC : NOT APPLICABLE - AD 2015-10-02- ZODIAC SEATS FRANCE BACKREST LINK CRACKS, EFFECTIVE DATE JUNE 12, 2015 DOES NOT APPLY. ZODIAC AEROSPACE SEATS ARE NOT INSTALLED IN THE AIRPLANE.									
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	KGYY	MANDATORY	MTH	22-Jul-2015	-				N/A
					HRS 1065.7					
					LDG 667					
	MOC : NOT APPLICABLE - AD 2015-10-02- ZODIAC SEATS FRANCE BACKREST LINK CRACKS, EFFECTIVE DATE JUNE 12, 2015 DOES NOT APPLY. ZODIAC AEROSPACE SEATS ARE NOT INSTALLED IN THE AIRPLANE.									
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	KGYY	MANDATORY	MTH	22-Jul-2015	-				N/A
					HRS 1065.7					
					LDG 667					
	MOC : NOT APPLICABLE - AD 2015-10-02- ZODIAC SEATS FRANCE BACKREST LINK CRACKS, EFFECTIVE DATE JUNE 12, 2015 DOES NOT APPLY. ZODIAC AEROSPACE SEATS ARE NOT INSTALLED IN THE AIRPLANE.									
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KGYY	MANDATORY	MTH	22-Jul-2015	-				N/A
					HRS 1065.7					
					LDG 667					
	MOC : NOT APPLICABLE - AD 2015-10-02- ZODIAC SEATS FRANCE BACKREST LINK CRACKS, EFFECTIVE DATE JUNE 12, 2015 DOES NOT APPLY. ZODIAC AEROSPACE SEATS ARE NOT INSTALLED IN THE AIRPLANE.									
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS, TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS		MANDATORY	MTH			12		24-Oct-2018	-10 m 12 d Over Due
	MOC :									
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT		MANDATORY				-			
	MOC :									
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS		MANDATORY				-			
	MOC :									
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH	KGYY	MANDATORY	DAYS	19-Apr-2018	-				Complete
					HRS 1655.1					
	MOC : COMPLIED WITH									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	MKE	MANDATORY	MTH	26-Jan-2015	-				N/A
					HRS 929.7					
					LDG 571					
	MOC : NOT APPLICABLE - AD 2014-18-01 ROCKWELL COLLINS MODE S TRANSPONDERS IS FOUND TO BE N/A THIS AIRCRAFT DUE TO EQUIPMENT NOT INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	MANDATORY	MTH 22-Jul-2015							N/A
		KGYY		HRS 1065.7						
				LDG 667						
MOC : NOT APPLICABLE - AD 2015-10-51-E AVIDYNE IFD MODEL R9 AND MODEL IFD540, EFFECTIVE DATE MAY 28, 2015 DOES NOT APPLY. AVIDYNE IFD'S ARE NOT INSTALLED IN THIS AIRPLANE.										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	MANDATORY	MTH 22-Jul-2015							N/A
		KGYY		HRS 1065.7						
				LDG 667						
MOC : NOT APPLICABLE - AD 2015-10-51-E AVIDYNE IFD MODEL R9 AND MODEL IFD540, EFFECTIVE DATE MAY 28, 2015 DOES NOT APPLY. AVIDYNE IFD'S ARE NOT INSTALLED IN THIS AIRPLANE.										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	MANDATORY	MTH 04-Jun-2015							Complete
		KGYY		HRS 1036.6						
				LDG 650						
MOC : COMPLIED WITH - PERFORMED AD 2015-08-07 OXYGEN MASK INFLATEABLE HARNESS, EFFECTIVE DATE JUNE 16, 2015 PER PARA (G) UTILIZING ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011. NO ACTION REQUIRED DUE TO PILOT OXYGEN MASK HARNESS MFD 0844 AND CO-PILOT MFD 0844.										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	MANDATORY	MTH			24		16-Jun-2017		-26 m 20 d
Over Due										
MOC :										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	MANDATORY								
MOC :										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	MANDATORY	MTH 05-Feb-2016							N/A
		KGYY		DAYS 1173.2						
				HRS 735						
				LDG						
MOC : NOT APPLICABLE - PERFORMED AD 2015-23-09, EFFECTIVE DATE DECEMBER 28, 2015, PER PARA (G). UTILIZED ZODIAC AEROSPACE SB MCF-SBU-35-001, REV 1, DATED DECEMBER 3, 2012 APPENDIX L. INSTALLED MASKS PILOT P/N MC10-16-101 S/N SE27818 AND CO-PILOT P/N MC10-16-101 S/N SE27823 ARE NOT LISTED. NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	MANDATORY	MTH 05-Feb-2016							N/A
		KGYY		DAYS 1173.2						
				HRS 735						
				LDG						
MOC : NOT APPLICABLE - PERFORMED AD 2015-23-09, EFFECTIVE DATE DECEMBER 28, 2015, PER PARA (G). UTILIZED ZODIAC AEROSPACE SB MCF-SBU-35-001, REV 1, DATED DECEMBER 3, 2012 APPENDIX L. INSTALLED MASKS PILOT P/N MC10-16-101 S/N SE27818 AND CO-PILOT P/N MC10-16-101 S/N SE27823 ARE NOT LISTED. NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09 PARA (H.2.1)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	MANDATORY	MTH 05-Feb-2016							N/A
		KGYY		DAYS 1173.2						
				HRS 735						
				LDG						
MOC : NOT APPLICABLE - PERFORMED AD 2015-23-09, EFFECTIVE DATE DECEMBER 28, 2015, PER PARA (G). UTILIZED ZODIAC AEROSPACE SB MCF-SBU-35-001, REV 1, DATED DECEMBER 3, 2012 APPENDIX L. INSTALLED MASKS PILOT P/N MC10-16-101 S/N SE27818 AND CO-PILOT P/N MC10-16-101 S/N SE27823 ARE NOT LISTED. NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	MANDATORY	MTH 05-Feb-2016							N/A
	KGYY		DAYS 1173.2							
			HRS 735							
			LDG							
	MOC : NOT APPLICABLE - PERFORMED AD 2015-23-09, EFFECTIVE DATE DECEMBER 28, 2015, PER PARA (G). UTILIZED ZODIAC AEROSPACE SB MCF-SBU-35-001, REV 1, DATED DECEMBER 3, 2012 APPENDIX L. INSTALLED MASKS PILOT P/N MC10-16-101 S/N SE27818 AND CO-PILOT P/N MC10-16-101 S/N SE27823 ARE NOT LISTED. NO FURTHER ACTION REQUIRED.									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	MANDATORY	MTH 05-Feb-2016							N/A
	KGYY		HRS 1173.2							
			LDG 735							
	MOC : NOT APPLICABLE - PERFORMED AD 2015-23-09, EFFECTIVE DATE DECEMBER 28, 2015, PER PARA (G). UTILIZED ZODIAC AEROSPACE SB MCF-SBU-35-001, REV 1, DATED DECEMBER 3, 2012 APPENDIX L. INSTALLED MASKS PILOT P/N MC10-16-101 S/N SE27818 AND CO-PILOT P/N MC10-16-101 S/N SE27823 ARE NOT LISTED. NO FURTHER ACTION REQUIRED.									
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	MANDATORY	MTH 05-Feb-2016							Complete
	KGYY		HRS 1173.2							
			LDG 735							
	MOC : COMPLIED WITH - PERFORMED AD 2015-23-09, EFFECTIVE DATE DECEMBER 28, 2015, PER PARA (G). UTILIZED ZODIAC AEROSPACE SB MCF-SBU-35-001, REV 1, DATED DECEMBER 3, 2012 APPENDIX L. INSTALLED MASKS PILOT P/N MC10-16-101 S/N SE27818 AND CO-PILOT P/N MC10-16-101 S/N SE27823 ARE NOT LISTED. NO FURTHER ACTION REQUIRED.									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	MANDATORY	MTH 08-Sep-2016							N/A
	KGYY		HRS 1292.9							
			LDG 804							
			ACH 126.6							
	MOC : NOT APPLICABLE - PBE INSPECTION, EFFECTIVE DATE JULY 15, 2016 DOES NOT APPLY. PBE NOT INSTALED IN AIRCRAFT.									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY								
	MOC :									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY	MTH							
	MOC :									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	MANDATORY								
	MOC :									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	MANDATORY								
	MOC :									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	MANDATORY								
	MOC :									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	MANDATORY	MTH							
							6		16-Apr-2018	-16 m 20 d
	MOC :									
										Over Due



CESCOM 10 - Aircraft Status Report

Owner: **DUNCAN AVIATION INCORPORATED - BATTLE CREEK**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:00PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	1786.8	1071	05-Sep-2019	.9
ENG 1	1786.8	1071	05-Sep-2019	.9
ENG 2	1786.8	1071	05-Sep-2019	.9
AIR COND	172.2		05-Sep-2019	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES									
				MANDATORY			-			
MOC :										
FAA 2010-17-06	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
E1		MKE		MANDATORY	MTH 21-Feb-2011		-			Complete
					HRS 255					
					LDG 141					
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH AD2010-17-06 BY COMPLETING ASL510-73-02 AND ASB A63071 R1. ASL AND ASB WERE DONE ON JUNE 30, 2010, WITH 82.1 HOURS AND 51 CYCLES.										
FAA 2010-17-06	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE									
E2		MKE		MANDATORY	MTH 21-Feb-2011		-			Complete
					HRS 255					
					LDG 141					
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH AD2010-17-06 BY COMPLETING ASL510-73-02 AND ASB A63071 R1. ASL AND ASB WERE DONE ON JUNE 30, 2010, WITH 82.1 HOURS AND 51 CYCLES.										



CESCOM 20 - Projected Maintenance Due

Owner: **DUNCAN AVIATION
INCORPORATED - BATTLE
CREEK**

Aircraft Model: **510 - CITATION MUSTANG**

Aircraft Serial: **510-0218**

Unit: **0218** Reg No: **N949JB**

Airworthiness: **10-Jun-2009**

Print Date: **05-Sep-2019 12:02PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 1	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 2	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
AIR COND	172.2		05-Sep-2019	.9	0.90	680.4		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

New Requirements/Action Items

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE		MTH	21-Jun-2018			288			?
	9914678-3	KGYG		40005369-2	HRS	1712.1				
				6859	LDG	1025				
	MISSING "MANUFACTURE DATE" TO INSTALLED "OVERHAULED" UNIT. PLEASE SUPPLY MISSING INFORMATION TO CLEAR (?)									
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE		MTH	21-Jun-2018			288			?
	9914678-4	KGYG		40005399-1	HRS	1712.1				
				7011	LDG	1025				
	MISSING "MANUFACTURE DATE" TO INSTALLED "OVERHAULED" UNIT. PLEASE SUPPLY MISSING INFORMATION TO CLEAR (?)									
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT		MTH							New Req
			RECOMMENDED	MSC						

Overdue Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION				DAYS		180		12-Mar-2017	-29 m 24 d
			MANDATORY		HRS		DAYS		1596.15	-190.65
							300 HRS			Over Due
052506A	INSPECT ELT SRSAT BEACON REGISTRATION		MTH	12-Mar-2015			24		31-Mar-2017	-29 m 5 d
					HRS	972.4				
					LDG	613				Over Due
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHSR SOFTWARE UPDATE		MTH				6 MTH		31-Mar-2017	-29 m 5 d
			MANDATORY				300 HRS		1607.22	-179.58
										Over Due
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES		MTH				24 MTH		16-Jun-2017	-26 m 20 d
			MANDATORY							Over Due
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.		MTH				6 MTH		16-Apr-2018	-16 m 20 d
			MANDATORY							Over Due
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS, TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS		MTH				12 MTH		24-Oct-2018	-10 m 12 d
			MANDATORY							Over Due
256002	ELT BATTERY	KMKE	MTH	20-Nov-2013	1		60	0	31-Dec-2018	-8 m 5 d
				DEC 2018	HRS	796.1		0		
					LDG	476		0		Over Due
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01): INSPECTION DOCUMENT 22		MTH	15-Feb-2017	-20		24		31-Jan-2019	-7 m 5 d
		KGYG			HRS	1389.8				
					LDG	854				Over Due
B341001	CALIBRATION TEST INDICATOR 14 CFR PART 91.411: INSPECTION DOCUMENT 22		MTH	15-Feb-2017	-31		24		31-Jan-2019	-7 m 5 d
AIRSPEED 051222 : A/S		KGYG		261440-1143						
				298581A						Over Due

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).



CESCOM 20 - Projected Maintenance Due

Owner: **DUNCAN AVIATION
INCORPORATED - BATTLE
CREEK**

Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0218**
 Unit: **0218** Reg No: **N949JB**
 Airworthiness: **10-Jun-2009**
 Print Date: **05-Sep-2019 12:02PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 1	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 2	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
AIR COND	172.2		05-Sep-2019	.9	0.90	680.4		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Overdue Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341001 NO. 1 <i>051222 : ADC</i>	CALIBRATION TEST GDC 74B AIRDATA SYSTEM	KGYY		14 CFR PART 91.411: INSPECTION DOCUMENT 22 011-01110-00 43805487	MTH 15-Feb-2017	-31	24		31-Jan-2019	-7 m 5 d Over Due
B341001 NO. 2 <i>051222 : ADC#2</i>	CALIBRATION TEST GDC 74B AIRDATA SYSTEM	KGYY		14 CFR PART 91.411: INSPECTION DOCUMENT 22 011-01110-00 43805498	MTH 15-Feb-2017	-31	24		31-Jan-2019	-7 m 5 d Over Due
B341001 STANDBY <i>051222 : STDBY</i>	CALIBRATION TEST ALTIMETER	KGYY		14 CFR PART 91.411: INSPECTION DOCUMENT 22 162350-1161 177833C	MTH 15-Feb-2017	-31	24		31-Jan-2019	-7 m 5 d Over Due
B345000 LEFT <i>051222 : XPDR1</i>	CALIBRATION TEST TRANSPONDER	KGYY		14 CFR PART 91.413 : INSPECTION DOCUMENT 22 011-00779-01 84805540	MTH 15-Feb-2017	-31	24		31-Jan-2019	-7 m 5 d Over Due
B345000 RIGHT <i>051222 : XPDR2</i>	CALIBRATION TEST TRANSPONDER	KGYY		14 CFR PART 91.413 : INSPECTION DOCUMENT 22 011-00779-01 84805544	MTH 15-Feb-2017	-31	24		31-Jan-2019	-7 m 5 d Over Due
256001 NO. 1	LIFE VEST	MKE		P01224-205 319242	MTH 26-Jan-2015 HRS 929.7 LDG 571		120	71 0 0	28-Feb-2019	-6 m 5 d Over Due
256001 NO. 2	LIFE VEST	MKE		P01224-205 319369	MTH 26-Jan-2015 HRS 929.7 LDG 571		120	71 0 0	28-Feb-2019	-6 m 5 d Over Due
256001 NO. 3	LIFE VEST	MKE		P01224-205 319215	MTH 26-Jan-2015 HRS 929.7 LDG 571		120	71 0 0	28-Feb-2019	-6 m 5 d Over Due
256001 NO. 4	LIFE VEST	MKE		P01224-205 319368	MTH 26-Jan-2015 HRS 929.7 LDG 571		120	71 0 0	28-Feb-2019	-6 m 5 d Over Due
256001 NO. 5	LIFE VEST	MKE		P01224-205 319318	MTH 26-Jan-2015 HRS 929.7 LDG 571		120	71 0 0	28-Feb-2019	-6 m 5 d Over Due
256001 NO. 6	LIFE VEST	MKE		P01224-205 319317	MTH 26-Jan-2015 HRS 929.7 LDG 571		120	71 0 0	28-Feb-2019	-6 m 5 d Over Due
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KGYY			MTH 21-Jun-2018 HRS 1712.1 LDG 1025	-88.9	12 450		30-Jun-2019 (2073.2)2073.2	-2 m 5 d 286.4 Over Due
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KGYY			MTH 21-Jun-2018 HRS 1712.1 LDG 1025	-88.9	12 450		30-Jun-2019 (2073.2)2073.2	-2 m 5 d 286.4 Over Due



CESCOM 20 - Projected Maintenance Due

Owner: **DUNCAN AVIATION
INCORPORATED - BATTLE
CREEK**

Aircraft Model: **510 - CITATION MUSTANG**

Aircraft Serial: **510-0218**

Unit: **0218** Reg No: **N949JB**

Airworthiness: **10-Jun-2009**

Print Date: **05-Sep-2019 12:02PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 1	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 2	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
AIR COND	172.2		05-Sep-2019	.9	0.90	680.4		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Overdue Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-06 051206	INSPECTION DOCUMENT 06	KGYY	MTH HRS LDG	21-Jun-2018 1712.1 1025		12		30-Jun-2019	-2 m 5 d Over Due
5-12-13 051213	INSPECTION DOCUMENT 13	KGYY	MTH HRS LDG	21-Jun-2018 1712.1 1025		12 450		30-Jun-2019 2162.1	-2 m 5 d 375.3 Over Due
5-12-14 051214	INSPECTION DOCUMENT 14	KGYY	MTH HRS LDG	21-Jun-2018 1712.1 1025		12 900		30-Jun-2019 2612.1	-2 m 5 d 825.3 Over Due
5-12-21 051221	INSPECTION DOCUMENT 21	KGYY	MTH HRS LDG	21-Jun-2018 1712.1 1025		12		30-Jun-2019	-2 m 5 d Over Due
5-12-35	INSPECTION DOCUMENT 35	UNK	MTH HRS LDG	18-Dec-2018 1786.8 1071		6		30-Jun-2019	-2 m 5 d Over Due
5-12-MD 0512MD	INSPECTION DOCUMENT MD	KGYY	MTH HRS LDG	21-Jun-2018 1712.1 1025		12		30-Jun-2019	-2 m 5 d Over Due
731020 E1	CHECK/REPLACE FUEL FILTER ELEMENT	KGYY	MTH HRS LDG	21-Jun-2018 1712.1 1025		12 900		30-Jun-2019 (2612.1)2612.1	-2 m 5 d 825.3 Over Due
731020 E2	CHECK/REPLACE FUEL FILTER ELEMENT	KGYY	MTH HRS LDG	21-Jun-2018 1712.1 1025		12 900		30-Jun-2019 (2612.1)2612.1	-2 m 5 d 825.3 Over Due
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	KGYY	PN SN-UNKNOWN MTH HRS LDG	18-Dec-2018 1786.8 1071		6 100		30-Jun-2019 (1886.8)1886.8	-2 m 5 d 100 Over Due
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	UNK	35C0412-01 SN-UNKNOWN MTH HRS LDG	18-Dec-2018 1786.8 1071		6 100		30-Jun-2019 (1886.8)1886.8	-2 m 5 d 100 Over Due
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK): INSPECTION DOCUMENT 06	KGYY	C352 X-465737 MTH HRS LDG	21-Jun-2018 1712.1 1025		12		30-Jun-2019	-2 m 5 d Over Due

Scheduled Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
790015 E1	REPLACE OIL FILTER ELEMENT	MKE	MTH HRS LDG	26-Jan-2015 929.7 571		900		(1829.7)1829.7	42.9



CESCOM 20 - Projected Maintenance Due

Owner: **DUNCAN AVIATION
INCORPORATED - BATTLE
CREEK**

Aircraft Model: **510 - CITATION MUSTANG**

Aircraft Serial: **510-0218**

Unit: **0218** Reg No: **N949JB**

Airworthiness: **10-Jun-2009**

Print Date: **05-Sep-2019 12:02PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 1	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 2	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
AIR COND	172.2		05-Sep-2019	.9	0.90	680.4		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
790015 E2	REPLACE OIL FILTER ELEMENT	MKE		MTH 26-Jan-2015 HRS 929.7 LDG 571			900		(1829.7)1829.7	42.9
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING			CATEGORY 3 MTH HRS			12 MTH 600 HRS		20-Nov-2019 (2394.17)2394.17	2 m 15 d 607.37
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING			CATEGORY 3 MTH HRS			12 MTH 600 HRS		20-Nov-2019 (2394.17)2394.17	2 m 15 d 607.37
5-12-07 051207	INSPECTION DOCUMENT 07	GYG		MTH 21-Nov-2017 HRS 1569.9 LDG 950			24		30-Nov-2019	2 m 25 d
5-12-15 051215	INSPECTION DOCUMENT 15	GYG		MTH 21-Nov-2017 HRS 1569.9 LDG 950			24		30-Nov-2019 2919.9	2 m 25 d 1133.1
5-12-02 051202	INSPECTION DOCUMENT 02	KGYG		MTH 12-Mar-2015 HRS 972.4 LDG 613			900		1872.4	85.6
5-12-MB 0512MB	INSPECTION DOCUMENT MB	KGYG		MTH 12-Mar-2015 HRS 972.4 LDG 613		-22.4	950		1900	113.2
B243005	FUNCTIONAL CHECK MAIN SHIP BATTERY	GILL TELEDYNE ICA TD14-8-01 LT VALVE-REGULATED BATTERY		7639-30LT G03003567 MTH 01-Aug-2018 HRS 1741.2			18 1800		29-Feb-2020 3541.2	5 m 24 d 1754.4
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	KGYY		PN SN-UNKNOWN HRS 1786.8			100		(1986.8)1986.8	200
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	UNK		35C0412-01 SN-UNKNOWN HRS 1786.8			100		(1986.8)1986.8	200
5-12-MA 0512MA	INSPECTION DOCUMENT MA	GYG		MTH 21-Nov-2017 HRS 1569.9 LDG 950		-12.8	500		2057.1	270.3
262003 LEFT	FIRE EXT CARTRIDGE	KGYY		13083-5 14G540-001 MTH 12-Mar-2015 HRS 972.4 LDG 613			72	8	31-Jul-2020	10 m 26 d
262003A LEFT 262003 : L	REPLACE FIRE EXT CARTRIDGE	*CF		13083-5 14G540-001 MTH 12-Mar-2015			72		31-Jul-2020	10 m 26 d
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	KGYY		PN SN-UNKNOWN HRS 1786.8			100		(2086.8)2086.8	300
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	UNK		35C0412-01 SN-UNKNOWN HRS 1786.8			100		(2086.8)2086.8	300
262003 RIGHT	FIRE EXT CARTRIDGE	KGYY		13083-5 14H543-001 MTH 12-Mar-2015 HRS 972.4 LDG 613			72	7	31-Aug-2020	11 m 26 d
262003A RIGHT 262003 : R	REPLACE FIRE EXT CARTRIDGE	*CF		13083-5 14H543-001 MTH 12-Mar-2015			72		31-Aug-2020	11 m 26 d
5-12-01 051201	INSPECTION DOCUMENT 01	KGYY		MTH 21-Jun-2018 HRS 1712.1 LDG 1025			450		2162.1	375.3
5-12-31 051231	INSPECTION DOCUMENT 31	KGYY		MTH 21-Jun-2018 HRS 1712.1 LDG 1025			450		2162.1	375.3



CESCOM 20 - Projected Maintenance Due

Owner: **DUNCAN AVIATION
INCORPORATED - BATTLE
CREEK**

Aircraft Model: **510 - CITATION MUSTANG**

Aircraft Serial: **510-0218**

Unit: **0218** Reg No: **N949JB**

Airworthiness: **10-Jun-2009**

Print Date: **05-Sep-2019 12:02PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 1	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 2	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
AIR COND	172.2		05-Sep-2019	.9	0.90	680.4		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	KGYY		PN SN-UNKNOWN	HRS 1786.8		100		(2186.8)2186.8	400
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	UNK		35C0412-01 SN-UNKNOWN	HRS 1786.8		100		(2186.8)2186.8	400
B243005	FUNCTIONAL CHECK MAIN SHIP BATTERY			GILL TELEDYNE ICA TD14-8-01 LT VALVE-REGULATED BATTERY 7639-30LT G03003567	MTH 01-Aug-2018		18		30-Nov-2020	14 m 25 d
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	KGYY		PN SN-UNKNOWN	HRS 1786.8		100		(2286.8)2286.8	500
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	UNK		35C0412-01 SN-UNKNOWN	HRS 1786.8		100		(2286.8)2286.8	500
351001 LEFT	CREW OXYGEN MASK 9914067-41	KGYY		MC10-16-101 SE27818	MTH 24-Jun-2015 HRS 1044.9 LDG 652		72	0	30-Jun-2021	21 m 25 d
351001 RIGHT	CREW OXYGEN MASK 9914067-41	KGYY		MC10-16-101 SE27823	MTH 24-Jun-2015 HRS 1044.9 LDG 652		72	0	30-Jun-2021	21 m 25 d
5-12-32 051232	INSPECTION DOCUMENT 32	KGYY			MTH 24-Jun-2015 HRS 1044.9 LDG 652		72		30-Jun-2021	21 m 25 d
5-12-ME 0512ME	INSPECTION DOCUMENT ME	KGYY			MTH 21-Jun-2018 HRS 1712.1 LDG 1025		36	1400	30-Jun-2021	21 m 25 d 3112.1 1325.3
720003 E1	INSPECT LOW UTILIZATION ENGINE	*CF			MTH 10-Jun-2009		144		30-Jun-2021	21 m 25 d
720003 E2	INSPECT LOW UTILIZATION ENGINE	*CF			MTH 10-Jun-2009		144		30-Jun-2021	21 m 25 d
B262101 051212	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST): INSPECTION DOCUMENT 12	*CF		C352 X-465737	MTH 10-Jun-2009		144		30-Jun-2021	21 m 25 d
B323001 051208 : LG	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST)	KGYY		40005369-2 6859	MTH 21-Jun-2018		36		30-Jun-2021	21 m 25 d
B324002 051208 : EB	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST)	KGYY		40005399-1 7011	MTH 21-Jun-2018		36		30-Jun-2021	21 m 25 d
793015 E1	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	KGYY		PN SN-UNKNOWN	HRS 1786.8		100		(2386.8)2386.8	600
793015 E2	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS	UNK		35C0412-01 SN-UNKNOWN	HRS 1786.8		100		(2386.8)2386.8	600
5-12-11 051211	INSPECTION DOCUMENT 11	KGYY			MTH 22-Jul-2015 HRS 1065.7 LDG 667		72		31-Jul-2021	22 m 26 d
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION): INSPECTION DOCUMENT 11	KGYY		C352 X-465737	MTH 22-Jul-2015 HRS 1065.7 LDG 667		72		31-Jul-2021	22 m 26 d
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD			PN SN-UNKNOWN	MTH 10-Jun-2009 ACH		800 FRE	0	800	627.8



CESCOM 20 - Projected Maintenance Due

Owner: **DUNCAN AVIATION
INCORPORATED - BATTLE
CREEK**

Aircraft Model: **510 - CITATION MUSTANG**

Aircraft Serial: **510-0218**

Unit: **0218** Reg No: **N949JB**

Airworthiness: **10-Jun-2009**

Print Date: **05-Sep-2019 12:02PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 1	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
ENG 2	1786.8	1071	05-Sep-2019	.9	0.90	680.4	680	756	24
AIR COND	172.2		05-Sep-2019	.9	0.90	680.4		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
B243005	FUNCTIONAL CHECK MAIN SHIP BATTERY	GILL TELEDYNE ICA TD14-8-01 LT VALVE-REGULATED BATTERY								
		7639-30LT	MTH	01-Aug-2018			18		31-Aug-2021	23 m 26 d
		G03003567								
256001	LIFE VEST	MKE		P01224-205	MSC		O/C			
NO. 1				319242						
256001	LIFE VEST	MKE		P01224-205	MSC		O/C			
NO. 2				319369						
256001	LIFE VEST	MKE		P01224-205	MSC		O/C			
NO. 3				319215						
256001	LIFE VEST	MKE		P01224-205	MSC		O/C			
NO. 4				319368						
256001	LIFE VEST	MKE		P01224-205	MSC		O/C			
NO. 5				319318						
256001	LIFE VEST	MKE		P01224-205	MSC		O/C			
NO. 6				319317						

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE									
				MTH						
				RECOMMENDED	MSC		-			
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM									
				MTH						
				RECOMMENDED	MSC		-			

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2015-08-07	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES									
PARA (H)				MSC						
				MANDATORY						